

INSURANCE

INS. CASE OWNER

Justin

CC6 / LCR18002377 / Uws3

LKK

IDAC

Surveyor

Marcus

DOI

06/02/18

Date / Time

06/02/18

Registered in Merimen

06/12/18

Pre-assign / CCU / FTE



Insured Vehicle No. : SLK 56935

Claim No. : 89597650959

Name of Insured : LCR

Policy No. : 0999995170

Insured Tel No. : HP:

Make / Model : TOYOTA SIENNA

Excess Sec II :SS D.O.A : 29/10/18

Place of Accident : ECP (TOWARDS CHANGE AIRPORT)

Is driver the owner? (YES NO) Nature of Accident :

If NO, Driver Name / Age : LIM CHEE WEE (LIN ZHENWEI)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. : (V/L YES NO)

Insured Liability : % Final ? Yes / No

SL 32366



INRS: WSP: Ngee Sing Auto
Tel: Liability: RMKS:



INRS: WSP: Tel: Liability: RMKS:



INRS: WSP: Tel: Liability: RMKS:



INRS: WSP: Tel: Liability: RMKS:

Date/ Time		STAGE	DATE/ PIC
08/02/18 (Surviving)	SL 32366 - NA/MS6170045761-3 009: 03/03/18 SLK 56935 - X	Non-Reporting Itr (1st) Non-Reporting Itr (2nd) Non-Reporting Itr (Final) Notification Itr (if non-pickup) Call OI After call Itr to OI	
12/1/18	Email letter to OI	Documentation Check List: Handler Typist	
		Notification Itr (if non-pickup)	
		After call Itr to OI	<input checked="" type="checkbox"/>
		Authorisation To Act	<input checked="" type="checkbox"/>
		Release Voucher	<input checked="" type="checkbox"/>
		Final Repair Bill	<input checked="" type="checkbox"/>
		Car Rental Invoice	
		Towing Invoice	
		LTA / GIA :	<input checked="" type="checkbox"/>
		Medical Bill	
		PIR	
		Mandate/Reject Instruction:	
		LOD	
		Payment Breakdown Form:	
		Post-Repair Photos:	
		Others:	

PRELIMINARY ADVICE Date/Time: Sent By: Confirm with: Confirm by:

Repair Cost: \$\$ (days) Reduction: % Email Call

FINAL SETTLEMENT Date/Time: 22/3/18 Confirm with: Ngee Sing. Email Call

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No. : 37 If NO or B 28, Ass. Lia :

Repair Cost: \$\$ 4651.61

Loss of Rental (LOR): \$\$ (days)

Loss of Use (LOU): \$\$ 400.00 (5100 x 4 days)

Loss of Income (LOI): \$\$ (5 x days)

LOR only LOU only LOR + LOU LOR + LOI [Tick only one]

GIA/LTA Search: \$\$ 2.00

Medical: \$\$

Disbursement: \$\$ (e.g. Tow/ Independent)

Legal Cost: \$\$

Total: \$\$ 5059.61 Global Sum \$\$:

FINAL PAYMENT Date/Time: Confirm with: Email Call

Payee 1: \$\$ 5059.61 Name 1: Ngee Sing Auto Works.

Payee 2: (Strike if N.A.) \$\$ Name 2:

Payee 3: (Strike if N.A.) \$\$ Name 3:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/LCR18002377/Uws3	
78 SHENTON WAY #08-16 CHARTIS BUILDINGS SINGAPORE 079120		Date : 06-02-2018	
		Code : LCR	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLK 5693S	Veh. Inspected	SLL 3236L
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	06/02/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	29/01/2018	Inspection Date	06/02/2018
Survey held at	NGEE SENG AUTO WORKS BLK. 3022A, UBI ROAD 1, #01-50 SINGAPORE 408716.		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
 Owner ID: 03271

Vehicle Details

Vehicle No.: SLL3236L
 Vehicle to be Exported: No
 Intended De-registration Date: 06 Feb 2018
 Vehicle Make: MINI
 Vehicle Model: COOPER S CLUBMAN AT LED NAV
 Primary Colour: White
 Manufacturing Year: 2016
 Engine No.: F854H392B48A20A
 Chassis No.: WMWLN720X02F25303
 Maximum Power Output: 141.0 kW (189 bhp)
 Open Market Value: \$32,611.00
 Original Registration Date: 21 Feb 2017
 First Registration Date: 21 Feb 2017
 Transfer Count: 1
 Actual ARF Paid: \$37,656.00

Intended PARF Rebate Details

PARF Eligibility: Yes
 PARF Eligibility Expiry Date: 20 Feb 2027
 PARF Rebate Amount: \$28,242.00

Intended COE Rebate Details

COE Expiry Date: 20 Feb 2027
 COE Category: B - Car above 1600cc or 97kW (130bhp)
 COE Period(Years): 10
 QP Paid: \$53,106.00
 COE Rebate Amount: \$48,016.00
Total Rebate Amount: \$76,258.00

The information contained herein is correct as at 06 Feb 2018

Vivian Lau (LKKAuto)

From: Vivian Lau (LKKAuto)
Sent: Monday, 12 February, 2018 5:50 PM
To: 'eyap@lioncityrentals.com.sg'
Cc: Hsiao Tong (LKKAuto); Joy Irene (LKKAuto)
Subject: ACCIDENT INVOLVING SLK 5693S & SLL 3236L ON 29/02/2018

Our Ref: CC6/LCR18002377/Uws3

12 February 2018

LION CITY RENTALS PTE LTD

Dear Sir/Madam,

ACCIDENT INVOLVING SLK 5693S & SLL 3236L ON 29/02/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please call us if you have further queries.

Thank you

Best Regards,

Vivian Lau | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-8625 | email: Vivianlau@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)


AUTHORIZATION TO ACT
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

I, Ng Mun leong ("the third party claimant")
of 3 Jalan Buloh Perindu Singapore 457661 (address),
owner of SLL 3236L (vehicle no.) hereby authorize
Ngee Seng Auto Works
("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. SLL 3236L that was
damaged pursuant to the accident which occurred on 29/1/18 (date) along
ECP Twds Airport (location)
involving vehicle no/s SLK 56938 ("the accident").

I further authorize the workshop to settle the above mentioned claim in a
manner that they deem fit and the workshop is further authorized to receive
payment furtherto settlement of my claim with payment cheque/s being made in
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my
behalf is on a without prejudice and without admission of liability basis insofar
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 6 day of 2 (month) 20 18 (year)



Signed by "the third party claimant"

隆 盛 摩 呀
NGEE SENG AUTO WORKS

Co. Reg. No. 5279150014
Blk 3022A, Ubi Road 1, #01-30
Singapore 408716
Tel: 6541 2276 Fax: 6743 9006



Signed by "the workshop"

RELEASE VOUCHER
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

We/I, Ngee Seng Auto Works ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte. Ltd. Lkk Auto Consultants Pte Ltd ("name of surveyor") with respect to the amount claimed for S\$ 4651.61 (repair costs), S\$ 400.00 (loss of use/rental) S\$ 8.00 (search fees) for vehicle no. SLL3236L that was damaged pursuant to the accident which occurred on 29/1/18 (date) along ECP Tudu Airport (location) involving vehicle no/s SLK 56A3S.

This is pursuant to the inspection conducted on 06/02/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Ng Muan Leong ("third party claimant") of vehicle no. SLL3236L to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte. Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SLL3236L (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any disputes arising out of the same.

Dated this 22 day of 3 (month) 20 18 (year)

cks



Signed by AIG appointed surveyor

拉盛摩呀
NGEE SENG AUTO WORKS

Co. Reg. No. 52791500M
 Blk 3022A, Ubi Road 1, #01-50
 Singapore 408716
 Tel: 6841 2276 Fax: 6742 9008

Chopped & Signed by "the workshop"



NGEE SENG AUTO WORKS 誼盛摩哆

REGISTRATION NO: 52791500M

Blk. 3022A, Ubi Road 1, #01-50, Singapore 408716. Tel: 6841 2276 Fax: 6743 9006

ALL TYPES OF MOTOR REPAIRS SERVICES, SPRAY PAINTING & INSURANCE CLAIMS.

AIG ASIA PACIFIC INSURANCE PTE LTD

78, Shenton Way #07-16

Chartis Building

Singapore 079120

ATTN : Motor Claims Depts

FINAL Repair Bill

:TP18002

Date

:12/03/2018

Ref No

:SLL 3236 L

Your Ref

:SLK 5693 S

Page

: 01

RE : VEHICLE NO. SLL 3236 L MINI COOPERS

PARTS BY PARTS

\$4,651.61



NGEE SENG AUTO WORKS

Enquire Vehicle & Owner Information (Vehicle No. SLK5693S As At 29 Jan 2018 / 15:30:00)**Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident
Law Firm Case No.: N1/02/2018(MISC3)

Current Owner Details

Owner ID Type: Company
Owner ID: 201624597K
Owner Name: LCRF PTE LTD
Registered Address Type: Private Residential (non-Condo Apt / non-House)
Registered Block/House No.: 60
Registered Street Name: ANSON ROAD
Registered Unit No.: # 11 - 01
Registered Building Name: MAPLETREE ANSON
Registered Postal Code: 079914

Current Vehicle Details

Vehicle No.: SLK5693S
Make Description/Model: TOYOTA / SIENTA 1.5X HYBRID AT ABS D/AIRBAG 2WD
Insurance Company Name: AIG ASIA PACIFIC INSURANCE PTE. LTD.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Feb 2018 Edit Reg		06 Feb 2018 00:00 Edit Adj Rpt	S\$4,651.62 Edit Estimates	S\$4,651.62 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	LCRF PTE LTD , Co. Reg. No.: 201624597K								
Main Claimant:	NG MUAN LEONG , ID: S26203271								
Vehicle Reg. No.:	SLL3236L	Date of Loss:	29/01/2018 15:00 - :59						
Claim Type:	TP / B959265509SG	Policy/Cover Note No.:	999995170 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLK5693S	Policy No. (Claimant):	1700084822						
Repairer:	Ngee Seng Auto Works (HQ) Block 3022A, Ubi Road 1, #01-50, 408716 Ubi - Tel: 6841 2276								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Wong, Justin] Justin.Wong@aig.com								
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 15/02/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLL3236L (8959265509SG)
 [SLK5693S]
 TP
 NG MUAN LEONG
 Jan 29 2018 3:30PM
 [LCRF PTE LTD]
 Ngee Seng Auto Works

Upload Documents	Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser v	
Letters/Correspondences					1 per page v	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print	
1	(Draft)	LKK Auto Consultants Pte Ltd (HQ) Third Party Express Settlement - Payment Breakdown		1 v Edit		
Assessment Reports					1 per page v	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print	
1	07/02/18 16:01	AIG Asia Pacific Insurance Pte. Ltd. (SG) Accident Statement <small>From: SC - Reg. No: SLK5693S, Claimant: LCRF PTE LTD</small>		1 v Load HTM		
Photos/Images					3 per page v	<input checked="" type="checkbox"/>
No	Relabel/Reorder			Thumbnail	Print	
1	06/02/18 19:10	LKK Auto Consultants Pte Ltd (HQ) General View		1 v Load JPG	<input checked="" type="checkbox"/>	
2	06/02/18 19:10	General View		1 v Load JPG	<input checked="" type="checkbox"/>	
3	06/02/18 19:10	General View		1 v Load JPG	<input checked="" type="checkbox"/>	
4	06/02/18 19:10	General View		1 v Load JPG	<input checked="" type="checkbox"/>	
5	06/02/18 19:10	General View		1 v Load JPG	<input checked="" type="checkbox"/>	
6	06/02/18 19:10	General View		1 v Load JPG	<input checked="" type="checkbox"/>	
7	06/02/18 19:10	General View		1 v Load JPG	<input checked="" type="checkbox"/>	
8	06/02/18 19:10	General View		1 v Load JPG	<input checked="" type="checkbox"/>	
9	06/02/18 19:10	General View		1 v Load JPG	<input checked="" type="checkbox"/>	
10	06/02/18 19:10	General View		1 v Load JPG	<input checked="" type="checkbox"/>	
11	06/02/18 19:10	General View		1 v Load JPG	<input checked="" type="checkbox"/>	
12	06/02/18 19:10	General View		1 v Load JPG	<input checked="" type="checkbox"/>	
13	06/02/18 19:10	General View		1 v Load JPG	<input checked="" type="checkbox"/>	
14	06/02/18 19:10	General View		1 v Load JPG	<input checked="" type="checkbox"/>	
15	06/02/18 19:10	General View		1 v Load JPG	<input checked="" type="checkbox"/>	
16	06/02/18 19:10	General View		1 v Load JPG	<input checked="" type="checkbox"/>	
17	06/02/18 19:10	General View		1 v Load JPG	<input checked="" type="checkbox"/>	
18	06/02/18 19:10	General View		1 v Load JPG	<input checked="" type="checkbox"/>	
19	06/02/18 19:10	General View		1 v Load JPG	<input checked="" type="checkbox"/>	
20	06/02/18 19:10	General View		1 v Load JPG	<input checked="" type="checkbox"/>	
21	06/02/18 19:10	General View		1 v Load JPG	<input checked="" type="checkbox"/>	
22	06/02/18 19:10	General View		1 v Load JPG	<input checked="" type="checkbox"/>	
23	06/02/18 19:10	General View		1 v Load JPG	<input checked="" type="checkbox"/>	
24	06/02/18 19:10	General View		1 v Load JPG	<input checked="" type="checkbox"/>	
25	06/02/18 19:10	General View		1 v Load JPG	<input checked="" type="checkbox"/>	
26	06/02/18 19:10	General View		1 v Load JPG	<input checked="" type="checkbox"/>	
27	06/02/18 19:10	General View		1 v Load JPG	<input checked="" type="checkbox"/>	
28	06/02/18 19:10	General View		1 v Load JPG	<input checked="" type="checkbox"/>	

29	06/02/18 19:10	General View	1	Load JPG	<input checked="" type="checkbox"/>
30	06/02/18 19:10	General View	1	Load JPG	<input checked="" type="checkbox"/>
31	06/02/18 19:10	General View	1	Load JPG	<input checked="" type="checkbox"/>
32	06/02/18 19:10	General View	1	Load JPG	<input checked="" type="checkbox"/>
33	06/02/18 19:10	General View	1	Load JPG	<input checked="" type="checkbox"/>
34	06/02/18 19:10	General View	1	Load JPG	<input checked="" type="checkbox"/>
35	06/02/18 19:10	General View	1	Load JPG	<input checked="" type="checkbox"/>
36	06/02/18 19:10	General View	1	Load JPG	<input checked="" type="checkbox"/>
37	06/02/18 19:10	General View	1	Load JPG	<input checked="" type="checkbox"/>
38	06/02/18 19:10	Chassis Number	1	Load JPG	<input checked="" type="checkbox"/>
39	06/02/18 19:10	General View	1	Load JPG	<input checked="" type="checkbox"/>
40	06/02/18 19:10	Odometer Reading	1	Load JPG	<input checked="" type="checkbox"/>
41	05/03/18 19:57	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
42	05/03/18 19:57	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
43	05/03/18 19:57	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
44	05/03/18 19:57	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
45	05/03/18 19:57	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
46	05/03/18 19:57	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
47	05/03/18 19:57	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
48	05/03/18 19:57	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
49	05/03/18 19:57	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
50	05/03/18 19:57	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
51	05/03/18 19:57	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
52	05/03/18 19:57	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
53	05/03/18 19:57	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
54	05/03/18 19:57	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
55	05/03/18 19:57	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
56	05/03/18 19:57	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
57	05/03/18 19:57	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
58	05/03/18 19:57	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
59	05/03/18 19:57	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
60	05/03/18 19:57	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
61	05/03/18 19:57	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
62	05/03/18 19:57	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
63	05/03/18 19:57	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
64	05/03/18 19:57	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
65	05/03/18 19:57	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
66	05/03/18 19:57	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
67	05/03/18 19:57	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
68	05/03/18 19:57	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
69	05/03/18 19:57	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
70	05/03/18 19:57	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
71	05/03/18 19:57	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
72	05/03/18 19:57	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	08/02/18 11:29	TP GIA REPORT	1	Load PDF	
2	08/02/18 11:29	TP ESTIMATE- MARKED	1	Load PDF	
3	12/02/18 17:52	Email letter to OIACCIDENT INVOLVING SLK 5693S & SLL 3236L ON 29.01.2018	1	Load PDF	

4	23/03/18 10:38	WORKSHOP INVOICE		Load PDF	
5	23/03/18 10:38	AUTHORISATION TO ACT FORM		Load PDF	
6	23/03/18 10:38	Release Voucher		Load PDF	
7	23/03/18 10:38	LTA SEARCH		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer
<small>Note: Remarks are private unless you show it to other parties.</small>

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SLK5693S (Insd veh)	Model:	MINI COOPER S 2.0 (A)
	SLL3236L (TP veh)		
Date of Accident:	29/01/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Repair Estimate	:	\$	10,723.00	
Final Repair Cost	:	\$	4,651.61	
Loss of Use	:	\$	400.00	4.00 days at \$100.00 per day
Rental (if any)	:	\$	0.00	days
LTA / GIA Search Fee	:	\$	8.00	
Others:	:	\$	0.00	
	:	\$		
Final Settlement Sum	:	\$	5,059.61	
Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below)				
A) For <u>Non GIA Registered Workshop</u> :		Agreed Liability _____ 100 _____ (%)		
B) For <u>GIA Registered Workshop</u> :		BOLA Applicable: Yes/ No BOLA Scenario No: _____		
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks _____				

Payment Instruction: Payee's Breakdown			
1)	Ngee Seng Auto Works	:	\$ 5,059.61
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

23 Mar
2018

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/LCR18002377/UWS3Q2

Date: 23/03/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 999995170
 Claimant Vehicle No: SLL3236L Insured Vehicle No: SLK5693S
 Date of Loss: 29/01/2018 Nature of Claim: TP Claim No: 8959265509SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLL3236L
 Make & Model: MINI COOPER S, 2.0 (A) Engine No: F854H392B48A20A
 Reg. Date: 21/02/2017 (Man. Year: 2016) Chassis No: WMWLN720X02F25303
 Colour: White Odometer: 14388 km
 Engine Capacity: 1998 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/40 R18 Rear Tyre Size: 225/40 R18
 Front Left Side: Bridgestone 7 mm Rear Left Side: Bridgestone 7 mm
 Front Right Side: Bridgestone 7 mm Rear Right Side: Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,073.00	3,221.62	3,851.38	54.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,650.00	1,430.00	2,220.00	60.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	10,723.00	4,651.62	6,071.38	56.62
+ Loss of Use (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		8.00		
Nett Liability (S\$)		5,059.62		

INSPECTION

Date of Assignment: 06/02/2018
 Date Inspected: 06/02/2018 Inspected At: Ngee Seng Auto Works (HQ)
 Block 3022A, Ubi Road 1, #01-50
 Singapore 408716
 Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID RH	Repair	1,740.00 F	*- FL
2	1		*BOOTLID COOPERS EMBLEM	Necessary	146.00 F	*66.50 FL
3	1		*BOOTLID MINI EMBLEM	Necessary	135.00 F	*72.06 FL
4	1		*BOOTLID CLUBMAN EMBLEM	Necessary	125.00 F	*64.88 FL
5	1		*BOOTLID CHROME MOULDING	Not Necessary	273.00 F	*- FL
6	1		*BOOTLID RUBBER	Twisted	326.00 F	*326.00 FL
7	1		*REAR BUMPER	Dented / Deformed	945.00 F	*945.00 FL
8	1		*REAR BUMPER REINFORCEMENT	Dented	680.00 F	*493.63 FL
9	2		*REAR BUMPER NUMBER PLATE LAMP	Not Necessary	330.00 F	*- FL
10	2		*REAR BUMPER REVERSE SENSOR	Shorted	590.00 F	*590.00 FL
11	1		*REAR BUMPER LOWER BRACKET	Bent	242.00 F	*242.00 FL
12	1		*REAR BUMPER SPOILER	Grazed	474.00 F	*474.00 FL
13	2		*REAR BUMPER LAMP	Not Necessary	694.00 F	*- FL
14	1		*SET REAR BUMPER CLIPS	Necessary	75.00 F	*75.00 FL
15	1		*EXHAUST HEAT SHIELD	Repair	198.00 F	*- FL
16	1		*REAR NUMBER PLATE	Bent	100.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	7,073.00	3,389.07
- List Item Discount on L Items 0.00/5.00% (S\$)	0.00	167.45
Total Parts (S\$)	7,073.00	3,221.62

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECKS WIRING ,CAMERA & REVERSE SENSOR	New	200.00	50.00
2	TO REMOVE & REFIX BOOT LID COMPONENT	New	200.00	0.00
3	TO REMOVE & REFIX WINDSCREEN	New	250.00	0.00
4	TO REMOVE & REFIX EXHAUST	New	150.00	60.00
5	TO PANEL BEATING	New	1,250.00	520.00
6	TO SPRAY PAINTING	New	1,600.00	800.00
Gross Labour Cost (S\$)			3,650.00	1,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >