

23/03/2001

ASS. REC. BY:

REF: CS/MSG18002384/Ktd/302

Instruction:

Survivor:
Mehmen

ASSIGNMENT (Office)

From (Person):

Fiavel Foo

of

MSIG

Date/Time:

6/2/18 @ 11.02am

Estimated Cost:

Bill to:

OD TP WS TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLL5110C

Insured:

SKV 5769L

at Workshop m/s

Cheng Hoe Motor

Tel:

6755 6142

of

Blk 1019 # 01-374 / 382

Policy No:

290383530MX

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

5/2/2018

CA / REV / REP. / REV 24 HRS

'w/p'

H.O.D. Endorsement:

Date/Time

11:37am @ 6/2/18

Person Contacted:

Wei Ling

Vehicle IN OUT

Date/Time

Action/Instruction (✓) Estimate

SLL 5110C - X

SKV 5769L - X


8/11

6/1 Lm 849501 Cabover Jam (Red: 1942.86 : 28%)

Kenneth

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s Chey Lhoc
 of _____
 Insured _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 14 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS
2123
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time	Action / Instruction
<u>7/2</u>	<u>File pass to Catherine</u>

Veh No: SLL 51106 Yr Regn: 02, 08
 Type: M. Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Suzuki c.c. 1490
 Colour: M. Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 198581 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JSAEZC21S00412076
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or _____
 Brake: Inorder / Jammed / Leaked / Burnt or _____
 Modl: Nil / SRim / STD A/Rim or _____
 Tyre Size: F: _____ R: _____
185/55R15
 DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front R/Bal. 6 mm Rear R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 5/2/18 D.O.I. 6/2/18
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear N/S & FR
 The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 08 NOV 2018

[Signature]
8/11/2018

Date/Time, File Pass to? : Prell. Report
 1) 9/11/18 : Final Report
 Date/Time, File Return to? _____

Days Of Repair: 14
 Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech Invs (\$)
 : Weekend (\$)

Survey Fee
 Transportation) S - RS) \$
 Photos)
 Others)
 TOTAL

200
10
210

Report Format: TP
 Lump Sum / I.B.I: (\$) 49504



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18002384/Ktd3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 06-02-2018	
Code : MSG			
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKV 5769L	Veh. Inspected	SLL 5110C
Policy No.	29038353QMX	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	MERIMEN (FEIVEL FOO)	Assign Date	06/02/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	05/02/2018	Inspection Date	
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	05 Feb 2018		06 Feb 2018 11:02 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	Wu Qiuming , ID: S7280764B		
Main Claimant:	Lim Soo Ling Angeline (Lin Suling) , ID: S7912885F		
Vehicle Reg. No.:	SLL5110C	Date of Loss:	05/02/2018 08:00 - :59
Claim Type:	TP	Policy/Cover Note No.:	29038353QMX (Comprehensive) Coverage: 29/10/2017 - 28/10/2018
Vehicle Reg. No. (Insured):	SKV5769L	Policy No. (Claimant):	
		Excess:	
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Fievel Foo Wen Yao - 6643 1316]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 07/02/2018]		
Adj Asg. Remarks:	request Kenneth Kong for survey		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

Eileen Ang

From: Joslin Lim
Sent: Monday, 5 February, 2018 3:51 PM
To: Muhd Ashik B Madi; Eileen Ang
Cc: Christopher Chionh; Foo Ai Ngoh; Fievel Foo
Subject: FW: Repair Survey (Single Joint Expert) /ENQUIRY OF LIABILITY - SLL5110C

Follow Up Flag: Follow up
Flag Status: Flagged

From: Koh Lay Hoon
Sent: Monday, 5 February, 2018 3:30 PM
To: Joslin Lim <joslin_lim@sg.msig-asia.com>
Subject: FW: Repair Survey (Single Joint Expert) /ENQUIRY OF LIABILITY - SLL5110C

From: Cheng Hoe Motor Pte Ltd (Yishun-June) [<mailto:chmotor@singnet.com.sg>]
Sent: Monday, February 05, 2018 3:28 PM
To: Claims <claims@sg.msig-asia.com>; Fievel Foo <Fievel_Foo@sg.msig-asia.com>
Subject: Repair Survey (Single Joint Expert) /ENQUIRY OF LIABILITY - SLL5110C

Dear Sir,

OUR CLIENT : SLL5110C
D
OA : 5/2/18 @0850hrs
YOUR I
NSURED : SKV5769L

(A) Kindly provide us your surveyor listing for the selection on the survey.

(B) Also, please advise on liability and are you agree on DIRECT SETTLEMENT?

Thank you.

Regards
June
Cheng Hoe Motor Pte Ltd
Tel :67556142
Fax : 67557719

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 2885F

Vehicle Details

Vehicle No.: SLL5110C

Vehicle to be Exported: Yes

Intended De-registration Date: 05 Feb 2018

Vehicle Make: SUZUKI

Vehicle Model: SWIFT 1.5 AT ABS AIRBAG
2WD

Primary Colour: Blue

Manufacturing Year: 2007

Engine No.: M15A1300217

Chassis No.: JSAEZC21S00412076

Maximum Power Output: 74.0 kW (99 bhp)

Open Market Value: \$11,429.00

Original Registration Date: 25 Feb 2008

First Registration Date: 25 Feb 2008

Transfer Count: 0

Actual ARF Paid: \$12,572.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 24 Feb 2018

PARF Rebate Amount: \$6,286.00

Intended COE Rebate Details

COE Expiry Date: 24 Feb 2023

COE Category: A - Car (1600cc & below)

COE Period(Years): 5

PQP Paid: \$21,061.00

COE Rebate Amount: \$67.00

Total Rebate Amount: \$6,353.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 05 Feb 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	05/02/2018 11:20
Date Of Accident	05/02/2018 08:50
Exact Location Of Accident	ALONG KJE (BEFORE EXIT 7)
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLL5110C
Insured/Policyholder	
Name Of Registered Owner	LIM SOO LING ANGELINE (LIN SULING)
NRIC No	S7912885F
Email Address	A_LINE_51@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-90488901
Alternative Phone No	OTHERS-90488901
Vehicle Particulars	
Manufacturer	SUZUKI
Model	SWIFT 1.5 AT ABS AIRBAG 2WD
Exact Purpose for which vehicle was being used at time of accident	PTE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5053158754-05
Cover Note Number	25/02/17 - 24/02/18
Driver	
Name of Driver	LIM SOO LING ANGELINE (LIN SULING)
NRIC No	S7912885F
Date Of Birth	02/05/1979
Occupation	INDOOR
Date Of Driving Pass	01/12/2005
Driving Experience	12 YEARS AND 2 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-90488901
Fax Number	
Contact Number	OTHERS-90488901
EMail Address	A_LINE_51@HOTMAIL.COM

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

Name of Driver LONG HIEN YAP

NRIC/Passport Number S1454992G

Contact Number 96741013

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name LIM SOO LING ANGELINE (LIN SULING)

Approximate Age

Injuries Sustain RIGHT ARM PAIN

Injured person in which vehicle? SLL5110C

Were seat belts worn?

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

Address	BLK 630 YISHUN ST.61 #09-51
Postcode	760630
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes,Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes,against whom?	

Circumstances of Accident

Heavy traffic along KJE, slowing moving traffic. My car (SLL5110C) was stopped due to slow moving traffic and suddenly SKM4169Y hit into my car and cause my car to move forward and hit SKV5769L at 8.50am on 05 Feb 2018. I have been coughing since the accident with right arm pain, will consult doctor later.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKV5769L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	
Name of Driver	WU QIUMING
NRIC/Passport Number	S7280764B
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SKM4169Y
-----------------------------	----------

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MCHM18017351 Vehicle Registration No: SLL5110C
Name (as shown in NRIC) : Lim Soo Ling Angelina NRIC/FIN/Passport No : S7912885F
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
Address : Blk 630 Yishun St. 61 #09-51 Singapore (760630)
Contact (Tel) : _____ Mobile No. : 90488901
Email Address : a-line-51@hotmail.com
Date of Accident : 05/02/2018 Time of Accident : 08:50
Place of Accident : Along KJE (Before Exit 7)
Insurance Company: NTUC Income

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:


The actual scenario should be my car was hit
by m/car SKV5769L and the impact pushed my car forward
to hit the rear of m/car SKM4169Y.

X Angelina
Policyholder / Driver's Signature
Date:

Sharon
Reporting Centre Personnel's Signature
Name: Sharon
NRIC/FIN No.:
Date: 05/2/18



SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Heavy Traffic along KJE, slowing moving traffic. My car ~~(SLL 5110C)~~ (SLL 5110C), was stopped due to slow moving traffic and suddenly SKM 4169Y hit into my car and cause my car to move forward & hit SKV 5769L, at 8.50am on 5 Feb 18.

I ~~will~~ have been coughing since the accident with right arm pain. Will consult doctor later.

Note : Please note that your insurer may have 14days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature: Angel
 Date & Time: _____
 Driver's Signature: Angel
 (If driver is not the policyholder)
 Date & Time: _____
 Reporting Centre/Personnel's Signature: M
 Name: (YS)
 NRIC/FIN No.: _____

GIARMC SketchPlanForm_V3 () Claim Own Policy () Claim Third Party () Reporting Only () Claim OD/TP at other workshop (_____)

MT/0980969

SKETCH PLAN

VEHICLE NO.: SLL 5110C
INSURER : ATUC
DATE & TIME: 05/18 @ 8.50am

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name: (YS)
NRIC/FIN No.:

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

SLL5110C
TP/MSIG

M/S : MSIG INSURANCE (S) PTE LTD (SGX)
 16 RAFFLES QUAY
 #24-01 HONG LEONG BUILDING
 SINGAPORE 048581

TEL: 68277660 FAX: 62257402

ATTN: Motor Claim Department

WS Ref: TP-MSIG

Claim Type: Third Party

Accident Date: 05/02/2018

TP Veh Reg No: SKV5769L

Estimate No: ES1890132/WS

Date: 06 Feb 2018

Policy No: 5053158754-05

Veh Reg No: SLL5110C

Make/Model: SUZUKI SWIFT 1.5 AT

Chassis No: JASEZC21S00412076

Engine No: M15A1300217

Reg. Date: 25/02/2008

Not Washed
11 Lamp @ ?
Respray After Paint

Estimate Repair Cost to Vehicle No :SLL5110C

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 FRONT BUMPER	549.65	1 PC	549.65	—
2 REAR BUMPER SIDE RETAINER	18.70	2 PC	37.40	✓
3 REAR BUMPER LH BRACKET	25.55	1 PCS	25.55	✓
4 FRONT BUMPER CLIPS	3.50	6 PC	21.00	✓
5 REAR TAILGATE	628.15	1 PC	628.15	✓
6 REAR TAILGATE INNER LOCK	180.10	1 PCS	180.10	✓
7 REAR TAILGATE INNER RUBBER	92.65	1 PCS	92.65	508.00 46.32
8 REAR TAILGATE LOGO	25.50	1 PC	25.50	—
9 REAR TAILGATE EMBLEM 'SWIFT'	24.35	1 PCS	24.35	—
10 REAR END PANEL	274.85	1 PC	274.85	✓
11 REAR END PANEL INNER TOP GARNISH	82.75	1 PC	82.75	—
12 REAR END PANEL INNER TOP GARNISH CLIP	3.50	3 PC	10.50	—
13 REAR PANEL INNER AIR-SCROP GRILLE	35.90	1 PCS	35.90	✓
14 LH TAIL LAMP	287.90	1 PCS	287.90	✓
15 LH TAIL LAMP PANEL	74.90	1 PCS	74.90	✓
16 REAR SPARE TYRE COMPARTMENT	382.15	1 PC	382.15	✓
17 REAR SPARE TYRE COMPARTMENT LH SIDE GARNISH	94.75	1 PC	94.75	✓
18 REAR EXHUAST PIPE	280.50	1 PCS	280.50	✓
19 REAR EXHUAST PIPE HOLDER	20.70	1 PCS	20.70	✓
20 FRONT BUMPER	628.15	1 PC	628.15	—
21 FRONT BUMPER TOP BEAM	172.75	1 PC	172.75	✓
22 FRONT BUMPER CENTRE GARNISH	73.30	1 PC	73.30	✓
23 FRONT BUMPER CLIP	3.50	6 PC	21.00	✓
24 FRONT BUMPER LH SIDE RETAINER	28.70	1 PC	28.70	✓
25 FRONT BUMPER LOWER RUBBER	60.75	1 PC	60.75	✓
26 FRONT GRILLE	69.65	1 PC	69.65	✓
27 FRONT GRILLE CLIPS	3.50	2 PCS	7.00	✓
28 HEAD LAMP	395.25	1 PCS	395.25	✓
29 FRONTLH FENDER EMBLEM 'WT'	23.45	1 PC	23.45	✓
			4,609.25	
		Less 15%	691.39	3,917.86
Special Net				
30 REAR WINDSCREEN GUM	40.00	1 PC	40.00	✓
31 REAR NUMBER PLATE	25.00	1 PCS	25.00	✓
32 REAR SPARE TYRE PANEL TOP COAT	100.00	1 PC	100.00	✓
			165.00	165.00

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : MSIG INSURANCE (S) PTE LTD (SGX)

16 RAFFLES QUAY
 #24-01 HONG LEONG BUILDING
 SINGAPORE 048581

TEL: 68277660 FAX: 62257402

ATTN: Motor Claim Department

WS Ref: TP-MSIG

Claim Type: Third Party

Accident Date: 05/02/2018

TP Veh Reg No: SKV5769L

Estimate No: ES1890132/WS

Date: 06 Feb 2018

Policy No: 5053158754-05

Veh Reg No: SLL5110C

Make/Model: SUZUKI SWIFT 1.5 AT

Chassis No: JASEZC21S00412076

Engine No: M15A1300217

Reg. Date: 25/02/2008

Estimate Repair Cost to Vehicle No :SLL5110C

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
Labour				
33 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	✓
34 REMOVE AND REFIX REAR BUMPER ASSY, TAIL LAMPS, TAILGATE AND ATTACHMENT. TO STRIAGHTEN, KNOCK OUT, CUTTING, WELDING AND RENEW REAR SPARE TYRE COMPARTMENT, REAR PANEL, TAIL LAMP PANEL. TO STRIAGHTEN, KNOCK AND REPAIR REAR LH CHASSISS, REAR LH FENDER INNER		1 LA		
35 TO BE CONTINUE.. PANEL AND REALIGN THE SAME	1,500.00	1 LA	1,500.00	1300
36 REMOVE AND REFIX REAR SEAT, CARPET, GARNISH, REAR SPEAKER AND BOARD, ETC	120.00	1 LA	120.00	100
37 REMOVE AND REFIX REAR EXHUAST PIPE AND CHECK LEAKING	80.00	1 LA	80.00	80
38 REMOVE AND REFIX FRONT BUMPER ASSY, GRILLE, HEAD LAMP. TO KNOCK AND REPAIR FRONT LH FENDER, FRONT SUPPORT PANEL AND REALIGN THE SAME	400.00	1 LA	400.00	320
39 PUTTY AND RESPRAY ON FRONT BUMPER, SUPPORT PANEL, FRONT LH FENDER	500.00	1 LA	500.00	450
40 RUSTPROOFING	90.00	1 LA	90.00	✓
			2,810.00	2,810.00

Total S\$ 6,892.86

Add GST @ 7% 482.50

Total Amount Payable S\$ 7,375.36

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@airtel.net.sg
 GST:201001158E RCB NO:201001158E

SLL5110C
 TP/MSIG

M/S : MSIG INSURANCE (S) PTE LTD (SGX)
 16 RAFFLES QUAY
 #24-01 HONG LEONG BUILDING
 SINGAPORE 048581

TEL: 68277660 **FAX:** 62257402
ATTN: Motor Claim Department
WS Ref: TP-MSIG
Claim Type: Third Party
Accident Date: 05/02/2018
TP Veh Reg No: SKV5769L

Estimate No: ES1890132/WS
Date: 06 Feb 2018
Policy No: 5053158754-05
Veh Reg No: SLL5110C
Make/Model: SUZUKI SWIFT 1.5 AT
Chassis No: JASEZC21S00412076
Engine No: M15A1303217
Reg. Date: 23/02/2008

Estimate Repair Cost to Vehicle No :SLL5110C

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
Labour				
33 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	✓
34 REMOVE AND REFIX REAR BUMPER ASSY, TAIL LAMPS, TAILGATE AND ATTACHMENT. TO STRAIGHTEN, KNOCK OUT, CUTTING, WELDING AND RENEW REAR SPARE TYRE COMPARTMENT, REAR PANEL, TAIL LAMP PANEL. TO STRAIGHTEN, KNOCK AND REPAIR REAR LH CHASSISS, REAR LH FENDER INNER		1 LA		
35 TO BE CONTINUE. PANEL AND REALIGN THE SAME	1,500.00	1 LA	1,500.00	? 1300
36 REMOVE AND REFIX REAR SEAT, CARPET, GARNISH, REAR SPEAKER AND BOARD, ETC	120.00	1 LA	120.00	100
37 REMOVE AND REFIX REAR EXHAUST PIPE AND CHECK LEAKING	80.00	1 LA	80.00	? 60
38 REMOVE AND REFIX FRONT BUMPER ASSY, GRILLE, HEAD LAMP. TO KNOCK AND REPAIR FRONT LH FENDER, FRONT SUPPORT PANEL AND REALIGN THE SAME	400.00	1 LA	400.00	320
39 PUTTY AND RESPLAY ON FRONT BUMPER, SUPPORT PANEL, FRONT LH FENDER	500.00	1 LA	500.00	450
40 RUSTPROOFING	90.00	1 LA	90.00	? ✓ 2440
			2,810.00	2,810.00

Total S\$ 6,892.86
 Add GST @ 7% 482.50
Total Amount Payable S\$ 7,375.36

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

For Cheng Hoe Motor Pte Ltd


 AUTHORISED SIGNATURE
 Pays #4187.90
 Less 15% 628.18
 #3559.72
 4632.94
 165.50
 2440
 #6211.04
 (2008) 45 #4950

Cheng Hoe Motor Pte Ltd

118, 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158F

SLL5110C

O.K.

TP/MSIG

M/S : MSIG INSURANCE (S) PTE LTD (SGX)

16 RAFFLES QUAY
 #24-01 HONG LEONG BUILDING
 SINGAPORE 048581

Estimate No: ES1890132/WS

Date: 06 Feb 2018

Policy No: 6053158754-05

TEL: 68877660

FAX: 62257402

Veh Reg No: SLL5110C

ATTN: Motor Claim Department

Make/Model: SUZUKI SWIFT 1.5 AT

WS Ref: TP-MSIG

Chassis No: JASEZC21S00412076

Claim Type: Third Party

Engine No: M15A1300217

Accident Date: 05/02/2018

Reg. Date: 25/02/2008

TP Veh Reg No: SKV5769L

Not Attached
11 Lmp @ ?
Recovery After Paint

Estimate Repair Cost to Vehicle No :SLL5110C

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 FRONT BUMPER	549.65	1 PC	549.65	✓
2 REAR BUMPER SIDE RETAINER	18.70	2 PC	37.40	✓
3 REAR BUMPER EL BRACKET	25.55	1 PCS	25.55	✓ R
4 FRONT BUMPER CLIPS	3.50	6 PC	21.00	✓
5 REAR TAILGATE	628.15	1 PC	628.15	✓
6 REAR TAILGATE INNER LOCK	180.10	1 PCS	180.10	✓
7 REAR TAILGATE INNER RUBBER	92.65	1 PCS	92.65	50% 46.325 ✓
8 REAR TAILGATE LOGO	25.50	1 PC	25.50	✓
9 REAR TAILGATE EMBLEM SWIFT	24.35	1 PCS	24.35	✓
10 REAR END PANEL	274.85	1 PC	274.85	✓ ✓
11 REAR END PANEL INNER TOP GARNISH	82.75	1 PC	82.75	✓
12 REAR END PANEL INNER TOP GARNISH CLIP	3.50	3 PC	10.50	✓
13 REAR PANEL INNER AIR-SCROP GRILLE	35.90	1 PCS	35.90	✓ ✓
14 LH TAIL LAMP	287.90	1 PCS	287.90	✓ ✓
15 LH TAIL LAMP PANEL	74.90	1 PCS	74.90	✓ ✓
16 REAR SPARE TYRE COMPARTMENT	382.15	1 PC	382.15	✓ ✓
17 REAR SPARE TYRE COMPARTMENT LH SIDE GARNISH	94.75	1 PC	94.75	X ✓
18 REAR EXHAUST PIPE	280.50	1 PCS	280.50	X ✓
19 REAR EXHAUST PIPE HOLDER	20.70	1 PCS	20.70	X ✓
20 FRONT BUMPER	628.15	1 PC	628.15	✓
21 FRONT BUMPER TOP BEAM	172.75	1 PC	172.75	✓ X
22 FRONT BUMPER CENTRE GARNISH	73.30	1 PC	73.30	✓ ✓
23 FRONT BUMPER CLIP	3.50	6 PC	21.00	✓
24 FRONT BUMPER LH SIDE RETAINER	28.70	1 PC	28.70	✓
25 FRONT BUMPER LOWER RUBBER	60.75	1 PC	60.75	✓ X
26 FRONT GRILLE	69.65	1 PC	69.65	✓ X
27 FRONT GRILLE CLIPS	3.50	2 PCS	7.00	✓ ✓
28 HEAD BAMP	395.25	1 PCS	395.25	✓ ✓
29 FRONT LH FENDER EMBLEM W/T	23.45	1 PC	23.45	✓
			4,609.25	3,559.72
		Less 15%	691.39	3,917.76
Special Net				
30 REAR WINDSCREEN GUM	40.00	1 PC	40.00	✓
31 REAR NUMBER PLATE	25.00	1 PCS	25.00	✓
32 REAR SPARE TYRE PANEL TOP COAT	100.00	1 PC	100.00	✓ ✓
			165.00	165.00

4187.90
608.18

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	05 Feb 2018		06 Feb 2018 11:02 Edit Adj Rpt	S\$4,950.00 Edit Estimates	S\$4,950.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	Wu Qiuming , ID: S7280764B								
Main Claimant:	Lim Soo Ling Angeline (Lin Suling) , ID: S7912885F								
Vehicle Reg. No.:	SLL5110C	Date of Loss:	05/02/2018 08:00 - :59 [119 Months and 11 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 548823	Policy/Cover Note No.:	29038353QMX (Comprehensive) Coverage: 29/10/2017 - 28/10/2018						
Vehicle Reg. No. (Insured):	SKV5769L	Policy No. (Claimant):							
		Excess:							
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Fievel Foo Wenyao - 6643 1316]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Imm.Advice due 07/02/2018]								
Adj Asg. Remarks:	request Kenneth Kong for survey								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLL5110C (548823)

[SKV5769L]

TP

Lim Soo Ling Angeline (Lin Suling)

Feb 5 2018 8:00AM

[Wu Qiuming]

Cheng Hoe Motor Pte Ltd

Upload Documents Upload Photos Compose New Letter			View	View in Browser <input type="checkbox"/>
Photos/Images			3 per page <input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/11/18 16:18	General View	 Load JPG	<input checked="" type="checkbox"/>
2	08/11/18 16:18	General View	 Load JPG	<input checked="" type="checkbox"/>
3	08/11/18 16:18	General View	 Load JPG	<input checked="" type="checkbox"/>
4	08/11/18 16:18	General View	 Load JPG	<input checked="" type="checkbox"/>
5	08/11/18 16:18	General View	 Load JPG	<input checked="" type="checkbox"/>
6	08/11/18 16:18	General View	 Load JPG	<input checked="" type="checkbox"/>
7	08/11/18 16:18	General View	 Load JPG	<input checked="" type="checkbox"/>
8	08/11/18 16:18	General View	 Load JPG	<input checked="" type="checkbox"/>
9	08/11/18 16:18	General View	 Load JPG	<input checked="" type="checkbox"/>
10	08/11/18 16:18	General View	 Load JPG	<input checked="" type="checkbox"/>
11	08/11/18 16:18	General View	 Load JPG	<input checked="" type="checkbox"/>
12	08/11/18 16:18	General View	 Load JPG	<input checked="" type="checkbox"/>
13	08/11/18 16:18	General View	 Load JPG	<input checked="" type="checkbox"/>
14	08/11/18 16:18	General View	 Load JPG	<input checked="" type="checkbox"/>
15	08/11/18 16:18	General View	 Load JPG	<input checked="" type="checkbox"/>
16	08/11/18 16:18	General View	 Load JPG	<input checked="" type="checkbox"/>
17	08/11/18 16:18	General View	 Load JPG	<input checked="" type="checkbox"/>
18	08/11/18 16:18	General View	 Load JPG	<input checked="" type="checkbox"/>
19	08/11/18 16:18	General View	 Load JPG	<input checked="" type="checkbox"/>
20	08/11/18 16:18	General View	 Load JPG	<input checked="" type="checkbox"/>
21	08/11/18 16:18	General View	 Load JPG	<input checked="" type="checkbox"/>
22	08/11/18 16:18	General View	 Load JPG	<input checked="" type="checkbox"/>
23	08/11/18 16:18	General View	 Load JPG	<input checked="" type="checkbox"/>
24	08/11/18 16:18	General View	 Load JPG	<input checked="" type="checkbox"/>
25	08/11/18 16:18	General View	 Load JPG	<input checked="" type="checkbox"/>
26	08/11/18 16:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
27	08/11/18 16:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
28	08/11/18 16:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
29	08/11/18 16:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
30	08/11/18 16:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
31	08/11/18 16:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
32	08/11/18 16:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
33	08/11/18 16:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
34	08/11/18 16:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
35	08/11/18 16:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	08/11/18 16:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	08/11/18 16:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	08/11/18 16:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	08/11/18 16:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	08/11/18 16:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	08/11/18 16:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	08/11/18 16:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	08/11/18 16:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	08/11/18 16:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	08/11/18 16:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	08/11/18 16:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	08/11/18 16:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	08/11/18 16:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	08/11/18 16:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	08/11/18 16:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	08/11/18 16:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	08/11/18 16:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	08/11/18 16:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	05/02/18 17:13	PRI from Cheng Hoe Motor	 Load PDF	
2	05/02/18 17:13	Survey Agree on SJE - LKK	 Load PDF	
3	05/02/18 17:13	Informed Cheng Hoe OI not yet report unable to comment on Liability	 Load PDF	
4	14/02/18 11:53	police report	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG18002384/KTD3E2**Date:** 20/11/2018REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29038353QMX
Claimant Vehicle No : SLL5110C	Insured Vehicle No :	SKV5769L
Date of Loss: 05/02/2018	Nature of Claim:	TP
		Claim No: 548823

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLL5110C	Engine No:	M15A1300217
Make & Model:	SUZUKI SWIFT 1.5 AT, 1.5 (M)	Chassis No:	JSAEZC21S00412076
Reg. Date:	25/02/2008 (Man. Year: 2007)	Odometer:	198581 km
Colour:	Metallic Blue		
Engine Capacity:	1490 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,082.86	3,765.08	317.78	7.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,810.00	2,440.00	370.00	13.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,892.86	6,205.08	687.78	9.98
Approved Total (Overridden) (S\$)		4,950.00		
	(S\$)	4,950.00	1,942.86	28.19
	+ GST 7.00/7.00% (S\$)	482.50	136.00	28.19
	Nett Amount (S\$)	7,375.36	5,296.50	2,078.86
			28.19	

INSPECTION

Date of Assignment:	06/02/2018	
Date Inspected:	06/02/2018 Inspected At:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761
Estimated Period of Repair:	14.0 days	

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 20 Nov 2018)
Parts: 144	SUZUKI SWIFT 1.5 AT 1.5 (M) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLL5110C)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	549.65 FL	*549.65 FL
2	2		*REAR BUMPER SIDE RETAINER	Distorted	37.40 FL	*37.40 FL
3	1		*REAR BUMPER LH BRACKET	Repair	25.55 FL	*- FL
4	6		*REAR BUMPER CLIPS	Necessary	21.00 FL	*21.00 FL
5	1		*REAR TAILGATE	Bent	628.15 FL	*628.15 FL
6	1		*REAR TAILGATE INNER LOCK	Dented	180.10 FL	*180.10 FL
7	1		*REAR TAILGATE INNER RUBBER (92.65)(50%)	Dented / Cut	78.75 FS	*46.32 FS
8	1		*REAR TAILGATE LOGO	Necessary	25.50 FL	*25.50 FL
9	1		*REAR END PANEL	Bent	274.85 FL	*274.85 FL
10	1		*REAR END PANEL INNER TOP GARNISH	Dented	82.75 FL	*82.75 FL
11	3		*REAR END PANEL INNER TOP GARNISH CLIP	Necessary	10.50 FL	*10.50 FL
12	1		*REAR PANEL INNER AIR-SCROP GRILLE	Dented	35.90 FL	*35.90 FL
13	1		*LH TAIL LAMP	Cut	287.90 FL	*287.90 FL
14	1		*LH TAIL LAMP PANEL	Bent	74.90 FL	*74.90 FL
15	1		*REAR SPARE TYRE COMPARTMENT	Buckled	382.15 FL	*382.15 FL
16	1		*REAR SPARE TYRE COMPARTMENT LH SIDE GARNISH	Dented	94.75 FL	*94.75 FL
17	1		*REAR EXHAUST PIPE	Bent	280.50 FL	*280.50 FL
18	1		*REAR EXHAUST PIPE HOLDER	Distorted	20.70 FL	*20.70 FL
19	1		*FRONT BUMPER	Buckled	628.15 FL	*628.15 FL
20	1		*FRONT BUMPER TOP BEAM	Serviceable	172.75 FL	*- FL
21	1		*FRONT BUMPER CENTRE GARNISH	Dented	73.30 FL	*73.30 FL
22	6		*FRONT BUMPER CLIP	Necessary	21.00 FL	*21.00 FL
23	1		*FRONT BUMPER LH SIDE RETAINER	Distorted	28.70 FL	*28.70 FL
24	1		*FRONT BUMPER LOWER RUBBER	Serviceable	60.75 FL	*- FL
25	1		*FRONT GRILLE	Serviceable	69.65 FL	*- FL
26	2		*FRONT GRILLE CLIPS	Not Necessary	7.00 FL	*- FL
27	1		*HEAD LAMP	MTG Cracked	395.25 FL	*395.25 FL
28	1		*FRONT LH FENDER EMBLEM WT	Necessary	23.45 FL	*23.45 FL
29	1		*REAR WINDSCREEN GUM	Necessary	40.00 FS	*40.00 FS
30	1		*REAR NUMBER PLATE	Cracked	25.00 FS	*25.00 FS
31	1		*REAR SPARE TYRE PANEL TOP COAT	Necessary	100.00 FS	*100.00 FS
32	1		*REAR TAILGATE EMBLEM SWIFT	Necessary	24.35 FL	*24.35 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,760.35	4,392.22
- List Item Discount on L Items 15.00/15.00% (\$\$)	677.49	627.14
Total Parts (\$\$)	4,082.86	3,765.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
2	REMOVE AND REFIX REAR SEAT, CARPET, GARNISH, REAR SPEAKER AND BOARD, ETC	New	120.00	100.00
3	REMOVE AND REFIX REAR EXHAUST PIPE AND CHECK LEAKING	New	80.00	60.00
4	REMOVE AND REFIX FRONT BUMPER ASSY, GRILLE, HEAD LAMP. TO KNOCK AND REPAIR FRONT LH FENDER, FRONT SUPPORT PANEL AND REALIGN THE SAME	New	400.00	320.00
5	PUTTY AND RESPRAY ON FRONT BUMPER, SUPPORT PANEL, FRONT LH FENDER	New	500.00	450.00
6	RUSTPROOFING	New	90.00	90.00
7	REMOVE AND REFIX REAR BUMPER ASSY, TAIL LAMPS, TAILGATE AND ATTACHMENT. TO STRAIGHTEN, KNOCK OUT, CUTTING, WELDING AND RENEW REAR SPARE TYRE COMPARTMENT, REAR PANEL, TAIL LAMP PANEL. TO STRAIGHTEN, KNOCK AND REPAIR REAR LH CHASSIS, REAR LH FENDER INNER PANEL AND REALIGN THE SAME	New	1,500.00	1,300.00
Gross Labour Cost (\$\$)			2,810.00	2,440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >