

SERVICE @ RIVERVIEW PTE LTD

10, Ang Mo Kio Autopoint #04-11

Ang Mo Kio Industrial Park 2A

Singapore 568047

Tel: 6481 9810 / 64814849 Fax: 6481 6256

Email: riverview@singnet.com.sg

Buss.reg.No: 200910700K

Lump sum
Repair (on 20%)

SKB2970X

Mercedes B200

List Price \$

Mers less tax

Parts

Tailgate (repair/spray paint)

Tailgate B200 emblem

Tailgate C&C emblem

Tailgate Mercedes Logo

Rear Bumper

Rear Bumper top chrome pad

Rear Bumper side chrome moulding

Rear Bumper lower spoiler

Rear Bumper side retainer

Rear Bumper reinforcement

Rear End panel (repair/spray paint)

special with item

Reverse parking sensors (set of 4 sensors)

Rear Bumper lower spoiler

Labour charges

1) To Renew & repair Accident

2) To Assemble reverse parking sensors & check for proper functions

3) To spray paint Tailgate, Rear Bumper & rear end panel

4) To carry out anti-rust treatment

X 198 TR

X 76 N/A

X 48 N/A

X 68 N/A

1604 def

268 N/A

X 2 ✓ 135 X 2 net

inc X 390 net

LH - 77 dis

inc X 575

X 885 R

Nett Price \$ 540

450 350

400 X m

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

800 600

800

800 600

800 400