



LIU'S BROTHER AUTO ENGINEERING WORKSHOP

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No. 532917931 Tel: 6744 1730 / 731 Fax: 6744 5746 Email: liubro@ymail.com

Invoice/Ref No: YP7609T180130

Estimate

Customer

Name: India International Insurance Pte Ltd

Address: Motor Claims Department

64 Cecil Street #04-00 & #05-00

IOB Building

Singapore 049711

Date:

02-02-18

Vehicle No:

YP7609T

Model/Make:

Mitsubishi Fuso

FK62FMZ1RDEB

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Front Bumper	\$ 3,336.80	
2	Bumper Bracket 02 pcs (@ \$5641.00)	\$ 1,282.00	
3	HeadLamp 02 pcs (@ \$1,002.50)	\$ 2,005.00	
4	Head Lamp Panel <i>Panel</i>	\$ 982.00	
5	Head Lamp Grille (Casing) 02 pcs (@ \$581.00) <i>1/2 new 1/2 old</i>	\$ 1,162.00	
6	Fog Lamp 02 pcs (\$485.00) <i>old ground</i>	\$ 970.00	
7	Grille <i>new</i>	\$ 1,423.00	
8	Grille clips 1 set <i>new</i>	\$ 42.00	
9	Grille "Mitsubishi" Emblem <i>new</i>	\$ 119.50	
10	Grille "Fighter" Emblem <i>new</i>	\$ 111.00	
11	Panel <i>old/new</i>	\$ 2,791.00	
12	Panel "FUSO" Emblem <i>new</i>	\$ 280.00	
13	Panel Lock 02 pcs (@ \$279.50) <i>new</i>	\$ 559.00	
14	Panel Hinge 02 pcs (@ \$129.00) <i>new</i>	\$ 258.00	
15	Corner Panel Garnish <i>old new</i>	\$ 1,184.00	
16	Inner Panel <i>new</i>	\$ 5,378.50	
17	Signal Lamp Rh <i>new</i>	\$ 212.00	
18	Radiator Spare Tank <i>new</i>	\$ 491.80	
19	Number Plate (Metal) <i>new</i>	\$ 28.00	
20	"Corporate" Advertisement Sticker <i>new</i>	\$ 400.00	
	To check all wiring & electrical components for proper function	\$ 50.00	
	To apply Rust Proofing, reseal tuff coating treatment on accident area	\$ 50.00	
	To remove & refix air con, re-fill air con gas & test for leakages	\$ 120.00	
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 1,500.00	
	To putty & spray painting & including touch up paint on accident affected areas	\$ 1,200.00	

Total Parts & Labour of estimate for damaged vehicle

\$ 25,935.60

Total amount in Lump Sum Basis for repaired vehicle

\$

SDLS:

Not Authorized
S/M 18
The photo before policy -
4th



M/s Liu's Brother Auto Engrg Wks

- KK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: