

Case Owner:

CC 4/III1800 2389, Upb3

LKK  
IDAC

Surveyor

marcus

DOI:

ASSIGNMENT

5/2/18

Date / Time:

6/2/18

Registered in Merimen:

6/2/18

Pre-assign / CCU / FTE



Insured Vehicle No.

96T 3380U

Name of Insured

ToH Kim MEAB

Insured Tel No.

HP: 97498570

Excess Sec II :S\$

D.O.A: 30/01/18

Is driver the owner?

(YES) NO

Nature of Accident:

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

ME91115

Honda

Turn of GUL mt d gul  
412

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

YP 7609T



INSRS:

WSP:

Tel:

Liability:

RMKS:

Un's  
Bro.



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

2/2/18  
CAT

YP 7609T  
30/01/18 to 30/01/18

STAGE

DATE / PIC

Non-Reporting ltr (1st):  
Non-Reporting ltr (2nd):  
Non-Reporting ltr (Final):  
Notification ltr (if non-pickup):  
Call OI:  
After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup):  
After call ltr to OI:  
Authorisation To Act:  
Release Voucher:  
Final Repair Bill:  
Car Rental Invoice:  
Towing Invoice:  
LTA / GIA:  
Medical Bill:  
PIR:  
Mandate/Reject Instruction:  
LOD:  
Payment Breakdown Form:  
Post-Repair Photos:  
Others:

2/2/18 - Seek 100% liability  
12/2/18 - III agreed 100%  
21/3/18 - File pass to type mandate.  
# 21/4/18 - DV sent  
15/5/18 - File pass to close

RECEIVED 15 MAY 2018

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost: S\$ ( days) Reduction: %

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Final Liability: % (Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost: S\$ 9000.00

Loss of Rental (LOR): S\$ ( days)

Loss of Use (LOU): S\$ 900.00 (\$150 x 6 days)

Loss of Income (LOI): S\$ ( \$ x days)

LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search: S\$ 2.00

Medical:

Disbursement:

Legal Cost:

(e.g. Tow/ Independent)

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total: S\$ 9902.00 Global Sum S\$: 9900.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1: S\$ 9900.00

Name 1:

Un's Brother Auto Engineering Workshop.

Payee 2: (Strike if N.A.)

Name 2:

Payee 3: (Strike if N.A.)

Name 3:

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo inspect Vehicle No: YP7609Tat Workshop mis 1-5 50

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_

Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_

Consistent? : Yes or No

Est. Repairs: 4

days

Res.: Yes or No

Lum Sum: 20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_

Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: YP7609TYr Regn: 10 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: M.F. Fuso Fk62c.c. 7545Colour: white

A/C: Insured / Std / NI / NA

Sp. Reading: 12750

T/Radio: Insured / Std / NI / NA

Engl/No: \_\_\_\_\_

C/No: FK62FMA30364Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / TS/Rim / STD A/Rim orTyre Size: F: 245/70R19.5

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front

Rear

R/Bal: 2

mm

R/Bal: 2/8

mm

L/Bal: 2

mm

L/Bal: 2/8

mm

D.O.A. 30/1/18D.O.I. 5/1/18

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

14/2/18continued 2/5 @ 9000 w.h. Susan.(Reel @ 16935.60 / 65%)

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

Photos

Others

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) \_\_\_\_\_



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile  |   |                            |            |   |
|--|---|----------------------------|------------|---|
| INDIA INTERNATIONAL INSURANCE PL   |   | Ref : CC4/III18002389/Upb3 |            |   |
| 64 CECIL STREET<br>#05-02 IOB BUILDING SINGAPORE 049711  |   | Date : 06-02-2018          |            |  |
|  |   | Code : III2                |            |   |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>  |   |                            |            |   |
| Insured Veh.   | SGT 3380U   | Veh. Inspected             | YP 7609T   |   |
| Policy No.   |   | Coverage (\$)              | 0.00       |   |
| Claim No.  |   | Excess (\$)                | 0.00       |   |
| Assign From  |   | Assign Date                | 06/02/2018 |   |
| <b>2. Vehicle Particulars &amp; Condition</b>  |   |                            |            |   |
| Make & Model   |   | c.c                        | 0          |   |
| Engine No.   | HIDDEN  | Year of Reg.               |            |   |
| Chassis No.  |   | Colour                     |            |   |
| Odometer   | -   | Steering                   |            |   |
| Brakes   |   | Modification               |            |   |
| General  |   |                            |            |   |
| <b>3. Conditions of Tyres</b>  |   |                            |            |   |
|  | Size  | Make                       | Balance    |   |
| R/H Front Tyre   |   |                            | mm         |   |
| L/H Front Tyre   |   |                            | mm         |   |
| R/H Rear Tyre  |   |                            | mm         |   |
| L/H Rear Tyre  |   |                            | mm         |   |
| <b>4. Description of Damages</b>   |   |                            |            |   |
|  |   |                            |            |   |
| <b>5. General Information</b>  |   |                            |            |   |
| Accident Date  | 30/01/2018  | Inspection Date            |            |   |
| Survey held at   | LIU'S BROTHER AUTO ENGINEERING WORKSHOP<br>1 KAKI BUKIT AVENUE 6 #01-01 AUTOBAY @ KAKI BUKIT<br>SINGAPORE<br>417883 |                            |            |   |
| <b>5a. Remarks</b>   |   |                            |            |   |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |   |                            |            |   |

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1, Kallang Road, Singapore 340001

Mobile: 97271731, Tel: 674 4738, 6738 1731, Fax: 6744 5746, Email: sales@lbe.com

Invoice/Ref No: YP7809T18D130

FK62FMA3036X  
2017**Estimate****Customer**

Name: India International Insurance Pte Ltd  
 Address: Motor Claims Department  
 64 Cecil Street #04-00 & #05-00  
 IOB Building Singapore 049711

Date: 02-02-18  
 Vehicle No: YP7809T  
 Model/Make: Mitsubishi Fuso  
 FK62FMZ1RDEB

| Item No. | Descriptions Of Parts   | Original Quotation / Estimation | Revised Quotation / Cost Of Repair |
|----------|---|---------------------------------|------------------------------------|
| 1        | Front Bumper <i>Ref 115.00</i>  | \$ 3,336.80                     |                                    |
| 2        | Bumper <i>Beam Ref 1436.50</i>  | \$ 1,282.00                     |                                    |
| 3        | Head Lamp 02 pcs (@ \$51,002.50) <i>one</i>                                     | \$ 2,005.00                     |                                    |
| 4        | Head Lamp <i>Panel</i>  | \$ 982.00                       |                                    |
| 5        | Head Lamp Grille (Casing) 02 pcs (@ \$581.00) <i>2/side of 550</i>              | \$ 1,162.00                     |                                    |
| 6        | Fog Lamp 02 pcs (\$5485.00) <i>o/s ground</i>                                   | \$ 970.00                       |                                    |
| 7        | Grille <i>one</i>   | \$ 1,423.00                     |                                    |
| 8        | Grille clips 1 set <i>one</i>   | \$ 42.00                        |                                    |
| 9        | Grille "Mitsubishi" Emblem <i>one</i>   | \$ 119.50                       |                                    |
| 10       | Grille "Fighter" Emblem <i>one</i>  | \$ 111.00                       |                                    |
| 11       | Panel <i>2/side of 115</i>  | \$ 2,791.00                     |                                    |
| 12       | Panel "FUSO" Emblem <i>one</i>  | \$ 280.00                       |                                    |
| 13       | Panel Lock 02 pcs (@ \$5279.50) <i>one</i>                                      | \$ 559.00                       |                                    |
| 14       | Panel Hinge 02 pcs (@ \$129.00) <i>one</i>                                      | \$ 258.00                       |                                    |
| 15       | Corner Panel Garnish <i>one</i>   | \$ 1,184.00                     |                                    |
| 16       | Inner Panel <i>one</i>  | \$ 5,378.50                     |                                    |
| 17       | Signal Lamp Rh <i>one</i>   | \$ 212.00                       |                                    |
| 18       | Radiator Spare Tank <i>one</i>  | \$ 491.80                       |                                    |
| 19       | Number Plate (Metal) <i>one</i>   | \$ 28.00                        |                                    |
| 20       | "Corporate" Advertisement Sticker <i>one</i>                                    | \$ 400.00                       |                                    |
|          | To check all wiring & electrical component for proper function                  | \$ 50.00                        |                                    |
|          | To apply Rust Proofing, re-seal tuff-coating treatment on accident area         | \$ 50.00                        |                                    |
|          | To remove & refix air con, re-fill air con gas & test for leakages              | \$ 120.00                       |                                    |
|          | Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc            | \$ 1,500.00                     |                                    |
|          | To putty & spray painting & including touch up paint on accident affected areas | \$ 1,200.00                     |                                    |

Total Parts &amp; Labour of estimate for damaged vehicle

\$ 25,935.60

Total amount in Lump Sum Basis for repaired vehicle

\$

SDLS:



M/s Liu's Brother Auto Engrg Wks

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Authorized  
 5/2/18  
 when photo taken policy

400g.  
 1/5 \$ 9000/2

119458  
 859-35



# LIU'S BROTHER AUTO ENGINEERING WORKSHOP

1. Auto Repair Services • 2. Auto Parts • 3. Auto Body Repairs • 4. Auto Insurance Claims • 5. Auto Accessories • 6. Auto Detailing • 7. Auto Wash • 8. Auto Storage • 9. Auto Rental • 10. Auto Insurance Brokerage

Invoice/Ref No: YP7609T180130

Customer

Estimate

Name: India International Insurance Pte Ltd

Address: Motor Claims Department

64 Cecil Street #04-00 & #05-00

IOB Building

Singapore 049711

Date:

02-02-18

Vehicle No:

YP7609T

Model/Make:

Mitsubishi Fuso

FK62FMZ1RDEH

| Item No. | Descriptions Of Parts   | Original Quotation / Estimation | Revised Quotation / Cost Of Repair |
|----------|---|---------------------------------|------------------------------------|
| 1        | Front Bumper  |                                 |                                    |
| 2        | Bumper Bracket 02 pcs (@ \$5641.00)   | \$ 3,336.80                     |                                    |
| 3        | HeadLamp 02 pcs (@ \$51,002.50)   | \$ 1,282.00                     |                                    |
| 4        | Head Lamp Panel   | \$ 2,005.00                     |                                    |
| 5        | Head Lamp Grille (Casing) 02 pcs (@ \$5581.00)                                  | \$ 982.00                       |                                    |
| 6        | Fog Lamp 02 pcs (\$5485.00)   | \$ 1,162.00                     |                                    |
| 7        | Grille  | \$ 970.00                       |                                    |
| 8        | Grille clips 1 set  | \$ 1,423.00                     |                                    |
| 9        | Grille "Mitsubishi" Emblem  | \$ 42.00                        |                                    |
| 10       | Grille "Fighter" Emblem   | \$ 119.50                       |                                    |
| 11       | Panel   | \$ 111.00                       |                                    |
| 12       | Panel "FUSO" Emblem   | \$ 2,791.00                     |                                    |
| 13       | Panel Lock 02 pcs (@ \$5279.50)   | \$ 280.00                       |                                    |
| 14       | Panel Hinge 02 pcs (@ \$5129.00)  | \$ 559.00                       |                                    |
| 15       | Corner Panel Garnish  | \$ 258.00                       |                                    |
| 16       | Inner Panel   | \$ 1,184.00                     |                                    |
| 17       | Signal Lamp Rh  | \$ 5,378.50                     |                                    |
| 18       | Radiator Spare Tank   | \$ 212.00                       |                                    |
| 19       | Number Plate (Metal)  | \$ 491.80                       |                                    |
| 20       | "Corporate" Advertisement Sticker   | \$ 28.00                        |                                    |
|          | To check all wiring & electrical component for proper function                  | \$ 400.00                       |                                    |
|          | To apply Rust Proofing, reseal ruff coating treatment on accident area          | \$ 50.00                        |                                    |
|          | To remove & refill air con, re-fill air con gas & test for leakages             | \$ 50.00                        |                                    |
|          | Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc            | \$ 120.00                       |                                    |
|          | To putty & spray painting & including touch up paint on accident affected areas | \$ 1,500.00                     |                                    |
|          |   | \$ 1,200.00                     |                                    |

Total Parts & Labour of estimate for damaged vehicle

\$ 25,935.60

Total amount in Lump Sum Basis for repaired vehicle

\$

SDLS:



M/s Liu's Brother Auto Engrg Wks

- LLK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Authorised  
s/r/p  
who photo taken policy - 4dy.

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

**Third Party Insurer Enquiry**

Our Ref No: GR-18-018027  
Date of Request: 02/02/2018

Your Ref No: Online Purchase

LIU'S BROTHER AUTO WORKSHOP  
1 Kaki Bukit Ave 6 #01-01  
Auto Bay@Kaki Bukit  
Singapore 417883

Dear Sir/Madam,

Enquiry Date: 02/02/2018  
Enquiry By: Susan Low Siew Yian  
TP Vehicle No: SGT3380U  
Accident Date: 30/01/2018

**Enquiry Result**

| TP Vehicle No. | Insurer                               | Period of Insurance   | Insurer Tel. No. |
|----------------|---------------------------------------|-----------------------|------------------|
| SGT3380U       | India International Insurance Pte Ltd | 18/04/2017-17/04/2018 | 63476100         |

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

|                |         |
|----------------|---------|
| Owner ID Type: | Company |
| Owner ID:      | 3585C   |

### Vehicle Details

|                                |                   |
|--------------------------------|-------------------|
| Vehicle No.:                   | YP7609T           |
| Vehicle to be Exported:        | No                |
| Intended De-registration Date: | 02 Feb 2018       |
| Vehicle Make:                  | MITSUBISHI        |
| Vehicle Model:                 | FUSO FK62FMZ1RDEB |
| Primary Colour:                | White             |
| Manufacturing Year:            | 2017              |
| Engine No.:                    | 6M60229746        |
| Chassis No.:                   | FK62FMA30364      |
| Maximum Power Output:          | -                 |
| Open Market Value:             | \$61,449.00       |
| Original Registration Date:    | 09 Oct 2017       |
| First Registration Date:       | 09 Oct 2017       |
| Transfer Count:                | 0                 |
| Actual ARF Paid:               | \$3,073.00        |
| Intended PARF Rebate Details   |                   |
| PARF Eligibility:              | No                |
| PARF Eligibility Expiry Date:  | -                 |

Enquire PARF/COE Rebate for Registered Vehicle

|                                |                         |
|--------------------------------|-------------------------|
| Vehicle Owner Particulars      |                         |
| Owner ID Type:                 | Company                 |
| Owner ID:                      | 3585C                   |
| Vehicle Details                |                         |
| Vehicle No.:                   | YP7609T                 |
| Vehicle to be Exported:        | No                      |
| Intended De-registration Date: | 05 Feb 2018             |
| Vehicle Make:                  | MITSUBISHI              |
| Vehicle Model:                 | FUSO FK62FMZ1RDEB       |
| Primary Colour:                | White                   |
| Manufacturing Year:            | 2017                    |
| Engine No.:                    | 6M60229746              |
| Chassis No.:                   | FK62FMA30364            |
| Maximum Power Output:          | -                       |
| Open Market Value:             | \$61,449.00             |
| Original Registration Date:    | 09 Oct 2017             |
| First Registration Date:       | 09 Oct 2017             |
| Transfer Count:                | 0                       |
| Actual ARF Paid:               | \$3,073.00              |
| Intended PARF Rebate Details   |                         |
| PARF Eligibility:              | No                      |
| PARF Eligibility Expiry Date:  | -                       |
| PARF Rebate Amount:            | \$0.00                  |
| Intended COE Rebate Details    |                         |
| COE Expiry Date:               | 08 Oct 2027             |
| COE Category:                  | C - Goods Vehicle & Bus |
| COE Period(Years):             | 10                      |
| QP Paid:                       | \$42,004.00             |
| COE Rebate Amount:             | \$40,637.00             |
| Total Rebate Amount:           | \$40,637.00             |

The information contained herein is correct as at 05 Feb 2018

OK



## Hsiao Tong (LKKAuto)

---

**From:** Hsiao Tong (LKKAuto)  
**Sent:** Tuesday, 13 February 2018 11:04 AM  
**To:** 'Susan Low'  
**Subject:** ACCIDENT INVOLVING SGT 3380U(III) & YP 7609T ON 30/01/2018 \*Our Ref: CC4/III18002389/Upb3

Your ref: **YP 7609T**  
Our Ref: CC4/III18002389/Upb3

*Without Prejudice*

Dear Sirs,

### **ACCIDENT INVOLVING SGT 3380U(III) & YP 7609T ON 30/01/2018**

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

**Hsiao Tong, Chew** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## Claim Audit

| AUDIT TRAIL |                      |                               |   |                              |
|-------------|----------------------|-------------------------------|---|------------------------------|
| No.         | On                   | Audit                         | Remarks   | By                           |
| 1           | 06 Feb 2018<br>17:45 | <b>Clim Veh Model Changed</b> | (201988) MITSUBISHI FK617MSJRDEC 7.5 D (M).   | [A] Lau<br>Shu Pei           |
| 2           | 06 Feb 2018<br>17:45 | <b>Clim Created</b>           | Reg No: YP7609T. Acct Date: 2018/01/30. Claim Type: TP. Insurer: India International Insurance Pte Ltd (HQ). TP Insurer: MS First Capital Insurance Ltd (HQ). Workshop: Liu's Brother Auto Engineering Workshop (kaki Bukit) (HQ) | [A] Lau<br>Shu Pei           |
| 3           | 06 Feb 2018<br>17:45 | <b>Adj Co Assigned</b>        | LKK Auto Consultants Pte Ltd (HQ):  | [A] Lau<br>Shu Pei           |
| 4           | 06 Feb 2018<br>17:45 | <b>Adj Next Rpt Changed</b>   | Next Rpt:Final Rpt.Due Date:2018/02/15  | [A] Lau<br>Shu Pei           |
| 5           | 06 Feb 2018<br>17:45 | <b>Adj Mandate Set</b>        | Approved:0.00.Reinsp:Adj decides.   | [A] Lau<br>Shu Pei           |
| 6           | 06 Feb 2018<br>17:45 | <b>Label Added</b>            | (30653):Direct Settlement.  | [A] Lau<br>Shu Pei           |
| 7           | 06 Feb 2018<br>17:45 | <b>Adj Adjuster Assigned</b>  | [None] -> MARCUS CHUA   | [A] Lau<br>Shu Pei           |
| 8           | 07 Feb 2018<br>10:00 | <b>Clim Dtl Modified</b>      | Claimant's Name: -> TOH KIM MENG. Claimant's ID: -> S7215419C.  | [A] Lau<br>Shu Pei           |
| 9           | 07 Feb 2018<br>14:23 | <b>Adj Mandate Request</b>    | Cur.Req:0.00:PODS Liability: 100% Remarks: Insured turned out from minor road and collided with third party who was on main road.   | [A]<br>CHEW<br>HSIAO<br>TONG |
| 10          | 07 Feb 2018<br>17:22 | <b>Adj Next Rpt Changed</b>   | Next Rpt:Final Rpt.Due Date:2018/02/15  | [I]<br>Lalitha<br>Krishnan   |
| 11          | 07 Feb 2018<br>17:22 | <b>Adj Mandate Set</b>        | Approved:0.00.  | [I]<br>Lalitha<br>Krishnan   |
| 12          | 12 Feb 2018<br>16:12 | <b>Adj Rpt Initiated</b>      |   | [A] Lau<br>Shu Pei           |
| 13          | 12 Feb 2018<br>16:12 | <b>Clim Details Notified</b>  |   | [A] Lau<br>Shu Pei           |
| 14          | 02 Apr 2018<br>14:51 | <b>Adj Mandate Request</b>    | Cur.Req:9902.00:PODS Liability: 100% Quantum:(a) COR:\$9,000.00 + (b)LOU(6d aysx\$150.00): \$900.00 + (c)LTA/GIA search fee: \$2.00 = Total:\$9,902.00 Vehicle Model: Mitsubishi Fuso FK62F (7545cc). For your approval please.   | [A]<br>CHEW<br>HSIAO<br>TONG |

### ACTIVITY

No record

### Merimen Billing for this case - Transaction History

| Ref No  | Ref Date            | Acc Type | Acc Agency                         | Acc From (Ref No)                       | Ref 1   | Ref 2 | Amount |
|---------|---------------------|----------|------------------------------------|---|---------|-------|--------|
| 1722194 | 12/02/2018<br>16:12 | Motor    | LKK Auto<br>Consultants Pte<br>Ltd | LKK Auto<br>Consultants Pte<br>Ltd (HQ) | YP7609T |       | 10.70  |

## Print Received Message

This mail is associated with :

**\*YP7609T (MC20182108)**  
**[SGT3380U]**

TP

STVE PTE. LTD.

Jan 30 2018 1:00PM

[TOH KIM MENG]

Liu's Brother Auto Engineering Workshop (kaki Bukit)

**From** India International Insurance Pte Ltd (HQ) (III\_SG), sent on 03/04/2018 08:53 AM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$9902.00) - YP7609T - Claim Handler: Lalitha Krishnan

Approved:9902.00.

## Hsiao Tong (LKKAUTO)

---

**From:** Hsiao Tong (LKKAUTO)  
**Sent:** Monday, 9 April 2018 11:44 AM  
**To:** 'Susan Low'  
**Subject:** RE: ACCIDENT INVOLVING SGT 3380U(III) & YP 7609T ON 30/01/2018 \*Our Ref: CC4/III18002389/Upb3

Without Prejudice

Hi Susan,

We refer to the above matter.

We propose settlement at a global sum of **S\$9,900.00(all-in)**.

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement."

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

**Hsiao Tong, Chew** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Hsiao Tong (LKKAUTO)  
**Sent:** Tuesday, 13 February 2018 11:04 AM  
**To:** 'Susan Low' <[liusbro@gmail.com](mailto:liusbro@gmail.com)>  
**Subject:** ACCIDENT INVOLVING SGT 3380U(III) & YP 7609T ON 30/01/2018 \*Our Ref: CC4/III18002389/Upb3

Your ref: **YP 7609T** *Without Prejudice*  
Our Ref: CC4/III18002389/Upb3

Dear Sirs,

**ACCIDENT INVOLVING SGT 3380U(III) & YP 7609T ON 30/01/2018**

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

## Hsiao Tong (LKKAuto)

---

**From:** Susan Low <liusbro@ymail.com>  
**Sent:** Saturday, 21 April 2018 9:25 AM  
**To:** Hsiao Tong (LKKAuto)  
**Subject:** Re: ACCIDENT INVOLVING SGT 3380U(III) & YP 7609T ON 30/01/2018 \*Our Ref: CC4/III18002389/Upb3

We hereby confirm acceptance of your offer. Kindly let us have your discharge for our client's execution and your cheque made in our favour as soon as possible.

Thank.

Best Regards,

Susan Low  
M/s Liu's Brother Auto Engineering Workshop  
No. 1 Kaki Bukit Avenue 6 #01-01  
AutoBay @ Kaki Bukit  
Singapore 417883  
Tel: 67411730 Fax: 67445746

---

**From:** Hsiao Tong (LKKAuto) <chewht@lkkauto.com>  
**To:** Susan Low <liusbro@ymail.com>  
**Sent:** Monday, 9 April 2018, 11:44  
**Subject:** RE: ACCIDENT INVOLVING SGT 3380U(III) & YP 7609T ON 30/01/2018 \*Our Ref: CC4/III18002389/Upb3

Without Prejudice

Hi Susan,

We refer to the above matter.

We propose settlement at a global sum of **\$9,900.00(all-in)**.

Please confirm acceptance.

**"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.**

**In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."**

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk S1, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Hsiao Tong (LKKAuto)

**Sent:** Tuesday, 13 February 2018 11:04 AM

**To:** 'Susan Low' <liusbro@gmail.com>

**Subject:** ACCIDENT INVOLVING SGT 3380U(III) & YP 7609T ON 30/01/2018 \*Our Ref: CC4/III18002389/Upb3

Your ref: **YP 7609T**

*Without Prejudice*

Our Ref: CC4/III18002389/Upb3

Dear Sirs,

**ACCIDENT INVOLVING SGT 3380U(III) & YP 7609T ON 30/01/2018**

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

**"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.**

**In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."**

Best Regards,

**Hsiao Tong, Chew** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | 5(408933)

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 3585C

### Vehicle Details

Vehicle No.: YP7609T

Vehicle to be Exported: No

Intended De-registration Date: 02 Feb 2018

Vehicle Make: MITSUBISHI

Vehicle Model: FUSO FK62FMZ1RDEB

Primary Colour: White

Manufacturing Year: 2017

Engine No.: 6M60229746

Chassis No.: FK62FMA30364

Maximum Power Output: -

Open Market Value: \$61,449.00

Original Registration Date: 09 Oct 2017

First Registration Date: 09 Oct 2017

Transfer Count: 0

Actual ARF Paid: \$3,073.00

### Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

Our Ref: YP7609T180130

Date: 15/02/2018

Your Ref:

India International Insurance Pte Ltd  
64 Cecil Street #04 / #05  
IOB Building  
Singapore 049711

?

**Attn: Motor Claims Department**

Dear Sir / Madam

**TRAFFIC ACCIDENT ALONG GUL AVENUE AND GUL CIRCLE  
INVOLVING YP7609T AND SGT3380U ON 30/01/2018**

We/I, **Messers Stve Pte Ltd** (Nric / ROC No: **198703585C**), the registered owners of m/vehicle – **YP7609T** at all material times of the above accident. Our/my vehicle was surveyed by "India" authorized appraiser and we/I based our/my claims on his recommendation for **S\$9,000-00** being the repair for **04** Days (Strictly on a Without Prejudice Basis).

We/I have ascertained that you were the insurers of the driver of m/vehicle **SGT3380U** when the same was involved in the aforesaid accident with our/my m/vehicle – **YP7609T**.

We/I whereby you are the insurers of m/vehicle **SGT3380U** and the driver / owner was caused solely by the negligence of your insured and as a result there of our / my m/vehicle – **YP7609T** has suffered loss and damage as follows:

|   |     |          |
|---|-----|----------|
| (a) Cost of repairs   | S\$ | 9,000-00 |
| (b) LOU for pre-repair notice 02 days @\$180-00 (7545 cc lorry) |     | 360-00   |
| (c) LOU Fee for 04 days @\$180-00                               |     | 720-00   |
| (d) GIA / LTA search fee  |     | 2-00     |

|                     |            |                  |
|---------------------|------------|------------------|
| <b>Total Amount</b> | <b>S\$</b> | <b>10,082-00</b> |
|---------------------|------------|------------------|

We/I enclose herewith copies of the supporting documents for vehicle no. **YP7609T** as follows:-

- (i) Motor Accident Report;
- (ii) Repair Invoices;

Kindly look into the matter and let us/me hear from you on the settlement of our / my claims as soon as possible.

Please remit us/me your settlement sum in favor of **M/s Liu's Brother Auto Engineering Workshop**. Forward the cheque to No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883.

Thank you.

Yours faithfully,



The owner of m/vehicle **YP7609T**  
Messers STVE Pte Ltd  
cc. Liu's Bro Auto Engrg Ws



# Authorization To Act

## **Attn: Motor Claims Department**

India International Insurance Pte Ltd  
64 Cecil Street #04 / #05  
IOB Building  
Singapore 049711

I / We, Messers Stve Pte Ltd ("the third party claimant") of No. 18 Tuas Avenue 10 Singapore 639142 (address), owner of YP7609T (vehicle no.) hereby authorize Liu's Brother Auto Engineering Workshop ("the workshop") to act for me / us with respect to my / our claim for repair costs and / or rental and / or loss of use ("claim") for my / our vehicle no. YP7609T that was damaged pursuant to the accident which occurred on 30/01/2018 (date) along Gul Avenue And Gul Circle (location) involving SGT3380U ("the accident").

I / We further authorize the workshop to settle my / our above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my / our claim with payment cheque / s being made in favour of the workshop.

I / We further acknowledge that any settlement the workshop may reach on my / our behalf is on a without prejudice and without admission of liability basis insofar as the driver / owner / insurers of the other vehicle / s is concerned.

Dated this 12th day of May (month) 20 18 (year)

### **3<sup>rd</sup> Party Claimant:**

Signature: \_\_\_\_\_

Name: Stve Pte Ltd

Address: No. 18 Tuas Avenue 10

Singapore 639142

ROC /Nric No: 198703585C

### **Workshop:**

Signature: \_\_\_\_\_

Name: Liu's Brother Auto Engrg Workshop

Address: 1 Kaki Bukit Avenue 6 #01-01

AutoBay @ Kaki Bukit

Singapore 417883

ROB No: 53291793J





**DISCHARGE VOUCHER**  
**III-Direct Settlement (PODS)**

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Eng S, Kaki Bukit Singapore 417981

MOB No: 93291700, Tel: 674 6781711, Fax: 674 6781706 Email: sales@lbe.com

Invoice/Ref No: YP7809T180130

**Final Bill**

|                 |                                       |                                    |
|-----------------|---------------------------------------|------------------------------------|
| <b>Customer</b> |                                       |                                    |
| <b>Name:</b>    | India International Insurance Pte Ltd | <b>Date:</b> 15-02-18              |
| <b>Address:</b> | Motor Claims Department               | <b>Vehicle No:</b> YP7609T         |
|                 | 64 Cecil Street #04-00 & #05-00       | <b>Model/Make:</b> Mitsubishi Fuso |
|                 | IOB Building, Singapore 049711        | FK62FMZ1RDEB                       |

| Item No. | Descriptions Of Parts   | Original Quotation / Estimation | Revised Quotation / Cost Of Repair |
|----------|---|---------------------------------|------------------------------------|
| 1        | <b>Front</b> Bumper   | \$ 3,336.80                     | \$ -                               |
| 2        | Bumper Bracket 02 pcs (@ \$5641.00)   | \$ 1,282.00                     | \$ -                               |
| 3        | HeadLamp 02 pcs (@ \$1,002.50)  | \$ 2,005.00                     | \$ -                               |
| 4        | Head Lamp Panel   | \$ 982.00                       | \$ -                               |
| 5        | Head Lamp Grille (Casing) 02 pcs (@ \$581.00)                                   | \$ 1,162.00                     | \$ -                               |
| 6        | Fog Lamp 02 pcs (\$\$485.00)  | \$ 970.00                       | \$ -                               |
| 7        | Grille  | \$ 1,423.00                     | \$ -                               |
| 8        | Grille clips 1 set  | \$ 42.00                        | \$ -                               |
| 9        | Grille "Mitsubishi" Emblem  | \$ 119.50                       | \$ -                               |
| 10       | Grille "Fighter" Emblem   | \$ 111.00                       | \$ -                               |
| 11       | Panel   | \$ 2,791.00                     | \$ -                               |
| 12       | Panel "FUSO" Emblem   | \$ 280.00                       | \$ -                               |
| 13       | Panel Lock 02 pcs (@ \$5279.50)   | \$ 559.00                       | \$ -                               |
| 14       | Panel Hinge 02 pcs (@ \$129.00)   | \$ 258.00                       | \$ -                               |
| 15       | Corner Panel Garnish  | \$ 1,184.00                     | \$ -                               |
| 16       | Inner Panel   | \$ 5,378.50                     | \$ -                               |
| 17       | Signal Lamp Rh  | \$ 212.00                       | \$ -                               |
| 18       | Radiator Spare Tank   | \$ 491.80                       | \$ -                               |
| 19       | Number Plate (Metal)  | \$ 28.00                        | \$ -                               |
| 20       | "Corporate" Advertisement Sticker   | \$ 400.00                       | \$ -                               |
|          | To check all wiring & electrical component for proper function                  | \$ 50.00                        | \$ -                               |
|          | To apply Rust Proofing, reseal tuff-coating treatment on accident area          | \$ 50.00                        | \$ -                               |
|          | To remove & refix air con, re-fill air con gas & test for leakages              | \$ 120.00                       | \$ -                               |
|          | Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc            | \$ 1,500.00                     | \$ -                               |
|          | To putty & spray painting & including touch up paint on accident affected areas | \$ 1,200.00                     | \$ -                               |

Total Parts &amp; Labour of estimate for damaged vehicle

\$ 25,935.60

Total amount in Lump Sum Basis for repaired vehicle

\$ 9,000.00

SDLS: Nine Thousand Only



M/s Liu's Brother Auto Engrg Wks

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

**TAX INVOICE**

Our Ref No: GR-18-018027

Date of Request: 02/02/2018

Your Ref No:

Online Purchase

LIU'S BROTHER AUTO WORKSHOP  
1 Kaki Bukit Ave 6 #01-01  
Auto Bay@Kaki Bukit  
Singapore 417883

Dear Sir/Madam,

Enquiry Date 02/02/2018  
Enquiry By Susan Low Siew Yian  
TP Vehicle No SGT3380U  
Accident Date 30/01/2018

| DESCRIPTION                      | AMOUNT (S\$) |
|----------------------------------|--------------|
| TP Insurer Enquiry               | 1.87         |
| GST Amount                       | 0.13         |
| Total Amount Due (GST Inclusive) | 2.00         |

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

## CLAIM SUBFOLDER TRACKING

| Case | Notified                                | Est Submitted | Adj Assigned   | Adj Rpt  | Adj Submitted                                  | Ins Auth'ed | Status  |
|------|---|---------------|--|--|--|-------------|---|
| Main | 07 Feb 2018<br><a href="#">Edit Reg</a> |               | 05 Feb 2018<br>00:00<br><a href="#">Edit Adj Rpt</a> | <b>\$59,000.00</b><br><a href="#">Edit Estimates</a> | <b>\$59,000.00</b><br><a href="#">View Rpt</a> |             | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

| Main  | Reference   | Claim Details          | Documents   | Show All |         |             |              |            |       |
|---|---|------------------------|---|----------|---------|-------------|--------------|------------|-------|
| <b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>   |   |                        |   |          |         |             |              |            |       |
| Insured:  | <b>TOH KIM MENG</b> , ID: S7215419C   |                        |   |          |         |             |              |            |       |
| Main Claimant:  | <b>STVE PTE. LTD.</b> , Co. Reg. No.: 198703585C  |                        |   |          |         |             |              |            |       |
| Vehicle Reg. No.:   | <b>YP7609T</b>  | Date of Loss:          | 30/01/2018 13:00 - :59<br>[3 Months and 21 Days From LTA Reg Date (Man Yr)] |          |         |             |              |            |       |
| Claim Type:   | <b>TP / MC20182108</b>  | Policy/Cover Note No.: | M491115   |          |         |             |              |            |       |
| Vehicle Reg. No. (Insured):   | <b>SGT3380U</b>   | Policy No. (Claimant): | D-16083837MFCV/4  |          |         |             |              |            |       |
|   |   | Excess:                |   |          |         |             |              |            |       |
| Repairer:   | <b>Liu's Brother Auto Engineering Workshop (kaki Bukit) (HQ)</b> Blk 1 Kaki Bt Ave 6 #01-01 Auto Bay @ Kaki Bt Singapore 417883, Kaki Bukit, 417883 Kaki Bukit - Tel: |                        |   |          |         |             |              |            |       |
| Handling Insurer:   | <b>India International Insurance Pte Ltd (HQ)</b> - Tel: 63476100 ... [Handled by <b>Lalitha Krishnan</b> - 6347 6139]  |                        |   |          |         |             |              |            |       |
| Claimant's Insurer:   | <b>MS First Capital Insurance Ltd (HQ)</b> - Tel: 62222311  |                        |   |          |         |             |              |            |       |
| Adjuster:   | <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MARCUS CHUA</b> ] ... [Final Rpt due 15/02/2018]   |                        |   |          |         |             |              |            |       |
| <b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>   |   |                        |   |          |         |             |              |            |       |
| <ul style="list-style-type: none"> <li>III_SG (03/04/2018): Alert - Adj Mandate Approved (\$59902.00) - YP7609T - Claim Handler: Lalitha Kris...</li> <li>III_SG (07/02/2018): Alert - Adj Mandate Approved (\$0.00) - YP7609T - Claim Handler: Lalitha Krishna...</li> </ul> |   |                        |   |          |         |             |              |            |       |
| <b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>   |   |                        |   |          |         |             |              |            |       |
| Due Date  | Priority  | Type                   | Task Group  | Subject  | Handler | Assigned By | Completed On | Created On | Done? |
| No results.   |   |                        |   |          |         |             |              |            |       |

## Claim Documents

\*YP7609T (MC20182108)  
[SGT3380U]



































TP















































STVE PTE. LTD.

























Jan 30 2018 1:00PM

[TOH KIM MENG]

Liu's Brother Auto Engineering Workshop (kaki Bukit)

|                  |                 |                                   |               |   |                    |                                     |            |  |                                     |  |
|------------------|-----------------|-----------------------------------|---------------|---|--------------------|-------------------------------------|------------|--|-------------------------------------|--|
| Upload Documents |                 |                                   | Upload Photos |   | Compose New Letter |                                     | View       |  | View in Browser                     |  |
| Photos/Images    |                 |                                   |               |   |                    |                                     | 3 per page |  | <input checked="" type="checkbox"/> |  |
| No               | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) |               | Thumbnail   | Print              |                                     |            |  |                                     |  |
| 1                | 07/02/18 14:22  | Odometer Reading                  |               |    | Load JPG           | <input checked="" type="checkbox"/> |            |  |                                     |  |
| 2                | 07/02/18 14:22  | General View                      |               |    | Load JPG           | <input checked="" type="checkbox"/> |            |  |                                     |  |
| 3                | 07/02/18 14:22  | Chassis Number                    |               |    | Load JPG           | <input checked="" type="checkbox"/> |            |  |                                     |  |
| 4                | 07/02/18 14:22  | General View                      |               |    | Load JPG           | <input checked="" type="checkbox"/> |            |  |                                     |  |
| 5                | 07/02/18 14:22  | General View                      |               |    | Load JPG           | <input checked="" type="checkbox"/> |            |  |                                     |  |
| 6                | 07/02/18 14:22  | General View                      |               |    | Load JPG           | <input checked="" type="checkbox"/> |            |  |                                     |  |
| 7                | 07/02/18 14:22  | General View                      |               |    | Load JPG           | <input checked="" type="checkbox"/> |            |  |                                     |  |
| 8                | 07/02/18 14:22  | General View                      |               |    | Load JPG           | <input checked="" type="checkbox"/> |            |  |                                     |  |
| 9                | 07/02/18 14:22  | General View                      |               |    | Load JPG           | <input checked="" type="checkbox"/> |            |  |                                     |  |
| 10               | 07/02/18 14:22  | General View                      |               |    | Load JPG           | <input checked="" type="checkbox"/> |            |  |                                     |  |
| 11               | 07/02/18 14:22  | General View                      |               |   | Load JPG           | <input checked="" type="checkbox"/> |            |  |                                     |  |
| 12               | 07/02/18 14:22  | General View                      |               |  | Load JPG           | <input checked="" type="checkbox"/> |            |  |                                     |  |
| 13               | 07/02/18 14:22  | General View                      |               |  | Load JPG           | <input checked="" type="checkbox"/> |            |  |                                     |  |
| 14               | 07/02/18 14:22  | General View                      |               |  | Load JPG           | <input checked="" type="checkbox"/> |            |  |                                     |  |
| 15               | 07/02/18 14:22  | General View                      |               |  | Load JPG           | <input checked="" type="checkbox"/> |            |  |                                     |  |
| 16               | 07/02/18 14:22  | General View                      |               |  | Load JPG           | <input checked="" type="checkbox"/> |            |  |                                     |  |
| 17               | 07/02/18 14:22  | General View                      |               |  | Load JPG           | <input checked="" type="checkbox"/> |            |  |                                     |  |
| 18               | 07/02/18 14:22  | General View                      |               |  | Load JPG           | <input checked="" type="checkbox"/> |            |  |                                     |  |
| 19               | 07/02/18 14:22  | General View                      |               |  | Load JPG           | <input checked="" type="checkbox"/> |            |  |                                     |  |
| 20               | 07/02/18 14:22  | General View                      |               |  | Load JPG           | <input checked="" type="checkbox"/> |            |  |                                     |  |
| 21               | 07/02/18 14:22  | General View                      |               |  | Load JPG           | <input checked="" type="checkbox"/> |            |  |                                     |  |
| 22               | 07/02/18 14:22  | General View                      |               |  | Load JPG           | <input checked="" type="checkbox"/> |            |  |                                     |  |
| 23               | 07/02/18 14:22  | General View                      |               |  | Load JPG           | <input checked="" type="checkbox"/> |            |  |                                     |  |
| 24               | 07/02/18 14:22  | General View                      |               |  | Load JPG           | <input checked="" type="checkbox"/> |            |  |                                     |  |
| 25               | 07/02/18 14:22  | General View                      |               |  | Load JPG           | <input checked="" type="checkbox"/> |            |  |                                     |  |
| 26               | 07/02/18 14:22  | General View                      |               |  | Load JPG           | <input checked="" type="checkbox"/> |            |  |                                     |  |
| 27               | 07/02/18 14:22  | General View                      |               |  | Load JPG           | <input checked="" type="checkbox"/> |            |  |                                     |  |
| 28               | 07/02/18 14:22  | General View                      |               |  | Load JPG           | <input checked="" type="checkbox"/> |            |  |                                     |  |
| 29               | 07/02/18 14:22  | General View                      |               |  | Load JPG           | <input checked="" type="checkbox"/> |            |  |                                     |  |
| 30               | 07/02/18 14:22  | General View                      |               |  | Load JPG           | <input checked="" type="checkbox"/> |            |  |                                     |  |
| 31               | 07/02/18 14:22  | General View                      |               |  | Load JPG           | <input checked="" type="checkbox"/> |            |  |                                     |  |
| 32               | 07/02/18 14:22  | General View                      |               |  | Load JPG           | <input checked="" type="checkbox"/> |            |  |                                     |  |
| 33               | 07/02/18 14:22  | General View                      |               |  | Load JPG           | <input checked="" type="checkbox"/> |            |  |                                     |  |
| 34               | 07/02/18 14:22  | General View                      |               |  | Load JPG           | <input checked="" type="checkbox"/> |            |  |                                     |  |
| 35               | 07/02/18 14:22  | General View                      |               |  | Load JPG           | <input checked="" type="checkbox"/> |            |  |                                     |  |
| 36               | 07/02/18 14:22  | General View                      |               |  | Load JPG           | <input checked="" type="checkbox"/> |            |  |                                     |  |
| 37               | 07/02/18 14:22  | General View                      |               |  | Load JPG           | <input checked="" type="checkbox"/> |            |  |                                     |  |

| Photos/Images |                 |                                   | 3 per page   | <input checked="" type="checkbox"/> |
|---------------|-----------------|-----------------------------------|--|-------------------------------------|
| No            | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail  | Print                               |
| 38            | 07/02/18 14:22  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 39            | 07/02/18 14:22  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 40            | 07/02/18 14:22  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 41            | 07/02/18 14:22  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 42            | 07/02/18 14:22  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 43            | 07/02/18 14:22  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 44            | 07/02/18 14:22  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 45            | 07/02/18 14:22  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 46            | 07/02/18 14:22  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 47            | 07/02/18 14:22  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 48            | 07/02/18 14:22  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 49            | 07/02/18 14:22  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 50            | 07/02/18 14:22  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 51            | 07/02/18 14:22  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 52            | 07/02/18 14:22  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 53            | 07/02/18 14:22  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 54            | 07/02/18 14:22  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 55            | 07/02/18 14:22  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 56            | 07/02/18 14:22  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 57            | 07/02/18 14:22  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 58            | 07/02/18 14:22  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 59            | 07/02/18 14:22  | General View                      |  Load JPG  | <input checked="" type="checkbox"/> |
| 60            | 07/02/18 14:22  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 61            | 07/02/18 14:22  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 62            | 07/02/18 14:22  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 63            | 07/02/18 14:22  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 64            | 07/02/18 14:22  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 65            | 07/02/18 14:22  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 66            | 07/02/18 14:22  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 67            | 07/02/18 14:22  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 68            | 07/02/18 14:22  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 69            | 07/02/18 14:22  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 70            | 09/02/18 10:33  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 71            | 09/02/18 10:33  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 72            | 09/02/18 10:33  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 73            | 09/02/18 10:33  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 74            | 09/02/18 10:33  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 75            | 09/02/18 10:33  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 76            | 09/02/18 10:33  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 77            | 09/02/18 10:33  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 78            | 09/02/18 10:33  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 79            | 09/02/18 10:33  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 80            | 09/02/18 10:33  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 81            | 09/02/18 10:33  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 82            | 09/02/18 10:33  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 83            | 09/02/18 10:33  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 84            | 09/02/18 10:33  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 85            | 09/02/18 10:33  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 86            | 09/02/18 10:33  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 87            | 09/02/18 10:33  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |

| Photos/Images |                 |  | 3 per page   | <input checked="" type="checkbox"/> |
|---------------|-----------------|--|--|-------------------------------------|
| No            | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)          | Thumbnail  | Print                               |
| 88            | 09/02/18 10:33  | Reinspection Photo                         |  Load JPG   | <input checked="" type="checkbox"/> |
| 89            | 09/02/18 10:33  | Reinspection Photo                         |  Load JPG   | <input checked="" type="checkbox"/> |
| 90            | 09/02/18 10:33  | Reinspection Photo                         |  Load JPG   | <input checked="" type="checkbox"/> |
| 91            | 09/02/18 10:33  | Reinspection Photo                         |  Load JPG   | <input checked="" type="checkbox"/> |
| 92            | 09/02/18 10:33  | Reinspection Photo                         |  Load JPG   | <input checked="" type="checkbox"/> |
| 93            | 09/02/18 10:33  | Reinspection Photo                         |  Load JPG   | <input checked="" type="checkbox"/> |
| 94            | 09/02/18 10:33  | Reinspection Photo                         |  Load JPG   | <input checked="" type="checkbox"/> |
| 95            | 09/02/18 10:33  | Reinspection Photo                         |  Load JPG   | <input checked="" type="checkbox"/> |
| 96            | 09/02/18 10:33  | Reinspection Photo                         |  Load JPG   | <input checked="" type="checkbox"/> |
| 97            | 09/02/18 10:33  | Reinspection Photo                         |  Load JPG   | <input checked="" type="checkbox"/> |
| 98            | 09/02/18 10:33  | Reinspection Photo                         |  Load JPG   | <input checked="" type="checkbox"/> |
| 99            | 09/02/18 10:33  | Reinspection Photo                         |  Load JPG   | <input checked="" type="checkbox"/> |
| 100           | 09/02/18 10:33  | Reinspection Photo                         |  Load JPG   | <input checked="" type="checkbox"/> |
| 101           | 09/02/18 10:33  | Reinspection Photo                         |  Load JPG   | <input checked="" type="checkbox"/> |
| 102           | 09/02/18 10:33  | Reinspection Photo                         |  Load JPG   | <input checked="" type="checkbox"/> |
| Documentation |                 |  | 1 per page   | <input checked="" type="checkbox"/> |
| No            | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)          | Thumbnail  | Print                               |
| 1             | 06/02/18 17:46  | TP GIA REPORT                              |  Load PDF   |                                     |
| 2             | 06/02/18 17:46  | EMAIL FROM III DD 0502201                  |  Load PDF   |                                     |
| 3             | 13/02/18 09:13  | TP ESTIMATE- MARKED                        |  Load PDF   |                                     |
| 4             | 26/03/18 12:59  | WORKSHOP INVOICE                           |  Load PDF   |                                     |
| 5             | 26/03/18 12:59  | GIA SEARCH                                 |  Load PDF  |                                     |
| 6             | 26/03/18 12:59  | LOD  |  Load PDF |                                     |
| 7             | 16/05/18 13:53  | AUTHORISATION TO ACT FORM                  |  Load PDF |                                     |
| 8             | 16/05/18 13:53  | DISCHARGE VOUCHER                          |  Load PDF |                                     |
| No            | Finalized On    | India International Insurance Pte Ltd (HQ) | Thumbnail  | Print                               |
| 1             | 07/02/18 09:23  | Singapore Accident Statement               |  Load PDF |                                     |

## Documents Checklist

| DOCUMENTS CHECKLIST  | Reset | Save | Print |
|--|-------|------|-------|
| There are no document checklists configured.   |       |      |       |
| <b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>       |       |      |       |
| <b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer<br><small>Note: Remarks are private unless you show it to other parties.</small> |       |      |       |



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18002389/UPB3Q2

Date: 16/05/2018

## REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No: M491115

Claimant Vehicle No: YP7609T

Insured Vehicle No: SGT3380U

Date of Loss: 30/01/2018

Nature of Claim: TP

Claim No: MC20182108

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: YP7609T

Make &amp; Model: MITSUBISHI FK617MSJRDEC, 7.5 D (M)

Engine No: 6M60229746

Reg. Date: 09/10/2017 (Man. Year: 2017)

Chassis No: FK62FMA30364

Colour: White

Odometer: 12750 km

Engine Capacity: 7545 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 245/70 R19.50

Rear Tyre Size: 245/70 R19.50 (D)

Front Left Side: Bridgestone 8 mm

Rear Left Side: Bridgestone 8/8 mm

Front Right Side: Bridgestone 8 mm

Rear Right Side: Bridgestone 8/8 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS                                   | Repairer's       | Adjuster's       | Difference       | Diff %       |
|--|------------------|------------------|------------------|--------------|
| Parts  | 23,015.60        | 9,253.35         | 13,762.25        | 59.80        |
| Miscellaneous Items                              | 0.00             | 0.00             | 0.00             |              |
| Labour   | 2,920.00         | 2,050.00         | 870.00           | 29.79        |
| Paintwork Labour                                 | 0.00             | 0.00             | 0.00             |              |
| Towing   | 0.00             | 0.00             | 0.00             |              |
| <b>Calculated Gross Total (S\$)</b>              | <b>25,935.60</b> | <b>11,303.35</b> | <b>14,632.25</b> | <b>56.42</b> |
| <b>Approved Total (Overridden) (S\$)</b>         |                  | <b>9,000.00</b>  |                  |              |
| <b>Nett Amount (S\$)</b>                         | <b>25,935.60</b> | <b>9,000.00</b>  | <b>16,935.60</b> | <b>65.30</b> |
| <b>+ Loss of Use (6.0 x S\$150.00/day) (S\$)</b> |                  | 900.00           |                  |              |
| <b>+ Doc/Search Fee (S\$)</b>                    |                  | 2.00             |                  |              |
| <b>Nett Liability (S\$)</b>                      |                  | <b>9,902.00</b>  |                  |              |
| <b>Global Sum Settlement (S\$)</b>               |                  | <b>9,900.00</b>  |                  |              |

## INSPECTION

Date of Assignment: 05/02/2018

Date Inspected: 05/02/2018 Inspected At:

Liu's Brother Auto Engineering Workshop  
(kaki Bukit) (HQ)

Blk 1 Kaki Bt Ave 6 #01-01 Auto Bay @

Kaki Bt Singapore 417883, Kaki Bukit  
Singapore 417883

Estimated Period of Repair: 4.0 days

---

**Adjuster:** MARCUS CHUA

**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

|                      |  |   |
|----------------------|--|---|
| <b>Part Source:</b>  | (Last Synchronised: 26 Mar 2018)   |   |
| <b>Parts:</b>        | N/A  | mitsubishi FK617MSJRDEC 7.5 D (M) (Model not available in database) |
| <b>Labour:</b>       | Repairer's   | (Price-denominated Standard List)                                   |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for YP7609T)   |   |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |   |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.   |   |

## Recommended Parts

| No. | Qty | Part No. | Particulars                            | Condition                | Repairer's | Amount       |
|-----|-----|----------|--|--------------------------|------------|--------------|
| 1   | 1   |          | *FRONT BUMPER                          | Badly Dented             | 3,336.80 F | *1,436.50 FL |
| 2   | 1   |          | *FRONT BUMPER BEAM                     | Bent                     | 1,282.00 F | *1,282.00 FL |
| 3   | 2   |          | *FRONT HEADLAMP                        | Cracked                  | 2,005.00 F | *2,005.00 FL |
| 4   | 1   |          | *FRONT HEAD LAMP PANEL                 | No such part             | 982.00 F   | *- FL        |
| 5   | 2   |          | *FRONT HEAD LAMP GRILLE (CASING)       | N/S Cracked / O/S Broken | 1,162.00 F | *970.20 FL   |
| 6   | 1   |          | *FRONT FOG LAMP                        | O/S Grazed               | 970.00 F   | *485.00 FL   |
| 7   | 1   |          | *FRONT GILLE                           | Cracked                  | 1,423.00 F | *1,423.00 FL |
| 8   | 1   |          | *SET FRONT GILLE CLIPS                 | Necessary                | 42.00 F    | *42.00 FL    |
| 9   | 1   |          | *FRONT GRILLE MITSUBISHI EMBLEM        | Necessary                | 119.50 F   | *119.50 FL   |
| 10  | 1   |          | *FRONT GRILLE FIGHTER EMBLEM           | Necessary                | 111.00 F   | *111.00 FL   |
| 11  | 1   |          | *FRONT PANEL                           | Dented / Bent            | 2,791.00 F | *2,791.00 FL |
| 12  | 1   |          | *FRONT PANEL FUSO EMBLEM               | Necessary                | 280.00 F   | *115.00 FL   |
| 13  | 2   |          | *FRONT PANEL LOCK                      | Repair                   | 559.00 F   | *- FL        |
| 14  | 2   |          | *FRONT PANEL HINGE                     | Not Necessary            | 258.00 F   | *- FL        |
| 15  | 1   |          | *FRONT CORNER PANEL GARNISH O/S        | Cracked                  | 1,184.00 F | *785.10 FL   |
| 16  | 1   |          | *FRONT INNER PANEL                     | Repair                   | 5,378.50 F | *- FL        |
| 17  | 1   |          | *FRONT SIGNAL LAMP RH                  | Not Necessary            | 212.00 F   | *- FL        |
| 18  | 1   |          | *FRONT RADIATOR SPARE TANK             | Deformed                 | 491.80 F   | *380.50 FL   |
| 19  | 1   |          | *FRONT NUMBER PLATE (METAL)            | Bent                     | 28.00 FS   | *14.00 FS    |
| 20  | 1   |          | *FRONT CORPORATE ADVERTISEMENT STICKER | Necessary                | 400.00 FS  | *280.00 FS   |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|   |                  |                  |
|---|------------------|------------------|
| <b>Sub Total (\$\$)</b>                                   | <b>23,015.60</b> | <b>12,239.80</b> |
| <b>- List Item Discount on L Items 0.00/25.00% (\$\$)</b> | <b>0.00</b>      | <b>2,986.45</b>  |

|                           |                  |                 |
|---------------------------|------------------|-----------------|
| <b>Total Parts (\$\$)</b> | <b>23,015.60</b> | <b>9,253.35</b> |
|---------------------------|------------------|-----------------|

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars   | Lab.Type | Repairer's      | Amount          |
|--------------------------------|---|----------|-----------------|-----------------|
| <b>Labour Items</b>            |   |          |                 |                 |
| 1                              | TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION                  | New      | 50.00           | 20.00           |
| 2                              | TO APPLY RUST PROOFING ,RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA          | New      | 50.00           | 30.00           |
| 3                              | TO REMOVE & REFIX AIR CON ,RE-FILL AIR CON GAS & TEST FOR LEAKAGES              | New      | 120.00          | 0.00            |
| 4                              | LABOR FOR PANEL BEATING,CUT,WELD ,STRAIGHTEN & REPLACING PARTS ETCS             | New      | 1,500.00        | 1,000.00        |
| 5                              | TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS | New      | 1,200.00        | 1,000.00        |
| <b>Gross Labour Cost (S\$)</b> |   |          | <b>2,920.00</b> | <b>2,050.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >