

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB7568C - *ALG*

AAD1802-021

Not Autharised
61 Sm \$360

Vehicle No.:

SHB7568C - JHOW

Chassis No.:

KL1LA69RJB078097

Date of Accident :

02.02.2018

Vehicle Make:

CHEVROLET

Vehicle Model:

CHEVROLET EPICA 2.0

Third Party Insurer :

ALG

		PART		LIST	
1	1	Front Door RH	\$	<i>AL</i> 1,133.00	<i>X</i>
2	1	Front Door Outer Moulding RH	\$	<i>SL</i> 220.00	
3	1	Front Door Outer Handle RH	\$	<i>SL</i> 125.00	
4	1	Front Side View Mirror RH	\$	<i>SL</i> 939.00	
5	1	Side Rocker Panel Garnish RH	\$	<i>SL</i> 236.40	
6	1	Rear Door RH	\$	<i>AL</i> 1,133.00	
7	1	Rear Door inner lock RH	\$	<i>SL</i> 425.00	
8	1	Rear Door outer weatherstrip moulding RH	\$	<i>SL</i> 85.00	
9	1	Rear Door outer handle RH	\$	<i>SL</i> 60.00	
10	1	Rear Fender RH	\$	<i>AL</i> 1,145.00	
11	1	Rear Fender Inner Cowling RH	\$	<i>SL</i> 76.60	
12	1	Rear Tail Lamp RH	\$	<i>SL</i> 479.30	
13	1	Rear Bumper	\$	<i>SL</i> 1,202.00	

TOTAL \$ 7,259.30

10% \$ 725.93

\$ 6,533.37

Special Nett

1	1 Set	Rear Bumper Fastener Clip	\$	<i>AL</i> 30.00	<i>X</i>
2	1 Set	Rear Fender Liner Clip	\$	<i>AL</i> 30.00	<i>X</i>
3	1	Door Sticker "Trans-cab"	\$	<i>AL</i> 80.00	<i>X</i>
4	1	Door Sticker "6555-3333"	\$	<i>AL</i> 80.00	<i>6555-3333</i>
5	1set	Side Rocker Panel Garnish Clip RH	\$	<i>AL</i> 60.00	<i>X</i>
6	1	Rear Tyre RH	\$	<i>SL</i> 360.00	<i>X</i>
7	1	Rear Wheel Rim RH	\$	<i>SL</i> 254.00	<i>X</i>
8	1	Hub Cup Rim RR RH	\$	<i>SL</i> 35.00	<i>X</i>

TOTAL \$ 929.00

TOTAL PARTS \$ 7,462.37

TRANS-CAB AUTO SERVICES PTE LTD**AAD1802-021**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB7568C -

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,700.00	100%
To Rust-Proofing Of The Affected Areas.	\$	220.00	X
To transfer of tire, rim and on wheel balancing.	\$	170.00	X
Putty and Spray Painting Of The Affected Portion.	\$	2,800.00	200%
To Check Electrical Lighting Concerned.	\$	170.00	X
To check steering geometry and computer wheel alignment	\$	220.00	X
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00	X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	170.00	X

TOTAL	\$	6,620.00
Over All Total	\$	14,082.37

REPAIR DAYS~~10 DAYS~~

1 day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: