## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AXA Insurance Pte Ltd 8 Shenton Way #24-01

AXA Tower Singapore 068811 From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park

Paya Ubi Industrial Park Singapore 408933

Attn: Cynthia Loh Date: 07 Mar 2018

# **Preliminary Advice**

Insured Vehicle No : SHC5871J

TP Vehicle No : SKU7575X Accident Date : 01/02/2018

Make : TOYOTA ESTIMA AERAS Assignment Date : 05/02/2018

Date of Inspection : 05/03/2018 Est. Duration of Repair : 6 days

Inspection At : Accord Auto Services Pte Ltd (HQ)

10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point

Singapore 568047

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages ....rear.... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,096.03
Revised Amount	:S\$	4,345.98
Check Items (Estimated)	:S\$	1,049.15
Total	:S\$	5,395.13

Lump Sum Repair :S\$

#### **Total Loss Consideration**

New for Old Value :\$\$
Pre-Accident Value :\$\$
COE / PARF Rebate :\$\$
Salvage Value :\$\$
Margin for Repair :\$\$

### Remarks

(	)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments: We have not authorized repairs.