

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Telefax

**Estimate** : Accident Repairs  
**Workshop** : Ubi Road 1  
**Contact No** : 6366 2323  
**Fax No** : 6841 1183  
**Reference** : PA/TP/0165/2018/GW  
**Date** : 3-Feb-18

Vehicle not IN workshop. Kindly arrange for survey.

## AXA Insurance Singapore Pte Ltd

8 Shenton Way  
#27-01 AXA Tower  
Singapore 068811

**Attn: Motor Claims Dept**  
**Tel: 6880 4602 - Fax 6880 4838**

**Owner's Name** : Ms. Teng YiWen,June  
**Address** : 381 Tanglin Rd  
#11-03  
Singapore 247965  
**Telephone** : HP +65 94310099  
**Type of Claim** : Third Party Claims  
**Policy No.** : 2100450428-02  
**Vehicle No** : **SLA 8282 C**  
**Model Code** : Audi A1 SB 1.0 TFSI S Tronic  
**Model / Year** : Jan-16  
**Engine No** : CHZ 057775  
**Chassis No** : WAUZZZ8X5GB058751  
**Mileage** :  
**Date In** :  
**Liability** : -  
**Excess Cost** : -  
**Estimated By** : Johnny Boo / Allan Wu  
**Accident Date** : 3-Feb-18  
**Place of Accident** : Bedok Library Carpark

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SLA 8282 C.

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlight, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	✓
2	To dismantle and renew front bumper and rhs headlight. Re-oraganise front crash management components. Reinstall all parts removed.	\$ <del>1,200.00</del>	900
3	To respray front bumper and rhs front fender.	\$ <del>1,400.00</del>	600
5	To carry out diagnostic check.	S/N \$ 192.00	✓
<b>TOTAL LABOUR CHARGES</b>		<b>: \$ <u>3,152.00</u></b>	

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No.SLA 8282 C

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>del.</i>	\$ 1,336.00	✓
2	FRONT BUMPER AIR GUIDE GRILLE -RH <i>Man</i>	\$ 353.00	X
3	FOAM FILLER PIECE <i>Man</i>	\$ 101.00	X
4	FRONT BUMPER SIDE REINFORCEMENT <i>Man</i>	\$ 605.00	X
5	HEADLIGHT-RH <i>at</i>	\$ 1,705.00	✓
6	HEADLIGHT MOUNTING ?	\$ 103.00	?
7	HEADLIGHT WASHER LIFT CYLINDER-RH ?	\$ 123.00	?
8	SUNDRIES ?	\$ 200.00	?
TOTAL SPARE PARTS CHARGES		: \$ 4,526.00	
TOTAL LABOUR CHARGES		: \$ 3,152.00	
GRAND TOTAL		: \$ 7,678.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name : Adrian Lg  
Surveyed Date : 09/02/18.  
Authorised Date :  
Excess Cost :  
Liability :  
Remarks : Not Authorised, 04 days

**Please Note** : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant