



PDI TUAS

ONG SHE-NA
496C TAMPINES STREET 43
#07-259
Singapore, 526496
Singapore

PDI TUAS

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV029011
Quote No. SER/QUO/1800211
QuoteDate 06/02/18
Salesperson Michelle Lee
Page 1

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	JETTA A6 1.4 TSI DSG 90KW HL	95,693	
License No.	VIN	Initial Registration	Sales Advisor
EZ3966Y	WVWZZZ16ZEM058795	29/04/15	Michelle Lee
Engine Code	Labor Type	Engine No.	Model Code
	M4	CAX E77840	1624G5

No.	Description	Qty.	UoM	Unit Price	Amount
P B&P MACP LABOUR	LABOUR	8	UNIT		3780 6,720.00
P B&P MACP LABOUR	R&R REAR LUGGAGE TRIM	1	UNIT		420 840.00
P B&P MACP PAINT	SPRAY PAINT	7	UNIT		3200 5,800.00
P B&P NUMBER PLATE	B&P NUMBER PLATE -NETT	1	pcs		Sum 80.00
P B&P SENSOR	SUPPLY & INSTALL REVERSE SE	1	Pieces		400.00
P B&P DIAG	PROGRAMMING & CALIBRATION	1	Time Un		480.00
P B&P MECH	COMPULSORY TO DO AFTER AC				
	ELECT WIRING & MECH COMPO	1	Time Un		280.00
	Nett				
	Sum Labor				14,400.00
P 1K8945300	BOLT	1	Pieces		? 8.81
P 1K9853675B GQF	NAME PLATE (TSI)	1	Pieces		52.53
P 1K9853687A 739	NAME PLATE (JETTA)	1	Pieces		55.80
P 3AF943021A	LED LICENCE PLATE LIGHT	2	Pieces		253.06
P 5C6807305	REINFORCEMENT	1	Pieces		514.20
P 5C6807393A	TAILLIGHT LOWER BRACKET LH	1	Pieces		83.42
P 5C6807393B	BUMPER SIDE BRACKET LH	1	Pieces		115.65
	Use Predecessor 5C6807393				
P 5C6807394A	TAILLIGHT LOWER BRACKET RH	1	Pieces		? 60.84
P 5C6807394B	BUMPER SIDE BRACKET RH	1	Pieces		104.09
	Use Predecessor 5C6807394				
P 5C6807421 GRU	REAR BUMPER	1	Pieces		1,061.34
P 5C6807433	SPOILER	1	Pieces		511.01
P 5C6807863	BUMPER CENTRE BRACKET	1	Pieces		77.46
P 5C6810689	TAILLIGHT PANEL LH	1	Pieces		? 177.77
	Predecessor 5C6813327				

Sum carried forward

17,475.98

Payments to:

- BBN: - Acc.-No..:

PDI TUAS

PDI TUAS

ONG SHE-NA
496C TAMPINES STREET 43
#07-259
Singapore, 526496
Singapore

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV029011
Quote No. SER/QUO/1800211
QuoteDate 06/02/18
Salesperson Michelle Lee
Page 2

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	JETTA A6 1.4 TSI DSG 90KW HL	95,693	
License No.	VIN	Initial Registration	Sales Advisor
EZ3966Y	WVWZZZ16ZEM058795	29/04/15	Michelle Lee
Engine Code	Labor Type	Engine No.	Model Code
	M4	CAX E77840	1624G5

Continued			17,475.98
P 5C6813301	REAR END PANEL	1 Pieces	1,282.34
P 5C6827025A	REAR BOOT LID	1 Pieces	1,796.25
	Use Predecessor 5C6827025		
P 5C6827301E	HINGE LH	1 Pieces	94.92
	Use Predecessor 5C6827301D		
P 5C6827302D	HINGE RH	1 Pieces	94.92
	Use Predecessor 5C6827302B		
P 5C6827505G	LOCK	1 Pieces	193.80
	Use Predecessor 5C6827505F		
P 5C6827507B	LOCK STRIKER	1 Pieces	51.47
P 5C6827520B 9B9	LOCK COVER	1 Pieces	17.84
P 5C6827705A 5AP	REAR BOOT LID WTHRSTRIP	1 Pieces	252.81
P 5C6853630E ULM	VW SIGN	1 Pieces	93.68
	Use Predecessor 5C6853630 ULM		
P 5C6863459G 9B9	END PANEL TRIM COVER	1 Pieces	83.60
P 5C6867605A 9B9	REAR BOOT LID TRIM	1 Pieces	279.93
P 5C6945093	TAILLIGHT INNER LH	1 Pieces	310.52
P 5C6945094A	TAILLIGHT INNER RH	1 Pieces	310.52
P 5C6945095E	TAILLIGHT OUTER LH	1 Pieces	498.60
	Use Predecessor 5C6945095A		
P 5C6945096E	TAILLIGHT OUTER RH	1 Pieces	498.62
P 5C6945105A	REFELCTOR LH	1 Pieces	87.44
P 5M0945167	ADJUSTPART	4 Pieces	33.80
P 5N0827566T	PUSH BUTTON	1 Pieces	138.09
	Use Predecessor 5N0827566B		
P 8D0853419D	REAR NUMBER PLATE PACKING	1 Pieces	14.61
Sum carried forward			23,609.74

Payments to:

- BBN: - Acc.-No.:

PDI TUAS

PDI TUAS

ONG SHE-NA
496C TAMPINES STREET 43
#07-259
Singapore, 526496
Singapore

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV029011
Quote No. SER/QUO/1800211
QuoteDate 06/02/18
Salesperson Michelle Lee
Page 3

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	JETTA A6 1.4 TSI DSG 90KW HL	95,693	Sales Advisor
License No.	VIN	Initial Registration	Michelle Lee
EZ3966Y	WVWZZZ16ZEM058795	29/04/15	Model Code
Engine Code	Labor Type	Engine No.	1624G5
	M4	CAX E77840	

Continued			23,609.74
P D 007600A1	INOXSPRAY	1 Pieces	78.44
P D 180003M2	2KADHESIV	1 Pieces	330.24
P D 476KD1M2	SEALANT	1 Pieces	89.30
P D 506KD1A3	2K FOAM	1 Pieces	182.27
P N 10621301	NUT	8 Pieces	17.20
P N 90346301	POP-RIVET	6 Pieces	9.12
P N 90766702	NUT	4 Pieces	9.96
Successor N 90766703			
Sum Item			9,926.27

Sum Labor	14,400.00
Sum Item	9,926.27

Total SGD	24,326.27
7% GST	1,702.84
Total SGD Incl. GST	26,029.11

Explanations
P = Proportionately Charged

Payment Terms No Credit

Payments to: - BBN: - Acc.-No.:

9 days
02/02/18 @ 1710
Resy by paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: