

Survey Department Check List (Case Handler)

Reference No.: NS/INC 18002418/RLxb
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 15/2/18
 Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18002418/R1vb

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 06-02-2018



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FBK 629E	Veh. Inspected	SHC 4745Y
Policy No.	5086979094	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	05/02/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	02/02/2018	Inspection Date	05/02/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

TP Claims against NTUC Income: Follow-Through Survey

S/NO	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	D.O.A	Time of Accident	Estimate	Tentative repair cost
1	MT/0980700-002	SMRT TAXIS PTE LTD	SHC 4745Y	FBK 629E	2/2/2018	16:00	\$7,449.80	\$2,197.53
2	MT/0981297-002	COMFORT TRANSPORTATION PTE LTD	SH 9778M	SKR 9188H	5/2/2018	16:30	\$2,607.04	\$2,103.04
3	MT/0981207-003	COMFORT TRANSPORTATION PTE LTD	SH 7825Z	SJR 750E	4/2/2018	14:30	\$8,852.40	\$2,900.00
4	MT/0983349-001	COMFORT TRANSPORTATION PTE LTD	SH 7789U	SLT 9304S	5/2/2018	23:20	\$3,524.54	\$2,298.09
5	MT/0981193-002	COMFORT TRANSPORTATION PTE LTD	SHC 2275A	SJK 7721E	5/2/2018	15:35	\$6,226.34	\$2,400.00
6	MT/0981140-002	CITYCAB PTE LTD	SHC 7318C	SLD 3740P	6/2/2018	6:40	\$2,548.38	\$1,970.70
7	MT/0982086-002	COMFORT TRANSPORTATION PTE LTD	SH 7929H	XD 6757E	12/2/2018	9:30	\$5,489.80	\$2,537.60
8	MT/0982270-002	COMFORT TRANSPORTATION PTE LTD	SHD 4205J	SFU 6132G	13/2/2018	15:45	\$6,687.20	\$2,300.00

Claim received from LKK

eBaoTech

GeneralClaim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No.

Date of Accident

02/02/2018 19:43

Vehicle No.(For Motor)

FBK629E

Search

Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
☒	5086979094	MUHAMMAD DANIAL MOHD ZAINI	S98071981	GMC	Third Party, Fire & Theft	FBK629E	FBK629E	16/12/2016	12/02/2018

Continue

Veron Chen (LKKAUTO)

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) <YeoPohsuan@smrt.com.sg>
Sent: Thursday, 15 February 2018 10:54 AM
To: Veron Chen (LKKAUTO); Rasul (LKKAUTO)
Cc: SUR; CS A Team; Shanti B Thaiyal Nayagi (Auto Svcs/Ext Biz Svcs/Claims & IA/Taxis/Claims)
Subject: RE: SHC4745Y

Hi

Amount confirmed as per your recommendation, thanks.

Aside Shanti,

Please provide the GIA report. Thanks.

Regards
Poh Suan

From: Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]
Sent: 15 February 2018 09:45
To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC); Rasul (LKKAUTO)
Cc: SUR; CS A Team
Subject: RE: SHC4745Y

Dear Poh Suan,

Confirmed amount of \$2,197.53 @ 4 working days

Kindly forward us a copy of GIA report.

Best Regards,
Veron Chen | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) [mailto:YeoPohsuan@smrt.com.sg]
Sent: Tuesday, 13 February 2018 11:16 AM
To: Rasul (LKKAUTO) <Rasul@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; CS A Team <cs-a@lkkauto.com>
Subject: SHC4745Y

Hi Rasul,

Attached herewith the repair estimate of SHC 4745Y having Case No: TAX/02/18/2011.

There is no change to the approved amount of \$2,197.53 @ 4 working days under part by part repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Thanks & Regards
Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)

Sent: 12 February 2018 06:49

To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)

Subject: Scan Data from FX-D421D6

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 15 February 2018 9:45 AM
To: 'Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)'; Rasul (LKKAUTO)
Cc: SUR; CS A Team
Subject: RE: SHC4745Y

Dear Poh Suan,

Confirmed amount of \$2,197.53 @ 4 working days

Kindly forward us a copy of GIA report.

Best Regards,
Veron Chen | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) [mailto:YeoPohsuan@smrt.com.sg]
Sent: Tuesday, 13 February 2018 11:16 AM
To: Rasul (LKKAUTO) <Rasul@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; CS A Team <cs-a@lkkauto.com>
Subject: SHC4745Y

Hi Rasul,

Attached herewith the repair estimate of SHC 4745Y having Case No: TAX/02/18/2011.

There is no change to the approved amount of \$2,197.53 @ 4 working days under part by part repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Thanks & Regards
Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)
Sent: 12 February 2018 06:49
To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)
Subject: Scan Data from FX-D421D6

Enquire Transfer Fee

Vehicle Details

Vehicle No. :	SHC4745Y
Vehicle Type :	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1 :	Air-Con (Taxi)
Vehicle Scheme :	Taxi (Company)
Vehicle Make :	TOYOTA
Vehicle Model :	PRIUS TAXI (SMRT)
Chassis No. :	JTDKN36U205766756
Propellant :	Petrol-Electric
Engine No. :	2ZR1651940
Motor No. :	3JM1651940
Engine Capacity :	1798 cc
Power Rating :	60.0 kW
Maximum Power Output :	100.0 kW (134 bhp)
Maximum Laden Weight :	1805 kg
Unladen Weight :	1370 kg
Year Of Manufacture :	2015
Original Registration Date :	08 Jan 2016
Lifespan Expiry Date :	07 Jan 2024
COE Category :	A - Car up to 1600cc & 97kW (130bhp)

PQP Paid : \$45,307.00

COE Expiry Date : 07 Jan 2024

Road Tax Expiry Date : 07 Jul 2018

PARF Eligibility Expiry Date : 07 Jan 2024

Inspection Due Date : 07 Jul 2018

Intended Transfer Date : 01 Mar 2018

CO2 Emission : 92.00 (g/km)

CEV/VES Rebate Utilised Amount : \$28,312.00

CO Emission : -

HC Emission : -

NOx Emission : -

PM Emission : -

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use [Enquire Road Tax Payable](#) for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

You may print this page for reference.

SMRT Accident Vehicle Repair Estimates

6718

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4745Y
 Ref. No : TAX/02/18/2011
 Reg. Date : 08/01/2016
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : MOHAMED RAZIB BIN OMAR
 Type of Accident : HEAD TO REAR
 Date / Time of Accident : 02/02/2018 02:16:00 PM
 Accident Reported Date / Time : 03/02/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024094446
 Special Instruction to ARC, if any :
 FBK629E / NME / Resumy by print
 Prepared Date : 03/02/2018 10:02:42 AM



Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U205766756

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,014.00	0.00
Total Spray Painting Charges	: 1,494.00	0.00
Total Material Charges	: 3,445.18	3,445.18
Other Charges	: 580.00	0.00
TOTAL	: 6,533.18	0.00
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 6.00	0.00 4 days - p/p
Prepared / Adjusted By	:	
Arc / Surveyor Sign Off Date	: 03/02/2018 11:24:41 AM	01/01/1900 12:00:00 AM

Prepared / Adjusted Date :

Remarks :

Prepared Date : 03/02/2018 11:22:58 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date :

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH REAR PORTION	1,014.00	0.00 400
Total Labour	1,014.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY BUMPER BEAM	180.00	0.00 100?
TO RESPRAY TAIL GATE	378.00	0.00 200
TO RESPRAY REAR PANEL	180.00	0.00 100
TO RESPRAY REAR FENDER LH	378.00	0.00 X
Total Spray Painting & Panel Beating	1,494.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 30
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 20
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 60
TO REPLACE SUNDRY PARTS	100.00	0.00 20
TO WASH AND VACUUM	60.00	0.00 40
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0.00 60
Total Other Costs	580.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52159-47905		6505548	BUMPER REAR	1	458.60	25.00	343.95	Replace	Replace <i>DE</i>	No
52023-12240		6505547	BUMPER REINFORCEMENT REAR	1	205.70	25.00	154.27	Replace	Replace <i>?</i>	No
52016-47030			ARM SUB-ASSY, RR BUMPER LH	1	139.60	25.00	104.70	Replace	Replace <i>?</i>	No
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace <i>X</i>	No
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace <i>new</i>	No
52592-47021			BUMPER SEAL, RR LH	1	88.90	25.00	66.67	Replace	Replace <i>?</i>	No
52576-47020		6505550	BUMPER SIDE RETAINER RR/LH	1	94.80	25.00	71.10	Replace	Replace <i>new</i>	No
67005-47241			TAILGATE ASY	1	1,007.90	25.00	755.92	Replace	Replace <i>Repair</i>	No
75374-47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace <i>new</i>	No
58307-47060		6505522	END PANEL	1	602.10	25.00	451.57	Replace	Replace <i>Repair</i>	No
	COMMO N	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Replace <i>X</i>	No
52563-47010			TAIL LAMP BRACKET, LH	1	30.70	25.00	23.02	Replace	Replace <i>?</i>	No
81561-47170		6505461	TAIL LAMP LH	1	548.40	10.00	493.56	Replace	Replace <i>Sub</i>	No
61602-47091		6505476	FENDER RR/LH	1	766.80	25.00	575.10	Replace	Replace <i>X</i>	No
	COMMO N		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace <i>X</i>	No
	COMMO N		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace <i>X</i>	No
TOTAL MATERIALS								3,445.21	3,445.18	
TOTAL MATERIALS(Discounted)								3,445.18	3,445.18	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									



SMRT Automotive Service Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

9-2-18 / 11:26

9-2-18 / 15:26

SMRT Accident Vehicle Repair Estimates

5-2-18 / 15:26

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4745Y

Ref. No : TAX/02/18/2011

Reg. Date : 08/01/2016

Vehicle Type : TAXI

Make : TOYOTA PRIUS

Model : PRIUS

Name of Driver : MOHAMED RAZIB BIN OMAR

Type of Accident : HEAD TO REAR

Date / Time of Accident : 02/02/2018 02:16:00 PM

Accident Reported Date / Time : 03/02/2018 12:00:00 AM

Surveyor is Required? : Yes

Survey by : Rasul

Vehicle is Towed Back? : No

Towed Back Date/Time :

Replacement Vehicle issued? : No

Accident Repair Job Card No : 000024094446

Special Instruction to ARC, if any :

FBK629E

Before paint photo, After repair photo FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR RASUL / HP : 9001 0068. email: rasul@lkkauto.com

Prepared Date : 03/02/2018 10:02:42 AM



Recording Camera

☐

Radio Antenna


☐1st witness

Date

5-2-18

2nd witness

Date



De 9/2/18 13.52 PASS

LEE SHENG AUTO PTE LTD

Vehicle Return Date: 09/02/2018

Vehicle Return Time: 10:30

SMRT staff sign: _____

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U205766756


Mileage : 0

Work Shop : . . .

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,014.00	400.00
Total Spray Painting Charges	: 1,494.00	500.00
Total Material Charges	: 1,416.20	1,067.53
Other Charges	: 580.00	230.00
TOTAL	: 4,504.20 7449.80	2,197.53
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 6.00	4.00
Prepared / Adjusted By	:	RASUL (LKK)
Arc / Surveyor Sign Off Date	: 03/02/2018 11:24:41 AM	05/02/2018 03:26:29 PM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 03/02/2018 11:22:58 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : QN-1802-0349

Invoice No :

Quotation Date : 11/2

Invoice Date :

Invoice Amount :

Prepared Date :

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH REAR PORTION	1,014.00 ✓	400.00
Total Labour	1,014.00	400.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00 ✓	200.00
TO RESPRAY BUMPER BEAM	180.00 ✗	0.00
TO RESPRAY TAIL GATE	378.00 ✓	200.00
TO RESPRAY REAR PANEL	180.00 ✗	100.00
TO RESPRAY REAR FENDER LH	378.00 ✓	0.00
Total Spray Painting & Panel Beating	1,494.00	500.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	30.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	20.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	60.00
TO REPLACE SUNDRY PARTS	100.00	20.00
TO WASH AND VACUUM	60.00	40.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	60.00
Total Other Costs	580.00	230.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached	
52159-47905		6505548	BUMPER REAR	1	458.60 ✓	25.00	343.95	Replace	Replace	No ✓	DE
52023-12240		6505547	BUMPER REINFORCEMENT REAR	1	205.70 X	25.00	154.27	Replace	Check	No X	SR
52016-47030			ARM SUB-ASSY, RR BUMPER LH	1	139.60 X	25.00	104.70	Replace	Check	No X	SR
			SENSOR REVERSE	0	180.00 X	0.00	0.00	Replace	Not given	No X	SR
			PIXEL STICKER	2	60.00 ✓	0.00	120.00	Replace	Replace	No ✓	SR
52592-47021			BUMPER SEAL, RR LH	1	88.90 X	25.00	66.68	Replace	Check	No X	SR
52576-47020		6505550	BUMPER SIDE RETAINER RR/LH	1	94.80 ✓	25.00	71.10	Replace	Replace	No ✓	HEC
67005-47241			TAILGATE ASY	1	1,007.90 R	100.00	0.00	Replace	Repair	No R	HEC
75374-47051			NAME PLATE (HYBRID)	1	51.90 ✓	25.00	38.92	Replace	Replace	No ✓	HEC
58307-47060		6505522	END PANEL	1	602.10 R	100.00	0.00	Replace	Repair	No R	
	COMMO N	4006314	SEALANT SIKAFLEX	0	37.00 X	0.00	0.00	Replace	Not given	No X	SR
52563-47010			TAIL LAMP BRACKET, LH	1	30.70 X	25.00	23.03	Replace	Check	No X	SR
81561-47170		6505461	TAIL LAMP LH	1	548.40 ✓	10.00	493.56	Replace	Replace	No ✓	SR
61602-47091		6505476	FENDER RR/LH	0	766.80 X	25.00	0.00	Replace	Not given	No X	SR
	COMMO N		SMRT LOGO	0	7.80 X	0.00	0.00	Replace	Not given	No X	SR
	COMMO N		STICKER DECAL 6555 8888	0	21.60 X	0.00	0.00	Replace	Not given	No X	SR
TOTAL MATERIALS							1,416.21	1,067.53			
TOTAL MATERIALS(Discounted)							1,416.20	1,067.53			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

$$\begin{array}{r}
 1067.53 \\
 + 400.00 \\
 + 730.00 \\
 \hline
 2197.53
 \end{array}$$



Thatcham escribe

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD		Ref: NS/INC18002418/R1vbn2	
73 BRAS BASAH ROAD			
#05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			
		Date: 02-03-2018	
		Code: INC4	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	FBK 629E	Veh. Inspected	SHC 4745Y
Policy No.	5086979094	Coverage (\$)	0.00
Claim No.	MT/0980700-002	Excess (\$)	0.00
Assign From		Assign Date	05/02/2018
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JTDKN36U205766756	Colour	MAROON
Odometer	249931	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	FALKEN	5 mm
L/H Front Tyre	195/65 R15	FALKEN	5 mm
R/H Rear Tyre	195/65 R15	FALKEN	5 mm
L/H Rear Tyre	195/65 R15	FALKEN	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.			
DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	02/02/2018	Inspection Date	05/02/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 4745Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BUMPER REAR (DISC 25%)	DEFORMED	458.60	343.95
1	BUMPER SIDE RETAINER RR/LH (DISC 25%)	NECESSARY	94.80	71.10
1	NAME PLATE (HYBRID) (DISC 25%)	NECESSARY	51.90	38.92
1	TAIL LAMP LH (DISC 10%)	SCRATCHED	548.40	493.56
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
1	BUMPER REINFORCEMENT REAR	SERVICEABLE	205.70	-
1	ARM SUB-ASSY,RR BUMPER LH	SERVICEABLE	139.60	-
1	SENSOR REVERSE	SERVICEABLE	180.00	-
1	BUMPER SEAL,RR LH	SERVICEABLE	88.90	-
1	TAIL LAMP BRACKET,LH	SERVICEABLE	30.70	-
1	FENDER RR/LH	SERVICEABLE	766.80	-
1	SEALANT SIKAFLEX	NOT NECESSARY	37.00	-
1	SMRT LOGO	NOT NECESSARY	7.80	-
1	STICKER DECAL 6555 8888	NOT NECESSARY	21.60	-
1	TAILGATE ASY	TO REPAIR	1,007.90	-
1	END PANEL	TO REPAIR	602.10	-
			4,361.80	1,067.53
LABOUR				
THATCHAM STANDARD REPAIR TIME ON BODY WORKS.			1,334.00	550.00
THATCHAM TTS STANDARD SPRAY PAINTING COST AND LABOUR.			1,594.00	520.00
TO REPLACE SUNDRY PARTS.			100.00	20.00
TO WASH AND VACUUM.			60.00	40.00
			3,088.00	1,130.00
GRAND TOTAL			7,449.80	2,197.53
RECOMMENDED COST OF REPAIRS (CONFIRMED)				2,197.53

Report Ref No. NS/INC18002418/R1vbn2

MOHAMMED RASUL BIN MOHD YUNUS
Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.