



LIU'S BROTHER AUTO ENGINEERING WORKSHOP

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J, Tel: 6741-1730 / 731, Fax: 6744-5746, Email: liubro@ymail.com

Invoice/Ref No: SLA4521P180126

Estimate

Customer

Name: EQ Insurance Company Limited
Address: Motor Claims Department
5 Maxwell Road #17-00
Tower Block MND Complex Singapore 069110

Date: 05-03-18
Vehicle No: SLA4521P
Model/Make: Nissan Sylphy
1.8 CVT ABS D/Airbag 2WD 4DR

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Bumper	\$ 607.00	N
2	Bumper Side Holders	\$ 21.10	N
3	Bumper Clips 1 set	\$ 50.00	SN
4	Bumper Reverse Sensor 1 set	\$ 220.00	SN
5	Bumper Bracket 02 pcs (@ \$33.60 N)	\$ 67.20	N
6	Bumper Sponges 03 pcs (@ \$85.10 N)	\$ 255.30	N
7	Bumper Beam	\$ 43.90	N
8	Bootlid "Nissan" Emblem	\$ 46.10	N
9	Bootlid "Sylphy" Emblem	\$ 87.00	N
10	Bootlid "XTRONIC" Emblem	\$ 52.50	N
11	Bootlid Reflector	\$ 120.50	N
12	Tail Lamp	\$ 365.00	N
13	End Panel	\$ 428.40	N
To check all wiring & electrical component for proper function		\$ 50.00	-
Remove and refix rear reverse sensor		\$ 80.00	-
Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc		\$ 680.00	-
To putty & spray painting & including touch up paint on accident affected areas		\$ 800.00	-
To apply Rust Proofing, reseat tuff-coating treatment on accident area		\$ 50.00	-
Remove & refix & upholstery to facilitate repair		\$ 100.00	-

Total Parts & Labour of estimate for damaged vehicle

\$ 4,124.00

Total amount in Part By Part / Lump Sum Basis for repaired vehicle

\$ -

SDLS:

not authorized
N/A



M/s Liu's Brother Auto Engrg Ws

7/1P \$2397.42
3 day

7-1263-8
102
1137.42
2397.42

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: