

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SGH 5973 J
TP/India

M/S : INDIA INT'L INSURANCE PTE LTD

64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711

TEL: 63476100

FAX: 62247743

ATTN: Motor Claim Department

WS Ref: TP/INDIA/YS

Claim Type: Third Party

Accident Date: 02/02/2018

TP Veh Reg No: SHC8955G

Estimate No: ES1890129/YISHUN

Date: 06 Feb 2018

Policy No: 5096998181

Veh Reg No: SGH5973J

Make/Model: TOYOTA VIOS 1.5E A

Chassis No: MR053HY4204191726

Engine No: 1NZX441347

Reg. Date: 16/06/2006

Estimate Repair Cost to Vehicle No :SGH5973J

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 FRONT BUMPER	286.40	1 PC	Bu 286.40	✓
2 FRONT BUMPER REINFORCEMENT	320.10	1 PC	M 320.10	✓
3 FRONT BUMPER RH SIDE RETAINER	8.90	1 PC	D/S 8.90	✓
4 FRONT BUMPER CLIPS	3.50	6 PC	M 21.00	✓
5 HEAD LAMP	247.60	2 PCS	495.20	?
6 REAR BUMPER	246.70	1 PC	Bu 246.70	✓
7 REAR BUMPER CLIPS	3.50	6 PC	M 21.00	✓
8 REAR BUMPER RH SIDE RETAINER	39.80	1 PC	D/S 39.80	✓
9 TAIL LAMP	189.00	2 PCS	378.00	4
10 TAIL LAMP INNER RUBBER	14.00	2 PCS	28.00	4
11 REAR BOOT LOGO	38.70	1 PC	M 38.70	✓
12 REAR BOOT EMBLEM 'VIOS'	45.80	1 PCS	M 45.80	✓
13 REAR BOOT EMBLEM '1.5'	36.70	1 PC	M 36.70	✓
14 REAR BOOT EMBLEM 'E'	40.70	1 PC	M 40.70	✓
15 REAR BOOT EMBLEM 'WTI'	36.70	1 PCS	M 36.70	✓
16 REAR BOOT INNER LOCK	29.60	1 PC	M 29.60	✓
17 REAR BOOT INNER RUBBER	48.20	1 PC	48.20	5000
18 REAR CENTRE PANEL	720.00	1 PC	B 720.00	✓
19 REAR CENTRE PANEL INNER TOP GARNISH	59.70	1 PC	M 59.70	✓
			2,901.20	
		Less 25%	725.30	2,175.90
Special Net				
20 FRONT NUMBER PLATE	35.00	1 PC	B 35.00	✓
21 FRONT GRILLE 'SPORT'	250.00	1 PCS	250.00	?
22 REVERSE SENSOR	200.00	1 PC	Shan 200.00	✓
			485.00	485.00
Labour				
23 REMOVE AND REFIX FRONT BUMPER ASSY, REINFORCEMENT, GRILLE, HEAD LAMP. TO KNOCK AND REPAIR, STRIAGHTEN FRONT SUPPORT PANEL, FRONT RH FENDER, BRACE PANEL AND REALIGN THE SAME	600.00	1 LA	600.00	8500
24 TO REMOVE AND REFIX AIR-CON, CHECK VACUUM AND REFILL GAS	100.00	1 LA	M 100.00	X
25 PUTTY AND RESPRAY ON FRONT RH FENDER, BRACE PANEL, SUPPORT PANEL, FRONT BUMPER AND REINFORCEMENT	600.00	1 LA	600.00	5000

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : INDIA INT'L INSURANCE PTE LTD

64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711

TEL: 63476100

FAX: 62247743

ATTN: Motor Claim Department

WS Ref: TP/INDIA/YS

Claim Type: Third Party

Accident Date: 02/02/2018

TP Veh Reg No: SHC8955G

Estimate No: ES1890129/YISHUN

Date: 06 Feb 2018

Policy No: 5096998181

Veh Reg No: SGH5973J

Make/Model: TOYOTA VIOS 1.5E A

Chassis No: MR053HY4204191726

Engine No: 1NZX441347

Reg. Date: 16/06/2006

Estimate Repair Cost to Vehicle No :SGH5973J

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
26 REMOVE AND REFIX REAR BUMPER ASSY, TAIL LAMPS. TO CUTTING, WELDING AND RENEW REAR PANEL. TO STRIAGHTEN, KNOCK AND REPAIR REAR SPARE TYRE PANEL, BOOT, REAR BOTH FENDERS, REAR BOTH CHASSISS AND REALIGN THE SAME	1,100.00	1 LA	1,100.00	900
27 PUTTY AND RESPRAY ON REAR SPARE TYRE PANEL, REAR BOTH FENDER, REAR BUMPER, BOOT, REAR SPARE TYRE COMPARTMENT	900.00	1 LA	900.00	800
28 RUSTPROOFING	90.00	1 LA	90.00	60
			3,390.00	3,390.00
			Total	S\$ 6,050.90
			Add GST @ 7%	423.56
			Total Amount Payable	S\$ 6,474.46

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: