

STUTTGART AUTO
NO:12 SUNGEI KADUT AVE (S) 729648 (FAX NO. 63602899)
ESTIMATED COST OF REPAIRS

INDIA INTERNATIONAL INSURANCE
64 CECIL STREET
#04-#05 IOB BUILDING
SINGAPORE 049711

NAME : Mr Lee Kah Ban
ADDRESS : Blk 52 Chai Chee Street
#10-334
Singapore 460052

WIP : 31516
DATE: 06.02.2018

ATTN: MOTOR CLAIMS
FAX :

TEL :

VEH NO :	SJT8818G	DATE IN :		CONTACT PERSON :	RICK	63602445
CHASSIS NO :	WP1ZZZ95ZHLB00843	MILEAGE :		TYPE OF CLAIM :	TP AGAINST SHA1744E	
MODEL :	Porsche Macan PDK	DATE REG.:	20-05-16	POLICY NO.:		

NATURE OF WORKS

S/NO	Parts Description	QTY	PART NO	(NETT) PRICES
1	LINING <i>Sumper</i> ✓ Deform.	1	P95B-807-221-A -G2X	\$ 868.10
2	GRILLE <i>Upper Center</i> ✓ Deform	1	P95B-807-683-H -1E0	\$ 302.00
3	FRONT SPOILER ✓ Deform.	1	P95B-807-061- -1E0	\$ 197.90
4	LICENSE PLATE BRACKET ✓ Deform	1	P95B-807-287- -1E0	\$ 79.20
5	P5Q0-919-275- -G2X/SENSOR ?	2	P5Q0-919-275-B -G2X	\$ 451.40
6	P5Q0-919-133- -GASKET ?	2	P5Q0-919-133- -9B9-	\$ 4.60
7	AIR DUCT ?	1	P95B-121-710- -1E0	\$ 141.20
8	AIR DUCT ✓ Deform.	1	P95B-121-707-G -	\$ 164.60
9	P95B-823-031-CY-GRV/LID ✓ DT	1	P95B-823-031-JY-GRV	\$ 2,896.40
10	GASKET ✓ NEC	2	P95B-823-739- -	\$ 14.40
11	CAVITY PRESERVATION X	1	P000-043-305-51-	\$ 79.60
12	NUT ✓ NEC	2	PWHT-004-974- -	\$ 3.00
13	P95B-805-806-F -1E0/LINING <i>Top Garish</i> ✓ Deform	1	P95B-805-806-K -1E0	\$ 67.50
14	P95B-807-417-G -G2X/BUMPER ✓ CRK <i>Bumper Rear</i>	1	P95B-807-417-K -G2X	\$ 856.60
15	SPOILER ✓ Deform	1	P95B-807-521-M -1E0	\$ 277.90
16	COVER ✓ Deform	1	P95B-807-834- -1E0	\$ 185.30
17	SCREW ✓ NEC	2	PN -907-750-01-	\$ 2.60
18	EXPANDER NUT ✓ NEC	2	PN -908-214-01-	\$ 3.40
19	EXPANSION RIVET ✓ NEC	6	PN -038-549-4 -	\$ 3.00
20	RETAINING CLIP ✓ NEC	1	P95B-807-286- -	\$ 5.70
21	SUPPORT ✓ NEC	1	P95B-807-997- -1E0	\$ 12.70
22	CAP X	1	P95B-807-500- -G2X	\$ 39.30
23	P5Q0-919-275- -G2X/SENSOR ?	2	P5Q0-919-275-B -G2X	\$ 451.40
24	P5Q0-919-133- -GASKET ?	2	P5Q0-919-133- -9B9-	\$ 4.60
25	DAMPING PART LH ✓ NEC	1	P95B-805-885- -	\$ 32.80
26	DAMPING PART RH ✓ NEC	1	P95B-805-886- -	\$ 32.80
27	P95B-807-863- -/ATTACHMENT STRIP ?	1	P95B-807-863-B -	\$ 107.40
28	BRACKET ? <i>Reinforcement</i>	1	P8R0-807-313-D -	\$ 309.30
29	BRACKET ? <i>Battery Compartment</i>	1	P95B-804-869- Y-GRV	\$ 467.00
30	SUPPORT ✓ NEC <i>Battery Compartment bracket</i>	1	P95B-805-609- -GRV	\$ 126.70
31	SUPPORT ✓ NEC	1	P95B-805-610- -GRV	\$ 126.70
32	P95B-813-303- Y-GRV/TERMINAL PIECE ?	1	P95B-813-303-AY-GRV	\$ 317.00
33	SEAL ✓ NEC	2	P95B-864-561- -	\$ 41.40
34	LOCK CARRIER ✓ DT	1	P95B-813-311- Y-GRV	\$ 466.00
35	SUPPORT ✓ NEC	1	P8R0-803-384-B -GRV	\$ 22.10
36	SEAL ✓ NEC	2	P95B-864-539- -	\$ 32.40
37	SUPPORT ✓ NEC	1	P8R0-803-383-B -GRV	\$ 22.10
38	HEAT PROTECTION ✓ Deform	1	P8R0-804-171-B -	\$ 80.90
39	HEAT PROTECTION ✓ Deform	1	P8R0-804-172-D -	\$ 80.80
40	LINING <i>Battery Compartment Under lining</i> ✓ Deform	1	P95B-825-216- -	\$ 81.60

41	PAD(not sure) ✓ Deform.	1	P95B-863-462- -	\$ 204.30
42	P95B-863-565-D -/LID Battery Compartment Frame ✓ CRK	1	P95B-863-565-F -	\$ 63.90
43	CLIP ✓ NEC	6	P8R0-839-723- -	\$ 15.00
44	INSULATION ✓ NEC	3	P8E5-863-811- -	\$ 60.00
45	WIRING HARNESS ?	1	P95B-971-104-P -	\$ 396.30
46	P95B-945-725-E -/REFLECTOR REAR (LEFT) ✓ CRK	1	P95B-945-725-L -	\$ 296.40
47	P95B-945-726-E -/REFLECTOR REAR (RH) ?	1	P95B-945-726-L -	\$ 296.40
48	LICENSE PLATE LIGHT ✓ CRK	2	P95B-631-620-00-	\$ 80.00
49	P95B-253-411- Y-/CENTER MUFFLER ?	1	P95B-253-411-AY-	\$ 1,473.00
50	REAR MUFFLER ?	1	P95B-253-612-DY-	\$ 1,635.70
51	REAR MUFFLER ?	1	P95B-253-611-DY-	\$ 1,635.70
52	TAIL PIPE ✓ BT	1	P95B-253-681- -	\$ 295.40
53	TAIL PIPE ✓ BT	1	P95B-253-682- -	\$ 295.40
54	CLAMPING SLEEVE EXHAUST SY ✓ NEC	2	P95B-111-220-20-	\$ 169.80
55	LENS-HEAD SCREW ✓ NEC	4	P999-073-594-01-	\$ 18.40
56	HEXAGON-HEAD BOLT ✓ NEC	4	PN -106-620-01-	\$ 4.40
57	(WB15) CLAMPING SLEEVE EXHAUST SYSTEM ✓ NEC	1	P95B-111-220-10-	\$ 80.00
58	INDICATION STICKER Bonnet Sticker ✓ NEC	1	P95B-010-820-F -	\$ 9.20
59	P7PP-010-714-R -/(WB35) WARNING SIGN ✓ NEC	1	P7PP-010-006-A -	\$ 6.10
60	(WE72) START/STOP WARNING SIGNSTICKER ✓ NEC	1	P7PP-010-786-T -	\$ 6.50
61	WARNING SIGN ✓ NEC	1	P95B-010-004-A -	\$ 7.70
62	SUPPORT } Reinforcement Bracket ?	1	P8R0-807-331-B -	\$ 115.80
63	SUPPORT ?	1	P8R0-807-332-E -	\$ 104.10
64	COMBINATION SCREW ✓ NEC	4	PN -907-075-02-	\$ 25.20
65	COMBINATION SCREW BM10X105X45 ✓ NEC	4	PN -907-721-02-	\$ 33.60
66	NUT ✓ NEC	4	PN -905-038-01-	\$ 6.40
67	SEALANT FOAM ✓ NEC	1	P999-915-337-40-	\$ 172.90
68	LINING BLACK (BOOT TOP GARNISH) ✓ Deform.	1	P95B-864-483-J -1E0	\$ 334.10
			SUB TOTAL	\$ 17,301.10
			LESS 10%	\$ 1,730.11
			Total Parts	\$ 15,570.99
	Labour Description			
1	TO REMOVE / REPLACE FRONT / REAR DAMAGED BUMPER, REAR END PANEL, BATTERY COMPARTMENT, BONETT & OTHER AFFECTED BODY PARTS & INCLUDING PANEL BEAT / STRAIGHTEN BODY PANELS & FITTINGS WHICHEVER NECESSARY INCLUDING ALIGNMENT OF BODY STRUCTURE.	1560/day		\$ 15,800.00 14840
2	TO SPRAY PAINT FRONT / REAR BUMPER, BONNET, REAR END PANEL, BATTERY COMPARTMENT, FRT / REAR LOWER SPOILER.	7000		\$ 7,200.00 5900
3	TO CARRY OUT BODY ANTI - RUST TO ALL AFFECTED AREAS.			\$ 500.00 300
4	TO APPLY THEROSTAT SEALANT TO AFFECTED AREAS			\$ 500.00 300
5	TO CHECK ELECTRICAL WIRING SYSTEM FOR PROPER FUNCTION ABILITY INCLUDING PARKING ASSIST	NETT		\$ 300.00 250

	SENSORS.			
6	TO REMOVE / REPLACE EXHAUST SYSTEM INCLUDE CHECK FOR LEAKAGE			\$ 2,340.00 1560
7	TO REMOVE / REFIT REAR COMPARTMENT TRIM BOARD, TO FACILITATE THE REPAIR.			\$ 2,340.00 780
9	TO RE-PROGRAMMED SYSTEM & ERASE FAULT CODES AFTER ACCIDENT REPAIR.	NETT		\$ 600.00 ✓
10	TO SUPPLY 1 SET OF NUMBER PLATE.	NETT		\$ 140.00 ✓
11	TO SUPPLY 1 CHASSIS STICKER	NETT		\$ 150.00 ✓
12	TOWING CHARGES		?	\$ 300.00
13	SUNDRIES.			\$ 100.00 50
		TOTAL LABOUR		\$ 30,070.00
		TOTAL PARTS		\$ 15,570.99
		GRAND TOTAL		\$ 45,640.99

Please note that this is **only an estimate**, base on our visual inspection. However should there be any additional work be found necessary in the course of repair and thus additional parts, materials and labor cost will be deem necessary, you will be inform accordingly prior to any action taken. In view of this, expected delays will be indivertible and therefore additional working days will be required. As such the loss of use and other incidentals will be adjusted accordingly.

Prepared By

Acknowledge By

16 days

Sebastian.
7/2/18.

- Part by part repair.

- Question Mark Item
Photo

- Photo Before Paint

90036121

sebastian.yeang@lkkauto.com.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: