



SC AUTO INDUSTRIES (S) PTE LTD

51 Senoko Road, Singapore 758133
T 65 6758 2222 F 65 6257 6931
E sales@scauto.com.sg
scauto.com.sg

Co. Reg. No. 199800107D

M/S TOUR ROYALE SERVICES PTE LTD
42 Craig Road
SINGAPORE 089680
Insured TOUR ROYALE SERVICES PTE LTD
Policy VBX/P1090834/00008

ESTIMATE Bill

GST Reg. No: 19-9800107D
Date: 24/1/2018
Our Case Ref. SC18/01/011/4TR-TP
Accident Date 2/1/2018

Damaged Vehicle No: PZ1688H

S/no	Description	QTY	Price	Disc	Amount
Replaced Parts					
1	DOOR RUBBER	1 PC	\$160.00	- cut	\$160.00
2	ALUMINIUM PROFILE	1 PC	\$240.00	- cut	\$240.00
Labour Charges					
1	SPRAY PAINTING	1	\$1,600.00	- 1000	\$1,600.00
2	LABOUR FOR LHS FRONT PORTION	1	\$1,960.00	- 640	\$1,960.00
Sub Total					
					\$ 3,960.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Authorised Signature