

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

AlG

Name : Yogees Rao A/L Ramachandran

Accident Date : 29-Jan-18

Vehicle No : JQN 6602

Vehicle Model : Yamaha LC135

Estimated Repair Costs

Qty	Description	Amount S(\$)
	<u>List Items</u>	
1	Front fender <i>one</i>	\$ 75.00
1	Front cowling inner bracket <i>bel</i>	\$ 55.00
2	Front fork tubes assy <i>bel / tw /</i>	\$ 640.00
1	Front wheel rim <i>10 / bent</i>	\$ 280.00
1	Fork under bracket <i>bel</i>	\$ 185.00
1	Front rim shaft <i>nu</i>	\$ 45.00
1	Front rim bearing <i>nu</i>	\$ 38.00
1	Front brake disc <i>11</i>	\$ 155.00
1	Handle bar <i>bel</i>	\$ 75.00
1	Handle bar end <i>cut</i>	\$ 28.00
1	Hand grip (1 set) <i>71cm</i>	\$ 45.00
1	Handle bar inner bracket <i>bel</i>	\$ 68.00
2	Side mirrors <i>520 / cut</i>	\$ 110.00
1	Brake lever <i>5cm</i>	\$ 32.00
2	Front signals <i>11</i>	\$ 130.00
1	Front signal lower garnish <i>cm</i>	\$ 85.00
1	Headlamp <i>11</i>	\$ 185.00
1	Fairing assy (1 set) <i>cut / cm</i>	\$ 425.00
1	Radiator <i>put</i>	\$ 458.00
1	Front footrest bracket <i>bel</i>	\$ 65.00
1	Front footrest rubber -L/H <i>70cm</i>	\$ 35.00
1	Gear pedal <i>cut</i>	\$ 42.00
1	Rear footrest -L/H <i>11</i>	\$ 40.00
1	Rear footrest bracket <i>11</i>	\$ 78.00
1	Side stand <i>u</i>	\$ 75.00
1	Main stand <i>u</i>	\$ 95.00
1	Rear fender <i>cut</i>	\$ 120.00
1	Basket <i>cre</i>	\$ 50.00
		\$ 3,714.00
		Less 10%
		\$ 371.40
		\$ 3,342.60

not Belm

2/s #
Take photo after up a
sdy. 1/2/18

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

Name : Yogees Rao A/L Ramachandran

Accident Date : 29-Jan-18

Vehicle No : JQN 6602

Vehicle Model : Yamaha LC135

Estimated Repair Costs

<u>Special Nett Items</u>			
1	Number plate (1 set)	net	\$ 28.00 20
2	Fork oils	net	\$ 30.00 /
2	Fork oil seals	net	\$ 56.00 /
1	Steering cone (1 set)	net	\$ 90.00 /
1	Rear box	net	\$ 180.00 /
1	Rear box bracket	net	\$ 100.00 /
1	Front tyre	net	\$ 120.00 502
1	Coolant	net	\$ 18.00 2
1	Sticker (1 set)	net	\$ 90.00 /
			\$ 712.00

<u>S/No.</u>	<u>Labour</u>	
1	To provide towing service.	\$ 35 50.00
2	To check wiring and reset headlamp focusing.	\$ 11 X 80.00
3	To provide labour.	\$ 300 380.00
4	To check , repair and straighten body frame.	\$ 280 350.00
		\$ 860.00

Grand Total \$ 4,914.60

Dollars: Four Thousand Nine Hundred Fourteen And Sixty Cents Only.



EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

S 16/1/18