



簡福星噴漆工廠

KAN FOOK SING MOTOR WORKSHOP

61 Defu Lane 12, Singapore 538147

Tel : (65) 6747 8040, 8855 2126, 6858 4361

Fax : (65) 6748 1006, 8281 8428

E-mail: kanfs@pecific.net.sg • Website: www.carparts.com.sg

Business Reg No: 29146800E
GST Reg No: M9-000333E

(SUPPLEMENTARY)

INSURER: MSIG Insurance (Singapore) Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	A80445646QMX	Date of Loss:	02/02/2018
Vehicle Reg. No.:	SKA3535T	Driveable?	
Driver Age/Info:	26 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	NO
Insured/Claimant:	ONG SAN POH	Contact No:	+6591072323
Driver:	ONG HENG LOONG,NICHOLAS		

Make/Model:	BMW 318I, 2.0 (A)	Vehicle Reg. Date:	29/10/2010
Vehicle Colour:	WHITE		
Engine No:	N46B20B10A1761A091	Chassis No:	WBAPF72060A794027
Odometer:	0 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	21

Description of Accident/Loss	REFER WITH POLICE REPORT TENANG/000114/18
Present Location:	KAN FOOK SING MOTOR WORKSHOP (DEFU)

COST OF CLAIMS	Amount
Parts	18,012.00
Miscellaneous Items	2,170.00
Labour	2,120.00
Paintwork Labour	1,200.00
Towing	0.00
Gross Total (S\$)	23,502.00
+ GST 7.00% (S\$)	1,645.14
Nett Amount (S\$)	25,147.14
+ Previous Estimates (S\$)	-642.00
Claim Total (S\$)	24,505.14

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 09 Feb 2018)

Parts: 143 BMW 318i 2.0 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Kan Fook Sing Motor Workshop/SKA3535T/09/02/2018 16:47

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT HEADLAMP RH ?	0.00	0.00	*550.00 F
2	1		*FRONT HEADLAMP LH ?	0.00	0.00	*550.00 F
3	1		*FRONT HEADLAMP LOWER BRACKET RH ?	0.00	0.00	*55.00 F
4	1		*FRONT HEADLAMP LOWER BRACKET LH ?	0.00	0.00	*55.00 F
5	1		*FRONT SUPPORT PANEL - CPA	0.00	0.00	*430.00 F
6	1		*FRONT BRACE PANEL ?	0.00	0.00	*18.00 F
7	1		*FRONT SUPPORT GARNISH - CPA	0.00	0.00	*120.00 F
8	1		*FRONT BUMPER - CPA ?	0.00	0.00	*650.00 F
9	1		*FRONT BUMPER REINFORCEMENT	0.00	0.00	*150.00 F
10	1		*FRONT BUMPER CENTRE GRILLE - OE	0.00	0.00	*45.00 F
11	1		*FRONT BUMPER FOGLAMP COVER RH - Mis	0.00	0.00	*40.00 F
12	1		*FRONT BUMPER FOGLAMP COVER LH - Mis	0.00	0.00	*40.00 F
13	1		*FRONT BUMPER SIDE RETAINER RH - MC	0.00	0.00	*15.00 F
14	1		*FRONT BUMPER SIDE RETAINER LH - MC	0.00	0.00	*15.00 F
15	1		*FRONT BUMPER SIDE RETAINER TOP RH - MC	0.00	0.00	*15.00 F
16	1		*FRONT BUMPER SIDE RETAINER TOP LH - MC	0.00	0.00	*15.00 F
17	1		*AIR DUCT - CPA ?	0.00	0.00	*65.00 F
18	1		*AIR CON CONDENSER - ST ?	0.00	0.00	*620.00 F
19	1		*RADIATOR ASSY ?	0.00	0.00	*650.00 F
20	1		*RADIATOR LOWER BRACKET RH ?	0.00	0.00	*16.00 F
21	1		*RADIATOR LOWER BRACKET LH ?	0.00	0.00	*16.00 F
22	1		*RADIATOR SIDE GARNISH RH ?	0.00	0.00	*58.00 F
23	1		*RADIATOR SIDE GARNISH LH - BT	0.00	0.00	*58.00 F
24	1		*RADIATOR FAN ASSY - BT	0.00	0.00	*720.00 F
25	1		*FRONT SHOCK ABSORBER RH ?	0.00	0.00	*490.00 F
26	1		*FRONT SHOCK ABSORBER LH ?	0.00	0.00	*490.00 F
27	1		*FRONT SHOCK ABSORBER BEARING RH ?	0.00	0.00	*12.00 F
28	1		*FRONT SHOCK ABSORBER BEARING LH ?	0.00	0.00	*12.00 F
29	1		*FRONT SHOCK ABSORBER MOUNTING RH ?	0.00	0.00	*140.00 F
30	1		*FRONT SHOCK ABSORBER MOUNTING LH ?	0.00	0.00	*140.00 F
31	1		*FRONT SHOCK ABSORBER STOPPER RH ?	0.00	0.00	*45.00 F
32	1		*FRONT SHOCK ABSORBER STOPPER LH ?	0.00	0.00	*45.00 F
33	1		*FRONT KNUCKLE ARM RH ?	0.00	0.00	*420.00 F
34	1		*FRONT KNUCKLE ARM LH ?	0.00	0.00	*420.00 F
35	1		*FRONT KNUCKLE BEARING RH - MC	0.00	0.00	*480.00 F
36	1		*FRONT KNUCKLE BEARING LH - MC	0.00	0.00	*480.00 F
37	1		*FRONT LOWER ARM RH ?	0.00	0.00	*240.00 F
38	1		*FRONT LOWER ARM LH - BT	0.00	0.00	*240.00 F
39	1		*FRONT TRAILING ARM RH ?	0.00	0.00	*145.00 F
40	1		*FRONT TRAILING ARM LH ?	0.00	0.00	*145.00 F
41	1		*FRONT STABILIZER BAR - BT	0.00	0.00	*290.00 F
42	1		*FRONT STABILIZER LINK RH - BT	0.00	0.00	*100.00 F
43	1		*FRONT STABILIZER LINK LH - BT	0.00	0.00	*100.00 F
44	1		*FRONT STABILIZER BUSH RH - BT	0.00	0.00	*30.00 F
45	1		*FRONT STABILIZER BUSH LH - BT	0.00	0.00	*30.00 F

46	1	*FRONT STABILIZER BRACKET RH	BT	0.00	0.00	*12.00F	/
47	1	*FRONT STABILIZER BRACKET LH	BT	0.00	0.00	*12.00F	/
48	1	*ENGINE CROSS MEMBER	BT	0.00	0.00	*930.00F	/
49	1	*STEERING TIE ROD RH	BT	0.00	0.00	*285.00F	/
50	1	*STEERING TIE ROD LH	BT	0.00	0.00	*285.00F	/
51	1	*STEERING TIE ROD END RH	BT	0.00	0.00	*190.00F	/
52	1	*STEERING TIE ROD END LH	BT	0.00	0.00	*190.00F	/
53	1	*REAR CROSS MEMBER	BT	0.00	0.00	*1,150.00F	/
54	1	*REAR CROSS MEMBER BRACKET RH	BT	0.00	0.00	*70.00F	/
55	1	*REAR CROSS MEMBER BRACKET LH	BT	0.00	0.00	*70.00F	/
56	1	*REAR CROSS MEMBER SIDE BRACKET RH	BT	0.00	0.00	*25.00F	/
57	1	*REAR CROSS MEMBER SIDE BRACKET LH	BT	0.00	0.00	*25.00F	/
58	1	*REAR SHOCK ABSORBER LH	BT	0.00	0.00	*300.00F	/
59	1	*REAR SHOCK ABSORBER STOPPER LH	BT	0.00	0.00	*20.00F	/
60	1	*CENTER EXHAUST PIPE	Cost	0.00	0.00	*950.00F	/
61	1	*REAR EXHAUST MUFFLER	BT	0.00	0.00	*600.00F	/
62	1	*REAR EXHAUST BUSH RH	BT	0.00	0.00	*25.00F	/
63	1	*REAR EXHAUST BUSH LH	BT	0.00	0.00	*25.00F	/
64	1	*FRONT FENDER SHIELD RH	TN	0.00	0.00	*85.00F	/
65	1	*FRONT FENDER SHIELD LH	TN	0.00	0.00	*85.00F	/
66	1	*FRONT FENDER SHIELD COVER RH	BT	0.00	0.00	*15.00F	/
67	1	*FRONT FENDER SHIELD COVER LH	BT	0.00	0.00	*15.00F	/
68	20	*FRONT FENDER SHIELD CLIP	MC	0.00	0.00	*30.00F	/
69	1	*ABS SENSOR LH	BT	0.00	0.00	*130.00F	/
70	1	*REAR LOWER ARM LH	BT	0.00	0.00	*280.00F	/
71	1	*REAR TRAILING ARM LH	BT	0.00	0.00	*240.00F	/
72	1	*REAR CONTROL ARM LH	BT	0.00	0.00	*180.00F	/
73	1	*REAR BALL JOINT LH	BT	0.00	0.00	*158.00F	/
74	1	*REAR KNUCKLE ARM LH	BT	0.00	0.00	*700.00F	/
75	1	*REAR KNUCKLE BEARING LH	MC	0.00	0.00	*100.00F	/
76	1	*REAR HUP LH	BT	0.00	0.00	*130.00F	/
77	1	*REAR TOP ARM LH	BT	0.00	0.00	*130.00F	/
78	1	*OXYGEN SENSOR	TN	0.00	0.00	*520.00F	/
79	1	*ENGINE UNDERCOVER	MC	0.00	0.00	*270.00F	/
80	1	*SIDE SKIRT LH	MC	0.00	0.00	*320.00F	/

F=Franchise part.

Total Parts (\$\$)

18,012.00

Kan Fook Sing Motor Workshop/SKA3535T/09/02/2018 16:47. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Cost + 15%

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	FRONT NUMBER PLATE / <i>Ms</i>	30.00
2	4	RIMS <i>7</i>	1,200.00
3	4	TYRES <i>7</i>	940.00
Sub Total (S\$)			2,170.00

Estimates on Labour

No	Particulars	Lab. Type	Amount
<u>Paintwork Labour</u>			
1	SPRAYPAINTING CHARGES	New	<i>1000</i> 1,200.00
<u>Labour Items</u>			
2	TO CHECK WIRING SYSTEM	New	<i>—</i> 30.00
3	TO CHECK ALIGNMENT	New	<i>—</i> 80.00
4	TO REMOVE/REFIT/REFILL AIR CON GAS	New	<i>—</i> 80.00
5	TO REMOVE/REFIT FRONT UNDERCARRIAGE	New	<i>200</i> 320.00
6	TO REMOVE/REFIT REAR UNDERCARRIAGE	New	<i>200</i> 320.00
7	TO REMOVE/REFIT EXHAUST SYSTEM	New	<i>—</i> 60.00
8	TO REMOVE/REFIT OIL TANK	New	<i>—</i> 60.00
9	TO REMOVE/REFIT ENGINE & GEAR BOX	New	<i>7</i> 450.00
10	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEE PARTS	New	<i>650</i> 720.00
Gross Labour Cost (S\$)			<i>2360</i> 3,320.00

Kan Fook Sing Motor Workshop/SKA3535T/09/02/2018 16:47. Not valid without Reference section.

Generated using Merlimen e-Claims IEAS

< END OF ESTIMATES >

10 Days

LKK Auto Consultants hence notify the Repairer of the following:

• To resurvey before/after spray painting

• To display damaged part(s) during resurvey

• Parts prices are subject to confirmation

• Third party survey is on a "Without Prejudice" basis

• No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: