

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J, Tel: 6741-1730 / 731, Fax: 6744-5746, Email: liubro@ymail.com

Invoice/Ref No: GZ8453D180113

Estimate**Customer***

Name: China Taiping Insurance (Singapore) Pte Ltd

Address: Motor Claims Department

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

Date:

05-02-18

Vehicle No:

GZ8453D

Model/Make:

Mitsubishi L300

HR Manual

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Front Bumper	\$ 842.00	
	Bumper Clips 1 set	\$ 48.00	
2	Corner Panel	\$ 199.50	
3	Head Lamp Outer Garnish	\$ 178.00	
4	"L300" Emblem	\$ 25.00	
5	Door "Corporate ROC Detail" Sticker	\$ 45.00	
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 400.00	
	To putty & spray painting & including touch up paint on accident affected areas	\$ 400.00	

Total Parts & Labour of estimate for damaged vehicle

\$ 2,137.50

Total amount in Lump Sum Basis for repaired vehicle

\$ -

SDLS:



M/s Liu's Brother Auto Engrg Wks

Not Authorized
 2/5 4.810/2
 7/2/18
 Wanghl. After up.
 3 dy.

P-377.5
 102
 339.75

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: