

12/03/2001

ASS. REC. BY:

REF:

CS/CTI 18002456/Sqd302

Special Instruction:

Surveyor:

Sebastian

ASSIGNMENT (Office)

From (Person):

Maimen
Jowyn Tay

of

CTI

Date/Time:

6/2/18 @ 5.46pm

Estimated Cost:

Bill to:

OD TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

WC 6433G

Insured:

at Workshop m/s

Fook Heng Motor

Tel:

6244 3203

of

100 Bedok North Ave 4 #13-1922

Policy No.:

DMCVSN/643701701

Claim No.:

SNM18D00605C01

Sum Insured:

Excess:

\$2,000-00

Make of Veh:

(Client's Record)

D.O.A.

30/01/2018

CA / REV

REP. / REV 24 HRS

~~Rep Blk 8~~ No. 29 Sg Kadut Str 4

H.O.D. Endorsement:

Date/Time:

9.39am @ 7/2/18

Person Contacted:

Annie

Vehicle IN/OUT

Date/Time

Action/Instruction

(✓)

Estimate

WC 6433G - NA / INC 17010007 / K4

D.O.A. 5/6/17

08/02/18

adjustment seen

03/7/18 @ 4.50pm

revert to Jowyn via email.

14/7/18 @

10.09am Alfred informed C/A B Ex \$2000 via Maimen.

14/2/18 @

4.55am informed Annie C/A B Ex \$2000 by email.

03/5/18 @

2.59pm confirmed with Annie CS \$15900, 14 days by email.

REF:

CTI Excess \$2000

Survivor

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 95k

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 14 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No:

WC 6453 G

Yr Regn:

26/7/2013

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Concrete mixer

Make:

Isuzu CY1452S

cc 1568

Colour

Multi Colour

A/C: Insured / Std / NI / NA

Sp. Reading

177602

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JALCYH52SD7000251

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 295/80R225

R: 1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Austone

Front

Rear

R/Bal.

6

mm

R/Bal.

6/6

mm

L/Bal.

6

mm

L/Bal.

6/6

mm

D.O.A.

30/1/2018

D.O.I.

7/2/18

Survey held at

Blk 8, 29 Sg Kabat St 4

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time / Action / Instruction

CPD 8 4713.25, 73%

RECEIVED

Date/Time, File Pass to?

☐

: Prel. Report

1) CPD 8 4713.25☐

: Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 14

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee:

☐

: Site Insp (\$

) S + RS. SI

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

) TOTAL

Report Format:

MER-TP

Lump Sum / LB.I: (\$

15900

TOTAL

220



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobiles

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18002456/Sqd3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 07-02-2018



Code : CTI

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	WC 6433G
Policy No.	DMCVSN1643701701	Coverage (\$)	0.00
Claim No.	SNM18D00605C01	Excess (\$)	2,000.00
Assign From	MERIMEN (JOWYN TAY)	Assign Date	07/02/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	30/01/2018	Inspection Date	07/02/2018
Survey held at	FOOK HENG MOTOR SERVICE 29 SUNGAI KADUT STREET 4 SINGAPORE 729054		

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Feb 2018		06 Feb 2018 17:46 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:		ST MANUFACTURING & TRADING, Co. Reg. No.: 53186557J		[Created by insurer]	
Vehicle Reg. No.:		WC6433G		Date of Loss:	
				30/01/2018 17:00 - :59	
Claim Type:		OD / SNM18D00605C01		Policy/Cover Note No.:	
				DMCVSN1643701701 (Comprehensive) Coverage: 26/07/2017 - 25/07/2018	
				Excess:	
				S\$2,000.00	
Repairer:		Fook Heng Motor Service (HQ) 100 BEDOK NORTH AVENUE 4 PEARL GARDENS, #13-1922, 460100 Sungei Kadut - Tel: 62443203			
Handling Insurer:		China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]			
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 15/02/2018]			
Driver/Custodian:		KALYANI KURUNTHAPPAN (40 / Male), NRIC: F8062369X, Tel: +6593532901			
Adj Asg. Remarks:		PLEASE PROCEED TO SURVEY & REVERT. EXCESS OF \$2,000.00 APPLIES.			

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#) [Compose Case Mail](#)

ALL ASSOCIATED TASKS

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Denise Tay (LKKAUTO)

From: Yeong Siew Lien <slmoter@yahoo.com.sg>
Sent: Thursday, 3 May 2018 2:59 PM
To: Denise Tay (LKKAUTO)
Subject: WC6433G/OD/CHINA - SETTLEMENT CLAIM

Dear LKK Auto Surveyor Team,

Thank you for your fax reply. We agreed the lump sum repair costs of \$15,900/- before excess \$2,000/- & 14 repair days as per your offer.

Thanks & best regards
Annie Yeong
Fook Heng Motor Service

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Wednesday, 14 February 2018 11:56 AM
To: slmoter@yahoo.com.sg
Cc: SUR
Subject: WC 6433G / OD / CHINA

Dear Annie,

As instructed by our client, please proceed to repair the insured vehicle **WC 6433G (Excess \$2000/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***WC6433G (SNM18D00605C01)**

OD

Jan 30 2018 5:00PM

[ST MANUFACTURING & TRADING]

Fook Heng Motor Service

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on 14/02/2018 10:09 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (\$19983.25) - WC6433G - Claim Handler: Jowyn Tay

Approved:19983.25:Please proceed to authorize repairs UP TO \$19,983.25 BEFORE Excess of \$2,000.00. RE-INSPECTION OF VEHICLE REQUIRED.

DOCUMENTS SUMMARY

There are no documents.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jowyn Tay

Date: 08 Feb 2018

Preliminary Advice

Vehicle No	: WC6433G	Accident Date	: 30/01/2018
Make	: ISUZU CYH52S	Policy No.	: DMCVSN1643701701
Assignment Date	: 06/02/2018	Excess	: S\$2,000.00
Date of Inspection	: 07/02/2018	Est. Duration of Repair	: 14.00
Inspection At	: FOOK HENG MOTOR SERVICE (HQ) 100 BEDOK NORTH AVENUE 4 PEARL GARDENS, #13-1922 SINGAPORE 460100		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	20,613.25
Revised Amount	:S\$	17,621.00
Check Items (Estimated)	:S\$	2,362.25
Total	:S\$	19,983.25

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	95,000.00
COE / PARF Rebate	:S\$	33,326.00
Salvage Value	:S\$	
Margin for Repair	:S\$	61,674.00

Braking System	:	In Order
Steering System	:	In Order
Tyre Condition (Front)	:	6/6mm
Tyre Condition (Rear)	:	6/6/6/6mm

Remarks


- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	6557J
Vehicle Details	
Vehicle No.:	WC6433G
Vehicle to be Exported:	No
Intended De-registration Date:	08 Feb 2018
Vehicle Make:	ISUZU
Vehicle Model:	CYH52S
Primary Colour:	Blue
Manufacturing Year:	2013
Engine No.:	6WG1418960
Chassis No.:	JALCYH52SD7000251
Maximum Power Output:	-
Open Market Value:	\$117,084.00
Original Registration Date:	26 Jul 2013
First Registration Date:	26 Jul 2013
Transfer Count:	1
Actual ARF Paid:	\$5,855.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	25 Jul 2023
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$61,011.00
COE Rebate Amount:	\$33,326.00
Total Rebate Amount:	\$33,326.00

The information contained herein is correct as at 08 Feb 2018

OK



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Dec11 Volkswagen Touareg Hybrid 3.0A.Well Kept



Brilliant Touareg's Hybrid
Powertrain, Refined
Technology, TipTop Cond. Call
ToView
Shine Connect StarAd



Browse by Category ▼

Sort by Date Posted ▼ 20 results/page ▼

2 vehicles

Isuzu CYH52S

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Isuzu CYH52S		Any	Any	Any	Any	Any	Any	Available
	Isuzu CYH52S (COE till 09/2027)		\$73,800	\$7,680 /yr	18-Sep-2007	15,681 cc	-	Truck	Available
	Fuel Type: Diesel Lowest Depreciation In The Market. Exporters Are Welcome To Discuss. Call Us To Find Out More Now! Come With Nice No WC1234Y. ABWIN (1994) Pte Ltd Posted: 05-Feb-2018 Tags: 2007 Isuzu CYH52S, Isuzu CYH52S, Isuzu, CYH52S, Used Isuzu								
	Isuzu CYH52S		\$89,000	\$62,110 /yr	17-Jul-2009	15,681 cc	-	Truck	Available
	Fuel Type: Diesel New Paint, Low Deposit. In House Loan Available. Posted: 15-Jan-2018 Tags: 2009 Isuzu CYH52S, Isuzu CYH52S, Isuzu, CYH52S, Used Isuzu								

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used Isuzu CYH52S, Isuzu CYH52S Singapore, used Isuzu CYH52S Singapore, used Isuzu CYH52S, used vehicles Singapore or even buy used Isuzu CYH52S Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

- Home
- New Car
- Used Car
- Sell Car
- Motoring Directory
- Products Guide
- Article
- Forum
- Tool & Tip

- About Us
- Careers
- Contact Us
- Sitemap

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	31/01/2018 11:11
Date Of Accident	30/01/2018 17:30
Exact Location Of Accident	SELETAR NORTH LINK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	WC6433G
Insured/Policyholder	
Name Of Registered Owner	ST MANUFACTURING & TRADING
Co Reg No	53186557J
Email Address	GLORYWOODSINGAPORE@YAHOO.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-63681618

Vehicle Particulars

Manufacturer	ISUZU
Model	CYH52S
Exact Purpose for which vehicle was being used at time of accident	WORK

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	COMMERCIAL VEHICLE
------------------	--------------------


Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCVSN1643701701
Cover Note Number	

Driver

Name of Driver	KALYANI KURUNTHAPPAN
Passport No/FIN	F8062369X
Date Of Birth	10/07/1977
Occupation	OUTDOOR
Date Of Driving Pass	17/05/2016
Driving Experience	1 YEAR AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93532901
Fax Number	
Contact Number	
Email Address	NOEMAIL

B-WC 4393E



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT:

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature _____
Date & Time: _____

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No.: _____

31/1/2018



中国太平
CHINA TAIPING

中国太平保险(新加坡)有限公司
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Co. Reg. No. 200208384E

MZ300/C
R SN
AN0420A
Cov. type: C

MOTOR COMMERCIAL VEHICLE

CERTIFICATE OF INSURANCE

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960
Road Transport Act, 1987 (Malaysia)
Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

ORIGINAL

CERTIFICATE No. DMCVSN1643701701 Engine No : 6WG1418960
Chano: JALCYH52SD7000251

1. Index Mark and Registration Number of Vehicle WC6433G AUTOSAFE

2. Name of Policy Holder M/S ST MANUFACTURING & TRADING

3. Effective date of the Commencement of Insurance for the purposes of the Regulations, Ordinance or Enactment 26 July 2017 Excess Sect. I S\$2,000.00
Excess Sect. II S\$1,000.00
EX ON WINDSCREEN S\$100.00

4. Date of Expiry of Insurance 25 July 2018

5. Persons or Classes of Persons entitled to drive:

Any person who is driving on the Policyholder's order or with their permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor vehicle.

6. Limitations as to use:

- (1) Use in connection with the Policyholder's business.
 - (2) Use for the carriage of passengers (other than for hire or reward) in connection with the Policyholder's business.
 - (3) Use for social, domestic or pleasure purposes.
- The Policy does not cover.
- (1) Use for hire or reward or racing, pace-making, reliability trial or speed testing.
 - (2) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle.

HIRE PURCHASE CO. : SWEE SENG CREDIT PTE LTD AS HP OWNER

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act 1987 (Malaysia), are not to be included under these headings.

I/We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Please see reverse



For CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Issued By: INXPRESS INSURANCE AGENCY PTE LTD
Authorised Officer

Authorised Signatory

FOOK HENG MOTOR SERVICE

Mailing Address: BLK 100 BEDOK NORTH AVENUE 4 #13-1922 SINGAPORE 460100

Workshop Add: NO 29 SUNGEI KADUT STREET 4 SUNGEI KADUT IND. EST. (S) 729054 (BLK 8)

Tel: 62443203 Fax: 64415451

E-mail: simoter@yahoo.com.sg

Business Reg. No: 52938821M

Date: 06th February, 2018

To: CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
THE MOTOR CLAIMS DEPARTMENT

VEHICLE INSPECTION REPORT FOR ISUZU CYH52S W03433G

NUMBER	LIST ITEMS	QUANTITY	NUMBER	UNIT PRICE
1)	front windscreen glass ✓ CRK	1 pc	1)	\$ 1,526.00
2)	front windscreen weatherstrip ✓ NEK	1 pc	2)	\$ 282.00
3)	wiper panel ✓ BT	1 pc	3)	\$ 285.00
4)	LH big panel handle ✓ BT	1 pc	4)	\$ 55.00
5)	front big panel ✓ CRK	1 pc	5)	\$ 1,360.00
6)	LH front big panel corang/grille ✓ CRK	1 pc	6)	\$ 85.00
7)	corner panel ✓ CRK	1 pc	7)	\$ 480.00
8)	front bumper ✓ BT	1 pc	8)	\$ 1,090.00
9)	front bumper top rubber complete ✓ Deform	1 pc	9)	\$ 138.00
10)	LH headlamp bracket ✓ BT	1 pc	10)	\$ 420.00
11)	LH headlamp ✓ CRK	1 pc	11)	\$ 428.00
12)	LH headlamp cowling ✓ Deform	1 pc	12)	\$ 105.00
13)	LH foglamp white ✓ MS	1 pc	13)	\$ 195.00
14)	LH signal lamp ✓ CRK	1 pc	14)	\$ 60.00
15)	LH mirror stay ✓ BT	1 pc	15)	\$ 198.00
16)	LH mirror stay lower aluminium bracket ✓ CRK	1 pc	16)	\$ 105.00
17)	LH mirror stay lower rubber ✓ Deform	1 pc	17)	\$ 65.00
18)	LH front round view mirror ✓ MS	1 pc	18)	\$ 50.00
19)	LH door complete ✓ Deform	1 pc	19)	\$ 4,200.00
20)	LH door hinge ✓ BT	2 pcs	20)	\$ 196.00
21)	stand panel ✓ CRK Deform	1 pc	21)	\$ 245.00
22)	LH aluminium lower step ✓ CRK	1 pc	22)	\$ 80.00
23)	LH step lower rubber ✓ CRK	1 pc	23)	\$ 135.00
24)	LH rear quarter panel ✓ BT	1 pc	24)	\$ 898.00
25)	LH door pillar ✓ BT	1 pc	25)	\$ 355.00
26)	dashboard top cover ✓ CRK	1 pc	26)	\$ 1,125.00
27)	dashboard top cover inner panel ✓ CRK	1 pc	27)	\$ 380.00
28)	space motor lower garnish ?	1 pc	28)	\$ 285.00 ✓ BT
				\$ 15,545.00
Less 15%				\$ 2,331.75
Total (Parts)				\$ 13,213.25

FOOK HENG MOTOR SERVICE

Mailing Address: BLK 100 BEDOK NORTH AVENUE 4 #13-1922 SINGAPORE 460100

Workshop Add: NO 29 SUNGEI KADUT STREET 4 SUNGEI KADUT IND. EST. (S) 729054 (BLK 8)

Tel: 62443203 Fax: 64415451

E-mail: slmoter@yahoo.com.sg

Business Reg. No: 52938821M

Cont'd sheet***2

Vehicle No. W064386

Total (Parts) b/t \$ 13,213.25

NUMBER	NETT ITEMS	QUANTITY/ NUMBER	UNIT PRICE	
29)	air-con heater ?	1 pc 29)	\$ 1,360.00	✓CPA
30)	air-con blower unit ?	1 pc 30)	\$ 760.00	✓CPA
		Total (Nett Items)	\$ 2,120.00	
	<u>LABOUR CHARGES & MISC</u>			
31)	To dismantle & replace damaged parts, panel beat where necessary.		\$ 3,000.00	2800
32)	To spray painting the entire cabin		\$ 1,400.00	1200
33)	To remove/renew front windscreen glass.		\$ 100.00	150
34)	To remove/refit aircon & refill gas to facilitate repairs.		\$ 350.00	250
35)	To remove/renew dashboard.		\$ 350.00	250
		Total (Labour)	\$ 5,200.00	
		All Total.	\$ 20,613.25	

Sebastian.
7/2/18 -
- Lump Sum Repair -
- Question Mark Item
Photo.
- Photo After Spray
Excess : \$2000
Revert

14 days

LKK Auto Consultants hence notify the Reparer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Reparer
Signature: _____
Date: _____

90036121
Sebastianyang@lkkauto.com

[Signature]
21/2/18

FOOK HENG MOTOR SERVICE

Mailing Address: BLK 100 BEDOK NORTH AVENUE 4 #13-1922 SINGAPORE 460100

Workshop Add: NO 29 SUNGEI KADUT STREET 4 SUNGEI KADUT IND. EST. (S) 729054 (BLK 8)

Tel: 62443203 Fax: 64415451

E-mail: slmoter@yahoo.com.sg

Business Reg. No: 52938821M

Date: 06th February, 2018

To: CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
THE MOTOR CLAIMS DEPARTMENT

VEHICLE INSPECTION REPORT FOR ISUZU CYH52S WC6433G

NUMBER	LIST ITEMS	QUANTITY	NUMBER	UNIT PRICE
1)	front windscreen glass ✓ CRK	1 pc	1)	\$ 1,586.00
2)	front windscreen weatherstrip ✓ NCC.	1 pc	2)	\$ 282.00
3)	wiper panel ✓ BT	1 pc	3)	\$ 285.00
4)	LH big panel handle ✓ BT	1 pc	4)	\$ 55.00
5)	front big panel ✓ CRK.	1 pc	5)	\$ 1,360.00
6)	LH front big panel sarong/grille ✓ CRK.	1 pc	6)	\$ 85.00
7)	corner panel ✓ CRK	1 pc	7)	\$ 480.00
8)	front bumper ✓ BT	1 pc	8)	\$ 1,390.00
9)	front bumper top rubber complete ✓ Deform.	1 pc	9)	\$ 198.00
10)	LH headlamp bracket ✓ BT	1 pc	10)	\$ 420.00
11)	LH headlamp ✓ CRK	1 pc	11)	\$ 428.00
12)	LH headlamp cowling ✓ Deform.	1 pc	12)	\$ 103.00
13)	LH foglamp white ✓ MS	1 pc	13)	\$ 185.00
14)	LH signal lamp ✓ CRK.	1 pc	14)	\$ 60.00
15)	LH mirror stay ✓ BT	1 pc	15)	\$ 198.00
16)	LH mirror stay lower aluminium bracket ✓ CRK	1 pc	16)	\$ 105.00
17)	LH mirror stay lower rubber ✓ Deform.	1 pc	17)	\$ 65.00
18)	LH front round view mirror ✓ MS	1 pc	18)	\$ 60.00
19)	LH door complete ✓ Deform.	1 pc	19)	\$ 4,200.00
20)	LH door hinge ✓ BT	2 pcs	20)	\$ 196.00
21)	stand panel ✓ CRK Deform	1 pc	21)	\$ 245.00
22)	LH aluminium lower step ✓ CRK.	1 pc	22)	\$ 80.00
23)	LH step lower rubber ✓ CRK.	1 pc	23)	\$ 135.00
24)	LH rear quarter panel ✓ BT	1 pc	24)	\$ 698.00
25)	LH door pillar ✓ BT	1 pc	25)	\$ 856.00
26)	dashboard top cover ✓ CRK	1 pc	26)	\$ 1,125.00
27)	dashboard top cover inner panel ✓ CRK	1 pc	27)	\$ 380.00
28)	speedometer lower garnish ? / BT	1 pc	28)	\$ 285.00
				\$ 15,545.00
Less 15%				\$ 2,331.75
Total (Parts)				\$ 13,213.25

Cont'd in Page 2***

FOOK HENG MOTOR SERVICE

Mailing Address: BLK 100 BEDOK NORTH AVENUE 4 #13-1922 SINGAPORE 460100
 Workshop Add: NO 29 SUNGEI KADUT STREET 4 SUNGEI KADUT IND. EST. (S) 729054 (BLK 8)
 Tel: 62443203 Fax: 64415451
 E-mail: slmoter@yahoo.com.sg
 Business Reg. No: 52938821M

Cont'd sheet***2

Vehicle No: WC6433G

Total (Parts) h/r \$ 13,213.25

NUMBER	NETT ITEMS	QUANTITY	NUMBER	UNIT PRICE
29)	air-con heater ? ✓ CAR	1 pc	29)	\$ 1,360.00
30)	air-con blower unit ? ✓ CAR	1 pc	30)	\$ 760.00
		Total (Nett Items)		\$ 2,120.00
	LABOUR CHARGES & MISC			
31)	To dismantle & replace damaged parts, panel beat where necessary.			\$ 3,000.00 2800
32)	To spray painting the entire cabin.			\$ 1,400.00 1200
33)	To remove/renew front windscreen glass.			\$ 180.00 150
34)	To remove/refit aircon & refill gas to facilitate repairs.			\$ 350.00 250
35)	To remove/renew dashboard.			\$ 350.00 250
		Total (Labour)		\$ 5,280.00
		All Total:		\$ 20,613.25

Dear Annie,

offer lump sum \$15,900
 before excess \$2000 &
 14 repair days.

Kindy confirm.

Thanks,
 Shiem Chan

Tel: 6256 3561
 LKK Auto

Sebastian.
 7/2/12.

- Lump Sum Repair -

- Question Mark Item
 Photo.

- Photo After Spray
 Excess : \$2000
 Revert

90036121

sebastianyeang@lkkauto.com.

14 days.

LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:
--

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Feb 2018		06 Feb 2018 17:46 Edit Adj Rpt	S\$15,900.00 Edit Estimates	S\$15,900.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	ST MANUFACTURING & TRADING, Co. Reg. No.: 53186557J	
Vehicle Reg. No.:	WC6433G	Date of Loss: 30/01/2018 17:00 - :59 [54 Months and 4 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / SNM18D00605C01	Policy/Cover Note No.: DMCVSN1643701701 (Comprehensive) Coverage: 26/07/2017 - 25/07/2018
		Excess: S\$2,000.00
Repairer:	Fook Heng Motor Service (HQ) 100 BEDOK NORTH AVENUE 4 PEARL GARDENS, #13-1922, 460100 Sungei Kadut - Tel: 62443203	
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sebastian Yeang Wai Keen] ... [Final Rpt due 15/02/2018]	
Driver/Custodian:	KALYANI KURUNTHAPPAN (40 / Male), NRIC: F8062369X, Tel: +6593532901	
Adj Asg. Remarks:	PLEASE PROCEED TO SURVEY & REVERT. EXCESS OF \$2,000.00 APPLIES.	

ASSOCIATED MAIL RECEIVED	View All Compose Case Mail
CHINA_TAIPING (14/02/2018): Alert - Adj Mandate Approved (S\$19983.25) - WC6433G - Claim Handler: Jowyn Tay	

ALL ASSOCIATED TASKS ☐		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*WC6433G (SNM18D00605C01)
 OD
 Jan 30 2018 5:00PM
 [ST MANUFACTURING & TRADING]
 Fook Heng Motor Service

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View View in Browser

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/02/18 16:49	Adjuster Immediate Advice	Load HTM	

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/02/18 16:09	General View	Load JPG	☒
2	08/02/18 16:09	General View	Load JPG	☒
3	08/02/18 16:09	General View	Load JPG	☒
4	08/02/18 16:10	General View	Load JPG	☒
5	08/02/18 16:10	General View	Load JPG	☒
6	08/02/18 16:10	General View	Load JPG	☒
7	08/02/18 16:10	General View	Load JPG	☒
8	08/02/18 16:10	General View	Load JPG	☒
9	08/02/18 16:10	General View	Load JPG	☒
10	08/02/18 16:10	General View	Load JPG	☒
11	08/02/18 16:10	General View	Load JPG	☒
12	08/02/18 16:10	General View	Load JPG	☒
13	08/02/18 16:10	General View	Load JPG	☒
14	08/02/18 16:10	General View	Load JPG	☒
15	08/02/18 16:10	General View	Load JPG	☒
16	08/02/18 16:10	General View	Load JPG	☒
17	08/02/18 16:10	General View	Load JPG	☒
18	08/02/18 16:10	General View	Load JPG	☒
19	08/02/18 16:10	General View	Load JPG	☒
20	08/02/18 16:10	General View	Load JPG	☒
21	08/02/18 16:10	General View	Load JPG	☒
22	08/02/18 16:10	General View	Load JPG	☒
23	08/02/18 16:10	General View	Load JPG	☒
24	08/02/18 16:10	General View	Load JPG	☒
25	08/02/18 16:10	General View	Load JPG	☒
26	08/02/18 16:10	General View	Load JPG	☒
27	08/02/18 16:10	General View	Load JPG	☒
28	08/02/18 16:10	General View	Load JPG	☒
29	08/02/18 16:10	General View	Load JPG	☒
30	08/02/18 16:10	General View	Load JPG	☒
31	08/02/18 16:10	General View	Load JPG	☒
32	08/02/18 16:10	General View	Load JPG	☒
33	08/02/18 16:10	General View	Load JPG	☒
34	08/02/18 16:10	General View	Load JPG	☒
35	08/02/18 16:10	General View	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	08/02/18 16:10	General View	 Load JPG	☒
37	08/02/18 16:10	Chassis Number	 Load JPG	☒
38	08/02/18 16:10	Odometer Reading	 Load JPG	☒
39	08/02/18 16:10	General View	 Load JPG	☒
40	08/02/18 16:10	General View	 Load JPG	☒
41	08/02/18 16:10	General View	 Load JPG	☒
42	08/02/18 16:10	General View	 Load JPG	☒
43	08/02/18 16:10	General View	 Load JPG	☒
44	08/02/18 16:10	General View	 Load JPG	☒
45	08/02/18 16:10	General View	 Load JPG	☒
46	08/02/18 16:10	General View	 Load JPG	☒
47	08/02/18 16:10	General View	 Load JPG	☒
48	08/02/18 16:10	General View	 Load JPG	☒
49	08/02/18 16:10	General View	 Load JPG	☒
50	08/02/18 16:10	General View	 Load JPG	☒
51	08/02/18 16:10	General View	 Load JPG	☒
52	08/02/18 16:10	General View	 Load JPG	☒
53	08/02/18 16:10	General View	 Load JPG	☒
54	08/02/18 16:10	General View	 Load JPG	☒
55	08/02/18 16:10	General View	 Load JPG	☒
56	08/02/18 16:10	General View	 Load JPG	☒
57	08/02/18 16:10	General View	 Load JPG	☒
58	08/02/18 16:10	General View	 Load JPG	☒
59	08/02/18 16:10	General View	 Load JPG	☒
60	08/02/18 16:10	General View	 Load JPG	☒
61	08/02/18 16:10	General View	 Load JPG	☒
62	08/02/18 16:10	General View	 Load JPG	☒
63	08/02/18 16:10	General View	 Load JPG	☒
64	08/02/18 16:10	General View	 Load JPG	☒
65	08/02/18 16:10	General View	 Load JPG	☒
66	08/02/18 16:10	General View	 Load JPG	☒
67	08/02/18 16:10	General View	 Load JPG	☒
68	08/02/18 16:10	General View	 Load JPG	☒
69	08/02/18 16:10	General View	 Load JPG	☒
70	08/02/18 16:10	General View	 Load JPG	☒
71	08/02/18 16:10	General View	 Load JPG	☒
72	08/02/18 16:10	General View	 Load JPG	☒
73	08/02/18 16:10	General View	 Load JPG	☒
74	08/02/18 16:10	General View	 Load JPG	☒
75	08/02/18 16:10	General View	 Load JPG	☒
76	08/02/18 16:10	General View	 Load JPG	☒
77	08/02/18 16:10	General View	 Load JPG	☒
78	08/02/18 16:10	General View	 Load JPG	☒
79	08/02/18 16:10	General View	 Load JPG	☒
80	08/02/18 16:10	General View	 Load JPG	☒
81	08/02/18 16:10	General View	 Load JPG	☒
82	08/02/18 16:10	General View	 Load JPG	☒
83	08/02/18 16:10	General View	 Load JPG	☒
84	08/02/18 16:10	General View	 Load JPG	☒
85	07/05/18 14:34	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
86	07/05/18 14:34	Reinspection Photo	 Load JPG	☒
87	07/05/18 14:34	Reinspection Photo	 Load JPG	☒
88	07/05/18 14:34	Reinspection Photo	 Load JPG	☒
89	07/05/18 14:34	Reinspection Photo	 Load JPG	☒
90	07/05/18 14:34	Reinspection Photo	 Load JPG	☒
91	07/05/18 14:34	Reinspection Photo	 Load JPG	☒
92	07/05/18 14:34	Reinspection Photo	 Load JPG	☒
93	07/05/18 14:34	Reinspection Photo	 Load JPG	☒
94	07/05/18 14:34	Reinspection Photo	 Load JPG	☒
95	07/05/18 14:34	Reinspection Photo	 Load JPG	☒
96	07/05/18 14:34	Reinspection Photo	 Load JPG	☒
97	07/05/18 14:34	Reinspection Photo	 Load JPG	☒
98	07/05/18 14:34	Reinspection Photo	 Load JPG	☒
99	07/05/18 14:34	Reinspection Photo	 Load JPG	☒
100	07/05/18 14:34	Reinspection Photo	 Load JPG	☒
101	07/05/18 14:34	Reinspection Photo	 Load JPG	☒
102	07/05/18 14:34	Reinspection Photo	 Load JPG	☒
103	07/05/18 14:34	Reinspection Photo	 Load JPG	☒
104	07/05/18 14:34	Reinspection Photo	 Load JPG	☒
105	07/05/18 14:34	Reinspection Photo	 Load JPG	☒
106	07/05/18 14:34	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	06/02/18 17:38	Quotation/Replacement/Repair Invoice - PG 1	 Load PDF	
2	06/02/18 17:38	Quotation/Replacement/Repair Invoice - PG 2	 Load PDF	
3	06/02/18 17:38	Quotation/Replacement/Repair Invoice - PG 3	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/02/18 16:08	ESTIMATE	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	SMRT Automotive Services Pte Ltd (Woodlands)	Thumbnail	Print
1	31/01/18 11:38	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	SMRT Automotive Services Pte Ltd (Woodlands)	Thumbnail	Print
1	31/01/18 11:34	Accident Photo	 Load JPG	☒
2	31/01/18 11:34	Accident Photo	 Load JPG	☒
3	31/01/18 11:34	Accident Photo	 Load JPG	☒
4	31/01/18 11:34	Accident Photo	 Load JPG	☒
5	31/01/18 11:34	Accident Photo	 Load JPG	☒
6	31/01/18 11:34	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	SMRT Automotive Services Pte Ltd (Woodlands)	Thumbnail	Print
1	31/01/18 11:33	Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI18002456/SQD3E2

Date: 11/05/2018

REFERENCE

Insured/Claimant: ST MANUFACTURING & TRADING Policy No: DMCVSN1643701701

Date of Loss: 30/01/2018

Nature of Claim: OD

Claim No: SNM18D00605C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **WC6433G**

Make & Model: ISUZU CYH52S, 15.7 D (M)

Engine No: 6WG1418960

Reg. Date: 26/07/2013 (Man. Year: 2013)

Chassis No: JALCYH52SD7000251

Colour: Multi-colour

Odometer: 177602 km

Engine Capacity: 15681 cc

Market Value/New Car Price: S\$95,000.00

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/80 R22.5

Rear Tyre Size: 295/80 R22.5 (D)

Front Left Side: Austone 6 mm

Rear Left Side: Austone 6/6 mm

Front Right Side: Austone 6 mm

Rear Right Side: Austone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,333.25	15,333.25	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,280.00	4,650.00	630.00	11.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,613.25	19,983.25	630.00	3.06
Approved Total (Overridden) (S\$)		15,900.00		
- Excess (S\$)	2,000.00	2,000.00	0.00	0.00
Nett Amount (S\$)	18,613.25	13,900.00	4,713.25	25.32

INSPECTION

Date of Assignment: 06/02/2018

Date Inspected: 07/02/2018 Inspected At:

Fook Heng Motor Service (HQ)
100 BEDOK NORTH AVENUE 4 PEARL
GARDENS, #13-1922
Singapore 460100

Estimated Period of Repair: 14.0 days

Adjuster: Sebastian Yeang Wai Keen

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 11 May 2018)
Parts: N/A ISUZU CYH52S 15.7 D (M) (Model not available in database)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for WC6433G)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN GLASS	Cracked	1,586.00 FL	*1,586.00 FL
2	1		*FRONT WINDSCREEN WEATHERSTRIP	Necessary	282.00 FL	*282.00 FL
3	1		*WIPER PANEL	Bent	285.00 FL	*285.00 FL
4	1		*LH BIG PANEL HANDLE	Bent	55.00 FL	*55.00 FL
5	1		*FRONT BIG PANEL	Cracked	1,360.00 FL	*1,360.00 FL
6	1		*LH FRONT BIG PANEL SARONG / GRILLE	Cracked	85.00 FL	*85.00 FL
7	1		*CORNER PANEL	Cracked	480.00 FL	*480.00 FL
8	1		*FRONT BUMPER	Bent	1,390.00 FL	*1,390.00 FL
9	1		*FRONT BUMPER TOP RUBBER COMPLETE	Deformed	198.00 FL	*198.00 FL
10	1		*LH HEADLAMP BRACKET	Bent	420.00 FL	*420.00 FL
11	1		*LH HEADLAMP	Cracked	428.00 FL	*428.00 FL
12	1		*LH HEADLAMP COWLING	Deformed	103.00 FL	*103.00 FL
13	1		*LH FOGLAMP WHITE	Missing	185.00 FL	*185.00 FL
14	1		*LH SIGNAL LAMP	Cracked	60.00 FL	*60.00 FL
15	1		*LH MIRROR STAY	Bent	198.00 FL	*198.00 FL
16	1		*LH MIRROR STAY LOWER ALUMINIUM BRACKET	Cracked	105.00 FL	*105.00 FL
17	1		*LH MIRROR STAY LOWER RUBBER	Deformed	65.00 FL	*65.00 FL
18	1		*LH FRONT ROUND VIEW MIRROR	Missing	60.00 FL	*60.00 FL
19	1		*LH DOOR COMPLETE	Deformed	4,200.00 FL	*4,200.00 FL
20	2		*LH DOOR HINGE	Bent	196.00 FL	*196.00 FL
21	1		*STAND PANEL	Deformed	245.00 FL	*245.00 FL
22	1		*LH ALUMINIUM LOWER STEP	Cracked	80.00 FL	*80.00 FL
23	1		*LH STEP LOWER RUBBER	Cracked	135.00 FL	*135.00 FL
24	1		*LH REAR QUARTER PANEL	Dented	698.00 FL	*698.00 FL
25	1		*LH DOOR PILLAR	Bent	856.00 FL	*856.00 FL
26	1		*DASHBOARD TOP COVER	Cracked	1,125.00 FL	*1,125.00 FL
27	1		*DASHBOARD TOP COVER INNER PANEL	Cracked	380.00 FL	*380.00 FL
28	1		*SPEEOMETER LOWER GARNISH	Bent	285.00 FL	*285.00 FL
29	1		*AIR-CON HEATER	Cracked	1,360.00 FS	*1,360.00 FS
30	1		*AIR-CON BLOWER UNIT	Cracked	760.00 FS	*760.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	17,665.00	17,665.00
- List Item Discount on L Items 15.00/15.00% (\$\$)	2,331.75	2,331.75

Total Parts (\$\$)	15,333.25	15,333.25
---------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY	New	3,000.00	2,800.00
2	TO SPRAY PAINTING THE ENTIRE CABIN	New	1,400.00	1,200.00
3	TO REMOVE/RENEW FRONT WINDSCREEN GLASS	New	180.00	150.00
4	TO REMOVE / REFIT AIRCON & REFILL GAS TO FACILITATE REPAIRS	New	350.00	250.00
5	TO REMOVE / RENEW DASHBOARD	New	350.00	250.00
Gross Labour Cost (S\$)			5,280.00	4,650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >