

ASS. REC BY

REF: CS/MSG18002459/M1+d3

Surveyor

MA

ASSIGNMENT (Office)

From (Person)

Munnen  
Muhd Ashik

of

MSG

Date/Time 6/2/18 @ 3:52pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHD 4460M

Insured:

SLR 8709A

at Workshop with

Soon Hock Motor

Tel:

64836016

of

Blk 10, AMK Ind. Prk 2A # 01-05/06

Policy No:

29013986 QMY

Claim No:

548803

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A 05/02/2018

CA / REV / REP. / REV 24 HRS <sup>lump</sup>

Date/Time

10:06am @ 7/2/17

Person Contacted

chris

H.O.D. Endorsement:

Vehicle IN OUT

Date/Time

Action/Instruction ( ) Estimate

SHD 4460M - CS3 / FCT17008354 / Gbm2

D.O.A: 29/4/17

SLR 8709A - CC3 / ICS17020376 / Rleh3

D.O.A: 23/9/17

8/2-

Revert preli via munnen

lump sum \$9500 - (red: 16,943.34 164%)

SHD4460M

2012

Reg No: SHD4460M. V Reg: Sep 2012  
 Type: M/Car / M/Cycle / Bus / Van / Lorry / ☒ Prime Mover /  
 Truck / Trailer or  
 Make: **HYUNDAI** Yr: **1991**  
 Colour: **Blue** A/C: ☐ Insured: ☐ Std: ☐ Nil / NA  
 Sp Reading: **47287** T/Fade: ☐ Insured: ☐ Std: ☐ Nil / NA  
 Eng No:  
 C No: **KMHETHK MCA830377**  
 Gen Cond: ☒ Good / Fair / Poor / Burnt  
 Steering: ☒ Good / Jammed / Leaked / Burnt or  
 Brake: ☒ Good / Jammed / Leaked / Burnt or  
 Mod: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size P1 215/60R16  
P2                       
 BS / DUN / EXNOVA / GY / FS / LIZA / MIO / QHTSU / PIR / SUMI /  
 TOYO / YOKO or Wetlake  
Front                      mm Front                      mm  
Rear                      mm Rear                      mm  
Left                      mm Left                      mm  
 DOA 5/2/2018 DO 7/2/2018  
 Survey held at                     

Date	Person Contacted
------	------------------

The LUC | Chassis frame | Body Structure affected due to collision.

Date	Time	Action	Instruction
------	------	--------	-------------

RECEIVED 04 APR 2010

44 Typist

Resurvey No. of Trip:

25/04/2014

Downloaded from <http://ajphaphysoc.org/>

Add Fee: ☐ Site Fee: ☐

### Report Format

Figure 1. (continued)

518 王 健

Copyright © 2004 John Wiley & Sons, Ltd.

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100
---	---	---	---	---	---	---	---	---	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	-----

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100
---	---	---	---	---	---	---	---	---	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	-----

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Feb 2018		06 Feb 2018 15:52 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

[Main](#)[Reference](#)[Claim Details](#)[Documents](#)[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	Yeo Chun Sion (Yang Junxiong), ID: S7930318F		
Main Claimant:	Comfort Transportation Pte Ltd, Co. Reg. No.: 199303821R		
Vehicle Reg. No.:	SHD4460M	Date of Loss:	05/02/2018 16:00 - :59
Claim Type:	TP / 548803	Policy/Cover Note No.:	29013986QMY (Comprehensive) Coverage: 30/08/2017 - 29/08/2018
Vehicle Reg. No. (Insured):	SLR8709A	Policy No. (Claimant):	
		Excess:	
Repairer:	Soon Hock Motor Pte Ltd (HQ) Blk 10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK Autopoint, 568047 Ang Mo Kio - Tel: 64836016		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Muhd Ashik B Madi - 6594 2548]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 07/02/2018]		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18002459/M11d3

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 07-02-2018



Code : MSG

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLR 8709A	Veh. Inspected	SHD 4460M
Policy No.	29013986QMY	Coverage (\$)	0.00
Claim No.	548803	Excess (\$)	0.00
Assign From	MERIMEN (MUHD ASHIK)	Assign Date	07/02/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	05/02/2018	Inspection Date	07/02/2018
Survey held at	CHUNNI MOTOR REPAIRS PTE LTD BLK 10 ANG MO KIO INDUSTRIAL PARK 2A AMK AUTOPOINT #03-19 SINGAPORE 568047		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Muhd Ashik B Madi

Date: 08 Feb 2018

**Preliminary Advice**

Insured Vehicle No	: SLR8709A	Accident Date	: 05/02/2018
TP Vehicle No	: SHD4460M	Assignment Date	: 06/02/2018
Make	: HYUNDAI SONATA NF	Est. Duration of Repair	: 12.00
Date of Inspection	: 07/02/2018		
Inspection At	: SOON HOCK MOTOR PTE LTD (HQ) BLK 10 ANG MO KIO INDUSTRIAL PARK 2A, #01-05/06 AMK AUTOPOINT SINGAPORE 568047		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages ..... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	26,443.34
Revised Amount	:S\$	12,887.66
Check Items (Estimated)	:S\$	6,596.48
Total	:S\$	19,484.14
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is economical/not economical for repair.
- ( x ) The above survey was conducted on a 'without prejudice' basis.

MCD018018193 / ComfortDelGro Engineering Pte Ltd - Layanp  
 ENTRY DATE & TIME: 06/02/2018 10:23  
 SUBMITTED BY: Catherine Por Moy Juan

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	06/02/2018 10:23
Date Of Accident	05/02/2018 15:55
Exact Location Of Accident	ALONG PIE TOWARD BEDOK
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD4460M
<b>Insured/Policyholder</b>	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768
<b>Vehicle Particulars</b>	
Manufacturer	HYUNDAI
Model	SONATA
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
<b>Insurance Company</b>	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088936MFSH
Cover Note Number	
<b>Driver</b>	
Name of Driver	JUMANI BIN ISMAIL
NRIC No	S1489160I
Date Of Birth	24/11/1961
Occupation	OUTDOOR
Date Of Driving Pass	18/09/1995
Driving Experience	22 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	27 #11-247 MARSILING DRIVE
Postcode	730027
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

**General Information of the Accident**

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

**Other Information**

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

**Details of Police Action**

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

**Circumstances of Accident**

SEE ATTACH.

**Attachment(s)**

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number	SLR8709A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	S1489160I
Contact Number	92381770
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	FRT & REAR
No. Of Passenger (Including Driver)	

**DETAILS OF OTHER VEHICLE PROPERTY 2**

Vehicle Registration Number	SLP6044H
-----------------------------	----------

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

REAR

No. Of Passenger (Including Driver)

**DETAILS OF OTHER VEHICLE PROPERTY 3**

Vehicle Registration Number

SLC210C

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

FRT

No. Of Passenger (Including Driver)



**SKETCH PLAN****IMPORTANT NOTICE**


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

CHUNNI MOTOR TRANSPORTATION PTE LTD  
CO. REG. NO. 199303821R

Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 05/02/2018 @ 17:40hrs

ALICE  
Reporting Centre Personnel's Signature  
Name: Alice Tee  
NRIC/FIN No.: -

## SKETCH PLAN



Along PIE Twds Bedok

A-SHD 4460M  
 B-SLR 8709A (Private Car)  
 C-SLP 6044H (Private Car)  
 D-SLC 210C (Private Car)

## Describe Circumstances of the Accident

On 05/02/2018 @ about 15:55hrs, my taxi (A) (SHD 4460M) was travelling along PIE Twds Bedok.

I saw in front of my vehicles slowing down and stopped, So I follow too. Out of sudden, there was a loud impact coming from the rear portion and caused my taxi (A), to lose control and surge forward, and colliding onto veh (C) (SLP 6044H) rear portion. My taxi (A) front and rear portion was damaged.

I assessed the damages to my taxi (A) and come to know that there were 4 vehicles involved in the chain accident.

No one was conveyed by the ambulance.

The parties involved in the accident are:

A-SHD 4460M.

B-SLR 8709A, NRIC: S 1489160I, Hp: 9238 1770.

C-SLP 6044H, Male Driver.

D-SLC 210C, Male Driver.

No injury in this accident.

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD  
 CO. REG. NO. 199303821R

policyholder's Signature  
 Date & Time

Driver's Signature (If driver is not the policyholder)  
 Date & Time 05/02/2018 @ 17:40hrs

ALICE

Reporting Centre Personnel's Signature  
 Name : Alice Tee  
 NRIC/FIN No : -

TO Survey by LKK (cont)

**CHUNNI MOTOR WORK PTE LTD**

### REPAIR ESTIMATE\*

VEHICLE NO : SHD 4460M

DATE : 6.02.2018

MAKE :

**TEL : 6542 5119**

**MODEL : HYUNDAI SONATA**

**FAX : 6542 6039**



ADLC

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Bonnet		R x	\$ 1,151.80
	Bonnet Hinge (LH/RH)	S R	87.50	\$x 175.00
	Bonnet Moulding		ave	\$ v 120.90
	Bonnet Lock		ave	\$ x 48.80
	Radiator Grille		dis	\$ ✓ 282.10
	Radiator Grille U Moulding		dis	\$ ✓ 108.90
	Front Bumper Cover		dnd	\$ — 538.80
	Front Bumper Sponge		suc	\$X 136.30
	Front Bumper Reinforcement		ave	\$ X 504.10
	Front Bumper Bracket Top (LH/RH)	S	22.40	\$ — 44.80
	Front Bumper Protector (LH/RH)	S	29.20	\$ — 58.40
	Front Bumper Bracket (LH/RH)	S ave }	20.10	\$ — 40.20
	Front Bumper Side Bracket	S	14.30	\$ ✓ 28.60
	Headlamp Support Panel Assy		X	\$ 1,023.00
	Headlamp (LH/RH)	S avg	797.90	\$ 1,595.80
	Radiator		ave	\$ x 814.80
	Radiator Fan Blade,Cowling,Motor Assy		ave	\$ m 651.30
	Radiator Bracket	S	m 6.20	\$ r 12.40
	Aircon Condenser		x	\$ 1,089.90
	Inter Cooler		x	\$ 771.50
	Inter Cooler Mounting (2 PCS)		y	\$ 24.80
	Wiring-ECM		Carey	\$ 3,107.80
	SUB TOTAL			\$ 12,330.00
	LESS 20%			\$ 2,466.00
	<b>DISCOUNTED TOTAL</b>			<b>\$ 9,864.00</b>
	Front Number Plate		disco	\$ L 25.00 Nett
	Front No Plate Trim Cover			\$ L 30.00 Nett
				\$ 55.00
	<b>Labour Charge</b>			
	Panel Beating			\$ 1,000.00 300/bae
	Spray Painting Charge			\$ 600.00 360
	Wiring Charge			\$ 50.00 20
	Tuff Kote			\$ 50.00 20
	Towing Charge			\$ 50.00 —
	Remove/Refix Aircon & Refill Gas			\$ 150.00 100% X
	Remove/Refix Dashboard			\$ 450.00 280% X
	Remove/Refix Fuse Box			\$ 180.00 X
	<b>TOTAL LABOUR</b>			<b>\$ 2,530.00</b>

SHD 4460M

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid		Unit	\$ 1,349.50
	Boot Lid Rubber		dis	\$ 110.90
	Boot Lid Hinge (LH/RH)	S	bst 170.60	\$ 341.20
	Boot Lid Lock Upper		bst	\$ 132.10
	Boot Lid Lock Lower		bst	\$ 30.30
	Boot Lid Key Lock		ave	\$ 78.20
	Boot Lid Sonata Plate		u.e	\$ 43.60
	Boot Lid Hyundai Plate		u.e	\$ 24.20
	Boot Lid 'H' Emblem		u.e	\$ 26.10
	Boot Lid CRDI Plate		u.e	\$ 22.70
	Boot Lid Lamp (LH/RH)	S	avg 230.20	\$ 460.40
	Boot Lid Trimboard		term	\$ 165.40
	Boot Lid Trimboard Clips (11pcs)		u.e	\$ 11.00
	Rear Bumper		dis	\$ 578.40
	Rear Bumper Reinforcement		bst	\$ 483.30
	Rear Bumper Clip		u.e	\$ 22.00
	Rear Bumper Bracket	S	bst 49.00	\$ 98.00
	Rear Bumper Sponge		term	\$ 137.40
	Rear Bumper Under Cover		dis	\$ 185.80
	Rear Bumper Protector (LH/RH)	OS dis	\$ 117.90 (38.00)	\$ 76.00
	Tail Lamp (LH/RH)		scr 344.00	\$ 688.00
	Tail Lamp Quarter Panel (LH/RH)	NS bst	\$ 05.12 (93.80)	\$ 187.60
	Rear Panel		bst	\$ 391.80
	Rear Panel Garnish		dis	\$ 95.80
	Spare Tyre Holder		ave	\$ 27.60
	Spare Tyre Panel		dis	\$ 863.00
	Spare Tyre Panel Cushion		ave	\$ 200.30
	Rear Towing Hook		R	\$ 135.30
	Member Assy- Rear Floor Centre		R	\$ 163.60
	Panel Assy-Rear Floor Side (RH)		R	\$ 88.55
	Exhaust Pipe Insulator		ave	\$ 56.10
	Exhaust Silencer		bst	\$ 723.00
	Exhaust Pipe Hanger		u.e	\$ 56.10
	Rear Fender (RH)		unit	\$ 1,935.90
	Rear Fender Inner Lining (RH)		dis	\$ 74.10
	Rear Tray Lugg Side (RH)		ave	\$ 37.40
	Rear Fender Trim Board (RH)		term	\$ 180.90
	Rear Windscreen Moulding		u.e	\$ 60.00
	Rear Wiring Assy		ave	\$ 1,458.00
	Fire Extinguisher Holder		ave	\$ 35.00
	<b>SUB TOTAL</b>			<b>\$ 11,834.55</b>
	<b>LESS 20%</b>			<b>\$ 2,366.91</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$ 9,467.64</b>

SHD 4460M

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Boot Lid Comfort Logo & Tel No. Sticker		we	S 30.00	Nett
	Rear No. Plate		cuq	S 25.00	Nett
	Rear Bumper Reverse Sensor		sha	S 135.70	Nett
	Rear Windscreen Sealant		we	S 46.00	Nett
				S 236.70	
	<b>Labour Charge</b>				
	Panel Beating			S 2,000.00	1200
	Spray Painting Charge			S 1,200.00	1000
	Wiring Charge			S 50.00	30
	Tuff Kote			S 100.00	60
	Rear Chassis Alignment Charge			S 400.00	X
	Remove/Refix Cushion & Upholstery Rear			S 150.00	60
	Remove/Refix Rear Windscreen Glass			S 120.00	100
	Remove/Refix Reverse Sensor			S 120.00	60
	Remove/Refix Exhaust Pipe			S 150.00	20
	<b>TOTAL LABOUR</b>			S 4,290.00	
	<b>ESTIMATE TOTAL</b>			S 26,443.34	
<p>Not Authorised          US Rep          After paint job          LKK Auto (ins)  <del>7/2/2018</del>          7/2/2018 @          12 w days            12/2/18</p>					
<p><b>LKK Auto Consultants</b> hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> <li>• To resurvey before/after spray painting</li> <li>• To display damaged part(s) during resurvey</li> <li>• Parts prices are subject to confirmation</li> <li>• Third party survey is on a "Without Prejudice" basis</li> <li>• No illegal modification(s) is allowed</li> <li>• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li> </ul> <p>Acknowledged by Repairer          Signature:           Date: 9/5/18 - 1 month          6 w days 11/2/2018</p>					
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Feb 2018		06 Feb 2018 15:52 <a href="#">Edit Adj Rpt</a>	<b>\$99,500.00</b> <a href="#">Edit Estimates</a>	<b>\$99,500.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS		[Created by Insurer]
Insured:	Yeo Chun Sion (Yang Junxiong), ID: 57930318F	
Main Claimant:	Comfort Transportation Pte Ltd, Co. Reg. No.: 199303821R	
Vehicle Reg. No.:	SHD4460M	Date of Loss: 05/02/2018 16:00 - :59 [64 Months and 8 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 548803	Policy/Cover Note No.: 29013986QMY (Comprehensive) Coverage: 30/08/2017 - 29/08/2018
Vehicle Reg. No. (Insured):	SLR8709A	Policy No. (Claimant):
		Excess:
Repairer:	Soon Hock Motor Pte Ltd (HQ) Blk 10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK Autopoint, 568047 Ang Mo Kio - Tel: 64836016	
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Muhd Ashik B Madi - 6594 2548]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MA CHIN FOOK] ... [Final Rpt due 08/03/2018]	
































ASSOCIATED MAIL RECEIVED		<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
There are no mail for this case.			

ALL ASSOCIATED TASKS		<a href="#">View All</a>	<a href="#">Search Tasks</a>	<a href="#">Create New Task</a>	<a href="#">Complete</a>				
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*SHD4460M (548803)**  
**[SLR8709A]**  
**TP**  
**Comfort Transportation Pte Ltd**  
**Feb 5 2018 4:00PM**  
**[Yeo Chun Sion (Yang Junxiong)]**  
**Soon Hock Motor Pte Ltd**

<a href="#">Upload Documents</a>		<a href="#">Upload Photos</a>	<a href="#">Compose New Letter</a>	<b>View</b> <a href="#">View in Browser</a>	
<b>Assessment Reports</b>				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	06/02/18 17:34	<b>Accident Statement</b> <small>From: SC - Reg. No: SLR8709A, Claimant: SIME DARBY SERVICES PTE LTD</small>		Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	08/02/18 15:52	<b>Adjuster Immediate Advice</b>		Load HTM	
<b>Photos/Images</b>				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	04/04/18 14:52	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
2	04/04/18 14:52	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
3	04/04/18 14:52	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
4	04/04/18 14:52	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
5	04/04/18 14:52	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
6	04/04/18 14:52	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
7	04/04/18 14:52	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
8	04/04/18 14:52	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
9	04/04/18 14:52	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
10	04/04/18 14:52	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
11	04/04/18 14:52	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
12	04/04/18 14:52	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
13	04/04/18 14:52	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
14	04/04/18 14:52	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
15	04/04/18 14:52	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
16	04/04/18 14:52	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
17	04/04/18 14:52	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
18	04/04/18 14:52	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
19	04/04/18 14:52	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
20	04/04/18 14:52	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
21	04/04/18 14:52	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
22	04/04/18 14:52	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
23	04/04/18 14:52	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
24	04/04/18 14:52	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
25	04/04/18 14:52	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
26	04/04/18 14:52	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
27	04/04/18 14:52	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
28	04/04/18 14:52	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
29	04/04/18 14:52	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
30	04/04/18 14:52	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
31	04/04/18 14:52	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
32	04/04/18 14:52	<b>General View</b>		Load JPG	



Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
33	04/04/18 14:52	General View	Load JPG	<input checked="" type="checkbox"/>
34	04/04/18 14:52	General View	Load JPG	<input checked="" type="checkbox"/>
35	04/04/18 14:52	General View	Load JPG	<input checked="" type="checkbox"/>
36	04/04/18 14:52	General View	Load JPG	<input checked="" type="checkbox"/>
37	04/04/18 14:52	General View	Load JPG	<input checked="" type="checkbox"/>
38	04/04/18 14:52	General View	Load JPG	<input checked="" type="checkbox"/>
39	04/04/18 14:52	General View	Load JPG	<input checked="" type="checkbox"/>
40	04/04/18 14:52	General View	Load JPG	<input checked="" type="checkbox"/>
41	04/04/18 14:52	General View	Load JPG	<input checked="" type="checkbox"/>
42	04/04/18 14:52	General View	Load JPG	<input checked="" type="checkbox"/>
43	04/04/18 14:52	General View	Load JPG	<input checked="" type="checkbox"/>
44	04/04/18 14:52	General View	Load JPG	<input checked="" type="checkbox"/>
45	04/04/18 14:52	General View	Load JPG	<input checked="" type="checkbox"/>
46	04/04/18 14:52	General View	Load JPG	<input checked="" type="checkbox"/>
47	04/04/18 14:52	General View	Load JPG	<input checked="" type="checkbox"/>
48	04/04/18 14:52	General View	Load JPG	<input checked="" type="checkbox"/>
49	04/04/18 14:52	General View	Load JPG	<input checked="" type="checkbox"/>
50	04/04/18 14:52	General View	Load JPG	<input checked="" type="checkbox"/>
51	04/04/18 14:52	General View	Load JPG	<input checked="" type="checkbox"/>
52	04/04/18 14:52	General View	Load JPG	<input checked="" type="checkbox"/>
53	04/04/18 14:52	General View	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	06/02/18 15:39	Estimate	Load PDF	
2	06/02/18 15:52	Survey Agree on SJE - LKK	Load PDF	
3	06/02/18 17:34	SHD4460M E-FILE REPORT From: SC - Reg. No: SLR8709A, Claimant: SIME DARBY SERVICES PTE LTD	Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18002459/M1TD3Q2

Date: 05/04/2018

## REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29013986QMY

Claimant Vehicle No : SHD4460M

Insured Vehicle No : SLR8709A

Date of Loss: 05/02/2018

Nature of Claim: TP

Claim No: 548803

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SHD4460M

Make &amp; Model: HYUNDAI SONATA NF, 2.0 CRDI AT ABS 2WD 4DR TURBO (A)

Engine No: D4EAC196456

Reg. Date: 28/09/2012 (Man. Year: 2012)

Chassis No: KMHET41VMCA830379

Colour: Blue

Odometer: 472817 km

Engine Capacity: 1991 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: West Lake 8 mm

Rear Left Side: West Lake 8 mm

Front Right Side: West Lake 8 mm

Rear Right Side: West Lake 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,623.34	9,237.66	10,385.68	52.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,820.00	3,350.00	3,470.00	50.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,443.34	12,587.66	13,855.68	52.40
Approved Total (Overridden) (S\$)		9,500.00		
(S\$)	26,443.34	9,500.00	16,943.34	64.07
+ GST 7.00/7.00% (S\$)	1,851.03	665.00	1,186.03	64.07
Nett Amount (S\$)	28,294.37	10,165.00	18,129.37	64.07

## INSPECTION

Date of Assignment: 06/02/2018

Date Inspected: 07/02/2018 Inspected At:

Soon Hock Motor Pte Ltd (HQ)  
Blk 10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK Autopoint  
Singapore 568047

Estimated Period of Repair: 6.0 days

---

**Adjuster:** MA CHIN FOOK**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 05 Apr 2018)
<b>Parts:</b>	143	HYUNDAI SONATA NF 2.0 CRDI AT ABS 2WD 4DR TURBO (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHD4460M)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Repair	1,151.80 FL	*- FL
2	2		*BONNET HINGE (LH/RH)	Repair	175.00 FL	*- FL
3	1		*BONNET MOULDING	Serviceable	120.90 FL	*- FL
4	1		*BONNET LOCK	Serviceable	48.80 FL	*- FL
5	1		*RADIATOR GRILLE	Distorted	282.10 FL	*282.10 FL
6	1		*RADIATOR GRILLE U MOULDING	Distorted	108.90 FL	*108.90 FL
7	1		*FRONT BUMPER COVER	Deformed	538.80 FL	*538.80 FL
8	1		*FRONT BUMPER SPONGE	Serviceable	136.30 FL	*- FL
9	1		*FRONT BUMPER REINFORCEMENT	Serviceable	504.10 FL	*- FL
10	2		*FRONT BUMPER BRACKET TOP (LH/RH)	Necessary	44.80 FL	*44.80 FL
11	2		*FRONT BUMPER PROTECTOR (LH/RH)	Necessary	58.40 FL	*58.40 FL
12	2		*FRONT BUMPER BRACKET (LH/RH)	Necessary	40.20 FL	*40.20 FL
13	2		*FRONT BUMPER SIDE BRACKET	Necessary	28.60 FL	*28.60 FL
14	1		*HEADLAMP SUPPORT PANEL ASSY	Serviceable	1,023.00 FL	*- FL
15	2		*HEADLAMP (LH/RH)	Cracked	1,595.80 FL	*1,595.80 FL
16	1		*RADIATOR	Serviceable	814.80 FL	*- FL
17	1		*RADIATOR FAN BLADE COWLING ,MOTOR ASSY	Serviceable	651.30 FL	*- FL
18	2		*RADIATOR BRACKET	Serviceable	12.40 FL	*- FL
19	1		*AIRCON CONDENSER	Serviceable	1,089.90 FL	*- FL
20	1		*INTER COOLER	Serviceable	771.50 FL	*- FL
21	2		*INTER COOLER MOUNTING	Serviceable	24.80 FL	*- FL
22	1		*WIRING-ECM	Serviceable	3,107.80 FL	*- FL
23	1		*FRONT NUMBER PLATE }	Distorted	25.00 FS	*40.00 FS
24	1		*FRONT NO PLATE TRIM COVER }	Distorted	30.00 FS	*- FS
25	1		*BOOT LID	Buckled	1,349.50 FL	*1,349.50 FL
26	1		*BOOT LID RUBBER	Distorted	110.90 FL	*110.90 FL
27	2		*BOOT LID HINGE (LH/RH)	Bent	341.20 FL	*341.20 FL
28	1		*BOOT LID LOCK UPPER	Bent	132.10 FL	*132.10 FL
29	1		*BOOT LID LOCK LOWER	Bent	30.30 FL	*30.30 FL
30	1		*BOOT LID KEY LOCK	Serviceable	78.20 FL	*- FL
31	1		*BOOT LID SONATA PLATE	Necessary	43.60 FL	*43.60 FL
32	1		*BOOT LID HYUNDAI PLATE	Necessary	24.20 FL	*24.20 FL
33	1		*BOOT LID H EMBLEM	Necessary	26.10 FL	*26.10 FL
34	1		*BOOT LID CRDI PLATE	Necessary	22.70 FL	*22.70 FL
35	2		*BOOT LID LAMP (LH/RH)	Cracked	460.40 FL	*460.40 FL
36	1		*BOOT LID TRIMBOARD	Torn	165.40 FL	*165.40 FL
37	11		*BOOT LID TRIMBOARD CLIPS	Necessary	11.00 FL	*11.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
38	1		*REAR BUMPER	Deformed	578.40 FL	*578.40 FL
39	1		*REAR BUMPER REINFORCEMENT	Bent	483.30 FL	*483.30 FL
40	1		*REAR BUMPER CLIP	Necessary	22.00 FL	*22.00 FL
41	2		*REAR BUMPER BRACKET	Bent	98.00 FL	*98.00 FL
42	1		*REAR BUMPER SPONGE	Torn	137.40 FL	*137.40 FL
43	1		*REAR BUMPER UNDER COVER	Distorted	185.80 FL	*185.80 FL
44	1		*REAR BUMPER PROTECTOR (LH/RH)	O/S Distorted /N/S Serviceable	76.00 FL	*38.00 FL
45	2		*TAIL LAMP (LH/RH)	Cracked	688.00 FL	*688.00 FL
46	1		*TAIL LAMP QUARTER PANEL (LH/RH)	N/S Bent / O/S Repair	187.60 FL	*93.80 FL
47	1		*REAR PANEL	Bent	391.80 FL	*391.80 FL
48	1		*REAR PANEL GARNISH	Distorted	95.80 FL	*95.80 FL
49	1		*SPARE TYRE HOLDER	Serviceable	27.60 FL	*- FL
50	1		*SPARE TYRE PANEL	Repair	863.00 FL	*- FL
51	1		*SPARE TYRE PANEL CUSHION	Serviceable	200.30 FL	*- FL
52	1		*REAR TOWING HOOK	Repair	135.30 FL	*- FL
53	1		*MEMBER ASSY -REAR FLOOR CENTRE	Repair	163.60 FL	*- FL
54	1		*PANEL ASSY -REAR FLOOR SIDE (RH)	Repair	88.55 FL	*- FL
55	1		*EXHAUST PIPE INSULATOR	Serviceable	56.10 FL	*- FL
56	1		*EXHAUST SILENCER	Bent	723.00 FL	*723.00 FL
57	1		*EXHAUST PIPE HANGER	Not Necessary	56.10 FL	*- FL
58	1		*REAR FENDER (RH)	Buckled	1,935.90 FL	*1,935.90 FL
59	1		*REAR FENDER INNER LINING (RH)	Distorted	74.10 FL	*74.10 FL
60	1		*REAR TRAY LUGG SIDE (RH)	Serviceable	37.40 FL	*- FL
61	1		*REAR FENDER TRIM BOARD (RH)	Torn	180.90 FL	*180.90 FL
62	1		*REAR WINDSCREEN MOULDING	Necessary	60.00 FL	*60.00 FL
63	1		*REAR WIRING ASSY	Serviceable	1,458.00 FL	*- FL
64	1		*FIRE EXTINGUISHER HOLDER	Serviceable	35.00 FL	*- FL
65	1		*BOOT LID COMFORT LOGO & TEL NO.STICKER	Necessary	30.00 FS	*30.00 FS
66	1		*REAR NO.PLATE	Cracked	25.00 FS	*25.00 FS
67	1		*REAR BUMPER REVERSE SENSOR	Shorted	135.70 FS	*135.70 FS
68	1		*REAR WINDSCREEN SEALANT	Necessary	46.00 FS	*46.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	24,456.25	11,477.90
- List Item Discount on L Items 20.00/20.00% (\$\$)	4,832.91	2,240.24
Total Parts (\$\$)	19,623.34	9,237.66

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	3,000.00	1,500.00
2	SPRAY PAINTING CHARGE	New	1,800.00	1,360.00
3	WIRING CHARGE	New	100.00	60.00
4	TUFF KOTE	New	150.00	80.00
5	TOWING CHARGE	New	50.00	50.00
6	REMOVE/REFIX AIRCON & REFILL GAS	New	150.00	0.00
7	REMOVE/REFIX DASHBOARD	New	450.00	0.00
8	REMOVE/REFIX FUSE BOX	New	180.00	0.00
9	REAR CHASSIS ALIGNMENT CHARGE	New	400.00	0.00
10	REMOVE/REFIX CUSHION & UPHOLSTERY REAR	New	150.00	60.00
11	REMOVE/REFIX REAR WINDSCREEN GLASS	New	120.00	100.00
12	REMOVE/REFIX REVERSE SENSOR	New	120.00	60.00
13	REMOVE/REFIX EXHAUST PIPE	New	150.00	80.00
<b>Gross Labour Cost (\$\$)</b>			<b>6,820.00</b>	<b>3,350.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >