

Not Authorised
1-B1
Refusing B6 paint
4 days

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 24 January 2018

Third Party Insurer: AIG

Vehicle No: SLR9017G

Third Party Veh No: SKD7944D

Model: TOYOTA SIENTA

Date of Accident: 21/01/18

Chassis: NHP1707089366

ESTIMATE

QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER		R \$1,235.70 ✓
1	FRONT BUMPER TOP RUBBER SEAL		m \$24.10 ✓
3	FRONT BUMPER TOP RUBBER SEAL CLIP	\$5.71	m \$17.13 ✓
1	FRONT BUMPER TOP BEAM		\$82.15 ✓
15	FRONT BUMPER CLIP	\$6.20	m \$93.00 ✓
1	FRONT BUMPER CENTRE GARNISH ASSY		cm \$832.10 ✓
1	FRONT BUMPER REINFORCEMENT		\$343.50 ?
1	FRONT BUMPER INNER SPONGE		\$72.80 ?
1	FRONT BUMPER LOGO EMBLEM		m \$65.70 ✓
1	FRONT SUPPORT PANEL		R \$1,087.80 X
1	FRONT SUPPORT PANEL TOP GARNISH		\$133.20 ?
6	FRONT SUPPORT PANEL TOP GARNISH CLIP	\$5.78	\$34.68 ?
1	FRONT SUPPORT PANEL APPROACHING SPEAKER WITH BRACKET		\$250.78 ?
1	FRONT BRACE PANEL		\$107.00 ?
1	HORN		\$126.40 ?
1	HYBRID INVERTER WITH CONVERTER COOLER		\$6,666.72 ?
1	AIRCON CONDENSER		\$1,298.60 ?
1	FRONT BONNET MECHANISM LOCK		R \$130.80 X
SUB TOTAL			\$12,602.16
Less 25%			-\$3,150.54
PARTS TOTAL			\$9,451.62

QTY	SPECIAL NETT	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER NUMBER PLATE WITH CASING		pcr \$50.00 4000
1	RADIATOR COOLANT		\$80.00 ?
S/N TOTAL			\$130.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 24 January 2018

Third Party Insurer: AIG

Vehicle No: SLR9017G

Third Party Veh No: SKD7944D

Model: TOYOTA SIENTA

Date of Accident: 21/01/18

Chassis: NHP1707089366

ESTIMATE

LABOUR CHARGES:

TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION

\$800.00 5001

TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION

\$600.00 4001

TO DISMANTLE & REPLACED AIRCON SYSTEM, VACUUM WITH FLUSHING/REFILL
AIRCON GAS/OIL

\$120.00 ?

TO DISMANTLE & REPLACED RADIATOR WITH HIGH PRESSURE TEST

\$120.00 ?

LABOUR TOTAL \$1,640.00

WINSON

TOTAL \$11,221.62