

ASS. REC. BY:

REF: CS/FCI 18002463/kqd3

n2

Special Instruction:

Surveyor:

CWS

Kenneth

ASSIGNMENT (Office)

From (Person):

Lumme jaw

of

FCI

Date/Time: 12/2/18 @ 5:34pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHD 824

Insured:

SHC 79481

at Workshop m/s

Trans-cab

Tel:

6287 6666

of

No. 2 Amk strt 63

Policy No:

Claim No:

D18001292MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 08/02/2018

CA / REV / REP. / REV 24 HRS / wpr

H.O.D. Endorsement:

Date/Time:

9:07am @ 13/2/18

Person Contacted:

Candy

Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SHD 824 - NBA / INCI 4006089 / SA D.O.A: 31/03/2014
	SHC 79481 - CS / FCI 16008858 / RH 3d1 D.O.A: 03/05/2016
19/2	Revert via email per advise
	Final Fig \$ 4489.22, 4 days. (Red B 34021.60, 88%)

REF: FCI

ASSIGNMENT

From: Date: 13/2/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SHD 824
at Workshop mis: Trans-cab

of:

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAO Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 04 days Res: Yes or No

Lum Sum: 1.B.1 \$ 3 Val: Yes or No

CA / REV / REP. / 24 HRS up

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SHD 824 V-Reg: 03 16

Type: M/Car / M/Cycle / Bush Van / Lorry / Taxi / Prime Mover

Truck / Trailer or

Make: Renault Latitude 1995

Colour: M. White 1R/ A.O. Insured / Std / NI / NA

Sp. Reading: 171690 T. Radio Insured / Std / NI / NA

Eng No:

O.No: VFIABL15AUC 282661

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inoper / Jammed / Leaked / Burnt or

Brake: Inoper / Jammed / Leaked / Burnt or

Mod: M / S/Rim / STD A/Rim or

Tyre Size: F: Giti 215/60R8

R: GY

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUM /

TOYO / YOKO or

Front:

Rear:

R.Bal: 8 mm

R.Bal: 3 mm

L.Bal: 8 mm

L.Bal: 3 mm

D.O.A: 8/2/18

D.O.A: 13/2/18

Survey held at:

Des. of Damages: Frt / Rear / O/S / NS / UIC / Rooftop or

O/S Rear

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

14/2 File pass to Coroner

RECEIVED 20 JUN 2018

Date/Time File Pass to:

20/6/18

☐ : Prelim. Report☐ : Final Report

Date/Time File Return to:

Days Of Repair: 4

Resurvey No. of Trips: 1

Add Fee:

☐ Site Insp \$☐ Inter. \$☐ Tech. Insp \$☐ Rep. Insp \$

Survey Fee

Transportation

Lum Sum

Photo

Other

Report Format:

Lum Sum / I.B.I. \$

70

4489.22

28X15: 420

170+420

50

50

12

580

OSP

20/6/18

702



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18002463/Kqd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 07-02-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7948J	Veh. Inspected	SHD 82Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18001292MFSH	Excess (\$)	0.00	
Assign From	CWS (LURENE JAW)	Assign Date	07/02/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	08/02/2018	Inspection Date		
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX : (065) 62564315

Your Ref: D18001292MFSH

Date: 19/2/2018

Our Ref: CS/FC118002463/Kqd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHD 82Y .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 13/2/2018 at the premises of M/s Trans-cab, and have the following to report: -

Workshop Estimate Amount	: S\$ <u>38,510.82</u> .
Revised Estimate Amount	: S\$ <u>4,489.22</u> .
"Check" Items Amount	: S\$ <u>-</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages at the o/s rear.



Comments/ Present Status:
Damages Consistent.

Yours faithfully
Kenneth
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	12-02-2018	Our Ref No. D18001292MFSH
Accident Date	08-02-2018	Claim Type. Third Party
Insured Vehicle	SHC7948J	Third Party Vehicle. SHD82Y
Survey Location	NO. 2 ANG MO KIO STREET 63	
Contact Person.	CANDY KONG	
Contact No.	62876666/ 62876666	Fax No. 62877764
Survey Type	WITHOUT PREJUDICE: PENDING BOTH VF TO DETERMINE LIABILITY	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS-CAB AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/234929)



PRI Documents



Close



PRI Header Details

Claim No	D18001292MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & TRANS-C/
Workshop Name	TRANS-CAB AUTO SERVICES PTE LTD (Contact Person : CANDY KONG)	Survey Location & Contact Details	NO. 2 ANG MO KIO STREET 63 Mobile: 62876666 , Phone: 62876666 , Fax: 62877766 EmailId: CANDY.KONG@TRANSCAB.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: PENDING BOTH VF TO DETERMIN		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHC7948J	TP Vehicle No	SHD82Y
PRI Recieved Date	12-02-2018 07:41:28 PM	Surveyor Appointed Date	12-02-2018 05:33:24 PM	Surveyor Accept Date	13-02-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	13-02-2018	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Monday, 19 February 2018 3:24 PM
To: Admin-D (LKKAUTO); 'Claim Workflow System'; assignments
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18001292MFSH/1
Attachments: PRELI ADVISED SHD 82Y.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SHD 82Y**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 13 February 2018 8:42 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18001292MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Monday, 12 February 2018 5:34 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18001292MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3878K
Vehicle Details	
Vehicle No.:	SHD82Y
Vehicle to be Exported:	Yes
Intended De-registration Date:	09 Feb 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	M9R8839C003022
Chassis No.:	VF1ABL15AUC282661
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	22 Mar 2016
First Registration Date:	22 Mar 2016
Transfer Count:	0
Actual ARF Paid:	\$19,998.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Mar 2024
PARF Rebate Amount:	\$14,998.00
Intended COE Rebate Details	

COE Expiry Date:	21 Mar 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$39,633.00
COE Rebate Amount:	\$30,297.00
Total Rebate Amount:	\$45,295.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 09 Feb 2018

OK

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD82Y - FCIL**AAD1802-098***Not Authored**Resurvey by paint*

Vehicle No.:

SHD82Y - CANDY

Chassis No.:

VF1ABL15AUC282661

Vehicle Make:

RENAULT

Vehicle Model:

LATITUDE

Date of Accident :

08.02.2018

Third Party Insurer :

FCIL**PART****LIST**

1	1	BUMPER COVER REAR	\$	SH 1,108.46	} X
2	1	BUMPER LOWER REAR	\$	SH 768.84	
3	1	BUMPER BRACKET CTR REAR	\$	SH 113.47	
4	1	BUMEPR BRACKET SIDE RH REAR	\$	SH 135.97	
5	1	BUMEPR RETAINER RH REAR	\$	SH 44.99	
6	1	BUMPER REFLECTOR RH	\$	SH 43.61	
7	1	BUMEPR BRACKET SIDE LH REAR	\$	SH 135.97	
8	1	BUMEPR RETAINER LH REAR	\$	SH 44.99	}
9	1	ROCKER PANEL OUTER RH	\$	N 987.49	
10	1	FENDER PANEL REAR RH	\$	B 3,299.13	✓
11	1	WHEELARCH REAR RH	\$	SH 543.47	} X
12	1	KUCKLE ARM REAR RH	\$	SH 736.67	
13	1	LOWER ARM REAR RH	\$	SH 905.99	
14	1	ABSORBER REAR RH	\$	SH 389.75	
15	1	TAILLAMP RH	\$	SH 552.55	
16	1	TAILLAMP PANEL RH	\$	N 986.70	
17	1	EXHAUST REAR	\$	N 7,489.05	
18	1	EXHAUST CAP REAR	\$	N 230.49	
19	1	DOOR PANEL REAR RH	\$	N 2,844.66	
20	1	DOOR GUIDE REAR RH	\$	SH 176.82	
21	1	DOOR HINGE UPPER RH	\$	N 274.50	
22	1	DOOR HINGE LOWER RH	\$	N 300.55	
23	1	DOOR CHECK REAR RH	\$	SH 203.06	
24	1	DOOR LOCK REAR RH	\$	N 908.75	
25	1	DOOR GRAB HANDLE REAR RH	\$	SH 210.96	
26	1	DOOR HANDLE OUTER REAR RH	\$	SH 126.49	
27	1	DOOR HANDLE CAP REAR RH	\$	SH 35.52	
28	1	DOOR HANDLE SEAL REAR RH	\$	SH 7.89	
29	1	DOOR HANDLE COVER REAR RH	\$	SH 13.22	
30	1	DOOR HANDLE MODULE REAR RH	\$	SH 133.60	
31	1	DOOR FINISHER REAR RH	\$	SH 423.10	
32	1	DOOR WHEATHESTRIIP REAR RH	\$	SH 410.66	
33	1	DOOR SEAL REAR RH	\$	SH 162.02	
34	1	DOOR WAIST SEAL OUTER REAR RH	\$	SH 334.69	

TRANS-CAB AUTO SERVICES PTE LTD

AAD1802-098

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD82Y - FCIL

35	1	DOOR MOULDING REAR RH	\$	<i>Sh</i>	176.82	X
36	1	DOOR PANEL FRT RH	\$	<i>n</i>	2,844.66	X

TOTAL	\$	28,105.56
10%	\$	2,810.56
	\$	25,295.00

Special Nett

1	1SET	PARKING AID	\$	<i>Sh</i>	700.00	} X
2	1SET	REAR BUMPER CLIP	\$	<i>nn</i>	66.00	
3	1SET	BUMPER BRACKET CTR CLIP	\$	<i>nn</i>	33.00	
4	1SET	BUMPR BRACKET SIDE CLIP RH RR	\$	<i>nn</i>	10.00	
5	1SET	BUMPR RETAINER RH CLIP RR	\$	<i>nn</i>	20.00	
6	1SET	BUMPER LOWER REAR RIVET	\$	<i>nn</i>	22.00	
7	1SET	BUMPER LOWER REAR CLIP	\$	<i>nn</i>	66.00	
8	1	EXHAUST MOUNTING REAR	\$	<i>Sh</i>	17.82	
9	1	TAILLAMP CLIP RH	\$	<i>nn</i>	5.00	} 405n
10	1SET	WHEELARCH CLIP RR RH	\$	<i>nn</i>	66.00	
11	2	REAR WINDSCREEN SELANT	\$	<i>nn</i>	80.00	
12	1	WINDSCREEN MOULDING	\$	<i>nci</i>	100.00	✓
13	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>nn</i>	100.00	305n
14	1	CAP HUB RH RR	\$	<i>Sh</i>	35.00	X
15	1	RIM RH RR	\$	<i>Sh</i>	385.00	X
16	1	TYRE RH RR	\$	<i>Sh</i>	330.00	X
17	1	DOOR STICKER "Trans-cab"	\$	<i>nn</i>	80.00	X
18	1	DOOR STICKER "Classic"	\$	<i>nn</i>	30.00	X
19	1	DOOR STICKER "6555-3333"	\$	<i>nn</i>	80.00	605n

TOTAL	\$	2,225.82
TOTAL PARTS	\$	27,520.82

Putty And Spray Painting Of The Affected Portion. \$ 4,500.00 *440*

To reinstall rear bumper parking sensor. \$ *nn* 170.00 X

To Rust-Proofing Of The Affected Areas. \$ 170.00 *30*

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same \$ 4,200.00 *600*

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD82Y - FCIL**AAD1802-098**

To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00 X
To repair and realign rear exhaust pipe.	\$	170.00 X
Towing Fees	\$	120.00 X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00 100%
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00 120%
To check steering geometry and computer wheel alignment	\$	220.00 X
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00 X
To transfer of tire, rim and on wheel balancing.	\$	170.00 X
To dismantle and refit rear undercarriage parts, final checking and testing.	\$	380.00 X

TOTAL	\$	10,990.00
Over All Total	\$	38,510.82

(PARTS BY PARTS)**Repair Days**~~15 Days~~

4 day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18002463/Kqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 20-06-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7948J	Veh. Inspected	SHD 82Y	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D18001292MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	12/02/2018	
2. Vehicle Particulars & Condition				
Make & Model	RENAULT LATITUDE (A)	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	VF1ABL15AUC282661	Colour	METALLIC WHITE / RED	
Odometer	171690	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	GITI	8 mm	
L/H Front Tyre	215/60 R16	GITI	8 mm	
R/H Rear Tyre	215/60 R16	GOODYEAR	3 mm	
L/H Rear Tyre	215/60 R16	GOODYEAR	3 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/02/2018	Inspection Date	13/02/2018	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 82Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BUMPER COVER REAR	SERVICEABLE	1,108.46	-
1	BUMPER LOWER REAR	SERVICEABLE	768.84	-
1	BUMPER BRACKET CTR REAR	SERVICEABLE	113.47	-
1	BUMPER BRACKET SIDE RH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER RH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR RH	SERVICEABLE	43.61	-
1	BUMPER BRACKET SIDE LH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER LH REAR	SERVICEABLE	44.99	-
1	ROCKER PANEL OUTER RH	TO REPAIR SEE LABOUR	987.49	-
1	FENDER PANEL REAR RH	BENT	3,299.13	3,299.13
1	WHEELARCH REAR RH	SERVICEABLE	543.47	-
1	KNUCKLE ARM REAR RH	SERVICEABLE	736.67	-
1	LOWER ARM REAR RH	SERVICEABLE	905.99	-
1	ABSORBER REAR RH	SERVICEABLE	389.75	-
1	TAILLAMP RH	SERVICEABLE	552.55	-
1	TAILLAMP PANEL RH	TO REPAIR SEE LABOUR	986.70	-
1	EXHAUST REAR	TO REPAIR SEE LABOUR	7,489.05	-
1	EXHAUST CAP REAR	TO REPAIR SEE LABOUR	230.49	-
1	DOOR PANEL REAR RH	TO REPAIR SEE LABOUR	2,844.66	-
1	DOOR GUIDE REAR RH	SERVICEABLE	176.82	-
1	DOOR HINGE UPPER RH	TO REPAIR SEE LABOUR	274.50	-
1	DOOR HINGE LOWER RH	TO REPAIR SEE LABOUR	300.55	-
1	DOOR CHECK REAR RH	SERVICEABLE	203.06	-
1	DORO LOCK REAR RH	TO REPAIR SEE LABOUR	908.75	-
1	DOOR GRAB HANDLE REAR RH	SERVICEABLE	210.96	-

Report Ref No. CS/FC118002463/Kqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR HANDLE OUTER REAR RH	SERVICEABLE	126.49	-
1	DOOR HANDLE CAP REAR RH	SERVICEABLE	35.52	-
1	DOOR HANDLE SEAL REAR RH	SERVICEABLE	7.89	-
1	DOOR HANDLE COVER REAR RH	SERVICEABLE	13.22	-
1	DOOR HANDLE MODULE REAR RH	SERVICEABLE	133.60	-
1	DOOR FINISHER REAR RH	SERVICEABLE	423.10	-
1	DOOR WEATHERSTRIP REAR RH	SERVICEABLE	410.66	-
1	DOOR SEAL REAR RH	SERVICEABLE	162.02	-
1	DOOR WAIST SEAL OUTER REAR RH	SERVICEABLE	334.69	-
1	DOOR MOULDING REAR RH	SERVICEABLE	176.82	-
1	DOOR PANEL FRT RH	TO REPAIR SEE LABOUR	2,844.66	-
	LESS 10% DISCOUNT		-2,810.56	-329.91
			25,295.00	2,969.22
	SPECIAL NETT ITEMS			
1	SET PARKING AID (SN)	SERVICEABLE	700.00	-
1	SET REAR BUMPER CLIP (SN)	NOT NECESSARY	66.00	-
1	SET BUMPER BRACKET CTR CLIP (SN)	NOT NECESSARY	33.00	-
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER RH CLIP RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR RIVET (SN)	NOT NECESSARY	22.00	-
1	SET BUMPER LOWER REAR CLIP (SN)	NOT NECESSARY	66.00	-
1	EXHAUST MOUNTING REAR (SN)	SERVICEABLE	17.82	-
1	TAILLAMP CLIP RH (SN)	NOT NECESSARY	5.00	-
1	SET WHEELARCH CLIP RH RR (SN)	NOT NECESSARY	66.00	-
2	REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	WINDSCREEN MOULDING (SN)	NECESSARY	100.00	100.00
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NECESSARY	100.00	30.00
1	CAP HUB RH RR (SN)	SERVICEABLE	35.00	-
1	RIM RH RR (SN)	SERVICEABLE	385.00	-
1	TYRE RH RR (SN)	SERVICEABLE	330.00	-
1	DOOR STICKER "TRANS-CAB" (SN)	NOT NECESSARY	80.00	-
1	DOOR STICKER "CLASSIC" (SN)	NOT NECESSARY	30.00	-

Report Ref No. CS/FC118002463/Kqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR STICKER "6555-3333" (SN)	NECESSARY	80.00	60.00
			2,225.82	230.00
	LABOUR			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		4,500.00	440.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.	NOT NECESSARY	170.00	-
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	30.00
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF ROCKER PANEL OUTER RH,TAILLAMP PANEL RH,EXHAUST REAR,EXHAUST CAP REAR,DOOR PANEL REAR RH,DOOR HINGE UPPER RH,DOOR HINGE LOWER RH,DOOR LOCK REAR RH AND DOOR PANEL FRT RH.		4,200.00	600.00
	TO TRANSFER OF BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TOWING FEES.	NOT NECESSARY	120.00	-
	TO TRANSFER OF REAR FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.		380.00	100.00
	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.		170.00	120.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO DISMANTLE AND REFIT REAR UNDERCARRIAGE PARTS,FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	-
	-		-	-
	-		-	-
	-		-	-
			10,990.00	1,290.00
GRAND TOTAL			38,510.82	4,489.22

Report Ref No. CS/FCI18002463/Kqd3n2



RECOMMENDED COST OF REPAIRS			4,489.22
-----------------------------	--	--	----------

Report Ref No. CS/FCI18002463/Kqd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.