

**TRANS-CAB AUTO SERVICES PTE LTD**

NO.2 ANG MO KIO ST63 SINGAPORE 569111  
 TEL NO. 6287 6666 FAX NO. 6257 1330  
 CO/GST REG NO. 201019626G  
**SHD9958L -**

AAD1802-040

*Not Authorized  
 L1ump @ 7750L*

Vehicle No.:  
 Chassis No.:  
 Vehicle Make:  
 Vehicle Model:  
 Date of Accident :  
 Third Party Insurer :

**SHD9958L - CANDY**  
 VF1ABL15AUC278118  
 RENAULT  
 LATITUDE  
 05.02.2018  
**AIG**

PART		LIST
1	1 BUMPER COVER REAR	\$ <i>Bu</i> 1,108.46 ✓
2	1 BUMPER LOWER REAR	\$ <i>Adidit</i> 768.84 ✓
3	1 BUMPER BRACKET CTR REAR	\$ <i>Sn</i> 113.47 X
4	1 BUMEP R BRACKET SIDE RH REAR	\$ <i>Sn</i> 135.97 X
5	1 BUMEP R RETAINER RH REAR	\$ <i>Sn</i> 44.99 X
6	1 BUMEP R BRACKET SIDE LH REAR	\$ <i>Sn</i> 135.97 X
7	1 BUMEP R RETAINER LH REAR	\$ <i>Dit Sn</i> 44.99 ✓
8	1 BUMPER REFLECTOR LH	\$ <i>CR</i> 43.61 ✓
9	1 BUMPER BEAM REAR	\$ <i>B</i> 777.52 ✓
10	1 BUMPER BEAM BRACKET LH REAR	\$ <i>B</i> 225.95 ✓
11	1 BOOT REAR	\$ <i>R</i> 2,872.68 X
12	1 BOOT FINISHER	\$ <i>Sn</i> 470.06 X
13	1 BOOT WHEATERSTRIP	\$ <i>Sn</i> 323.05 X
14	1 BOOT REFLECTOR LAMP LH	\$ <i>CR</i> 493.35 ✓
15	1 BOOT REFLECTOR LAMP RH	\$ <i>Sn</i> 493.35 X
16	1 BOOT BADGE 'RENAULT'	\$ <i>Ma</i> 225.36 ✓
17	1 BOOT BADGE	\$ <i>Ma</i> 225.36 ✓
18	1 BOOT STRUT LH	\$ <i>Sn</i> 276.08
19	1 BOOT STRUT RH	\$ <i>Sn</i> 276.08
20	1 BOOT HINGE LH	\$ <i>R</i> 367.84
21	1 BOOT HINGE RH	\$ <i>R</i> 367.84
22	1 BOOT SWITCH	\$ <i>SKR</i> 168.13 X
23	1 BOOT LOCK	\$ <i>R</i> 202.67
24	1 BOOT LOCK CATCH	\$ <i>R</i> 74.40
25	2 LICENCE PLATE LAMP	\$ <i>Sn</i> 50.52
26	2 BOOT RUBBER PLUG	\$ <i>Sn</i> 221.81
27	1 FENDER PANEL INNER TRIM REAR LH	\$ <i>Sn</i> 671.45
28	1 FENDER PANEL REAR LH	\$ <i>Bee</i> 3,299.13 ✓
29	1 WHEELARCH REAR LH	\$ <i>Sn</i> 543.47 X
30	1 TAILLAMP RH	\$ <i>Sn</i> 552.55 X
31	1 TAILLAMP PANEL RH	\$ <i>R</i> 986.70 X
32	1 TAILLAMP LH	\$ <i>my CR</i> 552.55 ✓
33	1 TAILLAMP PANEL LH	\$ <i>R</i> 986.70 X
34	1 OUTER PANEL REAR (End Panel)	\$ <i>R</i> 1,471.77 X

**TRANS-CAB AUTO SERVICES PTE LTD**

**AAD1802-040**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

**SHD9958L -**

35 1 OUTER PANEL REAR (End Panel)TRIM \$ *Sm* 404.56 X

<b>TOTAL</b>	\$	<b>19,977.24</b>
<b>10%</b>	\$	<b>1,997.72</b>
	\$	<b>17,979.52</b>

**Special Nett**

1	1SET	PARKING AID	\$	<i>Shon</i> 700.00 ✓
2	1SET	REAR BUMPER CLIP	\$	<i>na</i> 66.00 ✓
3	1SET	BUMPER BRACKET CTR CLIP	\$	<i>na</i> 33.00 ✓
4	1SET	BUMEPR BRACKET SIDE CLIP RH RR	\$	<i>na</i> 10.00 X
5	1SET	BUMEPR RETAINER RH CLIP RR	\$	<i>na</i> 20.00 X
6	1SET	BUMEPR BRACKET SIDE CLIP LH RR	\$	<i>na</i> 10.00 X
7	1SET	BUMEPR RETAINER CLIP LH RR	\$	<i>na</i> 20.00 X
8	1SET	BUMPER LOWER REAR RIVET	\$	<i>na</i> 22.00 X
9	1SET	BUMPER LOWER REAR CLIP	\$	<i>na</i> 66.00 ✓
10	1SET	BOOT FINISHER CLIP	\$	<i>na</i> 24.20 X
11	1	BOOT STICKER "Trans-cab"	\$	<i>na</i> 30.00 ✓
12	1	BOOT STICKER "6555-3333"	\$	<i>na</i> 30.00 ✓
13	1	BOOT INNER TRIM CLIP	\$	<i>na</i> 45.00 X
14	1SET	FENDER WHEELARCH REAR LH CLIP	\$	<i>na</i> 35.00 X
15	1	FENDER INNER TRIM CLIP LH	\$	<i>na</i> 28.00 X
16	1	TAILLAMP CLIP LH	\$	<i>na</i> 5.00 ✓
17	2	REAR WINDSCREEN SELANT	\$	<i>na</i> 80.00 <i>400na</i>
18	1	WINDSCREEN MOULDING	\$	<i>na</i> 100.00 ✓
19	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>na</i> 100.00 <i>300na</i>
20	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	<i>Sm</i> 385.00 X
21	1	SPARE TYRE	\$	<i>Sm</i> 330.00 X

<b>TOTAL</b>	\$	<b>2,139.20</b>
<b>TOTAL PARTS</b>	\$	<b>20,118.72</b>

Putty And Spray Painting Of The Affected Portion.	\$	4,500.00 <i>660</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00 <i>600</i>
To Rust-Proofing Of The Affected Areas.	\$	170.00 <i>300</i>
To reinstall rear bumper parking sensor.	\$	170.00 <i>600</i>

**TRANS-CAB AUTO SERVICES PTE LTD**

**AAD1802-040**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

**SHD9958L -**

To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>nn</i> 170.00	X
To repair and realign rear exhaust pipe.	\$	<i>nn</i> 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>nn</i> 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	} 1001
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	
To supply and re-do rear luggage floor panel insulation padding.	\$	<i>nn</i> 380.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00	X
Towing Fees	\$	<i>nn</i> 120.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	<i>1201</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00	X

<b>TOTAL</b>	<b>\$</b>	<b>11,160.00</b>
<b>Over All Total</b>	<b>\$</b>	<b>31,278.72</b>

**(PARTS BY PARTS)  
Repair Days**

*15Days*

*5 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: