

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

02/02/18 @ 1030hrs
svy only

From :
PEGASUS ENGINEERING & TRADING PTE LTD
C/O 51 DEFU LANE 10
539216

Officer in Charge : ALVIN LOW WAI LUN
Tel :
Email :

Customer :
GRAB RENTALS PTE LTD
18 SIN MING LANE
#01-08 MIDVIEW CITY
SINGAPORE 573960

Attn :
Tel :
Fax :

Quotation No : QO18/01-1158	Quotation Date : 20/01/2018	Terms : 30 DAYS
Vehicle No : SLL8854U	Chassis No : MHFB29F3502007320	Third Party Insurer :
Model : VIOS		Date of Accident :
Remarks : TP INSURER: AIG, INSURED'S VEHICLE NO: SLK3236S, DATE OF ACCIDENT: 12.12.2017		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
1	FRONT BUMPER	1	427.9000	427.90
2	FRONT BUMPER CLIPS	6	4.3000	25.80
3	FRONT BUMPER SIDE RETAINER	2	65.4000	130.80
4	FRONT BUMPER GRILLE	1	276.2000	276.20
5	FRONT BUMPER CHROME GARNISH	2	66.8000	133.60
6	FRONT BUMPER UNDER COVER/SPLASHIELD	1	209.1000	209.10
7	LESS 25% ITEM (1-6)	1	-300.8500	-300.85
8	TO CHECK ELECTRICAL LIGHTING CONCERNED	1	40.0000	40.00
9	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	1	300.0000	300.00
10	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	1	380.0000	380.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

not Allowed
LKK
1/5
2dy.
7/2/18
the photo attached

Sub Total 1,622.55
GST(7.00%) 113.58
Total (SGD) 1,736.13

Please conduct the survey at
Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216