

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9289J - III**AAD1802-043***Not Authorized
11 Sep @ 4850*

Vehicle No.:	SHD9289J - CANDY
Chassis No.:	KL1LA69RJB071017
Vehicle Make:	CHEVROLET
Vehicle Model:	EPICA 2.0
Date of Accident :	03.02.2018
Third Party Insurer :	III

		PART		LIST
1	1	Rear Bumper	\$	B ₁ 1,202.00 ✓
2	1	Rear Bumper Beam	\$	B ₁ 239.94 ✓
3	1	Rear Bumper Centre Absorber	\$	CM 260.00 ✓
4	1	Rear Bumper Side Retainer RH	\$	Sn 68.76 X
5	1	Rear Bumper Side Retainer LH	\$	Dis 68.76 ✓
6	1	Rear Bumper Reflectors RH	\$	CM 119.74 ✓
7	1	Rear Bumper Reflectors LH	\$	B ₁ 119.74 ✓
8	1	Rear Bumper Tow Hook Cover	\$	Sn 93.00 X
9	1	Rear Luggage Floor Panel	\$	R 973.00 X
10	1	Rear Luggage Floor Panel Insulator	\$	Sn 63.50 X
11	1	Rear Luggage Floor Panel Trim Board	\$	Sn 378.00 X
12	1	Rear End Panel Outer	\$	B ₁ 623.76 ✓
13	1	Rear End Panel Inner Trim	\$	Sn 263.84 X
14	1	Bootlid	\$	B ₁ 973.00 ✓
15	1	Bootlid inner trim board	\$	B ₁ 400.00 X
16	1	Bootlid Weatherstrip	\$	174.14 Sn Dist ₁ 344.28 50 Sn
17	1	Bootlid Lock - Top	\$	no 466.56 ✓
18	1	Bootlid 'CHEVROLET' Badge	\$	no 120.62 ✓
19	1	Bootlid Logo	\$	no 138.84 ✓
20	1	Bootlid 'EPICA LT' Badge	\$	no 119.84 ✓
21	1	Bootlid Reflector Centre	\$	Sn 217.97
22	1	Bootlid Reflector RH	\$	Sn 128.40
23	1	Bootlid Reflector LH	\$	Sn 128.40
24	1	Bootlid Hinge RH	\$	R 120.00
25	1	Bootlid Hinge LH	\$	R 120.00
26	1	Rear Tail Lamp RH	\$	Sn 479.30
27	1	Rear Tail Lamp Panel RH	\$	R 359.00
28	1	Rear Tail Lamp LH	\$	Sn 479.30
29	1	Rear Tail Lamp Panel LH	\$	R 359.00
30	1	Rear Exhaust Box (Muffler A-EXH,RR)	\$	R 1,110.00

TRANS-CAB AUTO SERVICES PTE LTD**AAD1802-043**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9289J - III

31	1	Rear Fender RH	\$	<i>R</i> 1,145.00 <i>X</i>
32	1	Rear Fender Inner Trim RH	\$	<i>Sn</i> 418.44 <i>X</i>
33	1	Rear Fender LH	\$	<i>R</i> 1,145.00 <i>X</i>
34	1	Rear Fender Inner Trim LH	\$	<i>Sn</i> 418.44 <i>X</i>

TOTAL	\$	13,665.43
10%	\$	1,366.54
	\$	12,298.89

Specical Nett

1	1Set	Licence Plate With Holder	\$	<i>Sn</i> 60.00 <i>X</i>
2	1Set	Bootlid inner trim board Clip	\$	<i>nn</i> 40.00 <i>X</i>
3	1Set	Rear Bumper Parking Sensor	\$	<i>nd</i> 300.00 <i>✓</i>
4	1Set	Rear Bumper Fastener Clip	\$	<i>nn</i> 44.00 <i>✓</i>
5	1Set	Rear Fender Inner Trim Clip LH	\$	<i>nn</i> 30.00 <i>X</i>
6	1Set	Rear Fender Inner Trim Clip RH	\$	<i>nn</i> 30.00 <i>X</i>
7	1Set	Rear Bumper End Dust Cover Clip	\$	<i>nn</i> 30.00 <i>X</i>
8	1	Rear Boot Sticker 'Trans-cab'	\$	<i>nn</i> 30.00 <i>✓</i>
9	1	Rear Boot Sticker '6555-3333'	\$	<i>nn</i> 30.00 <i>✓</i>
10	1	Rear Exhaust Mounting	\$	<i>Sn</i> 10.00 <i>X</i>
11	2	Rear Windscreen Sealant	\$	<i>nn</i> 80.00 <i>X</i>
12	1	Rear Windscreen Inner Sponge Seal	\$	<i>nn</i> 100.00 <i>X</i>
13	1	Spare Tyre	\$	<i>Sn</i> 180.00 <i>X</i>
14	1	Spare Wheel Rim	\$	<i>Sn</i> 126.74 <i>X</i>

TOTAL	\$	1,090.74
TOTAL PARTS	\$	13,389.63

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of
Parts, Adjust And Realign The Same

\$ 4,050.00 *600*

To Check Electrical Lighting Concerned.

\$ 170.00 *201*

To Rust-Proofing Of The Affected Areas.

\$ 170.00 *601*

Putty And Spray Painting Of The Affected
Portion.

\$ 4,200.00 *600*

TRANS-CAB AUTO SERVICES PTE LTD

AAD1802-043

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9289J - III

To reinstall rear bumper parking sensor.	\$	170.00 <i>601</i>
To transfer of end panel fittings and conduct water seepage test.	\$	<i>nn</i> 170.00 <i>X</i>
To transfer of luggage floor panel fittings and conduct water seepage test.	\$	<i>nn</i> 170.00 <i>X</i>
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	<i>nn</i> 170.00 <i>X</i>
To transfer of boot fittings and conduct water seepage test.	\$	<i>A</i> 170.00 <i>601</i>
Towing fees	\$	<i>nn</i> 120.00 <i>X</i>
To transfer of Fender fittings, attachments and perform water seepage test.	\$	170.00 <i>601</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>Repaired</i> 380.00 <i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00 <i>X</i>
	\$	10,330.00
TOTAL	\$	23,719.63

Repair Days

15 Days
5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: