



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

TPVD NISSAN TEANNA (SDU7898Y)

Date of Loss

3 February 2018

Time of Loss

18.25

Loss Description

SGD4944X (INSD) C/W SDU7898Y

Comment

Workshop Details

Total Rebate Amount

0

Nett Loss Amount

\$0.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (TP)

Target Date of Completion *

11/06/2018



Days of work completion *

125



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#
SDU7898Y

Registration State

SINGAPORE

Mileage

55170

CATEGORY

Manufacturing Year

POLICY INFORMAT...

ASSESSMENT INFO...

Purchase Date

dd/mm/yyyy



Registration Date *

30/10/2015



Age of Vehicle

2

Driver Details

CATEGORY

Driver Name

FNOL INFORMATI...

TAY YEOW CHAI

CATEGORY

Make

POST SURVEY INF...

POLICY INFORMAT... TPVD NISSAN

ASSESSMENT INFO... NISSAN

CATEGORY Model

POLICY INFORMAT... TEANNA

ASSESSMENT INFO... TEANA 2.0 XL CVT

CATEGORY Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT...

ASSESSMENT INFO... MNTBBAL33Z0005076

CATEGORY Date of Birth

FNOL INFORMATI...

POST SURVEY INF... dd/mm/yyyy



CATEGORY Age

FNOL INFORMATI... 0

POST SURVEY INF...

CATEGORY Occupation

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Education Qualification

FNOL INFORMATI... Other

POST SURVEY INF...

CATEGORY Driving Experience

CATEGORY Engine No

POLICY INFORMAT...

ASSESSMENT INFO... MR20041445R

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO... 1997

CATEGORY Sum Insured

POLICY INFORMAT...

ASSESSMENT INFO... 0

CATEGORY Market Value

POLICY INFORMAT...

ASSESSMENT INFO... 0

FNOL INFORMATI... 0

POST SURVEY INF...

CATEGORY Driver License #

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Issue Date

FNOL INFORMATI...

POST SURVEY INF... dd/mm/yyyy

CATEGORY License Expiration Date

FNOL INFORMATI...

POST SURVEY INF... dd/mm/yyyy

CATEGORY Address

FNOL INFORMATI... Singapore

POST SURVEY INF...

CATEGORY

Address type

FNOL INFORMATI...

Personal Correspondence

POST SURVEY INF...

CATEGORY

Gender

FNOL INFORMATI...

Unknown

POST SURVEY INF...

CATEGORY

Marital status

FNOL INFORMATI...

Unknown

POST SURVEY INF...

CATEGORY

Identification #

FNOL INFORMATI...

S1408620Z

POST SURVEY INF...



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

07/02/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

215/55R17

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Tyre Condition

Spare wheel

Rear Tyre Size

215/55R17

Front left side

MICHELIN6mm

Front right side

MICHELIN6mm

Rear left side

MICHELIN6mm

Rear right side

MICHELIN6mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes

No

Part Supplied by AXA

Yes No

Save

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts

Add Approve Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
		1	1			BOOT LID			Damaged	1080.4		30		756.28	Reviewing
		2	1			REAR BUMPER			Deformed	682.7		30		477.89	Reviewing
		3	2			REAR BUMPER BRACKET			Serviceable	0	0	0	0	0	Deny
		4	1			REAR END PANEL			Repair	0	0	0	0	0	Deny
		5	1			REAR END PANEL TOP GARNISH			Deformed	222.6		30		155.82	Reviewing

Labour

Add Approve Deny

EDIT		SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
		1		PANEL BEATING, REMOVAL AND REPLACING PARTS	600	0	0	Reviewing		
		2		TO SPRAY PAINT AFFECTED AREA	600	0	0	Reviewing		
		3		TUFF COAT	0	0	0	Deny		
		4		WIRING CHECK	30	0	0	Reviewing		
		5		REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINING TO FACILITATE REPAIR	40	0	0	Reviewing		

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
		6		REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	50	0	0	Reviewing		
		7		TRANSFER BOOTLID MECHANISM	60	0	0	Reviewing		
		8		TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT / CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC	0	0	0	Deny		

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
☐		1	DAYS OF REPAIR : 5 DAYS	Reviewing			
☐		2	BOOT LID LOGO (DISC 10%) (N)	Reviewing	47.88	NECESSARY	
☐		3	BOOT LID EMBLEM 'TEANA' (DISC 10%) (N)	Reviewing	67.59	NECESSARY	
☐		4	BOOT LID EMBLEM '2.0 XL' (DISC 10%) (N)	Reviewing	58.68	NECESSARY	
☐		5	BOOT LID EMBLEM 'XTRONIC CVT' (DISC 10%) (N)	Reviewing	58.68	NECESSARY	

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		6	BOOT LID TOP LOCK (DISC 10%) (N)	Reviewing	133.11	DAMAGED	
		7	BOOT LID LOWER LOCK	Deny	0	NOT NECESSARY	
		8	BOOT LID DETECTOR (DISC 10%) (N)	Reviewing	346.41	DAMAGED	
		9	BOOT LID WEATHER STRIP	Deny	0	NOT NECESSARY	
		10	REAR BUMPER SIDE RETAINER- 2PCS	Reviewing	100.08	NECESSARY	
		11	REAR BUMPER SPONGE	Reviewing	175.5	CRACKED	
		12	TAIL LAMP (2PCS) (DISC 10%) (N)	Reviewing	440.55	O/S CRACKED	

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
☐		13	REVERSE SENSOR (4PCS) (DISC 10%) (N)	Reviewing	460.08	DAMAGED - 2PCS ONLY	
☐		14	REAR NUMBER PLATE	Deny	0	NOT NECESSARY	
☐		15	BOOT LID SEALANT	Deny	0	NOT NECESSARY	
☐		16	SET REAR BUMPER CLIP	Reviewing	20	NECESSARY	
☐		17	SET TAIL LAMP CLIP	Deny	0	NOT NECESSARY	
☐		18	SET REAR END PANEL TOP GARNISH CLIPS	Reviewing	10	NECESSARY	
☐		19	REAR END PANEL SEALANT	Deny	0	NOT NECESSARY	

Assessment Details

General & Workshop Details		Vehicle & Driver Details		Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
Claim Amount	\$4,688.55			Claim Amount	\$4,688.55			

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$1,380.00	\$1,380.00
Miscellaneous	\$1,918.56	\$1,918.56
Spare Parts	\$1,389.99	\$1,389.99

Submit for Review

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Add

Approve

Deny

EDIT		SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		1	FINAL LUMP SUM	Reviewing	3700		

Assessment Details

General & Workshop Details		Vehicle & Driver Details		Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
Claim Amount	\$3,700.00			Claim Amount	\$3,700.00			

CATEGORY	ESTIMATE	REVISED AMOUNT
Miscellaneous	\$3,700.00	\$3,700.00

Submit for Review