

INS. CASE OWNER:

Pm

CC 4/III1800

WZ1, AKB3

LIC:  
IDAC:

Surveyor:

Adrian

DOI:

ASSIGNMENT

06/02/18

Date / Time:

06/02/18

Registered in Merimen:

7/2/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHO 3195K

Name of Insured:

LTP

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

04/02/18

Is driver the owner?

( YES / NO )

Nature of Accident:

If NO, Driver Name / Age:

ONG POON SOON

Driver Tel No.:

(VA: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

MOMODIS

HYOSUNG

HAWLOK RD LEAS CHIN

CWEE RD

OI GIA REPORT YES / NO : TP GIA REPORT YES / NO

Insured Liability:

%

Final ? Yes / No

SJP 8017L



INSRS:

WSP:

Tel:

Liability:

RMKS:

Yi Hong



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time		STAGE	DATE / PIC
8/2/18	8:15 AM	Non-Reporting Itr (1st):	
		Non-Reporting Itr (2nd):	
		Non-Reporting Itr (Final):	
08/02/18:	FILED REVIEWED. Car at 210 rear-ended.	Notification Itr (if non-pickup):	
	Sec 11 liability mandate via letter.	Call OI:	
		After call Itr to OI:	
19/03/2018:	Confirmed with TP repairer that they do not wish to proceed with no direct settlement.	Documentation Check List:	Handler Typist
		Notification Itr (if non-pickup)	
		After call Itr to OI	
20/03/2018:	Send email to JLE (Pymho) work file.	Authorisation To Act:	
		Release Voucher:	
20/03/2018:	File pass to Shupai to close	Final Repair Bill:	
	RECEIVED 21 MAR 2018	Car Rental Invoice:	
		Towing Invoice:	
		LTA / GIA:	
		Medical Bill:	
		PIR:	
		Mandate/Reject Instruction:	
		LOD:	
		Payment Breakdown Form:	
		Post-Repair Photos:	
		Others:	

<b>PRELIMINARY ADVICE</b>		Date/Time:	Sent By:
<b>FINALIZATION</b>		Date/Time:	Confirm with:
Repair Cost:	SS	( ) days	Reduction: %
<b>FINAL SETTLEMENT</b>		Date/Time:	Confirm with:
Final Liability:	%	(Agreed / Assessed)	BOLA S/N No.:
Repair Cost:	SS		
Loss of Rental (LOR):	SS	( ) days	
Loss of Use (LOU):	SS	(S x days)	
Loss of Income (LOI):	SS	(S x days)	
LOR only <input type="checkbox"/>	LOU only <input type="checkbox"/>	LOR + LOU <input type="checkbox"/>	LOR + LOI <input type="checkbox"/> [Tick only one]
GIA/LTA Search	SS		
Medical:	SS		
Disbursement:	SS	(e.g. Tow/ Independent)	
Legal Cost	SS		
<b>Total:</b>	SS	<b>Global Sum SS:</b>	
<b>FINAL PAYMENT</b>		Date/Time:	Confirm with:
Payee 1:	SS	Name 1:	
Payee 2: (Strike if N.A.)	SS	Name 2:	
Payee 3: (Strike if N.A.)	SS	Name 3:	

CONVARIANT

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$350.00

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV \_\_\_\_\_

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s: \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:		
IDAC Accident Rpt:		Consistent? : Yes or No
GIA / PR Seen:		Consistent? : Yes or No
Est. Repairs:	6 days	Res.: Yes or No
Lum Sum:	20 %	3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT \_\_\_\_\_

Veh No: SJR 8017L Yr Regn: 2009 July  
Type: M.Cycle / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or

Make:	Toyota Vios	cc	1497
Colour:	White.	A/C	Insured / Std / NI / NA
Sp. Reading	148759.	T/Radio:	Insured / Std / NI / NA

Eng/No: \_\_\_\_\_  
C/No: MR053HY9305121505

Gen. Cond: Good / Fair / Poor / Burnt  
Steering: In order / Jammed / Leaked / Burnt or  
Brake: In order / Jammed / Leaked / Burnt or  
Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/55R45  
R: 195/55R45

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front	Rear
R/Bal. <u>06</u> mm	R/Bal. <u>06</u> mm
L/Bal. <u>06</u> mm	L/Bal. <u>06</u> mm
D.O.A.	D.O.I. <u>06/02/18</u>

Survey held at Yithery  
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

N/S	Q/S

Date / Time	Action / Instruction
	TP111 (L/cum: \$3,000.00 / recd: \$3,527.25 / 53%.)

Date/Time: File Pass to? ☐: Prel. Report

[1] ☐ : Final Report

Data/Time: File Returns: 0/0

Report Format :

Lump Sum / I.B.I: (\$

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Transportation

Add Fee:  : Site Insp (\$

Interview (S)

**Tech. Invs** is

Weekend (S

Figure 1



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL		Ref : CC4/III18002471/Akb3		
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 07-02-2018		
		Code : III2		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHD 3195K	Veh. Inspected	SJR 8017L	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	07/02/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	04/02/2018	Inspection Date	06/02/2018	
Survey held at	YI HENG MOTOR WORKSHOP BLK 1 KAKI BUKIT AVE 6 #02-19 SINGAPORE 417883			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

# YI HENG MOTOR WORKSHOP

BLK 1, KAKI BUKIT AVENUE 6  
#02-19, SINGAPORE 417883  
TEL: 6 5090052 FAX: 6 7479402

06-02-18

OUR REF NO. SJR 8017L

TAN CHEE LEONG  
BLK 12, YORK HILL  
#06-50  
SINGAPORE 103012

TPM  
Zaini

## ESTIMATE BILL FOR VEHICLE SJR 8017L MODEL : TOYOTA VIOS

### LIST ITEM

1) BOOT LID	Painted		589.00	✓
2) BOOT LID WEATHERSTRIPE	cut		214.00	✓
3) BOOT LID BADGE	} re		53.00	✓
4) BOOT LID EMBLEM ' VIOS '			48.00	✓
5) BOOT LID EMBLEM ' SPORT '			38.00	✓
6) BOOT LID EMBLEM ' E '			42.00	✓
7) BOOT LID STOPPER	re	2 PCS @ \$ 10.50	21.00	+
8) BOOT LID LOCK	Painted		118.00	✓
9) BOOT LID STRIKER	re		34.00	+
10) BOOT LID HINGE	re	2 PCS @ \$ 114.00	228.00	+
11) TAIL LAMP ASSY	CH changed, RH cut	2 PCS @ \$ 471.00	942.00	656
12) TAIL LAMP BASE PANEL	RH deleted	2 PCS @ \$ 189.00	378.00	189
13) TAIL LAMP CLIP	re	2 PCS @ \$ 18.90	37.80	10
14) REAR BUMPER	Painted		578.00	459
15) REAR BUMPER SIDE ATTACHMENT	re	2 PCS @ \$ 48.30	96.60	✓
16) REAR BUMPER SPOILER	re		1031.00	+
17) REAR BUMPER CLIP	re	6 PCS @ \$ 18.90	113.40	30
18) REAR BUMPER SPLASH SHIELD	2 per	2 PCS @ \$ 118.00	236.00	+
19) REAR BUMPER SPLASH SHIELD CLIP	re	6 PCS @ \$ 12.90	77.40	+
20) REAR END PANEL	Painted		589.00	✓
21) REAR PANEL INNER GARNISH	Painted		211.00	✓
22) REAR PANEL INNER GARNISH CLIP	re	2 PCS @ \$ 12.90	25.80	10

# YI HENG MOTOR WORKSHOP

BLK 1, KAKI BUKIT AVENUE 6  
#02-19, SINGAPORE 417883  
TEL: 6 5090052 FAX: 6 7479402

23) SPARE TYRE BOARD	<i>torn</i>	214.00	<i>✓</i>
24) REAR FLOOR SPONGE	<i>torn</i>	254.00	<i>✓</i>
25) REAR FENDER INNER BOARD	<i>LH torn</i>	<del>790.00</del> 286.50	
26) REAR FENDER INNER BOARD CLIP	<i>10 PCS @ \$ 18.90</i>	189.00	<i>30</i>
27) REAR FENDER (LH)	<i>Ryis</i>	726.00	<i>+</i>
28) REAR WINDSCREEN MOULDING	<i>new</i>	124.00	<i>+</i>
29) REAR EXHAUST CHROME	<i>Best</i>	114.00	<i>✓</i>
30) REAR EXHAUST SILENCER	<i>Best</i>	359.00	<i>✓</i>
31) REAR EXHAUST MOUNTING	<i>2 PCS @ \$ 22.00</i>	44.00	<i>✓</i>
32) REAR BUMPER REFLECTOR	<i>2 PCS @ \$ 174.00</i>	<del>348.00</del> 203.20	
LESS DISCOUNT - 25%		8863.00	
		2215.75	
		6,647.25	

## SPECIAL NETT ITEM

1) REVERSE SENSOR WITH CONTROL UNIT	<i>Ryid</i>	350.00	<i>200</i>
2) REAR WINDSCREEN INNERSEAL	<i>new</i>	60.00	<i>+</i>
3) REAR WINDSCREEN GUM		60.00	<i>+</i>
		470.00	

## LABOUR CHARGE

1) TO CHECK WIRING SYSTEM	50.00	<i>30</i>
2) TO APPLY UNDER SEALING ON AFFECTED AREAS	120.00	<i>50</i>
3) TO REMOVE AND REFIX REAR WINDSCREEN	160.00	<i>+</i>
4) TO REMOVE AND REFIX REVERSE SENSOR WITH CONTROL UNIT	120.00	<i>50</i>
5) TO REMOVE AND REFIX BOOT LID LATCHING AND REALIGNMENT	240.00	<i>60</i>
6) TO REMOVE AND REFIX CUSHION, FLOOR BOARD, ROOF LINING, TRIM, GARNISH, UPHOLSTERY ETC	150.00	<i>60</i>

## 7) TO REMOVE AND REFIX REAR EXHAUST SILENCER

8) TO REPLACE NEW PARTS, CUT, WELD, KNOCK ETC

## 9) TO RESPRAY ON AFFECTED AREAS

Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer  
Signature:

Adrian Cj  
L/S 06/04/18  
06 Lys

2430

1000

10,527.25

total 6240.20

2/5 SK

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	0977H

### Vehicle Details

Vehicle No.:	SJR8017L
Vehicle to be Exported:	Yes
Intended De-registration Date:	06 Feb 2018
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS E AUTO
Primary Colour:	White
Manufacturing Year:	2009
Engine No.:	1NZX937362
Chassis No.:	MR053HY9305121505
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$12,468.00
Original Registration Date:	14 Jul 2009
First Registration Date:	14 Jul 2009
Transfer Count:	1
Actual ARF Paid:	\$12,468.00

### Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Jul 2019
PARF Rebate Amount:	\$6,857.00

### Intended COE Rebate Details

COE Expiry Date:	13 Jul 2019
COE Category:	A - Car (1600cc & below)

## Toyota Vios 1.5A E

<b>Price</b>	<b>\$22,800</b>
<b>Reg date</b>	11-Jun-2009
<b>Manufactured</b>	2009
<b>Mileage</b>	-
<b>Transmission</b>	Auto
<b>Engine Capacity</b>	1,497 cc
<b>Road Tax</b>	\$684 per year
<b>Power</b>	80.0 kW (107 bhp)
<b>Curb Weight</b>	1,095 kg
<b>Features</b>	1.5L DOHC VVT-i Engine, Automatic Transmission, SRS Airbags, Reverse Sensors.
<b>Accessories</b>	Sport Rims, Factory Fitted Audio System, Front Recording Camera, Electrical Retractable Side Mirrors With Indicator, Upholstery Leather Seats.
<b>Description</b>	Very Low Mileage! Extended Warranty Available! Very Affordable! Plenty Of Spare Parts Available! Well Kept By Previous Owner In Tip Top Condition, A Practical And Sporty Car That You Must Own! Buy It From Us With A Peace Of Mind, A Company Accredited With Outstanding Awards, Professional After Sales Service Assured. Drop By Our Air-con Showroom To Appreciate It In Pristine Condition Today!
<b>COE</b>	\$7,090
<b>OMV</b>	\$12,468
<b>ARF</b>	\$12,468
<b>Depreciation</b>	\$12,370 / year
<b>No. of owners</b>	2
<b>Type of Vehicle</b>	Mid-Sized Sedan
<b>Availability</b>	Available

### Seller Information

<b>Company</b>	Dickson Automobile = dealer's pricelist = 72 vehs sold   256 vehs available	
<b>Address</b>	55 Ubi Avenue 3 #01-01	
<b>Website</b>	dicksonauto.com.sg	
<b>Office No</b>	68447667	
<b>Contact Person(s)</b>	Eric Lee	91827304
	Ricky Eng	91853390
	Jonathan Quah	91901666

Posted on : 30-Dec-2017

Last Updated : 30-Dec-2017



## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 0977H

### Vehicle Details

Vehicle No.: SJR8017L

Vehicle to be Exported: Yes

Intended De-registration Date: 06 Feb 2018

Vehicle Make: TOYOTA

Vehicle Model: VIOS E AUTO

Primary Colour: White

Manufacturing Year: 2009

Engine No.: 1NZX937362

Chassis No.: MR053HY9305121505

Maximum Power Output: 80.0 kW (107 bhp)

Open Market Value: \$12,468.00

Original Registration Date: 14 Jul 2009

First Registration Date: 14 Jul 2009

Transfer Count: 1

Actual ARF Paid: \$12,468.00

### Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 13 Jul 2019

PARF Rebate Amount: \$6,857.00

### Intended COE Rebate Details

COE Expiry Date: 13 Jul 2019

COE Category: A - Car (1600cc & below)



## Catherine Chong (LKK Auto)

---

**From:** Motor Claim - III <motorclaim@iii.com.sg>  
**Sent:** Tuesday, 6 February, 2018 3:50 PM  
**To:** Yong Patric Yong; Legal Asia; 'sur@lkkauto.com'; Catherine Chong (LKK Auto)  
**Cc:** Marcus Phuah; Manivel Priyadarshini  
**Subject:** RE: RE:  
**Attachments:** 20180204 - III Request for Accident Report SJL8017L.PDF

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SJR8017L and let us have your report urgently.

This claim will be handled by Ms Priya.

\*Kindly upload this survey request email to merimen.

Thank You.

*Adrian*

*Best Regards,*

**Gabriel Wee**

Motor Claims Dept.

**India International Insurance Pte Ltd**

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

---

**From:** Yong Patric Yong [mailto:yihengmotorworkshop@yahoo.com.sg]  
**Sent:** 06 February, 2018 1:54 PM  
**To:** Legal Asia <legalasia@legalasia.net>; Motor Claim - III <motorclaim@iii.com.sg>  
**Cc:** Marcus Phuah <marcus@legalasia.net>  
**Subject:** Re: RE:

Hi,

We choose LKK Auto Consultants Pte Ltd.

From,  
Wan Ping

On Tuesday, 6 February 2018 01:44:40 PM, Motor Claim - III <motorclaim@iii.com.sg> wrote:

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

*Best Regards,*

**Gabriel Wee**

Motor Claims Dept.  
India International Insurance Pte Ltd  
64 Cecil Street | #05 IOB Building | Singapore 049711  
Tel: 6347 6100, Ext - 248

**From:** Legal Asia [<mailto:legalasia@legalasia.net>]

**Sent:** 06 February, 2018 11:46 AM

**To:** Motor Claim - III <[motorclaim@iii.com.sg](mailto:motorclaim@iii.com.sg)>

**Cc:** Marcus Phuah <[marcus@legalasia.net](mailto:marcus@legalasia.net)>; Yong Patric Yong <[yihengmotorworkshop@yahoo.com.sg](mailto:yihengmotorworkshop@yahoo.com.sg)>

**Subject:**

Dear Motor Claim

Kindly do the Pre Repair inspection on our Client's car SJR 8017L which was involved in accident with your insured taxi SHD 3195K,

Thank you.

Yours sincerely,

Andra Ou

*Personal Assistant to Mr. Marcus Phuah*

Marcus Phuah & Co.

Advocates & Solicitors

潘国良律师事务所

Income @ Raffles Building

16 Collyer Quay

Level 20 Suite 27

Singapore 049318

Website: <http://www.legalasia.net>

Email: [legalasia@legalasia.net](mailto:legalasia@legalasia.net)

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

**DISCLAIMER:**

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

**DISCLAIMER:**

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission

or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

## **Zaini (LKK Auto)**

---

**From:** Zaini (LKK Auto)  
**Sent:** Tuesday, 20 March 2018 12:21 PM  
**To:** manivel@iii.com.sg  
**Cc:** Hsiao Tong (LKKAuto)  
**Subject:** Your Ref: MCT18020118\_ACCIDENT INVOLVING SHD 3195K AND SJR 8017L ON 04.02.2018

### **WITHOUT PREJUDICE**

Our Ref: CC4/III18002471/Akb3  
Your Ref: MCT18020118

Dear Priya,

### **ACCIDENT INVOLVING SHD 3195K AND SJR 8017L ON 04.02.2018**

We refer to the above matter.

Kindly take note that we were informed by TP repairer that they do not wish to proceed with the direct settlement for the above matter.

As such, we will submit our survey report and close the file on our end.

Thank you.

Best Regards,

**Zaini Kusaini** | Case Handler

**LKK Auto Consultants Pte Ltd**

DIC: 6841-2132 | email: [Zaini@lkkauto.com](mailto:Zaini@lkkauto.com) | Fax: 6741-4108

Blk 51, PayaUbi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## Zaini (LKK Auto)

---

**From:** Zaini (LKK Auto)  
**Sent:** Tuesday, 20 March 2018 12:21 PM  
**To:** manivel@iii.com.sg  
**Cc:** Hsiao Tong (LKKAuto)  
**Subject:** Your Ref: MCT18020118\_ACCIDENT INVOLVING SHD 3195K AND SJR 8017L ON 04.02.2018

### WITHOUT PREJUDICE

Our Ref: CC4/III18002471/Akb3  
Your Ref: MCT18020118

Dear Priya,

### ACCIDENT INVOLVING SHD 3195K AND SJR 8017L ON 04.02.2018

We refer to the above matter.

Kindly take note that we were informed by TP repairer that they do not wish to proceed with the direct settlement for the above matter.

As such, we will submit our survey report and close the file on our end.

Thank you.

Best Regards,

Zaini Kusaini | Case Handler

LKK Auto Consultants Pte Ltd

DID: 4841-2132 | email: [zaini@lkkauto.com](mailto:zaini@lkkauto.com) | fax: 6741-4108

Blk 51, Payasibi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

WP

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Feb 2018 <a href="#">Edit Reg</a>		06 Feb 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$5,000.00</b> <a href="#">Edit Estimates</a>	<b>S\$5,000.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:		COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R							
Main Claimant:		TAN CHEE LEONG, ID: 57720977H							
Vehicle Reg. No.:		SJR8017L	Date of Loss:	04/02/2018 20:00 - :59					
Claim Type:		TP / MCT18020118	Policy/Cover Note No.:	MCOM0015					
Vehicle Reg. No. (Insured):		SHD3195K	Policy No. (Claimant):	5094919235					
		Excess:							
Repairer:		Yi Heng Motor Workshop (HQ) Blk 1 Kaki Bt Ave 6 #02-19, 417883 Kaki Bukit - Tel:							
Handling Insurer:		India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Priya]							
Claimant's Insurer:		NTUC Income Insurance Co-operative Ltd (HQ) - Tel:							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 19/02/2018]							
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>III_SG (08/02/2018): Alert - Adj Mandate Approved (S\$0.00) - SJR8017L - Claim Handler: Priya</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SJR8017L (MCT18020118)

[SHD3195K]




































TP

TAN CHEE LEONG

Feb 4 2018 8:00PM

[COMFORT TRANSPORTATION PTE LTD]

Yi Heng Motor Workshop

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images						3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail	Print		
1	16/03/18 14:51	General View					Load JPG	<input checked="" type="checkbox"/>	
2	16/03/18 14:51	Chassis Number					Load JPG	<input checked="" type="checkbox"/>	
3	16/03/18 14:51	General View					Load JPG	<input checked="" type="checkbox"/>	
4	16/03/18 14:51	General View					Load JPG	<input checked="" type="checkbox"/>	
5	16/03/18 14:51	General View					Load JPG	<input checked="" type="checkbox"/>	
6	16/03/18 14:51	General View					Load JPG	<input checked="" type="checkbox"/>	
7	16/03/18 14:51	General View					Load JPG	<input checked="" type="checkbox"/>	
8	16/03/18 14:51	General View					Load JPG	<input checked="" type="checkbox"/>	
9	16/03/18 14:51	General View					Load JPG	<input checked="" type="checkbox"/>	
10	16/03/18 14:51	General View					Load JPG	<input checked="" type="checkbox"/>	
11	16/03/18 14:51	General View					Load JPG	<input checked="" type="checkbox"/>	
12	16/03/18 14:51	General View					Load JPG	<input checked="" type="checkbox"/>	
13	16/03/18 14:51	General View					Load JPG	<input checked="" type="checkbox"/>	
14	16/03/18 14:51	General View					Load JPG	<input checked="" type="checkbox"/>	
15	16/03/18 14:51	General View					Load JPG	<input checked="" type="checkbox"/>	
16	16/03/18 14:51	General View					Load JPG	<input checked="" type="checkbox"/>	
17	16/03/18 14:51	General View					Load JPG	<input checked="" type="checkbox"/>	
18	16/03/18 14:51	General View					Load JPG	<input checked="" type="checkbox"/>	
19	16/03/18 14:51	General View					Load JPG	<input checked="" type="checkbox"/>	
20	16/03/18 14:51	General View					Load JPG	<input checked="" type="checkbox"/>	
21	16/03/18 14:51	General View					Load JPG	<input checked="" type="checkbox"/>	
22	16/03/18 14:51	General View					Load JPG	<input checked="" type="checkbox"/>	
23	16/03/18 14:51	General View					Load JPG	<input checked="" type="checkbox"/>	
24	16/03/18 14:51	General View					Load JPG	<input checked="" type="checkbox"/>	
25	16/03/18 14:51	General View					Load JPG	<input checked="" type="checkbox"/>	
26	16/03/18 14:51	General View					Load JPG	<input checked="" type="checkbox"/>	
27	16/03/18 14:51	General View					Load JPG	<input checked="" type="checkbox"/>	
28	16/03/18 14:51	General View					Load JPG	<input checked="" type="checkbox"/>	
29	16/03/18 14:51	General View					Load JPG	<input checked="" type="checkbox"/>	
30	16/03/18 14:51	General View					Load JPG	<input checked="" type="checkbox"/>	
31	16/03/18 14:51	General View					Load JPG	<input checked="" type="checkbox"/>	
32	16/03/18 14:51	General View					Load JPG	<input checked="" type="checkbox"/>	
33	16/03/18 14:51	General View					Load JPG	<input checked="" type="checkbox"/>	
34	16/03/18 14:51	General View					Load JPG	<input checked="" type="checkbox"/>	
35	16/03/18 14:51	General View					Load JPG	<input checked="" type="checkbox"/>	



36	16/03/18 14:51	General View	1	Load JPG	<input checked="" type="checkbox"/>
37	16/03/18 14:51	General View	1	Load JPG	<input checked="" type="checkbox"/>
38	16/03/18 14:51	General View	1	Load JPG	<input checked="" type="checkbox"/>
39	16/03/18 14:51	General View	1	Load JPG	<input checked="" type="checkbox"/>
40	16/03/18 14:51	General View	1	Load JPG	<input checked="" type="checkbox"/>
41	16/03/18 14:51	General View	1	Load JPG	<input checked="" type="checkbox"/>
42	16/03/18 14:51	General View	1	Load JPG	<input checked="" type="checkbox"/>
43	16/03/18 14:51	General View	1	Load JPG	<input checked="" type="checkbox"/>
44	16/03/18 14:51	General View	1	Load JPG	<input checked="" type="checkbox"/>
45	16/03/18 14:51	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
46	16/03/18 14:51	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
47	16/03/18 14:51	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
48	16/03/18 14:51	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
49	16/03/18 14:51	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
50	16/03/18 14:51	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
51	16/03/18 14:51	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
52	16/03/18 14:51	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
53	16/03/18 14:51	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
54	16/03/18 14:51	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
55	16/03/18 14:51	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
56	16/03/18 14:51	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
57	16/03/18 14:51	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
58	16/03/18 14:51	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
59	16/03/18 14:51	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
60	16/03/18 14:51	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
61	16/03/18 14:51	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
62	16/03/18 14:51	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
63	16/03/18 14:51	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
64	16/03/18 14:51	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
65	16/03/18 14:51	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
66	16/03/18 14:51	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
67	16/03/18 14:51	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
68	16/03/18 14:51	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
69	16/03/18 14:51	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
70	16/03/18 14:51	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
71	16/03/18 14:51	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
72	16/03/18 14:51	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
73	16/03/18 14:51	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
74	16/03/18 14:51	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
75	16/03/18 14:51	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
76	16/03/18 14:51	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
77	16/03/18 14:51	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
78	16/03/18 14:51	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
79	16/03/18 14:51	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
80	16/03/18 14:51	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
81	16/03/18 14:51	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
82	16/03/18 14:51	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
83	16/03/18 14:51	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
84	16/03/18 14:51	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
85	16/03/18 14:51	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>

86	16/03/18 14:51	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
87	16/03/18 14:51	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
88	16/03/18 14:51	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
89	16/03/18 14:51	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
90	16/03/18 14:51	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
91	16/03/18 14:51	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
92	16/03/18 14:51	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
93	16/03/18 14:51	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
94	16/03/18 14:51	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
95	16/03/18 14:51	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
96	16/03/18 14:51	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
97	16/03/18 14:51	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
98	16/03/18 14:51	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
99	16/03/18 14:51	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
100	16/03/18 14:51	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
101	16/03/18 14:51	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>					
				1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	07/02/18 14:55	EMAIL FROM III DD 07022018	1	Load PDF	
2	07/02/18 14:55	NOTICE	1	Load PDF	
3	07/02/18 16:58	TP POLICE REPORT	1	Load PDF	
4	07/02/18 16:58	TP GIA REPORT	1	Load PDF	
5	20/03/18 12:25	TP ESTIMATE - MARKED.	1	Load PDF	
6	20/03/18 13:50	EMAIL TO III SUBMIT REPORT.	1	Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print
1	08/02/18 08:59	Singapore Accident Statement	1	Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 100px; width: 100%;"></div>				
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18002471/AKB3Q2

Date: 26/03/2018

## REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015  
 Claimant Vehicle No: SJR8017L Insured Vehicle No: SHD3195K  
 Date of Loss: 04/02/2018 Nature of Claim: TP Claim No: MCT18020118

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SJR8017L  
 Make & Model: TOYOTA VIOS, 1.5 (A) Engine No: 1NZX937362  
 Reg. Date: 14/07/2009 (Man. Year: 2009) Chassis No: MR053HY9305121505  
 Colour: White Odometer: 148759 km  
 Engine Capacity: 1497 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

## CONDITION OF TYRES

Front Tyre Size: 195/55 R15 Rear Tyre Size: 195/55 R15  
 Front Left Side: Toyo 6 mm Rear Left Side: Toyo 6 mm  
 Front Right Side: Toyo 6 mm Rear Right Side: Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,117.25	3,809.97	3,307.28	46.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,410.00	2,430.00	980.00	28.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,527.25</b>	<b>6,239.97</b>	<b>4,287.28</b>	<b>40.73</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,000.00</b>		
<b>Nett Amount (S\$)</b>	<b>10,527.25</b>	<b>5,000.00</b>	<b>5,527.25</b>	<b>52.50</b>

## INSPECTION

Date of Assignment: 06/02/2018  
 Date Inspected: 06/02/2018 Inspected At: Yi Heng Motor Workshop (HQ)  
 Blk 1 Kaki Bt Ave 6 #02-19  
 Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: Zaini Bin Kusaini

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 26 Mar 2018)
<b>Parts:</b>	143	TOYOTA VIOS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJR8017L)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Buckled	589.00 FL	*589.00 FL
2	1		*BOOT LID WEATHERSTRIP	Cut	214.00 FL	*214.00 FL
3	1		*BOOT LID BADGE	Necessary	53.00 FL	*53.00 FL
4	1		*BOOT LID EMBLEM VIOS	Necessary	48.00 FL	*48.00 FL
5	1		*BOOT LID EMBLEM SPORT	Necessary	38.00 FL	*38.00 FL
6	1		*BOOT LID EMBLEM E	Necessary	42.00 FL	*42.00 FL
7	2		*BOOT LID STOPPER	Not Necessary	21.00 FL	*- FL
8	1		*BOOT LID LOCK	Damaged	118.00 FL	*118.00 FL
9	1		*BOOT LID STRIKER	Not Necessary	34.00 FL	*- FL
10	2		*BOOT LID HINGE	Not Necessary	228.00 FL	*- FL
11	2		*TAIL LAMP ASSY	N/S Cracked / O/S Cut	942.00 FL	*656.00 FL
12	1		*TAIL LAMP BASE PANEL	N/S Dented	378.00 FL	*189.00 FL
13	2		*TAIL LAMP CLIP	Necessary	37.80 FL	*10.00 FL
14	1		*REAR BUMPER	Deformed	578.00 FL	*459.00 FL
15	2		*REAR BUMPER SIDE ATTACHMENT	Necessary	96.60 FL	*96.60 FL
16	1		*REAR BUMPER SPOILER	Not Necessary	1,031.00 FL	*- FL
17	6		*REAR BUMPER CLIP	Necessary	113.40 FL	*30.00 FL
18	2		*REAR BUMPER SPLASH SHIELD	Not Necessary	236.00 FL	*- FL
19	6		*REAR BUMPER SPLASH SHIELD CLIP	Not Necessary	77.40 FL	*- FL
20	1		*REAR END PANEL	Dented	589.00 FL	*589.00 FL
21	1		*REAR PANEL INNER GARNISH	Deformed	211.00 FL	*211.00 FL
22	2		*REAR PANEL INNER GARNISH CLIP	Necessary	25.80 FL	*10.00 FL
23	1		*SPARE TYRE BOARD	Torn	214.00 FL	*214.00 FL
24	2		*REAR FLOOR SPONGE	Torn	254.00 FL	*254.00 FL
25	1		*REAR FENDER INNER BOARD	N/S Torn	790.00 FL	*286.50 FL
26	10		*REAR FENDER INNER BOARD CLIP	Necessary	189.00 FL	*30.00 FL
27	1		*REAR FENDER (LH)	Repair	726.00 FL	*- FL
28	1		*REAR WINDSCREEN MOULDING	Not Necessary	124.00 FL	*- FL
29	1		*REAR EXHAUST CHROME	Bent	114.00 FL	*114.00 FL
30	1		*REAR EXHAUST SILENCER	Bent	359.00 FL	*359.00 FL
31	2		*REAR EXHAUST MOUNTING	Not Necessary	44.00 FL	*- FL
32	2		*REAR BUMPER REFLECTOR	Cracked	348.00 FL	*203.20 FL
33	1		*REVERSE SENSOR WITH CONTROL UNIT	Damaged	350.00 FS	*200.00 FS
34	1		*REAR WINDSCREEN INNERSEAL	Not Necessary	60.00 FS	*- FS
35	1		*REAR WINDSCREEN GUM	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>9,333.00</b>	<b>5,013.30</b>
<b>- List Item Discount on L Items 25.00/25.00% (S\$)</b>	<b>2,215.75</b>	<b>1,203.33</b>
<b>Total Parts (S\$)</b>	<b>7,117.25</b>	<b>3,809.97</b>

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING SYSTEM	New	50.00	30.00
2	TO APPLY UNDER SEALING ON AFFECTED AREAS	New	120.00	50.00
3	TO REMOVE AND REFIX REAR WINDSCREEN	New	160.00	0.00
4	TO REMOVE AND REFIX REFIX REVERSE SENSOR WITH CONTROL UNIT	New	120.00	50.00
5	TO REMOVE AND REFIX BOOT LID FITTING AND REALIGNMENT	New	240.00	60.00
6	TO REMOVE AND REFIX CUSHION ,FLOOR BOARD ,ROOF LINING, TRIM GARNISH UPHOLSTERY ETC	New	150.00	60.00
7	TO REMOVE AND REFIX REAR EXHAUST SILENCER	New	150.00	80.00
8	TO REPLACE NEW PARTS ,CUT ,WELD ,KNOCK ETC	New	1,100.00	1,000.00
9	TO RESPRAY ON AFFECTED AREAS	New	1,320.00	1,100.00
Gross Labour Cost (S\$)			<b>3,410.00</b>	<b>2,430.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >