

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

7-Feb-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6327 H

1 pc	Rear bumper	✓	\$	696.00
1 pc	Rear bumper lower cover	✓	\$	206.00
1 pc	Rear bumper o/s side bracket @ \$29.00	✗	\$	29.00
1 pc	Rear bumper inner sponge	✗	\$	114.00
1 pc	Rear bumper reinforcement	✗	\$	607.00
1 pc	Rear bumper o/s stay @ \$53.00	✗	\$	53.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00	✗	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00	✗	\$	36.00
				<hr/>
				\$ 1,777.00
				<hr/>
				Less 10%
				\$ 177.70
				<hr/>
				\$ 1,599.30

S/NETT

1 set	Rear bumper clips	✓	\$	48.00
1 set	Reverse sensor	✓	\$	280.00 200
Sundry				\$ 50.00 ✗
To dismantle / replace/test reverse sensor to new bumper and reset to the same				\$ 120.00 20
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.				\$ 180.00 ✗
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same				\$ 450.00 200
To putty and spray painting on rear bumper				\$ 200.00 180
To apply rustproofing on the repaired and replaced panels.				\$ 200.00 ✗
				<hr/>
				\$ 3,127.30

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kelvin (LKK)
7/2/18 0950 hrs
2 B.T.
L/S
After Repair p/b

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: