

SMRT Accident Vehicle Repair Estimates

AxA

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB5816A
 Ref. No : TAX/02/18/2035
 Reg. Date : 27/02/2013
 Vehicle Type : TAXI
 Make : CHEVROLET EPICA 2.0 VCDI
 Model : EPICA-2.0
 Name of Driver : TEOH PAK SUN
 Type of Accident : HEAD TO SIDE
 Date / Time of Accident : 05/02/2018 09:30:00 PM
 Accident Reported Date / Time : 06/02/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024094506
 Special Instruction to ARC, if any :
 TOWED \$40 / UNKNOWN
 Prepared Date : 06/02/2018 02:08:02 PM



Sebastian.
 7/2/18.
 - Lump Sum Repair.
 - Question Mark Item
 Photo
 - Photo After Paint.

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : KL1LA69RJBB134851

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	1,690.00	0.00
Total Spray Painting Charges :	2,772.00	0.00
Total Material Charges :	9,937.80	9,937.80
Other Charges :	1,120.00	0.00
TOTAL :	15,519.80	0.00
Lum Sum Total :	15,500.00	0.00
No. of Repair Days :	10.00	0.00
Prepared / Adjusted By :		5 days.
Arc / Surveyor Sign Off Date :	07/02/2018 09:21:51 AM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 07/02/2018 09:21:51 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	1,690.00	0.00 800
Total Labour	1,690.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY REAR FENDER RH	378.00	0.00 200
TO RESPRAY RH REAR WHEEL HOUSE	180.00	0.00
TO RESPRAY REAR DOOR RH	378.00	0.00 200
TO RESPRAY ROCKER PANEL MOULDING	180.00	0.00 100
TO RESPRAY ROCKER PANEL	180.00	0.00 100
TO RESPRAY SILL MEMBER PANEL RH	180.00	0.00 100
TO RESPRAY RIM	180.00	0.00 50
TO RESPRAY FRONT DOOR RH	378.00	0.00 200
TO RESPRAY CENTER PILLAR RH	180.00	0.00 100
TO RESPRAY PANEL SIDE ROOF RH	180.00	0.00 X
Total Spray Painting & Panel Beating	2,772.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	80.00	0.00 ✓
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 40
TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	0.00 60
TO TRANSFER DOOR MECHANISM	240.00	0.00 120
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0.00 60
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0.00 30
TO REMOVE AND REFIT TYRE	120.00	0.00 X
TO REPLACE SUNDRY PARTS	100.00	0.00 20
TO WASH AND VACUUM	60.00	0.00 X
Total Other Costs	1,120.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
93745100	REAR	6504569	BUMPER RR	1	1,238.00	10.00	1,114.20	Replace	Replace ✓	No TN
96633534	REAR		BRACKET RR BUMPER SIDE RH	1	49.00	10.00	44.10	Replace	Replace ✓	No NEC
96632800	REAR	6504638	FENDER RH REAR	1	1,467.00	10.00	1,320.30	Replace	Replace ✓	No BT
	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace ✓	No NEC
	COMMON		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace ✓	No NEC
			LINER RH REAR FENDER (PROTECTOR)	1	65.00	10.00	58.50	Replace	Replace ?	No
96632584	BODY		WHEEL HOUSE INNER RH	1	734.27	10.00	660.84	Replace	Replace ✓	No
96635656	DOOR	6504604	PANEL RH REAR DOOR	1	1,863.00	10.00	1,676.70	Replace	Replace ✓	No
	COMMON		STICKER DECAL 6555 8888 (DOOR)	1	60.00	0.00	60.00	Replace	Replace ✓	No NEC
96635362	DOOR		REGULATOR W/GLASS RR RH	1	94.00	10.00	84.60	Replace	Replace ?	No
			MOTOR POWER WINDOW RH REAR	1	294.85	10.00	265.36	Replace	Replace ?	No
	DOOR		HINGE RR DOOR LOWER RH	1	24.00	10.00	21.60	Replace	Replace ✓	No BT
	DOOR		HINGE RR DOOR UPPER RH	1	30.00	10.00	27.00	Replace	Replace ✓	No BT
96635999	DOOR	6504605	CHECK REAR DOOR RH	1	22.00	10.00	19.80	Replace	Replace ✓	No
96851985	DOOR		LATCH REAR DOOR RH	1	539.00	10.00	485.10	Replace	Replace ?	No
	COMMON		HANDLE DOOR OUTER RH	1	60.00	10.00	54.00	Replace	Replace ✓	No SCR
			RH REAR, DOOR TOP BELT	1	85.87	10.00	77.28	Replace	Replace ✓	No NEC
96836524	DOOR		GLASS RUN RR DOOR RH	1	81.00	10.00	72.90	Replace	Replace ?	No
96635862	DOOR	6504556	W/STRIP QUARTER GLASS RH	1	23.00	10.00	20.70	Replace	Replace ✓	No NEC
96635890	DOOR		W/STRIP RR DOOR RH	1	71.00	10.00	63.90	Replace	Replace ✓	No
96635878	DOOR		RH REAR DOOR GARNISH	1	36.00	10.00	32.40	Replace	Replace ✓	No TN
96483050	DOOR		W/STRIP RR DOOR LOWER RH	1	5.00	10.00	4.50	Replace	Replace ✓	No NEC
96862916			W/STRIP A-DR OPG,RR RH	1	43.00	10.00	38.70	Replace	Replace ✓	No NEC
96862740	DOOR		TRIM RR DOOR RH	1	474.00	10.00	426.60	Replace	Replace ?	No
96466369			COVER A-ROCKER PNL,RR	1	23.00	10.00	20.70	Replace	Replace ✓	No
9637805	INTER RM		GARNISH LOWER CENTRE PILLAR RH	1	54.00	10.00	48.60	Replace	Replace ?	No
9632796			PANEL-ROCKER RH	1	597.00	10.00	537.30	Replace	Replace ✓	No DT
96397252			SILLMEMBER RH (ROCKER PNL)	1	503.00	10.00	452.70	Replace	Replace ✓	No OT
9634088	RIGHT	6504610	MOLDING PANEL RH ROCKER	1	304.00	10.00	273.60	Replace	Replace ✓	No CRK

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
-	COMMON	6504666	TYRE RIM	1	328.99	0.00	328.99	Replace	Replace R	No Yes
	COMMON	6503708	TYRE	1	126.74	0.00	126.74	Replace	Replace 60% ✓	No cut 076
6452311	COMMON		CAP HUB	1	21.95	10.00	19.75	Replace	Replace X	No
6635578	DOOR	6504597	PANEL RH FRONT DOOR	1	2,020.00	10.00	1,818.00	Replace	Replace ✓	No 07
	DOOR		SMRT LOGO DOOR	1	60.00	0.00	60.00	Replace	Replace ✓	No N5C
6635812	DOOR		GARNISH FRT DOOR CTR RH	1	36.00	10.00	32.40	Replace	Replace ✓	No N5C
6836522	DOOR		GLASS RUN FRT DOOR RH	1	80.00	10.00	72.00	Replace	Replace ?	No
6635832	DOOR		W/STRIP FRT DOOR RH	1	144.00	10.00	129.60	Replace	Replace X	No
6326749	DOOR	6504600	HINGE DOOR LOWER RH FRT	1	75.00	10.00	67.50	Replace	Replace X	No
6326750	DOOR	6504602	HINGE DOOR UPPER RH FRT	1	75.00	10.00	67.50	Replace	Replace X	No
6326817	DOOR	6504598	CHECK FRONT DOOR RH	1	25.00	10.00	22.50	Replace	Replace X	No
6632590			REINF A-RR PILLAR RH	1	105.00	10.00	94.50	Replace	Replace ?	No
			PILLAR CTR RH	1	574.21	10.00	516.79	Replace	Replace ?	No
6632794	RIGHT		PANEL-SIDE, ROOF RH	1	597.00	10.00	537.30	Replace	Replace ?	No
TOTAL MATERIALS							11,884.97	11,884.95		
TOTAL MATERIALS(Discounted)							9,937.80	9,937.80		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									