

BY:

REF:

CS/MG/18002495/T146

Special Instruction:

Supervisor:

Taufik

ASSIGNMENT (Office)

From (Person):

Clara Mula

of

MG

Date/Time:

09/02/2018 10:48am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKA 16818

Insured:

at Workshop m/s

Pertumana

Tel:

of

303 Alexandra Rd

Policy No:

290111630 BMY

Claim No:

548846

Sum Insured:

Excess:

\$ 700.00

Make of Veh:

D.O.A.

05.0.2018

(Client's Record)

CA / REY / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

09/02/2018 3:15am

Person Contacted:

Chia

Vehicle: IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SKA 16818 - X

8/2-

Report via merimen

09/2/18@

3:12pm Chen How informed C/A via Merimen.

09/2/18@

3:39pm Informed Mr Chen C/A & Ex: \$ 700 by email.

Part Bay Part \$16,154.55 (Red: 12273.10 !43%)

Copyright © 2007 John Wiley & Sons, Ltd.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18002495/T1tb

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 07-02-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.		Veh. Inspected	SKA 1681S
Policy No.	29014630QMY	Coverage (\$)	0.00
Claim No.	548846	Excess (\$)	700.00
Assign From	MERIMEN (CLARA MILAH)	Assign Date	07/02/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer		Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	05/02/2018	Inspection Date	07/02/2018
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Friday, 9 February 2018 3:39 PM
To: Chua Kee Sin
Cc: SUR
Subject: VEHICLE SKA 1681S (DOA: 05/02/2018)

Dear Mr Chua,

As instructed by our client, please proceed to repair the insured vehicle **SKA 1681S (excess \$700/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	07 Feb 2018 10:40	Cim Veh Model Changed	(204922) BMW 520I 2.0 AT D/AB 2WD 4DR LED NAV (A).	[I] Clara Milah Yeo
2	07 Feb 2018 10:40	Cim Created	Reg No: SKA1681S, Policy No: 29014630QMY, Acct Date: 2018/02/05, Claim Type: OD, Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ), Workshop: Performance Motors Limited (Alexandra), Ins.Status => Incoming Claim, Created from SA S:MPML18018564	[I] Clara Milah Yeo
3	07 Feb 2018 10:48	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):Please revert. Thanks.	[I] Clara Milah Yeo
4	07 Feb 2018 10:48	Adj Next Rpt Changed	Next Rpt:Im. Advice, Due Date:2018/02/08	[I] Clara Milah Yeo
5	07 Feb 2018 10:48	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.	[I] Clara Milah Yeo
6	07 Feb 2018 15:13	Assignment 1st Accessed		[A] CATHERINE CHONG KAI LING
7	07 Feb 2018 16:56	Adj Adjuster Assigned	[None] -> MOHD TAUFIKH BIN HAMID	[A] CATHERINE CHONG KAI LING
8	08 Feb 2018 14:41	Adj Rpt Initiated		[A] DENISE TAY KWEE CHENG
9	08 Feb 2018 16:03	Adj Im. Advice Submitted	Next Rpt:Final Rpt, Due Date:2018/03/09	[A] DENISE TAY KWEE CHENG
10	08 Feb 2018 16:03	Adj Next Rpt Changed	Next Rpt:Final Rpt, Due Date:2018/03/09	[A] DENISE TAY KWEE CHENG
11	08 Feb 2018 16:09	Adj Mandate Request	Cur.Req:19353.60:DAMAGE CONSISTENT REPAIR COST ECONOMICAL	[A] DENISE TAY KWEE CHENG
12	09 Feb 2018 15:12	Adj Next Rpt Changed	Next Rpt:Final Rpt, Due Date:2018/03/09	[I] NG CHEN HOW
13	09 Feb 2018 15:12	Adj Mandate Set	Approved:10055.25.	[I] NG CHEN HOW

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1719294	08/02/2018 14:41	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SKA1681S		10.70

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Clara Milah Yeo

Date: 08 Feb 2018

Preliminary Advice

Vehicle No	: SKA1681S	Accident Date	: 05/02/2018
Make	: BMW 520I	Policy No.	: 29014630QMY
Assignment Date	: 07/02/2018	Excess	: S\$700.00
Date of Inspection	: 07/02/2018	Est. Duration of Repair	: 7.00
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	24,957.70
Revised Amount	:S\$	10,055.25
Check Items (Estimated)	:S\$	9,298.35
Total	:S\$	19,353.60

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	210,000.00
COE / PARF Rebate	:S\$	77,440.00
Salvage Value	:S\$	
Margin for Repair	:S\$	132,560.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0878G
Vehicle Details	
Vehicle No.:	SKA1681S
Vehicle to be Exported:	Yes
Intended De-registration Date:	08 Feb 2018
Vehicle Make:	B.M.W.
Vehicle Model:	520D LED NAV
Primary Colour:	Black
Manufacturing Year:	2017
Engine No.:	58959894B47D20A
Chassis No.:	WBAJC32060GB64839
Maximum Power Output:	140.0 kW (187 bhp)
Open Market Value:	\$44,181.00
Original Registration Date:	30 Aug 2017
First Registration Date:	30 Aug 2017
Transfer Count:	0
Actual ARF Paid:	\$48,854.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Aug 2027
PARF Rebate Amount:	\$36,640.00
Intended COE Rebate Details	
COE Expiry Date:	29 Aug 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,000.00
COE Rebate Amount:	\$40,800.00
Total Rebate Amount:	\$77,440.00

The information contained herein is correct as at 08 Feb 2018

OK

<u>labour</u>	<u>parts</u>
2550	120.1
2399	1698.55
83	103.4
150	1481.9
230	62.55
5412	69.5
	1.5
	36.2
	100.6
	583.65
	344.75
	20.2
	18.15
	2.2
	4643.25

total

10055.25

<u>check items</u>	
<u>PARTS</u>	<u>LABOUR</u>
1281.95	950
833.6	531
15.55	150
15.55	1631
793.55	
80.25	
60.05	
57.05	
57.05	
51.1	
17	
180	
54.9	
86.9	
547.55	
216.15	
116.1	
53.9	
53.9	
111.5	
279.2	
102.95	
125.95	
34.6	
34.6	
36.25	
36.25	
583.65	
344.75	
30.55	
30.55	
994.8	
281.55	
23.85	
10.45	
33.8	
7667.35	

TOTAL

9298.35

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Feb 2018		07 Feb 2018 10:48 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

INSURED SUBFOLDER DETAILS		[Created by insurer]	
Insured:	WANG JINYONG, ID: S2760878G, Tel: +6592287985, Email: NOEMAIL		
Vehicle Reg. No.:	SKA1681S	Date of Loss:	05/02/2018 10:00 - :59
Claim Type:	OD / 548846	Policy/Cover Note No.:	29014630QMY (Comprehensive) Coverage: 30/08/2017 - 29/08/2018
		Excess:	S\$700.00
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Clara Milah Yeo]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 08/02/2018]		
Driver/Custodian:	WANG JINYONG (51 / Male), NRIC: S2760878G, Tel: +6592287985		
Adj Asp. Remarks:	Please revert. Thanks.		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

View All

Compose Case Mail



ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	View All	Search Tasks	Create New Task	Complete
No results.						Assigned By	Completed On	Created On	Done?

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/02/2018 16:06
Date Of Accident	05/02/2018 10:30
Exact Location Of Accident	SLE TOWARD WOODLAND
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKA1681S
Insured/Policyholder	
Name Of Registered Owner	WANG JINYONG
NRIC No	S2760878G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-92287985
Alternative Phone No	OFFICE-92287985

Vehicle Particulars

Manufacturer	BMW
Model	G30 520
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A29014630
Cover Note Number	

Driver

Name of Driver	WANG JINYONG
NRIC No	S2760878G
Date Of Birth	19/12/1966
Occupation	INDOOR
Date Of Driving Pass	18/03/2012
Driving Experience	5 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92287985
Fax Number	
Contact Number	OFFICE-92287985
Email Address	NOEMAIL

Address	895A WOODLANDS DRIVE 50 #06-12
Postcode	730895
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJU492J
Vehicle Make/Model/Colour	TOYOTA
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	NG MING JIE
NRIC/Passport Number	S9029637Z
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	FRONT
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

My car A was slowly to a stop due to traffic condition.
The car B behind fail to slow and hit my car rear

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time: 06/02/2018
12:50 pm

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: 6/2/2018
NRIC/PIN No.: @ 125660



MSIG Insurance (Singapore) Pte. Ltd.
4 Queen's Quay # 21-01, SGA Centre 2, Singapore 048807
Tel: 65 6827 7986 Fax: 65 6827 7980
E-mail: msig@msig.com.sg MSIG Reg. No. 29 94122100
CR No. 2004121100 CR No. 2004121100

Certificate of Insurance

ROAD TRANSPORT ACT 1987 (MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1989 (FEDERATION OF MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)
(REPUBLIC OF SINGAPORE)
THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1984 EDITION (REPUBLIC OF SINGAPORE)
OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form: M.X.1
Individual Domestic
Certificate No. A 28014330 OMV
Motor MAX PLUS
Comprehensive

Excess: S\$0700
Windscreen Excess: S\$0100
1. Index Mark and Registration Number of Vehicle
SPAS812

2. Name of Policyholder
Kang Jih Yong

3. Effective Date of the Commencement of Insurance for the purposes of the Act
10/08/2017

4. Date of Expiry of Insurance
28/08/2018

5. Persons or Classes of Persons entitled to drive*

Kang Jih Yong
Any other person, provided he is driving on the policyholder's order or with the policyholder's permission.

* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf made driving the Motor Vehicle.

6. Limitations as to use*

Use only for social, domestic and pleasure purposes and for the policyholder's business.
This Policy does not cover use for hire or reward racing pace-making reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

PLEASE NOTE ALL CLAIMS RELATED REPAIRS CAN BE CARRIED OUT AT ANY WORKSHOP OF YOUR CHOICE OR AT ANY MSIG AUTHORISED WORKSHOP LISTED IN THE ATTACHED.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

MSIG Insurance (Singapore) Pte. Ltd.

Approved Insurers

by Chief Executive Officer

REPUBLIC OF SINGAPORE DRIVING LICENCE

Portrait photo of a man.

Licence Number: **S2760878G**

Name: **WANG JINYONG**

Birth Date: **13 Dec 1966**

Issue Date: **18 Mar 2013**

002163824C



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3 Motor Cars $\leq$ 3000kg with $\leq$ 7 passengers, exclusive of the driver; and other motor vehicles $\leq$ 2500kg 18 Mar 2013

NP 428A



REPUBLIC OF SINGAPORE
NATIONAL ID CARD NO. S2760878G




NAME
WANG JINYONG

RACE
王 金 勇
CHINESE

DATE OF BIRTH
13-12-1966
SEX
M

COUNTRY OF BIRTH
CHINA



NRIC No. S2760878G



NATIONALLY
CHINESE
DATE OF ISSUE
06-04-2009

APT BLK 395A WOODLANDS DRIVE 50 #08-12
SINGAPORE 730895
NRIC No. S2760878G

DATE 06/09/2010

NO. 05

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559M GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796631 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 45797
Date Estimated : 06/02/2018
Prepared By : Chua Kee Sin

Page No. : 1 of 3

- ESTIMATE REPAIR FOR -

Wang Jinyong
Blk 895A Woodlands Drive 50
#06-12

Singapore 730895

- ACCOUNT - 66

MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKA1681S	G864839	30/08/2017	520D	0

DESCRIPTION

Replace rear tail end panel, boot lid, rear bumper and remove attachment etc include knock on accident dent

VALUE

2550 4,250.00

Spray painting rear floor pan, tail end pan, both lid, rear bumper and both side fender rear?

2349 5,120.00

To supply rear emboss number plate.

66 83.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 177.00

To remove and install boot compartment carpet and garnish to facilitate repairs.

230 271.00

To replace exhaust manifold and gasket including checks for leak.

807? 950.00

To carry out body cavity preservation.
(For cut panel).

100 451? 531.00

Sundries.

? 150.00

Total Labour 1: 11,532.00

DESCRIPTION

REAR SILENCER
TAILPIPE TRIM CHROME
COMPLETE TAIL TRIM
TAILGATE ALUMINIUM
LH TRUNK LID HINGE
RH TRUNK LID HINGE
LEFT PROTECT
RIGHT PROTEC
Carrier, bumper
REAR BUMPER BOTTOM REINFORCEMENT

QTY	PRIC	VALUE
1	1,281.95	1,281.95
2	120.10	240.20
1	833.60	833.60
1	1,698.55	1,698.55
1	113.65	113.65
1	113.65	113.65
1	15.55	15.55
1	15.55	15.55
1	793.55	793.55
1	80.25	80.25

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401359M GST Reg. No M2-0020081-X



101, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190112 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438183
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/830 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : **b1 45797**
Date Estimated : **06/02/2018**
Prepared By : **Chua Kee Sin**

Page No. : 2 of 3

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKA1681S	G864839	30/08/2017	520D	0

DESCRIPTION	QTY	PRIC	VALUE
REAR BUMPER CENTRE GUIDE	1	60.05	60.05
REAR BUMPER LH SIDE GUIDE	1	57.05	57.05
REAR BUMPER RH SIDE GUIDE	1	57.05	57.05
REAR BUMPER TRIM STRIP	1	103.40	103.40
REAR BUMPER TOWING EYE FLAP PRIMED	1	51.10	51.10
REAR BUMPER PANEL PRIMED (PDC/PMA)	1	1,481.90	1,481.90
LETTERING 520D	1	62.55	62.55
BREAKTHROUGH BUFFER	2	8.50	17.00
PLAQUE 82MM	1	69.50	69.50
GROMMET	2	0.75	1.50
LOCK TRUNK LID	1	180.00	180.00
STRIKER BOOT LID	1	54.90	54.90
LH TENSION SPRING	1	86.90	86.90
RH SPINDLE DRIVE	1	547.55	547.55
BOOT LID/TAILGATE PUSH BOTTON (RFK)	1	24.00	24.00
TRUNK LID POWER LOCK PANEL	1	216.15	216.15
Floor carpet	1	717.70	717.70
LOADING SILL COVER	1	116.10	116.10
Stowage comp right rear	1	53.90	53.90
Storage bin, left rear	1	53.90	53.90
REAR SILENCER HEAT INSULATION FRT	1	111.50	111.50
REAR SILENCER HEAT INSULATOR	1	279.20	279.20
HEAT INSULATOR rear	1	36.20	36.20
SOUND INSULA	1	102.95	102.95
TRUNK LID inner cover	1	125.95	125.95
Trim cover, left boot lid	1	34.60	34.60
Trim cover, right boot lid	1	34.60	34.60
BRACKET FOR HAZARD WARN. TRIANGLE	1	26.00	26.00
TRUNK LID GASKET	1	100.60	100.60
REAR LH REAR REFLECTOR	1	36.25	36.25
REAR RH REAR REFLECTOR	1	36.25	36.25
REAR LH LIGHT IN THE SIDE PANEL	1	583.65	583.65
REAR RH LIGHT IN THE SIDE PANEL	1	583.65	583.65
REAR LH LIGHT IN TRUNK LID	1	344.75	344.75
REAR RH LIGHT IN TRUNK LID	1	344.75	344.75
LH TAIL LIGHT FINISHER TRUNK LID	1	30.55	30.55
RH TAIL LIGHT FINISHER TRUNK LID	1	30.55	30.55
ULTRASONIC SENSOR BLACK	4	248.70	994.80
DECOUPING RING PDC TORQUE CONVERTER	4	5.05	20.20
BLIND RIVET AVIBVLB	33	0.55	18.15
SCREW (SF PLUS M5X15)	4	0.55	2.20
(DG/SL) BODY ADHESIVE K5B (195ML)	1	281.55	281.55
(DG) CLEANER R1 (100ML)	1	23.85	23.85
PUNCH RIVET N4	19	0.55	10.45
(S/L) SEAM SEAL 300ML	1	33.80	33.80

Total Parts : 13,425.70

Performance Motors Limited

A member of the Sime Darby Group

CO. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190128 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796634 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 45797
Date Estimated : 06/02/2018
Prepared By : Chua Kee Sin

Page No. : 3 of 3

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKA1681S	G864839	30/08/2017	520D	0

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims On / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date&Time 7/2/18 @ 1500 Excess \$ 700

Surveyor's Name Tan Jiah Sign Tan Jiah

Surveyor's Tel 97495149 Authorised Yes / No

Authorised Date Revert. Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No P.M. Yes / No

Surveyor's E-mail tanjiah@thant.com

No. of Working Days Recommend 7 days

[Signature]
13/2/18

Labour 1	:	11,532.00
Parts	:	13,425.70
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,747.04
Grand Total	:	26,704.74

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-K



SUPPLEMENTARY

Estimate No. : b1 45797
Date Estimated : 06/02/2018
Prepared By : Chua Kee Sin

Page No. :

REPAIR FOR -
Wang Jinyong
Blk 895A Woodlands Drive 50
#06-12

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Singapore 730895

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SKA1681S	G864839	30/08/2017	520D	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
# To replace rear silencer and attachments include alignment and conducting checks for leak	451.00		451.00	
# To replace intermediate pipe include alignment and conducting checks for leak	451.00		451.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# SILENCER CLAMPING BUSH *	60.60	1.00		60.60 <i>bt✓</i>
# SILENCER CLAMPING BUSH *	60.60	1.00		60.60 <i>bt✓</i>
# INTERMEDIATE PIPE EU5 *	528.00	1.00		528.00 <i>bt✓</i>
# REAR BUMPER CARRIER (ECE DIESEL) *	793.55	1.00		793.55 <i>bt✓</i>
# PLAQUE 74MM *	69.50	1.00		69.50 <i>new</i>
# REAR SILENCER LH HEAT INSULATION *	161.70	1.00		161.70 <i>bt✓</i>
# REAR LH UNDERBODY PANELLING *	69.60	1.00		69.60 <i>bt✓</i>
# UNDERBODY PANELLING REAR *	41.30	1.00		41.30 <i>bt✓</i>

Total Labour : 902.00
Total Parts : 1,784.85
Total Labour & Parts : 2,686.85

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 45797
Date Estimated : 06/02/2018
Prepared By : Chua Kee Sin

Page No. :

REPAIR FOR -
Wang Jinyong
Blk 895A Woodlands Drive 50
#06-12

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Singapore 730895

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE		
SKA1681S	G864839	30/08/2017	520D	0		
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT			
To replace rear bumper and attachments, tailgate and attachments, rear underbody panelling, rear RH light in side panel, rear LH light in trunk lid include making good the tail end panel and knocking out dents caused by the accident	2550.00		2,550.00			
* To spray painting rear bumper, boot lid and tail end panel	2537.00		2,537.00			
To supply rear emboss number plate.	83.00		83.00			
To check electrical wiring systems and lightings at the rear section for proper function.	150.00		150.00			
To remove and install boot compartment carpet and garnish to facilitate repairs.	230.00		230.00			
# To replace rear silencer and attachments include alignment and conducting checks for leak	451.00		451.00 (H)			
# To replace intermediate pipe include alignment and conducting checks for leak	451.00		451.00 (H)			
* To carry out body cavity preservation (Per panel)	100.00		100.00			
Sundries	150.00		150.00			

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# SILENCER CLAMPING BUSH *	60.60	1.00		60.60
# SILENCER CLAMPING BUSH *	60.60	1.00		60.60
REAR SILENCER	1,281.95	1.00		1,281.95
# INTERMEDIATE PIPE EU5 *	528.00	1.00		528.00
REAR SILENCER	783.10	1.00		783.10 (H)
TAILPIPE TRIM CHROME	120.10	1.00		120.10
TAILGATE ALUMINIUM	1,698.55	1.00		1,698.55
REAR BUMPER BOTTOM REINFORCEMENT	80.25	1.00		80.25



FINAL REPORT

REAR BUMPER CENTRE GUIDE	60.05	1.00	60.05
REAR BUMPER LH SIDE GUIDE	57.05	1.00	57.05
# REAR BUMPER CARRIER (ECE DIESEL) *	793.55	1.00	793.55
REAR BUMPER TRIM STRIP	103.40	1.00	103.40
REAR BUMPER PANEL PRIMED (PDC/PMA)	1,481.90	1.00	1,481.90
LETTERING 520D	62.55	1.00	62.55
# PLAQUE 74MM *	69.50	1.00	69.50
GROMMET	0.75	2.00	1.50
REAR SILENCER HEAT INSULATION FRT	111.50	1.00	111.50
# REAR SILENCER LH HEAT INSULATION *	161.70	1.00	161.70
REAR SILENCER HEAT INSULATOR	279.20	1.00	279.20
# REAR LH UNDERBODY PANELLING *	69.60	1.00	69.60
# UNDERBODY PANELLING REAR *	41.30	1.00	41.30
TRUNK LID GASKET	100.60	1.00	100.60
REAR RH LIGHT IN THE SIDE PANEL	583.65	1.00	583.65
REAR LH LIGHT IN TRUNK LID	344.75	1.00	344.75
ULTRASONIC SENSOR BLACK	248.70	2.00	497.40
DECOUPING RING PDC TORQUE CONVERTER	5.05	4.00	20.20

SUPPLEMENTARY ITEMS

Total Labour :	6,702.00
Total Parts :	9,452.55
Total Labour & Parts :	16,154.55
Deduction for Excess :	700.00
Total Repair Costs less Excess:	15,454.55
GST @7%:	1,081.82
Grand Total :	16,536.37

65329902.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Feb 2018		07 Feb 2018 10:48 Edit Adj Rpt	S\$16,154.55 Edit Estimates	S\$16,154.55 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	WANG JINYONG , ID: S2760878G, Tel: +6592287985, Email: NOEMAIL								
Vehicle Reg. No.:	SKA1681S	Date of Loss:	05/02/2018 10:00 - :59 [5 Months and 6 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 548846	Policy/Cover Note No.:	29014630QMY (Comprehensive) Coverage: 30/08/2017 - 29/08/2018						
		Excess:	S\$700.00						
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Clara Milah Yeo]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 09/03/2018]								
Driver/Custodian:	WANG JINYONG (51 / Male), NRIC: S2760878G, Tel: +6592287985								
Adj Asg. Remarks:	Please revert. Thanks.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- MSIG_SG (06/04/2018): Alert - Adj Mandate Approved (S\$16154.55) - SKA1681S - Claim Handler: Clara Mila... - MSIG_SG (09/02/2018): Alert - Adj Mandate Approved (S\$10055.25) - SKA1681S - Claim Handler: Clara Mila...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKA16815 (548846)
OD
Feb 5 2018 10:00AM
[WANG JINYONG]
Performance Motors Limited

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Video							1 per page		☒	
No	Finalized On	Performance Motors Limited (Alexandra)						Thumbnail	Print	
1	06/02/18 16:24	Video - Accident [Linked Accident Report Documents]						Load AVI		
Assessment Reports							1 per page		☒	
No	Finalized On	Performance Motors Limited (Alexandra)						Thumbnail	Print	
1	06/02/18 16:32	Accident Statement						Load HTM		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	08/02/18 16:03	Adjuster Immediate Advice						Load HTM		
2	04/04/18 16:47	Adjuster Immediate Advice						Load HTM		
3	13/04/18 17:12	Adjuster Immediate Advice						Load HTM		
Photos/Images							3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	09/02/18 12:02	Odometer Reading						Load JPG	☒	
2	09/02/18 12:02	Chassis Number						Load JPG	☒	
3	09/02/18 12:02	General View						Load JPG	☒	
4	09/02/18 12:02	General View						Load JPG	☒	
5	09/02/18 12:02	General View						Load JPG	☒	
6	09/02/18 12:02	General View						Load JPG	☒	
7	09/02/18 12:02	General View						Load JPG	☒	
8	09/02/18 12:02	General View						Load JPG	☒	
9	09/02/18 12:02	General View						Load JPG	☒	
10	09/02/18 12:02	General View						Load JPG	☒	
11	09/02/18 12:02	General View						Load JPG	☒	
12	09/02/18 12:02	General View						Load JPG	☒	
13	09/02/18 12:02	General View						Load JPG	☒	
14	09/02/18 12:02	General View						Load JPG	☒	
15	09/02/18 12:02	General View						Load JPG	☒	
16	09/02/18 12:02	General View						Load JPG	☒	
17	09/02/18 12:02	General View						Load JPG	☒	
18	09/02/18 12:02	General View						Load JPG	☒	
19	09/02/18 12:02	General View						Load JPG	☒	
20	09/02/18 12:02	General View						Load JPG	☒	
21	09/02/18 12:02	General View						Load JPG	☒	
22	09/02/18 12:02	General View						Load JPG	☒	
23	09/02/18 12:02	General View						Load JPG	☒	
24	09/02/18 12:02	General View						Load JPG	☒	
25	09/02/18 12:02	General View						Load JPG	☒	
26	09/02/18 12:02	General View						Load JPG	☒	
27	09/02/18 12:02	General View						Load JPG	☒	
28	09/02/18 12:02	General View						Load JPG	☒	

Video			1 per page	
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
29	09/02/18 12:02	General View	 Load JPG	☒
30	09/02/18 12:02	General View	 Load JPG	☒
31	09/02/18 12:02	General View	 Load JPG	☒
32	09/02/18 12:02	General View	 Load JPG	☒
33	09/02/18 12:02	General View	 Load JPG	☒
34	09/02/18 12:02	General View	 Load JPG	☒
35	09/02/18 12:02	General View	 Load JPG	☒
36	09/02/18 12:02	General View	 Load JPG	☒
37	09/02/18 12:02	General View	 Load JPG	☒
38	09/02/18 12:02	General View	 Load JPG	☒
39	09/02/18 12:02	General View	 Load JPG	☒
40	09/02/18 12:02	General View	 Load JPG	☒
41	09/02/18 12:02	General View	 Load JPG	☒
42	09/02/18 12:02	General View	 Load JPG	☒
43	09/02/18 12:02	General View	 Load JPG	☒
44	09/02/18 12:02	General View	 Load JPG	☒
45	09/02/18 12:02	General View	 Load JPG	☒
46	09/02/18 12:02	General View	 Load JPG	☒
47	09/02/18 12:02	General View	 Load JPG	☒
48	09/02/18 12:02	General View	 Load JPG	☒
49	09/02/18 12:02	General View	 Load JPG	☒
50	09/02/18 12:02	General View	 Load JPG	☒
51	09/02/18 12:02	General View	 Load JPG	☒
52	09/02/18 12:02	General View	 Load JPG	☒
53	09/02/18 12:02	General View	 Load JPG	☒
54	09/02/18 12:02	General View	 Load JPG	☒
55	09/02/18 12:02	General View	 Load JPG	☒
56	09/02/18 12:02	General View	 Load JPG	☒
57	09/02/18 12:02	General View	 Load JPG	☒
58	09/02/18 12:02	General View	 Load JPG	☒
59	09/02/18 12:02	General View	 Load JPG	☒
60	09/02/18 12:02	General View	 Load JPG	☒
61	04/04/18 16:41	Reinspection Photo	 Load JPG	☒
62	04/04/18 16:41	Reinspection Photo	 Load JPG	☒
63	04/04/18 16:41	Reinspection Photo	 Load JPG	☒
64	04/04/18 16:41	Reinspection Photo	 Load JPG	☒
65	04/04/18 16:41	Reinspection Photo	 Load JPG	☒
66	04/04/18 16:41	Reinspection Photo	 Load JPG	☒
67	04/04/18 16:41	Reinspection Photo	 Load JPG	☒
68	04/04/18 16:41	Reinspection Photo	 Load JPG	☒
69	04/04/18 16:41	Reinspection Photo	 Load JPG	☒
70	04/04/18 16:41	Reinspection Photo	 Load JPG	☒
71	04/04/18 16:41	Reinspection Photo	 Load JPG	☒
72	04/04/18 16:41	Reinspection Photo	 Load JPG	☒
73	04/04/18 16:41	Reinspection Photo	 Load JPG	☒
74	04/04/18 16:41	Reinspection Photo	 Load JPG	☒
75	04/04/18 16:41	Reinspection Photo	 Load JPG	☒
76	04/04/18 16:41	Reinspection Photo	 Load JPG	☒
77	04/04/18 16:41	Reinspection Photo	 Load JPG	☒
78	04/04/18 16:41	Reinspection Photo	 Load JPG	☒

Video			1 per page	☒
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
79	04/04/18 16:41	Reinspection Photo	 Load JPG	☒
80	04/04/18 16:41	Reinspection Photo	 Load JPG	☒
81	04/04/18 16:41	Reinspection Photo	 Load JPG	☒
82	04/04/18 16:41	Reinspection Photo	 Load JPG	☒
83	04/04/18 16:41	Reinspection Photo	 Load JPG	☒
84	04/04/18 16:41	Reinspection Photo	 Load JPG	☒
85	04/04/18 16:41	Reinspection Photo	 Load JPG	☒
86	04/04/18 16:41	Reinspection Photo	 Load JPG	☒
87	04/04/18 16:41	Reinspection Photo	 Load JPG	☒
88	04/04/18 16:41	Reinspection Photo	 Load JPG	☒
89	04/04/18 16:41	Reinspection Photo	 Load JPG	☒
90	04/04/18 16:41	Reinspection Photo	 Load JPG	☒
91	04/04/18 16:41	Reinspection Photo	 Load JPG	☒
92	04/04/18 16:41	Reinspection Photo	 Load JPG	☒
93	04/04/18 16:41	Reinspection Photo	 Load JPG	☒
94	04/04/18 16:41	Reinspection Photo	 Load JPG	☒
95	04/04/18 16:41	Reinspection Photo	 Load JPG	☒
96	04/04/18 16:41	Reinspection Photo	 Load JPG	☒
97	04/04/18 16:41	Reinspection Photo	 Load JPG	☒
98	04/04/18 16:41	Reinspection Photo	 Load JPG	☒
99	04/04/18 16:41	Reinspection Photo	 Load JPG	☒
100	04/04/18 16:41	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	07/02/18 10:50	TP SJU492J GIA report	 Load PDF	
2	07/02/18 10:50	Repair Estimate	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/02/18 16:10	ESTIMATE	 Load PDF	
2	29/03/18 15:45	supplementary	 Load PDF	
3	13/04/18 16:52	SUPPLEMENTARY	 Load PDF	
4	24/04/18 08:27	SUPPLEMENTARY PART	 Load PDF	

Linked Accident Report Documents

Video			View	View in Browser	☒
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print	
1	06/02/18 16:24	Video - Accident	 Load AVI		
Assessment Reports			1 per page	☒	
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print	
1	06/02/18 16:32	Accident Statement	 Load HTM		
Photos/Images			3 per page	☒	
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print	
1	06/02/18 16:24	Accident Photo	 Load JPG	☒	
2	06/02/18 16:24	Accident Photo	 Load JPG	☒	
3	06/02/18 16:24	Accident Photo	 Load JPG	☒	
4	06/02/18 16:24	Accident Photo	 Load JPG	☒	
5	06/02/18 16:24	Accident Photo	 Load JPG	☒	
6	06/02/18 16:24	Accident Photo	 Load JPG	☒	
7	06/02/18 16:24	Accident Photo	 Load JPG	☒	

Video				1 per page	☒
No	Finalized On	Performance Motors Limited (Alexandra)		Thumbnail	Print
8	06/02/18 16:24	Accident Photo		Load JPG	☒
Documentation				1 per page	☒
No	Finalized On	Performance Motors Limited (Alexandra)		Thumbnail	Print
1	06/02/18 16:26	Sketch Plan		Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer			
Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG18002495/T1TBQ2

Date: 24/04/2018

REFERENCE

Insured/Claimant: WANG JINYONG Policy No: 29014630QMY
Date of Loss: 05/02/2018 Nature of Claim: OD Claim No: 548846

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKA1681S**
Make & Model: BMW 520I, 2.0 AT D/AB 2WD 4DR LED NAV (A) Engine No: 58959894B47D20A
Reg. Date: 30/08/2017 (Man. Year: 2017) Chassis No: WBAJC32060G864839
Colour: Black Odometer: 11752 km
Engine Capacity: 1995 cc
Market Value/New Car Price: S\$210,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 245/45 R18 Rear Tyre Size: 245/45 R18
Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,226.65	9,685.55	6,541.10	40.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,201.00	6,469.00	5,732.00	46.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	28,427.65	16,154.55	12,273.10	43.17
- Excess (S\$)	700.00	700.00	0.00	0.00
(S\$)	27,727.65	15,454.55	12,273.10	44.26
+ GST 7.00/7.00% (S\$)	1,940.94	1,081.82	859.12	44.26
Nett Amount (S\$)	29,668.59	16,536.37	13,132.22	44.26

INSPECTION

Date of Assignment: 07/02/2018

Date Inspected: 07/02/2018 Inspected At:

Performance Motors Limited (Alexandra)
303 Alexandra Road, Sime Darby
Performance Centre
Singapore 159941

Estimated Period of Repair: 7.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Apr 2018)
Parts:	143	BMW 520I 2.0 AT D/AB 2WD 4DR LED NAV (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKA1681S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR EMBOSS NUMBER PLATE	Bent	83.00 FS	*83.00 FS
2	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
3	1		*REAR SILENCER	Bent	1,281.95 FS	*1,281.95 FS
4	1		*TAILPIPE TRIM CHROME	O/S Not Necessary / N/S Cut	240.20 FS	*120.10 FS
5	1		*COMPLATE TAIL TRIM	Not Necessary	833.60 FS	*- FS
6	1		*TAILGATE ALUMINIUM	Bent	1,698.55 FS	*1,698.55 FS
7	1		*LH TRUNK LID HINGE	Repair	113.65 FS	*- FS
8	1		*RH TRUNK LID HINGE	Repair	113.65 FS	*- FS
9	1		*LEFT PROTECT	Not Necessary	15.55 FS	*- FS
10	1		*RIGHT PROTEC	Not Necessary	15.55 FS	*- FS
11	1		*CARRIER ,BUMPER	Not Necessary	793.55 FS	*- FS
12	1		*REAR BUMPER BOTTOM REINFORCEMENT	Bent	80.25 FS	*80.25 FS
13	1		*REAR BUMPER CENTRE GUIDE	Deformed	60.05 FS	*60.05 FS
14	1		*REAR BUMPER LH SIDE GUIDE	Necessary	57.05 FS	*57.05 FS
15	1		*REAR BUMPER RH SIDE GUIDE	Not Necessary	57.05 FS	*- FS
16	1		*REAR BUMPER TRIM STRIP	Cut	103.40 FS	*103.40 FS
17	1		*REAR BUMPER TOWING EYE FLAP PRIMED	Not Necessary	51.10 FS	*- FS
18	1		*REAR BUMPER PANEL PRIMED (PDC/PMA)	Deformed	1,481.90 FS	*1,481.90 FS
19	1		*LETTERING 520D	Necessary	62.55 FS	*62.55 FS
20	2		*BREAKTHROUGH BUFFER	Not Necessary	17.00 FS	*- FS
21	1		*PLAQUE 82MM	Not Necessary	69.50 FS	*- FS
22	2		*GROMMET	Necessary	1.50 FS	*1.50 FS
23	1		*LOCK TRUNK LID	Not Necessary	180.00 FS	*- FS
24	1		*STRIKER BOOT LID	Not Necessary	54.90 FS	*- FS
25	1		*LH TENSION SPRING	Not Necessary	86.90 FS	*- FS
26	1		*RH SPINDLE DRIVE	Not Necessary	547.55 FS	*- FS
27	1		*BOOT LID /TAILGATE PUSH BOTTON (RFK)	Not Necessary	24.00 FS	*- FS
28	1		*TRUNK LID POWER LOCK PANEL	Not Necessary	216.15 FS	*- FS
29	1		*FLOOR CARPET	Not Necessary	717.70 FS	*- FS
30	1		*LOADING SILL COVER	Not Necessary	116.10 FS	*- FS
31	1		*STOWAGE COMP RIGHT REAR	Not Necessary	53.90 FS	*- FS
32	1		*STORAGE BIN ,LEFT REAR	Not Necessary	53.90 FS	*- FS
33	1		*REAR SILENCER HEAT INSULATION FRT	Bent	111.50 FS	*111.50 FS
34	1		*REAR SILENCER HEAT INSULATOR	Bent	279.20 FS	*279.20 FS
35	1		*HEAT INSULATOR REAR	Not Necessary	36.20 FS	*- FS
36	1		*SOUND INSULA	Not Necessary	102.95 FS	*- FS
37	1		*TRUNK LID INNER COVER	Not Necessary	125.95 FS	*- FS
38	1		*TRIM COVER ,LEFT BOOT LID	Not Necessary	34.60 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
39	1		*TRIM COVER ,RIGHT BOOT LID	Not Necessary	34.60 FS	*- FS
40	1		*BRACKET FOR HAZARD WARN , TRIANGLE	Not Necessary	26.00 FS	*- FS
41	1		*TRUNK LID GASKET	Necessary	100.60 FS	*100.60 FS
42	1		*REAR LH REAR REFLECTOR	Not Necessary	36.25 FS	*- FS
43	1		*REAR RH REAR REFLECTOR	Not Necessary	36.25 FS	*- FS
44	1		*REAR LH LIGHT IN THE SIDE PANEL	Not Necessary	583.65 FS	*- FS
45	1		*REAR RH LIGHT IN THE SIDE PANEL	Cracked	583.65 FS	*583.65 FS
46	1		*REAR LH LIGHT IN TRUNK LID	Cut	344.75 FS	*344.75 FS
47	1		*REAR RH LIGHT IN TRUNK LID	Not Necessary	344.75 FS	*- FS
48	1		*LH TAIL LIGHT FINISHER TRUNK LID	Not Necessary	30.55 FS	*- FS
49	1		*RH TAIL LIGHT FINISHER TRUNK LID	Not Necessary	30.55 FS	*- FS
50	4		*ULTRASONIC SENSOR BLACK	Not Working	994.80 FS	*497.40 FS
51	4		*DECOUPING RING PDC TORQUE CONVERTER	Necessary	20.20 FS	*20.20 FS
52	1		*BLIND RIVET AVIBVLB (33 PCS)	Not Necessary	18.15 FS	*- FS
53	4		*SCREW (SF PLUS M5X15)	Not Necessary	2.20 FS	*- FS
54	1		*(DG/SL) BODY ADHESIVE K5B (195ML)	Not Necessary	281.55 FS	*- FS
55	1		*(DG) CLEANER R1 (100ML)	Not Necessary	23.85 FS	*- FS
56	19		*PUNCH RIVET N4	Not Necessary	10.45 FS	*- FS
57	1		*(S/L) SEAM SEAL 300ML	Not Necessary	33.80 FS	*- FS
58	1		*SILENCER CLAMPING BUSH	Bent	60.60 FS	*60.60 FS
59	1		*SILENCER CLAMPING BUSH	Bent	60.60 FS	*60.60 FS
60	1		*INTERMEDIATE PIPE EU5	Bent	528.00 FS	*528.00 FS
61	1		*REAR BUMPER CARRIER (ECE DIESEL)	Bent	793.55 FS	*793.55 FS
62	1		*PLAQUE 74MM	Necessary	69.50 FS	*69.50 FS
63	1		*REAR SILENCER LH HEAT INSULATION	Bent	161.70 FS	*161.70 FS
64	1		*REAR LH UNDERBODY PANELLING	Bent	69.60 FS	*69.60 FS
65	1		*UNDERBODY PANELLING REAR	Bent	41.30 FS	*41.30 FS
66	1		*TAILPIPE TRIM CHROME	Bent	783.10 FS	*783.10 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 16,226.65 9,685.55

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR SILENCER AND ATTACHMENTS INCLUDE ALIGNMENT AND CONDUCTING CHECKS FOR LEAK	New	451.00	451.00
2	TO REPLACE INTERMEDIATE PIPE INCLUDE ALIGNMENT AND CONDUCTING CHECKS FOR LEAK	New	451.00	451.00
3	REPLACE REAR TAIL END PANEL,BOOT LID ,REAR BUMPER AND REMOVE ATTACHMENT ETC INCLUDE KNOCK ON ACCIDENT DENT	New	4,250.00	2,550.00
4	SPRAY PAINTING REAR FLOOR PAN ,TAIL END PAN ,BOTH LID ,REAR BUMPER AND BOTH SIDE FENDER REAR	New	5,120.00	2,537.00
5	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
6	TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS	New	271.00	230.00
7	TO REPLACE EXHAUST MANIFOLD AND GASKET INCLUDING CHECKS FOR LEAK	New	950.00	0.00
8	TO CARRY OUT BODY CAVITY PRESERVATION (FOR CUT PANEL)	New	531.00	100.00
Gross Labour Cost (\$\$)			12,201.00	6,469.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >