

12/10/2018

ASS. REC. BY:

REF: CS/CTI/8002502/Tlqdz02

Special Instruction:

Survivor
Member

Tauhiah

ASSIGNMENT (Office)

From (Person):

Jayn Tay

of

CTI

Date/Time:

7/2/18 @ 9:34am

Estimated Cost:

Bill to:

OD TP WS TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SIF58321

Insured:

GY8960L

at Workshop m/s

Ver mogen Ace

Tel:

of

1 Bukit Batok Crescent # 04-54/55

Policy No:

DMCVSN 3063171702

Claim No:

SNMIRD0067602

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

04/02/2018

CA / REV / REP. / REV 24 HRS up

H.O.D. Endorsement:

Date/Time:

11:19am @ 7/2/18

Person Contacted:

ezei

Vehicle:

IN/OUT

Date/Time

Action/Instruction () Estimate

SIF58321-X

GY8960L-CC3/AXA15004544/R/3e3g2

D.O.A: 12/3/15

01/6/18 @

10.32m confirmed with Paulo Buldoz final fig \$850, 3 days.
(Red 64467.60, 842)

Taylor

CTI

ASSIGNMENT

SLF 58324

2016 Aug

Page: _____ Date: _____
 Estimated Cost: _____
 OD / TP WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop: _____
 at: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Vehicle: _____
 Type: D (M/Cycle) Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Mark: Florida Vezel _____
 Colour: Black _____
 Sp. Reading: _____
 Eng No: _____
 C No: R411115165
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / A/Rim / STD A/Rim or
 Tyre Size: P 205/60R16
 R: _____

NS	OS
☒	

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection:
 Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? Yes or No
 GIA PR Seen: _____ Consistent? Yes or No
 Est. Repairs: 3 days Res: Yes or No
 Cum. Surp: _____ % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUM /
 TOYO / YOKO or other
 Front: _____ Rear: _____
 R/Bal: 6 mm R/Bal: 6 mm
 L/Bal: 6 mm L/Bal: 6 mm
 D.O.A: _____ D.O.I: 7/2/18
 Surveyed at: Vormagen Boro.
 Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or
n/s lead
 The U/C / Chassis frame / Body Structure effected due to collision

Date Time Action Instruction Getty meek

RECEIVED 01 JUN 2018

One Time Fee Pass: ☐ Preli. Report
0/6 Final ☐ Final Report

Days Of Repair: 3
 Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp: \$
☐ Interview: \$
☐ Report: \$
☐ Other: \$

Survey Fee
 Transportation

210

Report Format: over TP
 Lump Sum: 850

210

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Feb 2018		07 Feb 2018 09:34 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	POPULAR SPORTS TRADING COMPANY		[Created by insurer]
Main Claimant:	LCRF PTE LTD, Co. Reg. No.: 201624597K		
Vehicle Reg. No.:	SLF5832J	Date of Loss:	04/02/2018 10:00 - :59
Claim Type:	TP / SNM18D00676C02	Policy/Cover Note No.:	DMCVSN3063171702 (Comprehensive) Coverage: 16/09/2017 - 15/09/2018
Vehicle Reg. No. (Insured):	GY8960L	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Vermogen Ace Pte Ltd (HQ) 1 Bukit Batok Crescent, #04-54/55 WCEGA Plaza, 658064 Bukit Batok - Tel: 65155230		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]		
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 19/02/2018]		
Adj Asg. Remarks:	1) REQUESTED FOR MARCUS 2) PLEASE PROCEED TO SURVEY ON WITHOUT PREJUDICE		
ASSOCIATED MAIL RECORD			

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI18002502/T1qd3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 07-02-2018	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GY 8960L	Veh. Inspected	SLF 5832J
Policy No.	DMCVSN3063171702	Coverage (\$)	0.00
Claim No.	SNM18D00678C02	Excess (\$)	0.00
Assign From	MERIMEN (JOWYN TAY)	Assign Date	07/02/2018
2. Vehicle Particulars & Condition			
Make & Model	c.c		0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.	Colour		
Odometer	-	Steering	
Brakes	Modification		
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	04/02/2018	Inspection Date	07/02/2018
Survey held at	VERMOGEN ACE PTE LTD 1 BUKIT BATOK CRESCENT #04-54/55 WCEGA PLAZA SINGAPORE 658064		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 1 June 2018 10:37 AM
To: 'Baldoz Juan Paulo Bongon'; Asher Sng (LKKAUTO); Vic (LKKAUTO); Guo Qiang (LKKAUTO); Taufikh (LKKAUTO); Rasul (LKKAUTO)
Cc: Vmg admin; Glorioso Eric Paul Patambang; Tezano Exequiel Dawal; Minoko Chan; Edmond Lim; Quantum Risk; Lina Rosli; Luis Tan; Paul Tan
Subject: RE: SLF5832J DOA: 04/02/2018 TO FINALISE (CHINA TAIPING TP)

Dear Paulo Baldoz,

Confirm final fig \$850 before GST and 3 repair days.

Kindly send the relevant documents to China Taiping Insurance company.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Baldoz Juan Paulo Bongon [mailto:paulo.b@vermogen-group.com]
Sent: Saturday, 21 April 2018 12:46 PM
To: Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>; Vic (LKKAUTO) <vicalpeh@lkkauto.com>; Guo Qiang (LKKAUTO) <GuoQiang@lkkauto.com>; Ai Phing (LKKAUTO) <aiphing@lkkauto.com>; Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>; Taufikh (LKKAUTO) <Taufikh@lkkauto.com>; Rasul (LKKAUTO) <Rasul@lkkauto.com>
Cc: Vmg admin <vmg@vermogen-group.com>; Glorioso Eric Paul Patambang <eric.g@vermogen-group.com>; Tezano Exequiel Dawal <ezel.t@vermogen-group.com>; Minoko Chan <minoko@vermogen-group.com>; Edmond Lim <edmond@vermogen-group.com>; Quantum Risk <Info@quantum-risk.com.sg>; Lina Rosli <linarosli@vermogen-group.com>; Luis Tan <luis@vermogen-group.com>; Paul Tan <paul@vermogen-group.com>
Subject: SLF5832J DOA: 04/02/2018 TO FINALISE (CHINA TAIPING TP)

Hi Taufikh,

Please check and confirm finalise COR @ \$850 bef gst. 3 working days.

Excluded: PRS, RS, WEEKENDS, PH.

Thank you

Best Regards,



Paulo Baldoz
Vermogen Ace Pte Ltd
6358 3031

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/02/2018 16:27
Date Of Accident	04/02/2018 10:05
Exact Location Of Accident	TOH GUAN ROAD (BLK 282)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLF5832J
Insured/Policyholder	-
Name Of Registered Owner	LCRF PTE LTD
Co Reg No	201624597K
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90106639
Alternative Phone No	OFFICE-66944919

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL-1.5 X CVT (A)
Exact Purpose for which vehicle was being used at time of accident	HIRER
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	DENNIS CHEW
NRIC No	S1614421E
Date Of Birth	05/06/1963
Occupation	OUTDOOR
Date Of Driving Pass	01/06/1981
Driving Experience	36 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90106639
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	44 BENOI RD BLOCK B
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GY8960L
Vehicle Make/Model/Colour	
Details Of Properties	VEH. B
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Accident Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/PIN No.:

Accident Sketch Plan Pg. 2

SKETCH PLAN

A-5LF5832J

B-6Y8960L



Toh Guan Road (Blk 282)

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along Blk 282 Toh Guan Road, I saw vehicle B filter in to the left car pouch, I continue driving straight and hit a impact on my Rear Left portion.

DECLARATION

(We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



SLF5832J

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER : CHINA TAIPING
OWN INSURER : AIG
CLAIM TYPE : TP
Date of Accident : 4/2/2018

Vehicle Reg. No. : SLF5832J
Vehicle Reg. Date: 31-Aug-2016
Make / Model : H. VEZEL 1.5X CVT
Engine No. : L15B4035169
Chassis No. : RU11115163

COST OF CLAIMS

Parts Cost / List Items : \$ 3,762.00
Plus/Less 20% \$ 752.40
Total Cost / List : \$ 3,009.60
Special Nett Items : \$ 360.00
Total Parts Amount : \$ 3,369.60
Total Labour Amount : \$ 1,950.00
Gross Total : \$ 5,319.60
GST % : 7% \$ 372.37
Nett Amount : \$ 5,691.97

Surveyor Name and Company :

Tan Jiah
Date of survey : 7/2/18 @ 1700

Part by Part / Lump Sum : 3 days

Resurvey Before Paint / After Paint

Authorize/Not Authorize/Without Prejudice

Email : sup@lkkauto.com 12/2/18

Fax No :

HP No : 97495749

This claim is handled by : PAULO BALDOZ

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : SLF5832J
 Vehicle Reg. Date: 31/8/2016
 Make / Model : H. VEZEL 1.5X CVT
 Engine No. : L15B4035169
 Chassis No. : RU11115163

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	Tail lamp LH	X	\$ 489.00	Jan	
2	1set	Tail lamp clips	X	\$ 36.00	Jan	
3	1	Rear bumper	X Ref	\$ 950.00	Jan	
4	1set	Rear bumper clips	X	\$ 50.00	Jan	
5	1	Rear bumper retainer LH	X	\$ 72.00	Jan	
6	1	Rear bumper bracket LH	X	\$ 116.00	Jan	
7	1	Rear bumper reflector LH	X	\$ 167.00	Jan	
8	1	Rear bumper cover LH	Ry	\$ 210.00	Jan	
9	1set	Rear bumper cover clips	Ref X	\$ 50.00	Jan	
10	1	Rear bumper cover retainer LH	X	\$ 42.00	Jan	
11	1	Rear fender LH	Ry	\$ 950.00	Jan	
12	1	Rear fender inner trim LH	X	\$ 480.00	Jan	
13	1	Rear fender Air duct LH	X	\$ 150.00	Jan	
14	1	Reverse sensor	X	\$ 300.00	Jan	
15	1	Sundries	20 X	\$ 60.00	Jan	
16	0	0				
17	0	0				
18	0	0				
19	0	0				
20	0	0				
21	0	0				
22	0	0				
23	0	0				
24	0	0				
25	0	0				
26	0	0				
27	0	0				
28	0	0				
29	0	0				
30	0	0				
31	0	0				
32	0	0				
33	0	0				
34	0	0				
35	0	0				
36	0	0				
37	0	0				
38	0	0				
39	0	0				
40	0	0				

Tel : 6358 3031 | Fax No : 6694 4929

PAGE 1

[illegible]



SLF5832J

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER : CHINA TAIPING
OWN INSURER : AIG
CLAIM TYPE : TP
Date of Accident : 4/2/2018

Vehicle Reg. No. : SLF5832J
Vehicle Reg. Date: 31-Aug-2016
Make / Model : H. VEZEL 1.5X CVT
Engine No. : L15B4035169
Chassis No. : RU11115163

COST OF CLAIMS

Parts Cost / List Items : \$ 3,762.00
Plus/Less 20% \$ 752.40
Total Cost / List : \$ 3,009.60
Special Nett Items : \$ 360.00
Total Parts Amount : \$ 3,369.60
Total Labour Amount : \$ 1,950.00
Gross Total : \$ 5,319.60
GST % : 7% \$ 372.37
Nett Amount : \$ 5,691.97

Surveyor Name and Company :

Tan Jiah
Date of survey : 7/2/18 @ 17W
Part by Part / Lump Sum : 3 days
Resurvey Before Paint / After Paint
Authorize/Not Authorize/Without Prejudice
Email : sup@kkant.com
Fax No :
HP No : 97495749

This claim is handled by : PAULO BALDOZ

L = 850

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : SLF5832J
 Vehicle Reg. Date: 31/8/2016
 Make / Model : H. VEZEL 1.5X CVT
 Engine No. : L15B4035169
 Chassis No. : RU11115163

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	Tail lamp LH	X	\$ 489.00		
2	1set	Tail lamp clips	X	\$ 36.00		
3	1	Rear bumper	X RV	\$ 950.00		
4	1set	Rear bumper clips	X	\$ 50.00		
5	1	Rear bumper retainer LH	X	\$ 72.00		
6	1	Rear bumper bracket LH	X	\$ 116.00		
7	1	Rear bumper reflector LH	X	\$ 167.00		
8	1	Rear bumper cover LH	RV	\$ 210.00		
9	1set	Rear bumper cover clips	RV X	\$ 50.00		
10	1	Rear bumper cover retainer LH	X	\$ 42.00		
11	1	Rear fender LH	RV	\$ 950.00		
12	1	Rear fender inner trim LH	X	\$ 480.00		
13	1	Rear fender Air duct LH	X	\$ 150.00		
14	1	Reverse sensor	X		\$ 300.00	
15	1	Sundries	20		\$ 60.00	
16	0	0				
17	0	0				
18	0	0				
19	0	0				
20	0	0				
21	0	0				
22	0	0				
23	0	0				
24	0	0				
25	0	0				
26	0	0				
27	0	0				
28	0	0				
29	0	0				
30	0	0				
31	0	0				
32	0	0				
33	0	0				
34	0	0				
35	0	0				
36	0	0				
37	0	0				
38	0	0				
39	0	0				
40	0	0				

6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. :	SLF5832J
Vehicle Reg. Date:	31/8/2016
Make / Model :	H. VEZEL 1.5X CVT
Engine No. :	L15B4035169
Chassis No. :	RU11115163

Estimates on Labour

[illegible]
$$L = 850$$

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Feb 2018		07 Feb 2018 09:34 Edit Adj Rpt	S\$850.00 Edit Estimates	S\$850.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	POPULAR SPORTS TRADING COMPANY, Co. Reg. No.: -	
Main Claimant:	LCRF PTE LTD, Co. Reg. No.: 201624597K	
Vehicle Reg. No.:	SLF5832J	Date of Loss: 04/02/2018 10:00 - :59 [17 Months and 4 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM18D00676C02	Policy/Cover Note No.: DMCVSN3063171702 (Comprehensive) Coverage: 16/09/2017 - 15/09/2018
Vehicle Reg. No. (Insured):	GY8960L	Policy No. (Claimant):
		Excess: S\$0.00
Repairer:	Vermogen Ace Pte Ltd (HQ) Blk B, 44 Benoi Rd, 629904 Pioneer - Tel: 65155230	
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]	
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 19/02/2018]	
Adj Asg. Remarks:	1) REQUESTED FOR MARCUS 2) PLEASE PROCEED TO SURVEY ON WITHOUT PREJUDICE.	

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

*SLF5832J (SNM18D00676C02)
[GY8960L]
TP
LCRF PTE LTD
Feb 4 2018 10:00AM
[POPULAR SPORTS TRADING COMPANY]
Vermogen Ace Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/06/18 11:25	Chassis Number	Load JPG	☒
2	01/06/18 11:25	General View	Load JPG	☒
3	01/06/18 11:25	General View	Load JPG	☒
4	01/06/18 11:25	General View	Load JPG	☒
5	01/06/18 11:25	General View	Load JPG	☒
6	01/06/18 11:25	General View	Load JPG	☒
7	01/06/18 11:25	General View	Load JPG	☒
8	01/06/18 11:25	General View	Load JPG	☒
9	01/06/18 11:25	General View	Load JPG	☒
10	01/06/18 11:25	General View	Load JPG	☒
11	01/06/18 11:25	General View	Load JPG	☒
12	01/06/18 11:25	General View	Load JPG	☒
13	01/06/18 11:25	General View	Load JPG	☒
14	01/06/18 11:25	General View	Load JPG	☒
15	01/06/18 11:25	General View	Load JPG	☒
16	01/06/18 11:25	General View	Load JPG	☒
17	01/06/18 11:25	General View	Load JPG	☒
18	01/06/18 11:25	General View	Load JPG	☒
19	01/06/18 11:26	Reinspection Photo	Load JPG	☒
20	01/06/18 11:26	Reinspection Photo	Load JPG	☒
21	01/06/18 11:26	Reinspection Photo	Load JPG	☒
22	01/06/18 11:26	Reinspection Photo	Load JPG	☒
23	01/06/18 11:26	Reinspection Photo	Load JPG	☒
24	01/06/18 11:26	Reinspection Photo	Load JPG	☒
25	01/06/18 11:26	Reinspection Photo	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	07/02/18 09:35	E-filed GIA report	Load PDF	

Linked Accident Report Documents

			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	Vermogen Ace Pte Ltd (HQ)	Thumbnail	Print
1	05/02/18 17:45	Accident Statement	Load HTM	
Photos/Images			3 per page	☒

Assessment Reports			1 per page	☒
No	Finalized On	Vermogen Ace Pte Ltd (HQ)	Thumbnail	Print
No	Finalized On	Vermogen Ace Pte Ltd (HQ)	Thumbnail	Print
1	05/02/18 17:43	Accident Photo	 Load JPG	☒
2	05/02/18 17:43	Accident Photo	 Load JPG	☒
3	05/02/18 17:43	Accident Photo	 Load JPG	☒
4	05/02/18 17:43	Accident Photo	 Load JPG	☒
5	05/02/18 17:43	Accident Photo	 Load JPG	☒
6	05/02/18 17:43	Accident Photo	 Load JPG	☒
7	05/02/18 17:43	Accident Photo	 Load JPG	☒
8	05/02/18 17:44	Accident Photo	 Load JPG	☒
9	05/02/18 17:44	Accident Photo	 Load JPG	☒
10	05/02/18 17:44	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Vermogen Ace Pte Ltd (HQ)	Thumbnail	Print
1	05/02/18 17:43	Accident Sketch Plan	 Load TIF	☒
2	05/02/18 17:43	IC AND LICENSE	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18002502/T1QD3E2

Date: 04/06/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN3063171702
Claimant Vehicle No :	SLF5832J	Insured Vehicle No :	GY8960L
Date of Loss:	04/02/2018	Nature of Claim:	TP
		Claim No:	SNM18D00676C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLF5832J	Engine No:	L15B4035169
Make & Model:	HONDA VEZEL, 1.5 X CVT (A)	Chassis No:	RU11115163
Reg. Date:	31/08/2016 (Man. Year: 2016)	Odometer:	0 km
Colour:	Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	OTANI 6 mm	Rear Left Side:	OTANI 6 mm
Front Right Side:	OTANI 6 mm	Rear Right Side:	OTANI 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,369.60	0.00	3,369.60	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,950.00	850.00	1,100.00	56.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,319.60	850.00	4,469.60	84.02
+ GST 7.00/7.00% (S\$)	372.37	59.50	312.87	84.02
Nett Amount (S\$)	5,691.97	909.50	4,782.47	84.02

INSPECTION

Date of Assignment:	07/02/2018	Inspected At:	Vermogen Ace Pte Ltd (HQ)
Date Inspected:	07/02/2018		1 BUKIT BATOK CRESCENT
			#04-54/55 WCEGA PLAZA
			SINGAPORE 658064
Estimated Period of Repair:	3.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Jun 2018)
Parts:	M1-SUV	HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLF5832J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL LAMP LH	Not Necessary	489.00 FL	*-FL
2	1		*SET TAIL LAMP CLIPS	Not Necessary	36.00 FL	*-FL
3	1		*REAR BUMPER	Repair	950.00 FL	*-FL
4	1		*SET REAR BUMPER CLIPS	Not Necessary	50.00 FL	*-FL
5	1		*REAR BUMPER RETAINER LH	Not Necessary	72.00 FL	*-FL
6	1		*REAR BUMPER BRACKET LH	Not Necessary	116.00 FL	*-FL
7	1		*REAR BUMPER REFLECTOR LH	Not Necessary	167.00 FL	*-FL
8	1		*REAR BUMPER COVER LH	Repair	210.00 FL	*-FL
9	1		*SET REAR BUMPER COVER CLIPS	Not Necessary	50.00 FL	*-FL
10	1		*REAR BUMPER COVER RETAINER LH	Not Necessary	42.00 FL	*-FL
11	1		*REAR FENDER LH	Repair	950.00 FL	*-FL
12	1		*REAR FENDER INNER TRIM LH	Not Necessary	480.00 FL	*-FL
13	1		*REAR FENDER AIR DUCT LH	Not Necessary	150.00 FL	*-FL
14	1		*REVERSE SENSOR	Not Necessary	300.00 FS	*-FS
15	1		*SUNDRIES	Not Necessary	60.00 FS	*-FS
					Sub Total (S\$)	4,122.00 0.00
					- List Item Discount on L Items 20.00/20.00% (S\$)	752.40 0.00
					Total Parts (S\$)	3,369.60 0.00

F=Franchise part, S=SpcNett, L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO STRAIGHTEN AND PANEL BEATING ACCIDENT AREA. REAR PORTION, REAR BUMPER COVER LH, REAR FENDER LH	New	800.00	400.00
2	TO PUTTY, RESPRAY PAINTING AND POLISH ACCIDENT AREA. REAR PORTION. REAR BUMPER COVER LH, REAR FENDER LH, RR DOOR LH	New	800.00	400.00
3	TO REMOVE AND REFIT REVERSE SENSOR	New	100.00	0.00
4	TO RUST PROOF AFFECTED AREAS	New	150.00	30.00
5	TO CHECK AND RECTIFY WIRING AFTER DISCONNECT AND CONNECT	New	100.00	20.00
Gross Labour Cost (S\$)			1,950.00	850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >