

22/03/2001

ASS. REC. BY:

REF: CS/CTI18002509/ R1vd3ⁿ² Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

Jowyn Tay

of CTI

Date/Time: 6/2/18 @ 4:36pm

Estimated Cost:

Bill to:

OD ☒ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLB 4169T

Insured:

SJF 4000Z

at Workshop m/s

Borneo Motors

Tel:

66311857

of

2pcindan Crescent, 128462

Policy No:

DMPCSN 30 90061700

Claim No:

SNM18D 00673C02

Sum Insured:

Excess:

D.O.A. 5/2/18

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time:

10:09am @ 7/2/18

Person Contacted:

thomas

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLB 4169T - x
	SJF 4000Z - (CG/AIG/12004429/Kb/a3q2) D.O.A: 29/02/12
7/3/18	Final fig \$10,139.42 (Reel 7098.30, 41/15 confirmed by email)

Signature: Rasul

REF: 92

3053H

ASSIGNMENT

From: _____ Date: 26-02-2018

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLB 4169T

at Workshop m/s: Borneo motor

of: 2 Pandan Crescent

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: Thomas

(Policy Condition)

10am - 12pm

Remark: The veh had commenced its repair at the time of inspection.



Bel. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 7 days

7/3 Rasul

Res.: Yes or No

Lum Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No: SLB 4169T Yr Regn: 2016 AP12

Type: M.Cycle / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA

WISH 1.8 CRT

cc 1798

Colour: MARON

A/C Insured / Std / NI / NA

Sp Reading: 24988

T/Radio: Insured / Std / NI / NA

Eng/No: JTDG620W70J003904

C/No: _____

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R16

R: 22

BS / DUN / EXNOVA / GYFS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

mm

R/Bal. 6 mm

mm

L/Bal. 6 mm

mm

L/Bal. 6 mm

mm

D.O.A. 05/02/18

D.O.I. 26/02/18

Survey held at: Borneo motor

Des. of Damages: Frt / Rear / O/S / NIS / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

RECEIVED 07 MAR 2018

Date/Time File Pass to?

☐

: Preli. Report

Date/Time File Return to?

☐

: Final Report

7/3- typist

Report Format: merimen

Lump Sum / I.B.I: 10,139.42

Days Of Repair: 7

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

8-80 \$

Photo:

Others:

Add Fee:

☐

Site Insp. \$

☐

Interview \$

☐

Tech. Insp. \$

☐

Weekend \$

TOTAL:

020

Survey Department Check List (Case Handler)

Reference No.: CS/CTI/8003509/Rlvcl3
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are ACCURATE.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From	✓			
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No				
C	Insurance Authorisation (CA /REV/REP)	✓			
C	Report Type				
C	Weekend Charges	✓			
N	Survey held at/Repairer				
C	Excess				

Surveyor (

): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages				

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)	✓			
C	Days of repair	✓			
C	Finalised Amount				
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 23/8
Case Handler Date

*C: Critical *N: Non-Critical



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18002509/R1vd3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 07-02-2018



Code : CTI

Policy Particulars :- THIRD PARTY CLAIM

1.	Insured Veh.	SJF 4000Z	Veh. Inspected	SLB 4169T
	Policy No.	DMPCSN3090061700	Coverage (\$)	0.00
	Claim No.	SNM18D00673C02	Excess (\$)	0.00
	Assign From	MERIMEN (JOWYN TAY)	Assign Date	07/02/2018

Vehicle Particulars & Condition

2.	Make & Model	c.c	0
	Engine No.	HIDDEN	Year of Reg.
	Chassis No.		Colour
	Odometer		Steering
	Brakes		Modification
	General		

Conditions of Tyres

3.		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm

Description of Damages

4.

General Information

5.

Accident Date 05/02/2018 Inspection Date

Survey held at BORNEO MOTORS (S) PTE LTD
2 PANDAN CRESCENT
SINGAPORE 128462

Remarks

5a.

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Feb 2018		06 Feb 2018 16:36 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured: LIN ANQING RAY, ID: S8306642C

Main Claimant: TAN KOK PENG LAWRENCE, ID: S7443053H

Vehicle Reg. No.: SLB4169T

Claim Type: TP / SNM18D00673C02

Vehicle Reg. No. (Insured): SJF4000Z

Reparer: Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent, 128462 West Coast - Tel: 66311857

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]

Claimant's Insurer: AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288

Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 15/02/2018]

Adj Asg. Remarks: PLEASE PROCEED TO SURVEY AND ARRANGE FOR DIRECT SETTLEMENT.

Date of Loss: 05/02/2018 11:00 - :59

Policy/Cover Note No.: DMPCSN3090061700 (Comprehensive)
Coverage: 24/11/2017 - 23/11/2018

Policy No. (Claimant): VPA/P1911168

Excess: S\$0.00

[Created by insurer]

[View All](#) [Compose Case Mail](#)

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 7 March 2018 12:54 PM
To: 'Thomas Pang PTCBC'; Shu Pei (LKKAUTO); Rasul (LKKAUTO)
Cc: Admin A; SUR
Subject: RE: FINALIZE REPORT FOR SLB4169T ***LKK REF:CS/CTI18002509/R1vd3

Dear Thomas,

Confirmed finalize \$10,139.42 before GST

No of days: 7 days

Final invoice and all supporting documents sent to CNTPI

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Thomas Pang PTCBC [mailto:Thomas.Pang@borneomotors.com.sg]
Sent: Wednesday, 7 March 2018 11:50 AM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; Shu Pei (LKKAUTO) <shupeil@lkkauto.com>; Rasul (LKKAUTO) <Rasul@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: FINALIZE REPORT FOR SLB4169T ***LKK REF:CS/CTI18002509/R1vd3

Dear Veron,

Attach before paint for your perusal.

Thank you

Regards

Thomas

From: Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]
Sent: Wednesday, March 7, 2018 11:24 AM
To: Shu Pei (LKKAUTO); Thomas Pang PTCBC; Rasul (LKKAUTO)
Cc: Admin A; SUR
Subject: RE: FINALIZE REPORT FOR SLB4169T ***LKK REF:CS/CTI18002509/R1vd3

Dear Thomas,

Kindly forward us before paint photos.

Best Regards,
Veron Chen | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Shu Pei (LKKAuto)
Sent: Wednesday, 7 March 2018 10:27 AM
To: Thomas.Pang@borneomotors.com.sg; Rasul (LKKAuto) <Rasul@lkkauto.com>; Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: FINALIZE REPORT FOR SLB4169T ***LKK REF:CS/CTI18002509/R1vd3

Dear Thomas,

Thank you for your email.

Our respective case handler will look into the matter and revert to you in due course.

Dear Rasul / Veron,

For your information and necessary action please.

To check availability of the case handler, you may contact the undersigned.

Best Regards,
Shu Pei | Admin
LKK Auto Consultants Pte Ltd
Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Thomas Pang PTCBC [mailto:Thomas.Pang@borneomotors.com.sg]
Sent: Wednesday, 7 March 2018 9:35 AM
To: Rasul (LKKAuto) <Rasul@lkkauto.com>; SUR <sur@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: FINALIZE REPORT FOR SLB4169T

Dear Rasul,

Attach finalize report for your perusal.

Thank you

Regards

Thomas
Borneo Motors
DID:6631 1860 FAX:6773 3094

This e-mail (and any attachment) is intended for the addressee(s) only and contains information that is legally privileged and confidential. If you are not the intended recipient, please be advised that you have received this e-mail in error and that any use, dissemination, distribution, printing or copying of this communication is unauthorized and strictly prohibited. Kindly notify us by replying to the sender's e-mail address and delete this e-mail immediately. E-mail transmissions cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, delayed or incomplete, or could contain viruses. We therefore do not accept

liability for any errors or omissions in the contents of this e-mail which arise as a result of e-mail transmission, and you are advised to carry out your own virus checks and confirm the accuracy of the contents of this e-mail before relying on it for any purpose.

This e-mail (and any attachment) is intended for the addressee(s) only and contains information that is legally privileged and confidential. If you are not the intended recipient, please be advised that you have received this e-mail in error and that any use, dissemination, distribution, printing or copying of this communication is unauthorized and strictly prohibited. Kindly notify us by replying to the sender's e-mail address and delete this e-mail immediately. E-mail transmissions cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, delayed or incomplete, or could contain viruses. We therefore do not accept liability for any errors or omissions in the contents of this e-mail which arise as a result of e-mail transmission, and you are advised to carry out your own virus checks and confirm the accuracy of the contents of this e-mail before relying on it for any purpose.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 05/02/2018 16:58
Date Of Accident 05/02/2018 11:50
Exact Location Of Accident CHANGI NORTH STREET 1
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLB4169T
Insured/Policyholder
Name Of Registered Owner TAN KOK PENG LAWRENCE
NRIC No S7443053H
Email Address LAWSER@SINGNET.COM.SG
Mobile Phone No (LOCAL) +65-97770785
Alternative Phone No OFFICE-63151721

Vehicle Particulars

Manufacturer TOYOTA
Model WISH-1.8 CVT (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY
PRIVATE CAR

Vehicle Category

Insurance Company

Name of Insurance Company AXA INSURANCE PTE LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number VPA/P1911168
Cover Note Number

Driver

Name of Driver TAN KOK PENG LAWRENCE
NRIC No S7443053H
Date Of Birth 31/12/1974
Occupation INDOOR
Date Of Driving Pass 14/04/1997
Driving Experience 20 YEARS AND 9 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-97770785
Fax Number
Contact Number OFFICE-63151721
Email Address LAWSER@SINGNET.COM.SG

Address BLK 171C EDGEDALE PLAINS #09-446
 Postcode 823171
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1 NAME: : ABDUL HALIM S/O ABDUL RAHIM
 GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJF4000Z
 Vehicle Make/Model/Colour HONDA/WHITE COLOUR
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver LIN ANQING RAY
 NRIC/Passport Number S8306642C
 Contact Number 96835386
 Address BLK 988C BUANGKOK GREEN #05-77
 Postcode 533988
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver) 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time

05/12/18


Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident

Accident Date: 05-05-2018

Accident Time: 11:50 a.m.

I was waiting for the traffic light to turn green at the cross junction
Change North Street 1.

The traffic light turn green and I was about to turn left at the cross junction,
Vehicle (SIF 40002) knock my car back with a loud bang.
Both of us, vehicle owners took our particular on site.

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date &
Time

05/05/2018

Driver's Signature (If driver is not the policyholder) / Date
& Time



Witnessed by Reporting Centre
Personnel



Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingsapore.com.sgToyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188Co Reg No : 196700086Z
GST Reg No : MR-8500000-9**ESTIMATE**

Join Toyota ME @ http://toyotame.borneomotors.com.sg & earn points to redeem for attractive items!

Account Detail		Account No		Customer Detail	
THIRD PARTY CLAIM		S1000020 / TPCLAIM		Mr Tan Kok Peng Lawrence 171C Edgedale Plains #09-446 Singapore 823171 Mobile: 97770785	
		Document No			
		0			
		Document Date			
		05/02/2018			

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
16	HPXNP	S6	07/04/2016	SLB4169T	0	29524	72/DS/SLB4169T

Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On
JTDGG20W70J003904	2ZR1744543	60	Thomas Pang W T	--/--/----	0.00	--/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY TP INS: TP VEH: SJF4000Z DATE OF ACC: 05.02.2018				✓ 50 100.00
2	B	BP-LAB DRILL HOLE AND INSTALL REVERSE SENSOR (N ETT)				✓ 169.50
3	B	BP-LAB CHECK WIRING AND CONDUCT WATER TEST (NET T)				✓ 169.50
4	B	BP-LAB REMOVE INTERIOR UPHOLSTERY TO FAC REPAIR (NETT)				✓ 678.00
5	B	BP-ECU TO RESET ECU AND REPROGRAMME (NETT)				✓ 678.00
6	L	BP-LPO SUPPLY REGN PLATE (PO#)				✓ 80.00
7	B	BP-LAB REPLACE ACC DAMAGED PARTS AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS				✓ 1695 3390.00 out part 2712!
8	B	BP-RES RESPRAY ACC AFFECTED AREAS				out part (2750) ✓ 1668 3336.00
9	Z	BP-SLANT SUPPLY SEALANT (NETT)				✓ 100 390.00 net
10	B	BP-LAB REMOVE AND TRANSFER TAILGATE COMPONENTS ONTO NEW TAILGATE (NETT)				✓ 339.00
11	B	BP-LAB R/I TAILGATE SPOILER TO FAC REPAIR (NETT)				✓ 169.50

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

3619882

3619882

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 05/02/2018
TIME 17:01

VEHICLE NO SLB4169T

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD**Borneo Motors**



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive rewards. Tel no.: 6631 1188

Account Detail	Account No	Customer Detail
THIRD PARTY CLAIM	S1000020 / TPCLAIM	Mr Tan Kok Peng Lawrence 171C Edgedale Plains #09-446 Singapore 823171 Mobile: 97770785
	Document No	
	0	
	Document Date	
	05/02/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
16	HPXNP	S6	ZGE20R	07/04/2016	SLB4169T	0	29524 72/DS/SLB4169T
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
JTDGG20W70J003904	22R1744543	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
12	B	BP-WS REPLACE REAR TAILGATE GLASS (NETT)				✓ 436.00
13	L	BP-LPO SUPPLY 3M SOLAR FILM (REAR TAILGATE GLASS)				✓ 480.00
14	1	T52159-68907 REAR BUMPER COVER,	1.00	574.90		DE 574.90 ✓
15	2	S52161-OK040 PIECE, RR BUMPER	10.00	3.90		na 39.00 ✓
16	3	T52156-68030 L/RR BUMPER SUPPORT,	1.00	93.90		? 93.90 ✓
17	4	T52576-68020 L/R SIDE BPR RETAINER,	1.00	44.40		? 44.40 ✓
18	5	T52155-68030 R/RR BUMPER SUPPORT,	1.00	93.90		? 93.90 ✓
19	6	T52575-68020 R/R SIDE BPR RETAINER,	1.00	44.40		? 44.40 ✓
20	7	SP2061-12010 22 3RO SENSOR	1.00	151.60		R ? 151.60 ✓
21	8	T58307-68031 REAR LOWER FLR PANEL,	1.00	520.00		R ? 520.00 ✓
22	9	T52181-68010 REAR BUMPER ARM,	1.00	52.10		? 52.10 ✓
23	0	T52181-68010 REAR BUMPER ARM,	1.00	52.10		? 52.10 ✓
24	1	T67935-68020 B0 PLATE BACK DOOR	1.00	288.70		? 288.70 ✓
25	2	T68105-68071 REAR BACK DOOR GLASS,	1.00	1009.20		photo na 1009.20 ✓
26	3	T67005-68041 PANEL ASSY, BACK DOOR	1.00	1428.40		st ? 1428.40 ✓
27	4	T67881-68030 RR BACK DOOR W/STRIP,	1.00	325.80		? 325.80 ✓
28	5	T69350-28151 LOCK ASSY, BACK DOOR	1.00	399.60		? 399.60 ✓
29	6	T08826-08609 SUPER FAST URETHANE BLACK	1.00	90.08		na 90.08 ✓
30	7	T08826-08682 SINGLE STEP PRIMER	1.00	173.44		na 173.44 ✓

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

3619883

PLEASE TEAR ALONG PERFORATED LINE

3619883

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 05/02/2018
TIME 17:01

VEHICLE NO SLB4169T

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

**Borneo Motors**



Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingapore.com.sg
Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Join Toyota ME @ http://toyotame.borneomotors.com.sg & earn points to redeem for attractive items!

Account Detail	Account No	Customer Detail
THIRD PARTY CLAIM	S1000020 / TPCLAIM	Mr Tan Kok Peng Lawrence 171C Edgedale Plains #09-446 Singapore 823171 Mobile: 97770785
	Document No	
	Document Date	
	0	
	05/02/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
16	HPXNP	S6	07/04/2016	SLB4169T	0	29524	72/DS/SLB4169T
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
JTDGG20W70J003904	2ZR1744543	60	Thomas Pang W T		--/--/----	0.00	--/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
31	8	T90975-02086 TOYOTA SYMBOL EMBLEM,	1.00	72.20		72.20
32	9	T75444-68010 LUGGAGE "VALVE Matic "	1.00	39.70		39.70
33	0	T89997-30070 ELECTRICAL ANTENNA,	1.00	160.60		160.60
34	1	T81551-68062 LENS & BODY, RR	1.00	344.00		344.00
35	2	T81561-68062 LENS, RR COMB LH	1.00	344.00		344.00
36	3	T81581-68020 LENS & BODY, RR	1.00	285.10		285.10
37	4	T81591-68020 LENS & BODY, RR	1.00	285.10		285.10

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

Rasul
Hp 90010068
7-9 days
26/02/18 @ 1000
Resurvey by paint

[Signature]
13/18

Part on behalf of	Customer's Signature	Change Summary	Total
Borneo Motors	Please acknowledge receipt of vehicle	Parts 6,912.22	17,237.72
		Labour 9,765.50	GST 7.00% 1,206.64
		Materials 560.00	Less 0.00
		Lubrication/Fluid 0.00	
		Others 0.00	
			Amount Due 18,444.36

PLEASE TEAR ALONG PERFORATED LINE

3619884

3619884

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 05/02/2018
TIME 17:01

VEHICLE NO SLB4169T

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingsapore.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

ESTIMATE

Account Detail	Account No	Customer Detail
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1	
	Document No	
	0	Mr Tan Kok Peng Lawrence 171C Edgedale Plains #09-446 Singapore 823171 Mobile: 97770785
	Document Date	
	05/03/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
16	HPXNP S6	ZGE20R	07/04/2016	SLB4169T	19624	29524	72/DS/SLB4169T
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	

JTDGG20W70J003904 2ZR1744543 60 Thomas Pang W T 26/02/2018 8.00 03/03/2018 18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY TP INS: CHINA TAIPING TP VEH: SJF4000Z DATE OF ACC: 05.02.2018 BY:LKK-RASUL @ 26.02.2018 07 WORKING DAYS				50.00
2	B	BP-LAB DRILL HOLE AND INSTALL REVERSE SENSOR (N	*			169.50
		ETT)				169.50
3	B	BP-LAB CHECK WIRING AND CONDUCT WATER TEST (NET	*			678.00
		T)				
4	B	BP-LAB REMOVE INTERIOR UPHOLSTERY TO FAC REPAIR	*			678.00
		(NETT)				80.00
5	B	BP-ECU TO RESET ECU AND REPROGRAMME (NETT)	18			1695.00
6	L	BP-LPO SUPPLY REGN PLATE (PO# 15951)	E33			
7	B	BP-LAB REPLACE ACC DAMAGED PARTS	*			
		AND STRAIGHTEN/REALIGN				
		ACC AFFECTED AREAS	*			1668.00
8	B	BP-RES RESPRAY ACC AFFECTED AREAS	*			100.00
9	Z	BP-SLANT SUPPLY SEALANT (NETT)	*			339.00
10	B	BP-LAB REMOVE AND TRANSFER TAILGATE COMPONENTS	*			
		ONTO NEW TAILGATE (NETT)				

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

3621119

3621119

05/03/2018
15:42

SLB4169T



Borneo Motors



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingsapore.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no: 6631 1188

ESTIMATE

Account Detail				Account No		Customer Detail			
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept				S1000003 / ICCI1		Mr Tan Kok Peng Lawrence 171C Edgedale Plains #09-446 Singapore 823171 Mobile: 97770785			
				Document No					
				0					
				Document Date					
				05/03/2018					
Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks		
16	HPXNP S6	ZGE20R	07/04/2016	SLB4169T	19624	29524	72/DS/SLB4169T		
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On			
JTDGG20W70J003904	2ZR1744543	60	Thomas Pang W T	26/02/2018	8.00	03/03/2018 18.00			
L	Cd	Job/Parts Description				Qty	Unit Price	Disc %	Amount
11	B	BP-LAB	R/I TAILGATE SPOILER TO FAC REPAIR (NETT *)						169.50
12	B	BP-WS	REPLACE REAR TAILGATE GLASS (NETT) *						436.00
13	L	BP-LPO	SUPPLY 3M SOLAR FILM (REAR TAILGATE GLASS) M30						480.00
		PO:16039							
14	1	T52159-68907	COVER RR BUMPER				1.00	574.90	574.90
15	2	S52161-0K040	PIECE, RR BUMPER				10.00	3.90	39.00
16	3	T68105-68071	GLASS BACK DOOR				1.00	1009.20	1009.20
17	4	T67005-68041	PANEL ASSY, BACK DOOR				1.00	1428.40	1428.40
18	5	T08826-08609	SUPER FAST URETHANE BLACK				1.00	90.08	90.08
19	6	T08826-08682	SINGLE STEP PRIMER				1.00	173.44	173.44
20	7	T90975-02086	EMBLEM, SYMBOL				1.00	72.20	72.20
21	8	T75444-68010	PLATE, LUGGAGE COMPT				1.00	39.70	39.70
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.									
For & on behalf of Borneo Motors			Customer's Signature			Change Summary		Total	
			Please acknowledge receipt of vehicle			Parts	3,426.92	GST 7.00%	10,139.42
						Labour	6,152.50		709.76
						Materials	560.00	Less	0.00
						Lubrication/Fluid	0.00		
						Others	0.00	Amount Due	10,849.18
362112									
362112									

05/03/2018
15:42

SLB4169T



Borneo Motors

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18002509/R1VD3N2
Date: 13/03/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3090061700
Claimant Vehicle No :	SLB4169T	Insured Vehicle No :	SJF4000Z
Date of Loss:	05/02/2018	Nature of Claim:	TP
		Claim No:	SNM18D00673C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLB4169T	Engine No:	2ZR1744543
Make & Model:	TOYOTA WISH, 1.8 CVT (A)	Chassis No:	JTDGG20W70J003904
Reg. Date:	07/04/2016 (Man. Year: 2016)	Odometer:	24988 km
Colour:	Maroon		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R16	Rear Tyre Size:	195/65R16
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	7,392.22	3,656.92	3,735.30	50.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,845.50	6,482.50	3,363.00	34.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	17,237.72	10,139.42	7,098.30	41.18
+ GST 7.00/7.00% (\$\$)	1,206.64	709.76	496.88	41.18
Nett Amount (\$\$)	18,444.36	10,849.18	7,595.18	41.18

INSPECTION

Date of Assignment:	06/02/2018	
Date Inspected:	26/02/2018	Inspected At:
		Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent Singapore 128462

Estimated Period of Repair: 7.0 days

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 13 Mar 2018)	
Parts: M1-MPV	TOYOTA WISH 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SLB4169T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER COVER	Deformed	574.90 FS	*574.90 FS
2	10		*PIECE,RR BUMPER	Necessary	39.00 FS	*39.00 FS
3	1		*L/RR BUMPER SUPPORT	Not Necessary	93.90 FS	*- FS
4	1		*L/R SIDE BPR RETAINER	Not Necessary	44.40 FS	*- FS
5	1		*R/RR BUMPER SUPPORT	Not Necessary	93.90 FS	*- FS
6	1		*R/R SIDE BPR RETAINER	Not Necessary	44.40 FS	*- FS
7	1		*3R0 SENSOR	Not Necessary	151.60 FS	*- FS
8	1		*REAR LOWER FLR PANEL	Repair	520.00 FS	*- FS
9	1		*REAR BUMPER ARM	Not Necessary	52.10 FS	*- FS
10	1		*REAR BUMPER ARM	Not Necessary	52.10 FS	*- FS
11	1		*PLATE BACK DOOR	Not Necessary	288.70 FS	*- FS
12	1		*REAR BACK DOOR GLASS	Necessary	1,009.20 FS	*1,009.20 FS
13	1		*PANEL ASSY,BACK DOOR	Bent	1,428.40 FS	*1,428.40 FS
14	1		*RR BACK DOOR W/STRIP	Not Necessary	325.80 FS	*- FS
15	1		*LOCK ASSY,BACK DOOR	Not Necessary	399.60 FS	*- FS
16	1		*SUPER FAST URETHANE BLACK	Necessary	90.08 FS	*90.08 FS
17	1		*SINGLE STEP PRIMER	Necessary	173.44 FS	*173.44 FS
18	1		*TOYOYA SYMBOL EMBLEM	Necessary	72.20 FS	*72.20 FS
19	1		*LUGGAGE VALVE MATIC	Necessary	39.70 FS	*39.70 FS
20	1		*ELECTRICAL ANTENNA	Not Necessary	160.60 FS	*- FS
21	1		*LENS & BODY RR	Not Necessary	344.00 FS	*- FS
22	1		*LENS,RR COMB LH	Not Necessary	344.00 FS	*- FS
23	1		*LENS & BODY,RR	Not Necessary	285.10 FS	*- FS
24	1		*LENS & BODY,RR	Not Necessary	285.10 FS	*- FS
25	1		*REGN PLATE	Bent	80.00 FS	*80.00 FS
26	1		*SEALANT	Necessary	300.00 FS	*100.00 FS
27	1		*SUNDRY	Necessary	100.00 FS	*50.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	7,392.22	3,656.92
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	DRILL HOLE AND INSTALL REVERSE SENSOR	New	169.50	169.50
2	CHECK WIRING AND CONDUCT WATER TEST	New	169.50	169.50
3	REMOVE INTERIOR UPHOLSTERY TO FAC REPAIR	New	678.00	678.00
4	TO RESET ECU AND REPROGRAMME	New	678.00	678.00
5	REPLACE ACC DAMAGED PARTS AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS	New	3,390.00	1,695.00
6	RESPRAY ACC AFFECTED AREAS	New	3,336.00	1,668.00
7	REMOVE AND TRANSFER TAILGATE COMPONENTS ONTO NEW TAILGATE	New	339.00	339.00
8	R/I TAILGATE SPOILER TO FAC REPAIR	New	169.50	169.50
9	REPLACE REAR TAILGATE GLASS	New	436.00	436.00
10	SUPPLY 3M SOLAR FILM (REAR TAILGATE GLASS)	New	480.00	480.00
Gross Labour Cost (\$\$)			9,845.50	6,482.50

Report was unsubmitted during this print-out.

< END OF ESTIMATES >