

ASS. REC. BY

REF

CS/CTI 18002515/TI 14d3

Print Instructions

SURVIVOR

Meinen

Tauflich

ASSIGNMENT (Office)

From (Person)

Sharon Hyn

of CTI

Date/Time 7/12/18 @ 1:06pm

Estimated Cost

Bill to

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLE 3963H

Insured: SDA 2389M

at Workshop m/s

Vermogen Ace

Tel: G 5155230

of

1 Bkt Batok Crescent #04-54/55

Policy No:

DMPCSN 303991702

Claim No:

SNM18D 00637C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 2/2/18

CA / REV / REP. / REV 24 HRS

Wp

H.O.D. Endorsement

Date/Time

2:39pm - 7/12/18

Person Contacted

EZEI

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLE 3963H-X
	SDA 2389M - C03/AIG09023378/CWJ
7/14/18 @ 2:31pm	Confirmed with Paulo Buldoz LS \$2750, 4 days. (Ref \$14111.76, 84%).

D.O.A. 15/10/2009

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Feb 2018		07 Feb 2018 13:06 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	LEE CHER CHIANG, ID: S7902088E		
Main Claimant:	LCRF PTE LTD, Co. Reg. No.: 201624597K		
Vehicle Reg. No.:	SLE3963H	Date of Loss:	02/02/2018 08:00 - :59
Claim Type:	TP / SNM18D00637C02	Policy/Cover Note No.:	DMPCSN3039991702 (Comprehensive)
Vehicle Reg. No. (Insured):	SDA2389M	Policy No. (Claimant):	999995062
		Excess:	\$50.00
Repairer:	Vermogen Ace Pte Ltd (HQ) 1 Bukit Batok Crescent, #04-54/55 WCEGA Plaza, 658064 Bukit Batok - Tel: 65155230		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Sharon Han - 63896]		
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 19/02/2018]		
Driver/Custodian (Insured):	LEE CHER CHIANG (38 / Male), NRIC: S7902088E		
Adj Asg, Remarks:	NO EST, CASE WITH SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI18002515/T1qd3		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 07-02-2018		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SDA 2389M	Veh. Inspected	SLE 3963H	
Policy No.	DMPCSN303991702	Coverage (\$)	0.00	
Claim No.	SNM18D00637C02	Excess (\$)	0.00	
Assign From	MERIMEN (SHARON HAN)	Assign Date	07/02/2018	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	02/02/2018	Inspection Date	07/02/2018	
Survey held at	VERMOGEN ACE PTE LTD 1 BUKIT BATOK CRESCENT #04-54/55 WCEGA PLAZA SINGAPORE 658064			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Shiau Chan (LKKAUTO)

From: Baldoz Juan Paulo Bongon <paulo.b@vermogen-group.com>
Sent: Wednesday, 25 April 2018 12:31 PM
To: Shiau Chan (LKKAUTO)
Cc: Taufikh (LKKAUTO); Vmg admin; Glorioso Eric Paul Patambang; Tezano Exequiel Dawal; Minoko Chan; Edmond Lim; Lina Rosli; Luis Tan; Paul Tan; SUR
Subject: Re: SLE3963H DOA: 02/02/2018 TO FINALISE (CHINA TAIPING TP)

Hi Shiau,

Confirmed finalise COR @ **\$2,750** bef gst (lump sum) 4 working days.

Excluded: PRS, RS, WEEKENDS, PH.

Thank you

Best Regards,



Paulo Baldoz
Vermogen Ace Pte Ltd
6358 3031

On Wed, Apr 25, 2018 at 12:13 PM, Shiau Chan (LKKAUTO) <siewsc@lkkauto.com> wrote:

Dear Paulo Baldoz,

Offer Lump Sum \$2,750.00 before GST and 4 repair days. (due to adjust TAILGATE to \$1,200.00 instead of \$1,860.00)

Kindly confirm.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/02/2018 14:38
Date Of Accident	02/02/2018 08:10
Exact Location Of Accident	CHOA CHU KANG DR
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLE3963H
Insured/Policyholder	
Name Of Registered Owner	LCRF PTE LTD
Co Reg No	201624597K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	Office-66944919

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999995062
Cover Note Number	

Driver

Name of Driver	TAN QING RUI
NRIC No	S8910301J
Date Of Birth	27/03/1989
Occupation	OUTDOOR
Date Of Driving Pass	11/01/2010
Driving Experience	8 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	

Fax Number	
Contact Number	
EMail Address	NOEMAIL
Address	44 BENOI ROAD BLOCK B (ENTRANCE 6 BENOI SECTOR)
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	Name: : UNKNOWN Gender: : Female

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO PHOTOS AND VIDEO. THANK YOU.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SDA2389M
Vehicle Make/Model/Colour	
Details Of Properties	VEH B
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan



SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NAC/FIN No.:

NIKO



Car A: SLE3963H

Car B: SPA2389M

Location:

Choa Chu kang Dr

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 02/02/18 at 8:10am, my vehicle A was approaching a red traffic light along Choa Chu kang Dr. After waiting for a few seconds the traffic light signal green, I then proceed a little but however the vehicle in front of me stopped so I follow suit. After which, I felt a impact on my vehicle A. I then went down and assess the accident scene. I wish to state that I have in-car camera in my vehicle A.

DECLARATION

(We declare the foregoing particulars are true in every respect.)

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: NIKO
NRIC/FIN No.:

REPUBLIC OF SINGAPORE DRIVING LICENCE

Card No. S8910301J

Name TAN QING RUI

Birth Date 27 Mar 1989

Valid Until 11 Jan 2019

001820121A

VMG USE ONLY

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S8910301J

Name TAN QING RUI

陳清銳

Race CHINESE

Date of birth 27-03-1989

Sex M

Country of birth SINGAPORE

S8910301J

Land Transport Authority

VOCATIONAL LICENCE

Licence No. S8910301J

Name TAN QING RUI

Card Issue Date - 20/12/2017

Please visit www.lta.gov.sg to check the status of this vocational licence

VMG USE ONLY

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

Class 3 Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver, and other motor vehicles <= 2500kg

Valid Until 11 Jan 2019

001820121A

VMG USE ONLY

3503841

001820121A

Card No. S8910301J

Date of issue 02-04-2004

Address
APT BLK 106 GANGBA ROAD
#09-139
SINGAPORE 670106

This card is not transferable and is the property of the Land Transport Authority (LTA). It must be surrendered to LTA on request. If found, please return to LTA, 10 Sin Ming Drive, Singapore 575701.

Type	Description	Issue Date
13	PRIVATE HIRE CAR VL	20/12/2017

VMG USE ONLY





SLE3963H

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER : CHINA TAIPING
OWN INSURER : AIG
CLAIM TYPE : TP
Date of Accident : 2/2/2018

Vehicle Reg. No. : SLE3963H
Vehicle Reg. Date: 14-Sep-2016
Make / Model : H. VEZEL 1.5X CVT
Engine No. : L15B4037365
Chassis No. : RU11117361

COST OF CLAIMS

Parts Cost / List Items : \$ 14,389.70
Plus/Less 20% \$ 2,877.94
Total Cost / List : \$ 11,511.76
Special Nett Items : \$ 1,080.00
Total Parts Amount : \$ 12,591.76
Total Labour Amount : \$ 4,270.00
Gross Total : \$ 16,861.76
GST % : 7% \$ 1,180.32
Nett Amount : \$ 18,042.08

Surveyor Name and Company :

Tan Jiah
Date of survey : 7/2/18 @ 1645
Part by Part / Lump Sum : 4 days
Resurvey Before Paint / After Paint
Authorize/Not Authorize/Without Prejudice
Tan Jiah @ LKK Auto Consultants
Email : ser@lkkauto.com
Fax No :
HP No : 97495749

This claim is handled by : EZEL

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLE3963H**

Vehicle Reg. Date: **9/14/2016**

Make / Model : **H. VEZEL 1.5X CVT**

Engine No. : **L15B4037365**

Chassis No. : **RU11117361**

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	Tailgate	bx	\$ 1,860.00	1200	
2	1	Tailgate outer garnish	X	\$ 285.00		
3	1 set	Tailgate outer garnish clips	X	\$ 40.00		
4	1	Tailgate logo	NEI	\$ 52.00		
5	1	Tailgate emblem "VEZEL"	NEI	\$ 56.20		
6	2	Tailgate lamp LH/RH	X	\$ 980.00		
7	2set	Tailgate lamp clips	X	\$ 50.00		
8	1	Tailgate outer handle switch	X	\$ 180.00		
9	2	Tailgate damper LH/RH	X	\$ 424.00		
10	1	Tailgate wiper motor	X	\$ 250.00		
11	1	Tailgate wiper blade	X	\$ 75.00		
12	1	Tailgate buzzer	X	\$ 150.00		
13	1	Tailgate inner handle	X	\$ 74.00		
14	1	Tailgate inner lock	X	\$ 245.00		
15	1	Tailgate lock sensor	X	\$ 220.00		
16	1	Tailgate striker	X	\$ 32.00		
17	1	Tailgate trimboard	X	\$ 295.00		
18	1 set	Tailgate trimboard clips	X	\$ 45.00		
19	1	Tailgate weatherstrip	X	\$ 145.00		
20	1 set	Tailgate windscreen moulding	NEI	\$ 164.00		
21	2	Tail lamp LH/RH	X	\$ 978.00		
22	1set	Tail lamp clips	X	\$ 36.00		
23	1	Rear bumper	NEI	\$ 950.00		
24	1set	Rear bumper clips	NEI	\$ 50.00		
25	2	Rear bumper retainer LH/RH	X	\$ 144.00		
26	2	Rear bumper bracket LH/RH	X	\$ 232.00		
27	2	Rear bumper reflector LH/RH	X	\$ 334.00		
28	2	Rear bumper cover LH/RH	X	\$ 420.00		
29	1set	Rear bumper cover clips	X	\$ 50.00		
30	2	Rear bumper cover retainer LH/RH	X	\$ 84.00		
31	1	Rear end panel outer	Rp	\$ 585.00		
32	1	Rear end panel inner	X	\$ 396.00		
33	1	Rear end panel top garnish	X	\$ 184.00		
34	1set	Rear end panel top garnish clips	X	\$ 25.00		
35	1	Spare tyre panel	X	\$ 1,230.00		
36	1	Spare tyre panel insulator	X	\$ 240.00		
37	1	Spare tyre panel top board	X	\$ 420.00		
38	1	Spare tyre tool tray	X	\$ 430.00		
39	2	Rear fender inner trim LH/RH	X	\$ 480.00		
40	2	Rear fender Air duct LH/RH	X	\$ 150.00		

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLE3963H**

Vehicle Reg. Date: **9/14/2016**

Make / Model : **H. VEZEL 1.5X CVT**

Engine No. : **L15B4037365**

Chassis No. : **RU11117361**

PAGE 2

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
41	1	Exhaust muffler	X	\$ 855.00		
42	1	Exhaust muffler mounting	X	\$ 79.50		
43	1	Exhaust muffler heat shield	X	\$ 165.00		
44	2	Rear plate lamp LH/RH	X	\$ 250.00		
45	1	Rear number plate with frame	X		\$ 50.00	
46	1	Tailgate windscreen sealant	NA		\$ 80.00	
47	1	Tailgate windscreen inner seal	NA		\$ 80.00	
48	1	Rear end panel sealant	X AN		\$ 80.00	
49	1	Reverse sensor	? RVV	200	\$ 300.00	
50	1	Spare tyre panel sealant	X AN		\$ 80.00	
51	1	Spare tyre panel padding	X AN		\$ 350.00	
52	1	Sundries	20 ALL		\$ 60.00	
53	0	0				
54	0	0				
55	0	0				
56	0	0				
57	0	0				
58	0	0				
59	0	0				
60	0	0				
61	0	0				
62	0	0				
63	0	0				
64	0	0				
65	0	0				
66	0	0				
67	0	0				
68	0	0				
69	0	0				
70	0	0				
71	0	0				
72	0	0				
73	0	0				
74	0	0				
75	0	0				
76	0	0				
77	0	0				
78	0	0				
79	0	0				
80	0	0				

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. :	SLE3963H
Vehicle Reg. Date:	9/14/2016
Make / Model :	H. VEZEL 1.5X CVT
Engine No. :	L15B4037365
Chassis No. :	RU11117361

Estimates on Labour

[illegible]



SLE3963H

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER : CHINA TAIPING
OWN INSURER : AIG
CLAIM TYPE : TP
Date of Accident : 2/2/2018

Vehicle Reg. No. : SLE3963H
Vehicle Reg. Date: 14-Sep-2016
Make / Model : H. VEZEL 1.5X CVT
Engine No. : L15B4037365
Chassis No. : RU11117361

COST OF CLAIMS

Parts Cost / List Items : \$ 14,389.70
Plus/Less 20% \$ 2,877.94
Total Cost / List : \$ 11,511.76
Special Nett Items : \$ 1,080.00
Total Parts Amount : \$ 12,591.76
Total Labour Amount : \$ 4,270.00
Gross Total : \$ 16,861.76
GST % : 7% \$ 1,180.32
Nett Amount : \$ 18,042.08

Surveyor Name and Company :

Tan Jiah
Date of survey : 7/2/18 @ 1645
Part by Part / Lump Sum : 4 days
Resurvey Before Paint / After Paint
Authorize/Not Authorize/Without Prejudice
Email : 94495749@kkan.com
Fax No :
HP No : 94495749

This claim is handled by : EZEL

P = 3132.20
- 20%
2505.76
SM = 380
L = 1110
3995.76
- 20%
3196.61
LIS = 3150

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No.: **SLE3963H**
 Vehicle Reg. Date: **9/14/2016**
 Make / Model: **H. VEZEL 1.5X CVT**
 Engine No.: **L15B4037365**
 Chassis No.: **RU11117361**

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	Tailgate	bx ✓	\$ 1,860.00		
2	1	Tailgate outer garnish	X	\$ 285.00		
3	1 set	Tailgate outer garnish clips	X	\$ 40.00		
4	1	Tailgate logo	rel ✓	\$ 52.00		
5	1	Tailgate emblem "VEZEL"	rel ✓	\$ 56.20		
6	2	Tailgate lamp LH/RH	X	\$ 980.00		
7	2set	Tailgate lamp clips	X	\$ 50.00		
8	1	Tailgate outer handle switch	X	\$ 180.00		
9	2	Tailgate damper LH/RH	X	\$ 424.00		
10	1	Tailgate wiper motor	X	\$ 250.00		
11	1	Tailgate wiper blade	X	\$ 75.00		
12	1	Tailgate buzzer	X	\$ 150.00		
13	1	Tailgate inner handle	X	\$ 74.00		
14	1	Tailgate inner lock	X	\$ 245.00		
15	1	Tailgate lock sensor	X	\$ 220.00		
16	1	Tailgate striker	X	\$ 32.00		
17	1	Tailgate trimboard	X	\$ 295.00		
18	1 set	Tailgate trimboard clips	X	\$ 45.00		
19	1	Tailgate weatherstrip	X	\$ 145.00		
20	1 set	Tailgate windscreen moulding	rel ✓	\$ 164.00		
21	2	Tail lamp LH/RH	X	\$ 978.00		
22	1set	Tail lamp clips	X	\$ 36.00		
23	1	Rear bumper	rel ✓	\$ 950.00		
24	1set	Rear bumper clips	rel ✓	\$ 50.00		
25	2	Rear bumper retainer LH/RH	X	\$ 144.00		
26	2	Rear bumper bracket LH/RH	X	\$ 232.00		
27	2	Rear bumper reflector LH/RH	X	\$ 334.00		
28	2	Rear bumper cover LH/RH	X	\$ 420.00		
29	1set	Rear bumper cover clips	X	\$ 50.00		
30	2	Rear bumper cover retainer LH/RH	X	\$ 84.00		
31	1	Rear end panel outer	Rp	\$ 585.00		
32	1	Rear end panel inner	X	\$ 396.00		
33	1	Rear end panel top garnish	X	\$ 184.00		
34	1set	Rear end panel top garnish clips	X	\$ 25.00		
35	1	Spare tyre panel	X	\$ 1,230.00		
36	1	Spare tyre panel insulator	X	\$ 240.00		
37	1	Spare tyre panel top board	X	\$ 420.00		
38	1	Spare tyre tool tray	X	\$ 430.00		
39	2	Rear fender inner trim LH/RH	X	\$ 480.00		
40	2	Rear fender Air duct LH/RH	X	\$ 150.00		

P= 3132.20

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : SLE3963H
 Vehicle Reg. Date: 9/14/2016
 Make / Model : H. VEZEL 1.5X CVT
 Engine No. : L15B4037365
 Chassis No. : RU11117361

PAGE 2

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
41	1	Exhaust muffler	X	\$ 855.00		
42	1	Exhaust muffler mounting	X	\$ 79.50		
43	1	Exhaust muffler heat shield	X	\$ 165.00		
44	2	Rear plate lamp LH/RH	X	\$ 250.00		
45	1	Rear number plate with frame	X		\$ 50.00	
46	1	Tailgate windscreen sealant	NA		\$ 80.00	
47	1	Tailgate windscreen inner seal	NA		\$ 80.00	
48	1	Rear end panel sealant	X		\$ 80.00	
49	1	Reverse sensor	?	200	\$ 300.00	
50	1	Spare tyre panel sealant	X		\$ 80.00	
51	1	Spare tyre panel padding	X		\$ 350.00	
52	1	Sundries	20		\$ 60.00	
53	0	0				
54	0	0				
55	0	0				
56	0	0				
57	0	0				
58	0	0				
59	0	0				
60	0	0				
61	0	0				
62	0	0				
63	0	0				
64	0	0				
65	0	0				
66	0	0				
67	0	0				
68	0	0				
69	0	0				
70	0	0				
71	0	0				
72	0	0				
73	0	0				
74	0	0				
75	0	0				
76	0	0				
77	0	0				
78	0	0				
79	0	0				
80	0	0				

SN- 2180

6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

PAGE 1

[illegible] $L = 1110$

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Feb 2018		07 Feb 2018 13:06 Edit Adj Rpt	S\$2,750.00 Edit Estimates	S\$2,750.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	LEE CHER CHIANG, ID: S7902088E								
Main Claimant:	LCRF PTE LTD, Co. Reg. No.: 201624597K								
Vehicle Reg. No.:	SLE3963H	Date of Loss:	02/02/2018 08:00 - :59 [18 Months and 13 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D00637C02	Policy/Cover Note No.:	DMPCSN3039991702 (Comprehensive)						
Vehicle Reg. No. (Insured):	SDA2389M	Policy No. (Claimant):	999995062						
		Excess:	S\$0.00						
Repairer:	Vermogen Ace Pte Ltd (HQ) 1 Bukit Batok Crescent, #04-54/55 WCEGA Plaza, 658064 Bukit Batok - Tel: 65155230								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Sharon Han - 63896]								
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 19/02/2018]								
Driver/Custodian (Insured):	LEE CHER CHIANG (38 / Female), NRIC: S7902088E								
Adj. Asg. Remarks:	NO EST, CASE WITH SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLE3963H (SNM18D00637C02)
[SDA2389M]
TP
LCRF PTE LTD
Feb 2 2018 8:00AM
[LEE CHER CHIANG]
Vermogen Ace Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Video			1 per page	☒
No	Finalized On	Vermogen Ace Pte Ltd (HQ)	Thumbnail	Print
1	02/02/18 15:17	Video - Accident [Linked Accident Report Documents]	Load MP4	
Assessment Reports			1 per page	☒
No	Finalized On	Vermogen Ace Pte Ltd (HQ)	Thumbnail	Print
1	02/02/18 15:18	Accident Statement	Load HTM	
2	05/02/18 09:53	Addendum Sheet	Load TIF	
3	05/02/18 09:58	Accident Statement Addm. #1	Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Vermogen Ace Pte Ltd (HQ)	Thumbnail	Print
1	02/02/18 14:55	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
2	02/02/18 14:55	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
3	02/02/18 14:55	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
4	02/02/18 14:55	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
5	02/02/18 14:55	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
6	02/02/18 14:55	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
7	02/02/18 14:55	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/04/18 13:48	General View	Load JPG	☒
2	25/04/18 13:48	General View	Load JPG	☒
3	25/04/18 13:48	General View	Load JPG	☒
4	25/04/18 13:48	General View	Load JPG	☒
5	25/04/18 13:48	General View	Load JPG	☒
6	25/04/18 13:48	General View	Load JPG	☒
7	25/04/18 13:48	General View	Load JPG	☒
8	25/04/18 13:48	General View	Load JPG	☒
9	25/04/18 13:48	General View	Load JPG	☒
10	25/04/18 13:48	General View	Load JPG	☒
11	25/04/18 13:48	General View	Load JPG	☒
12	25/04/18 13:48	General View	Load JPG	☒
13	25/04/18 13:48	General View	Load JPG	☒
14	25/04/18 13:48	General View	Load JPG	☒
15	25/04/18 13:48	General View	Load JPG	☒
16	25/04/18 13:48	General View	Load JPG	☒
17	25/04/18 13:48	General View	Load JPG	☒
18	25/04/18 13:48	General View	Load JPG	☒

Video			1 per page	☒
No	Finalized On	Vermogen Ace Pte Ltd (HQ)	Thumbnail	Print
19	25/04/18 13:48	General View	 Load JPG	☒
20	25/04/18 13:48	General View	 Load JPG	☒
21	25/04/18 13:48	General View	 Load JPG	☒
22	25/04/18 13:48	General View	 Load JPG	☒
23	25/04/18 13:48	General View	 Load JPG	☒
24	25/04/18 13:48	General View	 Load JPG	☒
25	25/04/18 13:48	General View	 Load JPG	☒
26	25/04/18 13:48	General View	 Load JPG	☒
27	25/04/18 13:48	General View	 Load JPG	☒
28	25/04/18 13:48	General View	 Load JPG	☒
29	25/04/18 13:49	Reinspection Photo	 Load JPG	☒
30	25/04/18 13:49	Reinspection Photo	 Load JPG	☒
31	25/04/18 13:49	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	07/02/18 13:05	PRS	 Load PDF	
2	07/02/18 13:06	OI GIA REPORT	 Load PDF	
No	Finalized On	Vermogen Ace Pte Ltd (HQ)	Thumbnail	Print
1	02/02/18 14:57	IC [Linked Accident Report Documents]	 Load TIF	
2	05/02/18 09:53	Sketch Plan [Linked Accident Report Documents]	 Load TIF	
3	05/02/18 09:53	POLICE REPORT [Linked Accident Report Documents]	 Load TIF	

Linked Accident Report Documents

Video			View	View in Browser
No	Finalized On	Vermogen Ace Pte Ltd (HQ)	Thumbnail	Print
1	02/02/18 15:17	Video - Accident	 Load MP4	
Assessment Reports			1 per page	☒
No	Finalized On	Vermogen Ace Pte Ltd (HQ)	Thumbnail	Print
1	02/02/18 15:18	Accident Statement	 Load HTM	
2	05/02/18 09:53	Addendum Sheet	 Load TIF	
3	05/02/18 09:58	Accident Statement Addm. #1	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Vermogen Ace Pte Ltd (HQ)	Thumbnail	Print
1	02/02/18 14:55	Accident Photo	 Load JPG	☒
2	02/02/18 14:55	Accident Photo	 Load JPG	☒
3	02/02/18 14:55	Accident Photo	 Load JPG	☒
4	02/02/18 14:55	Accident Photo	 Load JPG	☒
5	02/02/18 14:55	Accident Photo	 Load JPG	☒
6	02/02/18 14:55	Accident Photo	 Load JPG	☒
7	02/02/18 14:55	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Vermogen Ace Pte Ltd (HQ)	Thumbnail	Print
1	02/02/18 14:57	IC	 Load TIF	
2	05/02/18 09:53	Sketch Plan	 Load TIF	
3	05/02/18 09:53	POLICE REPORT	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer			
Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT18002515/T1QD3Q2

Date: 25/04/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN3039991702

Claimant Vehicle
No: SLE3963HInsured Vehicle
No: SDA2389M

Date of Loss: 02/02/2018

Nature of Claim: TP

Claim
No: SNM18D00637C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLE3963H

Make & Model: HONDA VEZEL, 1.5 (A)

Engine No: L15B4037385

Reg. Date: 20/07/2016 (Man. Year: 2016)

Chassis No: RU11117361

Colour: White

Odometer: 0 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,591.76	2,357.76	10,234.00	81.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,270.00	1,110.00	3,160.00	74.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,861.76	3,467.76	13,394.00	79.43
Approved Total (Overridden) (S\$)		2,750.00		
(S\$)	16,861.76	2,750.00	14,111.76	83.69
+ GST 7.00/7.00% (S\$)	1,180.32	192.50	987.82	83.69
Nett Amount (S\$)	18,042.08	2,942.50	15,099.58	83.69

INSPECTION

Date of Assignment: 07/02/2018

Date Inspected: 07/02/2018 Inspected At:

Vermogen Ace Pte Ltd (HQ)
1 Bukit Batok Crescent, #04-54/55
WCEGA Plaza
Singapore 658064

Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Apr 2018)
Parts:	M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLE3963H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	1,860.00 FL	*1,200.00 FL
2	1		*TAILGATE OUTER GARNISH	Not Necessary	285.00 FL	*- FL
3	1		*SET TAILGATE OUTER GARNISH CLIPS	Not Necessary	40.00 FL	*- FL
4	1		*TAILGATE LOGO	Necessary	52.00 FL	*52.00 FL
5	1		*TAILGATE EMBLEM VEZEL	Necessary	56.20 FL	*56.20 FL
6	2		*TAILGATE LAMP LH/RH	Not Necessary	980.00 FL	*- FL
7	2		*SET TAILGATE LAMP CLIPS	Not Necessary	50.00 FL	*- FL
8	1		*TAILGATE OUTER HANDLE SWITCH	Not Necessary	180.00 FL	*- FL
9	2		*TAILGATE DAMPER LH/RH	Not Necessary	424.00 FL	*- FL
10	1		*TAILGATE WIPER MOTOR	Not Necessary	250.00 FL	*- FL
11	1		*TAILGATE WIPER BLADE	Not Necessary	75.00 FL	*- FL
12	1		*TAILGATE BUZZER	Not Necessary	150.00 FL	*- FL
13	1		*TAILGATE INNER HANDLE	Not Necessary	74.00 FL	*- FL
14	1		*TAILGATE INNER LOCK	Not Necessary	245.00 FL	*- FL
15	1		*TAILGATE LOCK SENSOR	Not Necessary	220.00 FL	*- FL
16	1		*TAILGATE STRIKER	Not Necessary	32.00 FL	*- FL
17	1		*TAILGATE TRIMBOARD	Not Necessary	295.00 FL	*- FL
18	1		*SET TAILGATE TRIMBOARD CLIPS	Not Necessary	45.00 FL	*- FL
19	1		*TAILGATE WEATHERSTRIP	Not Necessary	145.00 FL	*- FL
20	1		*SET TAILGATE WINDSCREEN MOULDING	Necessary	164.00 FL	*164.00 FL
21	2		*TAIL LAMP LH/RH	Not Necessary	978.00 FL	*- FL
22	1		*SET TAIL LAMP CLIPS	Not Necessary	36.00 FL	*- FL
23	1		*REAR BUMPER	Deformed	950.00 FL	*950.00 FL
24	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
25	2		*REAR BUMPER RETAINER LH/RH	Not Necessary	144.00 FL	*- FL
26	2		*REAR BUMPER BRACKET LH/RH	Not Necessary	232.00 FL	*- FL
27	2		*REAR BUMPER REFLECTOR LH/RH	Not Necessary	334.00 FL	*- FL
28	2		*REAR BUMPER COVER LH/RH	Not Necessary	420.00 FL	*- FL
29	1		*SET REAR BUMPER COVER CLIPS	Not Necessary	50.00 FL	*- FL
30	2		*REAR BUMPER COVER RETAINER LH/RH	Not Necessary	84.00 FL	*- FL
31	1		*REAR END PANEL OUTER	Repair	585.00 FL	*- FL
32	1		*REAR END PANEL INNER	Not Necessary	396.00 FL	*- FL
33	1		*REAR END PANEL TOP GARNISH	Not Necessary	184.00 FL	*- FL
34	1		*SET REAR END PANEL TOP GARNISH CLIPS	Not Necessary	25.00 FL	*- FL
35	1		*SPARE TYRE PANEL	Not Necessary	1,230.00 FL	*- FL
36	1		*SPARE TYRE PANEL INSULATOR	Not Necessary	240.00 FL	*- FL
37	1		*SPARE TYRE PANEL TOP BOARD	Not Necessary	420.00 FL	*- FL
38	1		*SPARE TYRE TOOL TRAY	Not Necessary	430.00 FL	*- FL
39	2		*REAR FENDER INNER TRIM LH/RH	Not Necessary	480.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	2		*REAR FENDER AIR DUCT LH/RH	Not Necessary	150.00 FL	*- FL
41	1		*EXHAUST MUFFLER	Not Necessary	855.00 FL	*- FL
42	1		*EXHAUST MUFFLER MOUNTING	Not Necessary	79.50 FL	*- FL
43	1		*EXHAUST MUFFLER HEAT SHIELD	Not Necessary	165.00 FL	*- FL
44	2		*REAR PLATE LAMP LH/RH	Not Necessary	250.00 FL	*- FL
45	1		*REAR NUMBER PLATE WITH FRAME	Not Necessary	50.00 FS	*- FS
46	1		*TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*80.00 FS
47	1		*TAILGATE WINDSCREEN INNER SEAL	Necessary	80.00 FS	*80.00 FS
48	1		*REAR END PANEL SEALANT	Not Necessary	80.00 FS	*- FS
49	1		*REVERSE SENSOR	Not Working	300.00 FS	*200.00 FS
50	1		*SPARE TYRE PANEL SEALANT	Not Necessary	80.00 FS	*- FS
51	1		*SPARE TYRE PANEL PADDING	Not Necessary	350.00 FS	*- FS
52	1		*SUNDRIES	Necessary	60.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc

Sub Total (\$\$)	15,469.70	2,852.20
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,877.94	494.44
Total Parts (\$\$)	12,591.76	2,357.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO STRAIGHTEN AND PANEL BEATING ACCIDENT AREA,REAR PORTION.TAILGATE ,TAILGATE OUTER GARNISH ,REAR BUMPER COVER LH/RH,REAR END PANEL,SPARETYRE PANEL,REAR FENDER LH/RH	New	1,400.00	400.00
2	TO REMOVE AND TRANSFER TAILGATE COMPONENTS	New	150.00	60.00
3	TO REMOVE AND REFIT TAILGATE WINDSCREEN	New	150.00	120.00
4	TO REMOVE AND REFIT REVERSE SENSOR	New	120.00	30.00
5	TO RUST PROOF AFFECTED AREAS	New	250.00	30.00
6	TO CHECK AND RECTIFY WIRING AFTER DISCONNECT AND CONNECT	New	100.00	30.00
7	TO REMOVE AND REFIT INTERIOR PARTS TO GIVE WAY THE REPAIR	New	150.00	40.00
8	TO REMOVE AND ALIGN EXHAUST PIPE	New	150.00	0.00
9	TO PUTTY,RESPRAY PAINTING AND POLISH ACCIDENT AREA,REAR PORTION .TAILGATE ,TAILGATE OUTER GARNISH ,REAR BUMPER COVER LH/RH,REAR END PANEL,SPARETYRE PANEL,REAR FENDER LH/RH	New	1,800.00	400.00
Gross Labour Cost (\$\$)			4,270.00	1,110.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >