

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG.MO KIO ST63 SINGAPORE 569111

TEL'NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5045Z - AIG

AAD1802-053

Not Authorised
21 Sep 889001

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC5045Z - CANDY

VF1ABL15AUC276053

RENAULT

LATITUDE

05.02.2018

AIG**PART****LIST**

1	1	BUMPER COVER FRT	\$	<i>Sn</i>	1,259.42	✓
2	1	BUMPER ABSORBER FRT	\$	<i>Sn</i>	394.68	X
3	1	BUMPER BEAM FRT	\$	<i>R</i>	914.08	X
4	1	BUMPER SPOILER FRT	\$	<i>Sn</i>	181.75	X
5	1	BUMPER UNDERTRAY FRT	\$	<i>Sn</i>	472.83	X
6	1	BUMPER GRILLE LOWER FRT	\$	<i>Sn</i>	266.80	X
7	1	BUMPER FOG LAMP GRILLE LH	\$	<i>Sn</i>	207.22	X
8	1	BUMPER RETAINER FRT LH	\$	<i>Dit</i>	151.41	✓
9	1	BUMPER BRACKET FRT LH	\$	<i>R</i>	181.75	X
10	1	HEADLAMP LH	\$	<i>myem</i>	1,184.43	✓
11	1	HEADLAMP PANEL FRT LH	\$	<i>R</i>	152.15	X
12	1	FENDER PANEL FRT LH	\$	<i>R</i>	783.83	✓
13	1	FENDER INSULATOR LH	\$	<i>Sn</i>	130.84	} X
14	1	FENDER BRACKET FRT LH	\$	<i>R</i>	34.14	
15	1	WHEELARCH FRT LH	\$	<i>R</i>	278.84	
16	1	RADAITOR GRILLE	\$	<i>Sn</i>	1,707.78	
17	1	RADAITOR GRILLE BADGE 'RENAULT'	\$	<i>Sn</i>	173.36	
18	1	RADAITOR GRILLE FRAME	\$	<i>Sn</i>	1,353.75	} X
19	1	FRAME FULL SUPPORT PANEL	\$	<i>Sn</i>	615.90	
20	1	FRAME FULL SUPPORT BRACKET	\$	<i>R</i>	89.79	
21	1	BONNET	\$	<i>R</i>	1,941.63	} X
22	1	DOOR MIRROR LH	\$	<i>Sn</i>	1,483.40	
23	1	DOOR MIRROR GLASS LH	\$	<i>Sn</i>	242.33	
24	1	DOOR MIRROR BACK COVER LH	\$	<i>Sn</i>	218.46	} X
25	1	DOOR MIRROR LAMP LH	\$	<i>Sn</i>	194.18	
26	1	DOOR PANEL FRT LH	\$	<i>R</i>	2,844.66	✓
27	1	DOOR FRAME PANEL FRT LH	\$	<i>R</i>	5,550.98	X
28	1	DOOR HINGE UPPER LH	\$	<i>R</i>	274.50	X
29	1	DOOR HINGE LOWER LH	\$	<i>R</i>	300.55	X
30	1	DOOR CHECK FRT LH	\$	<i>Sn</i>	194.77	X
31	1	DOOR LOCK FRT LH	\$	<i>R</i>	908.75	X
32	1	DOOR CATCH FRT LH	\$	<i>Sn</i>	131.23	X
33	1	DOOR GRAB HANDLE FRT LH	\$	<i>Sn</i>	210.96	X
34	1	DOOR HANDLE OUTER FRT LH	\$	<i>R</i>	477.76	✓

TRANS-CAB AUTO SERVICES PTE LTD**AAD1802-053**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5045Z - AIG

35	1	DOOR HANDLE CAP FRT LH	\$	<i>mt</i>	35.52	—
36	1	DOOR HANDLE SEAL FRT LH	\$	<i>mt</i>	7.89	—
37	1	DOOR HANDLE COVER FRT LH	\$	<i>Sn</i>	13.22	X
38	1	DOOR HANDLE MODULE FRT LH	\$	<i>Sn</i>	133.60	X
39	1	DOOR FINISHER FRT LH	\$	<i>Sn</i>	515.06	X
40	1	DOOR MOULDING FRT LH	\$	<i>Sn</i>	176.82	X
41	1	DOOR WHETHERSTRIP FRT LH	\$	<i>Sn</i>	410.27	X
42	1	DOOR SEAL LOWER FRT LH	\$	<i>Sn</i>	91.17	X
43	1	DOOR SEAL FRT LH	\$	<i>Sn</i>	72.82	X
44	1	DOOR GLASS RUNNER SEAL FRT LH	\$	<i>Sn</i>	626.36	X
45	1	DOOR WAIST SEAL OUTER FRT LH	\$	<i>Sn</i>	291.27	X
46	1	ROCKER PANEL OUTER LH	\$	<i>N</i>	987.49	X
47	1	DOOR PANEL REAR LH	\$	<i>Ry</i>	2,844.66	✓
48	1	DOOR GUIDE REAR LH	\$	<i>N</i>	176.82	} X
49	1	DOOR HINGE UPPER LH	\$	<i>N</i>	274.50	
50	1	DOOR HINGE LOWER	\$	<i>Sn</i>	300.55	
51	1	DOOR CHECK REAR LH	\$	<i>Sn</i>	203.06	
52	1	DOOR GRAB HANDLE REAR LH	\$	<i>Sn</i>	210.96	
53	1	DOOR HANDLE OUTER REAR LH	\$	<i>Sn</i>	126.49	
54	1	DOOR HANDLE CAP REAR LH	\$	<i>Sn</i>	35.52	
55	1	DOOR HANDLE SEAL REAR LH	\$	<i>Sn</i>	7.89	
56	1	DOOR HANDLE COVER REAR LH	\$	<i>Sn</i>	13.22	
57	1	DOOR HANDLE MODULE REAR LH	\$	<i>Sn</i>	133.60	
58	1	DOOR FINISHER REAR LH	\$	<i>Sn</i>	423.10	
59	1	DOOR MOULDING REAR LH	\$	<i>Sn</i>	176.82	
60	1	DOOR SEAL REAR LH	\$	<i>Sn</i>	162.02	
61	1	DOOR WAIST SEAL OUTER REAR LH	\$	<i>Sn</i>	334.69	
62	1	FENDER PANEL REAR LH	\$	<i>N</i>	3,299.13	
63	1	BUMPER COVER REAR	\$	<i>Sn</i>	1,108.46	

TOTAL	\$	38,701.89
10%	\$	3,870.19
	\$	34,831.70

Specical Nett

1	1SET	WHEELARCH CLIP FRT LH	\$	<i>na</i>	66.00	X
2	1SET	FRONT BUMPER CLIP	\$	<i>na</i>	66.00	✓
3	1SET	BUMPER SUPPORT FRT CLIP LH	\$	<i>na</i>	9.80	X
4	1SET	BUMEPR RETAINER FRT CLIP LH	\$	<i>na</i>	12.50	X
5	1	RIM LH FRT	\$	<i>Sn</i>	385.00	X
6	1	TYRE LH FRT	\$	<i>Sn</i>	330.00	X
7	1	DOOR STICKER "Trans-cab"	\$	<i>Mr</i>	80.00	<i>born</i>

TRANS-CAB AUTO SERVICES PTE LTD

AAD1802-053

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5045Z - AIG

8	1	DOOR STICKER "Classic"	\$	<i>nn</i>	30.00	<i>15sn</i>
9	1	DOOR STICKER "6555-3333"	\$	<i>nn</i>	80.00	<i>60sn</i>

TOTAL	\$	1,059.30
TOTAL PARTS	\$	35,891.00

To Check Electrical Lighting Concerned.	\$	170.00	<i>2ol</i>
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,200.00	<i>60q</i>
Putty and spray painting of the affected portion.	\$	4,500.00	<i>132ol</i>
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	170.00	<i>6ol</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00	<i>X</i>
To check steering geometry and computer wheel alignment	\$	220.00	<i>6ol</i>
To Remove And Refit Front W/Screen Glass To Facilitate Bodywork Repair.	\$	<i>nn</i> 170.00	<i>X</i>
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00	<i>12ol</i>
Towing fees	\$	<i>nn</i> 120.00	<i>X</i>
To rust-proofing of the affected areas.	\$	170.00	<i>Pol</i>

TOTAL	\$	10,060.00
Over All Total	\$	45,951.00

(PARTS BY PARTS) Repair Days**15 Days**

5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: