

TRANS-CAB AUTO SERVICES PTE LTD
 NO.2 ANG MO KIO ST63 SINGAPORE 569111
 TEL NO. 6287 6666 FAX NO. 6257 1330
 CO/GST REG NO. 201019626G
SHD186G - AIG

AAD1802-037

Not Authorized
Returning By paint 86501

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD186G - JHOW

VF1ABL15AUC282239

RENAULT

LATITUDE

03.02.2018

AIG

PART

LIST

1	1	BUMPER COVER FRT	\$	1,259.42	X
2	1	BUMPER SPOILER FRT	\$	181.75	
3	1	BUMPER FOG LAMP GRILLE LH	\$	207.22	
4	1	BUMPER RETAINER FRT LH	\$	151.41	
5	1	BUMPER RETAINER FRT RH	\$	151.41	
6	1	BUMPER SUPPORT FRT LH	\$	123.88	
7	1	BUMPER SUPPORT FRT RH	\$	123.88	
8	1	BUMPER BEAM FRT	\$	914.08	
9	1	RADAITOR GRILLE	\$	1,707.78	
10	1	RADAITOR GRILLE BADGE 'RENAULT'	\$	225.36	
11	1	RADAITOR GRILLE FRAME	\$	1,353.75	
12	1	FRAME FULL SUPPORT PANEL	\$	615.90	
13	1	FRAME FULL SUPPORT BRACKET	\$	89.79	
14	1	BONNET	\$	1,941.63	
15	1	HEADLAMP LH	\$	1,184.43	
16	1	HEADLAMP PANEL FRT LH	\$	152.15	
17	1	FENDER PANEL FRT LH	\$	783.83	
18	1	WHEELARCH FRT LH	\$	278.84	
19	1	DOOR MIRROR LH	\$	1,483.40	
20	1	DOOR MIRROR GLASS LH	\$	148.20	
21	1	DOOR MIRROR BACK COVER LH	\$	218.46	
22	1	DOOR PANEL FRT LH	\$	2,844.66	
23	1	DOOR HINGE UPPER LH	\$	274.50	
24	1	DOOR HINGE LOWER LH	\$	300.55	
25	1	DOOR PANEL REAR LH	\$	2,844.66	

TOTAL	\$	19,560.94
10%	\$	1,956.09
	\$	17,604.85

Specical Nett

1	1SET	FRONT BUMPER CLIP	\$	66.00 X
2	1SET	WHEELARCH CLIP LH	\$	66.00 X

TRANS-CAB AUTO SERVICES PTE LTD**AAD1802-037**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD186G -

3	1	TOW COVER FRT	\$	14.50	}
4	1	CAP HUB LH FRT	\$	35.00	
5	1	RIM LH FRT	\$	385.00	
6	1	TYRE LH FRT	\$	330.00	
7	1SET	BUMPER SUPPORT FRT CLIP LH	\$	9.80	
8	1SET	BUMPER RETAINER FRT CLIP LH	\$	12.50	
9	1	DOOR STICKER "Trans-cab"	\$	80.00	
10	1	DOOR STICKER "Classic"	\$	30.00	}

TOTAL	\$	1,028.80
TOTAL PARTS	\$	18,633.65

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 2,800.00 *2001*

To Check Electrical Lighting Concerned.

\$ 170.00 *101*

Putty and spray painting of the affected portion.

\$ 3,000.00 *4401*

To check steering geometry and computer wheel alignment

\$ 220.00 *X*

Towing Fees

\$ 120.00 *X*

To transfer of tire, rim and on wheel balancing.

\$ 170.00 *X*

To rust-proofing of the affected areas.

\$ 170.00 *X*

To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.

\$ 170.00 *X*

TOTAL	\$	6,820.00
Over All Total	\$	25,453.65

(PARTS BY PARTS) Repair Days**10-Days**

2 days
 LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: