

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHF610M - AIG**AAD1802-051***Not Authorised*
L1 Imp &

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHF610M - CANDY

VF1ABL15AUC278449

RENAULT

LATITUDE

05.02.2018

AIG**PART****LIST**

1	1	BUMPER COVER REAR	\$	<i>By</i> 1,108.46	—
2	1	BUMPER LOWER REAR	\$	<i>mis</i> 768.84	—
3	1	BUMPER BRACKET CTR REAR	\$	<i>Dis</i> 113.47	—
4	1	BUMEPR BRACKET SIDE RH REAR	\$	<i>Sn</i> 135.97	X
5	1	BUMEPR RETAINER RH REAR	\$	<i>Sn</i> 44.99	X
6	1	BUMPER REFLECTOR RH	\$	<i>CM</i> 43.61	—
7	1	BUMEPR BRACKET SIDE LH REAR	\$	<i>Sn</i> 135.97	X
8	1	BUMEPR RETAINER LH REAR	\$	<i>Sn</i> 44.99	X
9	1	BUMPER REFLECTOR LH	\$	<i>Sn</i> 43.61	X
10	1	BUMPER BEAM REAR	\$	<i>By</i> 777.52	—
11	1	BUMPER BEAM BRACKET LH REAR	\$	<i>By</i> 225.95	—
12	1	BUMPER BEAM BRACKET RH REAR	\$	<i>By</i> 225.95	—
13	1	BOOT REAR	\$	<i>By</i> 2,872.68	—
14	1	BOOT FINISHER	\$	<i>Sn</i> 470.06	X
15	1	BOOT WHEATERSTRIP	\$	<i>Dis/By</i> 323.05	<i>50/50</i>
16	1	BOOT REFLECTOR LAMP LH	\$	<i>CM</i> 493.35	—
17	1	BOOT REFLECTOR LAMP RH	\$	<i>CM</i> 493.35	—
18	1	BOOT BADGE 'RENAULT'	\$	<i>Re</i> 225.36	—
19	1	BOOT BADGE	\$	<i>Re</i> 225.36	—
20	1	BOOT STRUT LH	\$	<i>Sn</i> 276.08	X
21	1	BOOT STRUT RH	\$	<i>Sn</i> 276.08	X
22	1	BOOT HINGE LH	\$	<i>R</i> 367.84	X
23	1	BOOT HINGE RH	\$	<i>R</i> 367.84	X
24	1	BOOT INNER TRIM	\$	<i>Sn</i> 586.45	X
25	1	BOOT SWITCH	\$	<i>Sn</i> 168.13	X
26	1	BOOT LOCK	\$	<i>Re</i> 202.67	—
27	1	BOOT LOCK CATCH	\$	<i>R</i> 74.40	X
28	2	LICENCE PLATE LAMP	\$	<i>Sn</i> 50.52	X
29	2	BOOT RUBBER PLUG	\$	<i>Sn</i> 221.81	X
30	1	FENDER PANEL INNER TRIM REAR LH	\$	<i>Sn</i> 671.45	X
31	1	FENDER PANEL REAR LH	\$	<i>R</i> 3,299.13	X
32	1	WHEELARCH REAR LH	\$	<i>Sn</i> 543.47	X
33	1	FENDER PANEL INNER TRIM REAR RH	\$	<i>Sn</i> 671.45	X
34	1	FENDER PANEL REAR RH	\$	<i>R</i> 3,299.13	X

TRANS-CAB AUTO SERVICES PTE LTD**AAD1802-051**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHF610M - AIG

35	1	WHEELARCH REAR RH	\$	<i>Sn</i> 543.47 X
36	1	TAILLAMP RH	\$	<i>mgcns</i> 552.55 ✓
37	1	TAILLAMP PANEL RH	\$	<i>R</i> 986.70 X
38	1	TAILLAMP LH	\$	<i>mgcns</i> 552.55 ✓
39	1	TAILLAMP PANEL LH	\$	<i>R</i> 986.70 X
40	1	OUTER PANEL REAR (End Panel)	\$	<i>Ry</i> 1,471.77 ✓
41	1	OUTER PANEL REAR (End Panel)TRIM	\$	<i>nd</i> 404.56 ✓
42	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	<i>R1/Bu</i> 2,189.88 ✓
43	1	SPARE WHEEL PANEL TRIM	\$	<i>Sn</i> 612.21 X
44	1	EXHAUST REAR	\$	<i>R</i> 7,489.05 X
45	1	EXHAUST CAP REAR	\$	<i>nd</i> 230.49 ✓

TOTAL	\$	35,868.94
10%	\$	3,586.89
	\$	32,282.05

Specical Nett

1	1SET	PARKING AID	\$	<i>Shom</i> 700.00 ✓
2	1SET	REAR BUMPER CLIP	\$	<i>na</i> 66.00 ✓
3	1SET	BUMPER BRACKET CTR CLIP	\$	<i>na</i> 33.00 ✓
4	1SET	BUMEPR BRACKET SIDE CLIP RH RR	\$	<i>na</i> 10.00 X
5	1SET	BUMEPR RETAINER RH CLIP RR	\$	<i>na</i> 20.00 X
6	1SET	BUMEPR BRACKET SIDE CLIP LH RR	\$	<i>na</i> 10.00 X
7	1SET	BUMEPR RETAINER CLIP LH RR	\$	<i>na</i> 20.00 X
8	1SET	BUMPER LOWER REAR RIVET	\$	<i>na</i> 22.00 X
9	1SET	BUMPER LOWER REAR CLIP	\$	<i>na</i> 66.00 ✓
10	1	EXHAUST MOUNTING REAR	\$	<i>Sn</i> 17.82 X
11	1SET	BOOT FINISHER CLIP	\$	<i>na</i> 24.20 X
12	1	BOOT STICKER "Trans-cab"	\$	<i>na</i> 30.00 ✓
13	1	BOOT STICKER "6555-3333"	\$	<i>na</i> 30.00 ✓
14	1	BOOT INNER TRIM CLIP	\$	<i>na</i> 45.00 X
15	1SET	FENDER WHEELARCH REAR RH CLIP	\$	<i>na</i> 35.00 X
16	1SET	FENDER WHEELARCH REAR LH CLIP	\$	<i>na</i> 35.00 X
17	1	FENDER INNER TRIM CLIP LH	\$	<i>na</i> 28.00 X
18	1	FENDER INNER TRIM CLIP LH	\$	<i>na</i> 28.00 X
19	1	TAILLAMP CLIP RH	\$	<i>na</i> 5.00 ✓
20	1	TAILLAMP CLIP LH	\$	<i>na</i> 5.00 ✓
21	2	REAR WINDSCREEN SELANT	\$	<i>na</i> 80.00 X
22	1	WINDSCREEN MOULDING	\$	<i>na</i> 100.00 X
23	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>na</i> 100.00 X
24	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	<i>Sn</i> 385.00 X

TRANS-CAB AUTO SERVICES PTE LTD

AAD1802-051

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHF610M - AIG

25	1	SPARE TYRE	\$	na 330.00 X
----	---	------------	----	-------------

TOTAL	\$	2,225.02
TOTAL PARTS	\$	34,507.07

Putty And Spray Painting Of The Affected Portion.	\$	5,600.00 880.00
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	5,400.00 1200.00
To Rust-Proofing Of The Affected Areas.	\$	170.00 90.00
To reinstall rear bumper parking sensor.	\$	170.00 60.00
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00 60.00
To repair and realign rear exhaust pipe.	\$	170.00
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00
To supply and re-do rear luggage floor panel insulation padding.	\$	380.00 80.00
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	na 380.00 X
Towing Fees	\$	na 120.00 X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	na 170.00 X
To check steering geometry and computer wheel alignment	\$	na 220.00 X

TRANS-CAB AUTO SERVICES PTE LTD
NO.2 ANG MO KIO ST63 SINGAPORE 569111
TEL NO. 6287 6666 FAX NO. 6257 1330
CO/GST REG NO. 201019626G
SHF610M - AIG

AAD1802-051

TOTAL	\$	13,460.00
Over All Total	\$	47,967.07

(PARTS BY PARTS)
Repair Days

~~20~~Days
10 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during survey
- Parts prices are subject to quotation
- Third party survey is on a "No Fault Found" basis
- No illegal modifications allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: