



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
ESTIMATE COST OF REPAIRS



AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN : MOTOR CLAIMS FAX :		NAME : Mr Seow Khee Choon ADDRESS : 8 Hindhede Place Singapore 587858 TEL :		WIP : 61431 EXCESS : DATE: 7-Feb-18	
VEH NO :	SBU92A	DATE IN :		CONTACT PERSON :	JESS 6395 7874
CHASSIS NO :	JM6BM4278G0300965	MILEAGE :	42264	TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA3 2.0L	DATE REG.:	10-Mar-15	POLICY NO. :	

NATURE OF WORKS

Parts Description

NO	QTY	REVISED	PRICES
1	FRONT BUMPER / Re	1	MBHR3-50-031BBB \$ 1,031.70
2	RETAINER(LHS), FRONT BUMPER / L ABC	1	MBHN1-50-0U1E \$ 18.70
3	RETAINER(RHS), FRONT BUMPER / L ABC	1	MBHN1-50-0T1F \$ 18.70
4	BRACKET(LHS), FRONT BUMPER X NN	1	MBHN1-50-162 \$ 15.10
5	BRACKET(RHS), FRONT BUMPER / MCL	1	MBHN1-50-152 \$ 15.10
6	COVER(RHS), FOGLAMP / L mis	1	MBJE1-50-C11A \$ 46.40
7	CHROME(RHS), FOGLAMP / L mis	1	MBJE1-50-C12 \$ 106.70
8	FRONT REINFORCEMENT ?	1	MB45A-50-070A \$ 444.50
9	GROMMET, FRONT BUMPER / }	2	MGHP9-50-0Z5 \$ 5.40
10	CLIP, FRONT BUMPER / }	14	MC274-50-133 \$ 49.00
11	FASTENER, FRONT BUMPER / }	2	MB45A-56-146A \$ 5.60
12	GRILLE TOP / Re	1	MBHN1-50-033 50 \$ 335.00
13	RIVET, GRILLE TOP / L ABC	6	MS51S-51-833 \$ 22.80
14	RIVET, GRILLE TOP / L ABC	4	MTK21-50-355 \$ 34.80
15	BRACKET TOP, GRILLE ?	1	MBHN1-50-717D \$ 102.40
16	CHROME(LHS), FRONT BUMPER # ?	1	MBHN1-50-7K1A \$ 176.70
17	CHROME(RHS), FRONT BUMPER / CMA	1	MBHN1-50-7J1A \$ 176.70
18	GRILLE:BLACK (GLOSS) / Cut	1	MBJE1-50-712B \$ 581.60
19	MASCOT, FRONT / MCL	1	MC235-51-731A \$ 44.20
20	BRACKET(LHS), FRONT BUMPER X NN	1	MBHN1-50-163 \$ 15.10
21	BRACKET(RHS), FRONT BUMPER / MCL	1	MBHN1-50-153 \$ 15.10
22	PIN LOCATOR, GRILLE / }	2	MKD45-50-1K5A \$ 5.40
23	GROMMET, GRILLE / }	2	MKD45-50-ES1 \$ 5.40
24	RIVET, GRILLE / }	2	MEA01-50-037 \$ 15.20
25	FASTENER, GRILLE / }	8	MGD7A-50-EA1 \$ 24.00
26	PLATE,SET (REINFORCEMENT) ?	1	MBHN1-50-1C0B \$ 158.40
27	FASTENER, PLATE SET / MCL	4	MGD7A-50-EA1 \$ 12.00
28	GRILLE,UNDER ?	1	MBJD6-50-R10A \$ 693.60
29	PLATE,SET (CENTER) ?	1	MBHN9-50-1C0A \$ 32.40
30	COVER(RHS), HEADLAMP WASHER / M.S	1	MBHT4-51-8G1 50 \$ 85.10

31	ACTUATOR(RHS), HEADLAMP WASHER	✓ mis	1	MBHT4-51-82X	\$ 242.40
32	CLAMP, ACTUATOR	✓ mis	1	MTK33-51-829	\$ 16.40
33	TANK, WASHER	X ✓ NN	1	MGHP9-67-481	\$ 104.00
34	HEADLAMP RHS	✓	1	MBHT6-51-031A	\$ 2,245.00
35	CLIP, HEADLAMP	X ✓ NN	2	MFB01-50-133C	\$ 7.60
36	RIVET, HEADLAMP	X ✓ NN	1	MB092-51-833	\$ 3.30
37	REAR BUMPER	✓ re	1	MBPD8-50-221ABB	\$ 1,074.80
38	RETAINER(LHS), REAR BUMPER	✓ { MC	1	MBHN1-50-2J1A	\$ 36.10
39	RETAINER(RHS), REAR BUMPER	✓ { MC	1	MBHN1-50-2H1A	\$ 36.10
40	BRACKET(LHS), REAR BUMPER	X ✓ NN	1	MBHN9-51-077B	\$ 45.60
41	BRACKET(RHS), REAR BUMPER	✓ MC	1	MBHN9-51-067B	\$ 45.60
42	BRACKET LOWER, REAR BUMPER	X ✓ NN	1	MBHR2-50-251A	\$ 23.70
43	BRACKET CENTER, REAR BUMPER	X ✓ NN	1	MKD53-50-251	\$ 5.10
44	SENSOR, ULTRASONIC	✓ 2 pcs. { DM	4	MKD47-67-UC1 50	\$ 775.60
45	RETAINER, SENSOR	✓ 2 pcs. { DM	4	MKD47-67-UC5A50	\$ 69.20
46	TAPE PROTECTOR, SENSOR	✓ MC	3	MG51D-50-EM1A	\$ 24.30
47	CORD, SHORT (SENSOR)	?	1	MBHR1-67-290	\$ 153.00
48	REINFORCEMENT REAR	✓ BT — photo.	1	MB45A-50-260	\$ 537.30
49	FASTENER, REAR BUMPER	✓	4	MB45A-56-146A	\$ 11.20
50	CLIP, REAR BUMPER	✓ { MC	2	MGJ21-50-049	\$ 6.40
51	RIVET, REAR BUMPER	✓ { MC	4	MBBM4-50-355	\$ 16.80
52	GROMMET, REAR BUMPER	✓	1	M9991-00-501	\$ 2.80
53	GROMMET, REAR BUMPER	✓	4	MBHN1-50-0Z1A	\$ 10.00
54	REFLECTOR LHS	X ✓ NN	1	MD350-51-5L0E	\$ 50.40
55	REFLECTOR RHS	X ✓ NN	1	MD350-51-5M0E	\$ 50.40
56	COVER(LHS), TOWING	✓ { cut	1	MBHN1-50-EL1 BB	\$ 15.70
57	COVER(RHS), TOWING	✓ { cut	1	MBHN1-50-EK1 BB	\$ 16.20
58	REAR END PANEL	X repair.	1	MB4YA-70-75Z	\$ 505.10
59	BOOT LID	✓ Bue	1	MBHY5-52-61XA	\$ 852.65
60	HINGE(LHS), BOOT LID	?	1	MB45A-52-720B	\$ 145.40
61	HINGE(RHS), BOOT LID	?	1	MB45A-52-710B	\$ 145.40
62	WEATHERSTRIP, BOOT LID	✓ re	1	MBHN1-56-951A	\$ 107.70
63	LOCK, BOOT LID	?	1	MBHY1-56-82XA	\$ 177.30
64	MAZDA, EMBLEM	✓ { MC	1	MBHN1-51-721	\$ 53.40
65	MASCOT, REAR	✓ { MC	1	MBHN1-51-730	\$ 74.40
66	SKYACTIV, EMBLEM	✓ { MC	1	MBHN1-51-771	\$ 63.60
67	ANTENNA, KEYLESS	X ✓ NN	1	MKD47-67-6NXXA	\$ 105.80
68	CLIP, ANTENNA	X ✓ NN	1	MKD45-67-6NYA	\$ 2.50
69	GASKET(LHS), TAILLAMP	✓	1	MBHN1-51-163	\$ 20.90
70	GASKET(RHS), TAILLAMP	✓	1	MBHN1-51-153	\$ 20.90
71	FASTENER, TAILLAMP	✓	2	MKD53-51-146B	\$ 7.80
72	GROMMET, TAILLAMP	✓ { MC	2	MGJ6A-51-14Y	\$ 29.80
73	GASKET(LHS), BOOT LID LAMP	✓	1	MB45A-51-3J8	\$ 20.90
74	GASKET(RHS), BOOT LID LAMP	✓	1	MB45A-51-3H8	\$ 20.90
75	FASTENER, BOOT LID LAMP	✓	2	MEG21-51-146	\$ 11.80
76	GROMMET, BOOT LID LAMP	✓	2	MGA7B-51-146	\$ 6.20
77	GUARD(LHS), STONE	✓	1	MBHS2-50-4P2	\$ 17.30

78	GUARD(RHS), STONE	1	MBHS2-50-4R2	\$	16.50
TOTAL PARTS				\$	12,324.05
LESS 10%				\$	1,232.41
TOTAL PARTS COST				\$	11,091.65

Labour Description					
1	MZ-BR-FRONT3	TO REPLACE FRONT BUMPER, FRONT REINFORCEMENT AND GRILLE TOP. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	660	990	\$ 2,640.00
2	MZ-SP-SFRT03	TO RESPRAY FRONT BUMPER, FRONT REINFORCEMENT AND GRILLE TOP.	630	945	\$ 2,520.00
3	MZ-BR-REAR05	TO REPLACE REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL AND BOOT LID. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.		1980	\$ 3,960.00
4	MZ-SP-SREAR5	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL AND BOOT LID.		2835	\$ 3,150.00
5	MZ-BR-SEALER	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING	NN	X	\$ 350.00
6	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.		150	\$ 250.00
7	MZ-BR-TRIMS2	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.		330	\$ 660.00
8	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.		330	\$ 660.00
9	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS.		330	\$ 660.00
10	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		150	\$ 250.00
11	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		180	\$ 350.00
12	MZ-BR-SUNDRI	SUNDRIES.	30	NETT	\$ 100.00

10 Days.

before paint photos.

Gen. Qiang - 82880282

08/2/18.

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED

TOTAL LABOUR	\$ -	\$ 15,550.00
TOTAL PARTS	\$ -	\$ 11,091.65
TOTAL	\$ -	\$ 26,641.65
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	\$ -
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

the Receiver of the following:

to resurvey before/after spray painting

to display damaged part(s) during resurvey

Parts prices are subject to confirmation

Third party survey is on a "Without Prejudice" basis

No illegal modification(s) is allowed

Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

TRANS EUROKARS PTE LTD

Acknowledged by Repairer

Signature:

Date: