


SMRT Accident Vehicle Repair Estimates

7-2-18 / 10:41
7-2-18 / 14:41
6-1-18 / 14:41

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB628J
Ref. No : TAX/02/18/2027
Reg. Date : 28/10/2016
Vehicle Type : TAXI
Make : TOYOTA PRIUS
Model : PRIUS4
Name of Driver : LIM MING KEAT (LIN MINGJI)
Type of Accident : SIDE SWIPE
Date / Time of Accident : 04/02/2018 09:30:00 AM
Accident Reported Date / Time : 05/02/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by : Sebastian
Vehicle is Towed Back? : No
Towed Back Date/Time :
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024094483
Special Instruction to ARC, if any :
DROVE IN /FBH2102K NTUC P/P
BEFORE PAINT PHOTO, FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL SURVEYOR SEBASTIAN (LKK)
& Email : sebastianeang @lkkauto.com HP:90036121
Prepared Date : 05/02/2018 02:35:01 PM



Recording Camera

☐ ☒

Radio Antenna

☐ ☒

1st witness

Date 6-2-18

2nd witness

Date

Vehicle to Wega Date In: 6/02 Towing:

Time In: 1700 Driver: TAT.

Wega Job No: 02/0108

Vehicle sent to SMRT Date In: 1-2-2018 Towing:

Time In: 3-50 Driver:

Received by (SMRT):