

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB1973E

Ref. No : TAX/02/18/2030

Reg. Date : 10/10/2017

Vehicle Type : TAXI

Make : TOYOTA PRIUS

Model : PRIUS4

Name of Driver : YEO HAI CHOON

Type of Accident : SIDE SWIPE

Date / Time of Accident : 05/02/2018 12:00:00 PM

Accident Reported Date / Time: 05/02/2018 12:00:00 AM

Surveyor is Required? : Yes

Survey by :

Vehicle is Towed Back? : No

Towed Back Date/Time :


Replacement Vehicle issued? : No

Accident Repair Job Card No : 000024094486

Special Instruction to ARC, if any:

PC6461H - AXA

Prepared Date : 05/02/2018 02:43:21 PM



Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No: JTDKB3FU203572698 Mileage : 0

Work Shop : Repair Completed Date / Time :

Summary of Repair Estimates

Quotation from ARC Adjusted by Surveyor, if applicable

Total Labout Charges : 845.00 0.00

Total Spray Painting Charges : 756.00 0.00

 Total Material Charges
 : 4,290.97
 4,290.97

 Other Charges
 : 340.00
 0.00

TOTAL : 6,231.97 0.00

Lum Sum Total : 0.00 0.00

No. of Repair Days : 5.00 0.00

Prepared / Adjusted By :

Arc / Surveyor Sing Off Date : 06/02/2018 08:37:30 AM 01/01/1900 12:00:00 AM

Prepared / Adjusted Date :

Remarks :

Prepared Date : 06/02/2018 08:37:30 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : Invoice No :

Quotation Date : Invoice Date :

Invoice Amount : Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH FRONT PORTION	845.00	0.00
Total Labour	845.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT FENDER RH	378.00	0.00
TO REPSRAY FRONT BUMPER	378.00	0.00
Total Spray Painting & Panel Beating	756.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00
TO REPLACE SUNDRY PARTS	100.00	0.00
TO WASH AND VACUUM	60.00	0.00
Total Other Costs	340.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommen d	Surveyor Approved	Photos Attached
53801470 80			FENDER SUB-ASSY, FR , RH	1	933.10	25.00	699.82	Replace	Replace	No
75374471 40			EMBLEM, SIDE PANEL (HYBRID)	1	52.90	25.00	39.67	Replace	Replace	No
52119479 62			COVER, FR BUMPER	1	495.50	25.00	371.62	Replace	Replace	No
52115470 50			SUPPORT, FR BUMPER RH	1	76.90	25.00	57.67	Replace	Replace	No
81145476 91			UNIT, HEADLAMP , RH	1	2,558.90	10.00	2,303.01	Replace	Replace	No
81210470 20			LAMP ASSY, FOG, RH	1	910.20	10.00	819.18	Replace	Replace	No
TOTAL MATERIALS							4,290.99	4,290.97		
	TOTAL MATERIALS(Discounted)							4,290.97	4,290.97	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									