

# Treasure Appraisal Services

9 Joo Chiat Place Singapore 427743  
HP: (65) 9833 1618 Fax: (65) 6747 1017  
Email: treasureappraisal@gmail.com  
Reg No: 53218791A

PHOTOCOPY



## TAX INVOICE

Bill to : Draaisma Henderikus Jan

C/O : Hendon Automotive Pte Ltd  
280 Woodlands Industrial Park E5 #01-19  
Harvest @ Woodlands  
Singapore 757322  
Tel: 9459 2885 Fax: 6334 5178  
Contact: Lynn Sim HP:

Invoice No : TAS-1710-1083

Date : 02-Oct-17

Report No : T-HD-170830/4853B

Terms : COD

S/N	Descriptions	Amount (\$\$)
1	<p>Service Rendered In Respect of:</p> <p>Vehicle Number : SLB 4853 B Vehicle Make/Model : Volvo XC70 Date of Inspection : 30-Aug-17 Date of Accident : 18-Aug-17</p> <p>Appraisal fees include transportation and follow-up inspection.</p> <p>Submission of appraisal report by hand.</p> <p>Photography services including storage of media and submission of color photograph copies by hand.</p> <p><b>SINGAPORE DOLLARS SIX HUNDRED AND EIGHTY-TWO ONLY</b></p>	\$ 682.00
Total		\$ 682.00

E. & O.E

All cheques should be crossed and made payable to "Treasure Appraisal Services".

All cheques should indicate our "Invoice No" on the reverse side of the cheque.

for Treasure Appraisal Services



# Treasure Appraisal Services

9 Joo Chiat Place Singapore 427743  
HP: (65) 9833 1618 Fax: (65) 6747 1017  
Email: treasureappraisal@gmail.com  
Reg No: 53218791A



## VEHICLE ASSESSMENT REPORT

Report No : T-HD-170830/4853B  
Date : 02-Oct-17

### REFERENCE

Assigned By : Draaisma Henderikus Jan  
Name of Workshop : Hendon Automotive Pte Ltd  
Place of Inspection : 280 Woodlands Industrial Park E5 #01-19 Harvest @ Woodlands Singapore 757322  
Date of Assignment : 30-Aug-17  
Date of Accident : 18-Aug-17  
Date of Inspection : 30-Aug-17

### PARTICULARS OF DAMAGED VEHICLE

Vehicle Reg No	: SLB 4853 B	Chassis No	: YV1BZ985681015115
Year of Reg	: Dec-07	Odometer/km	: 129097
Make/Model	: Volvo XC70	Engine No	: B6324S23100714520
Vehicle Colour	: Grey	Engine Capacity	: 3192 cc
Vehicle Type	: Wagon	Transmission Type	: Auto

### PRE-ACCIDENT CONDITION OF VEHICLE (STATIC TESTS ONLY)

General Condition	: Good		
Body Paint Work	: Good	Footbrake	: Serviceable
Steering	: Serviceable	Handbrake	: Serviceable
Front Undercarriage	: Serviceable	Rear Undercarriage	: LHS Damaged

TIRES CONDITION		Tire Brand		Size		Tread Balance
Front RH	:	Michelin	:	235/55 R17	:	80%
Rear RH	:	Michelin	:	235/55 R17	:	80%
Front LH	:	Michelin	:	235/55 R17	:	80%
Rear LH	:	Michelin	:	235/55 R17	:	80%

Road Wheels Type : Sport Rim

Note: The above percentages represent the estimated remaining balance of the tire treads in mm.  
\* Denotes damaged components.

### SYNOPSIS OF DAMAGES

At the time of survey, we noted that the vehicle has sustained an impact damages on the rear LHS multiple portions.

For further detail of the damages, please refer to our schedule and 62 pcs of surveyed photograph attached.



# Treasure Appraisal Services

9 Joo Chiat Place Singapore 427743  
HP: (65) 9833 1618 Fax: (65) 6747 1017  
Email: treasureappraisal@gmail.com  
Reg No: 53218791A



## RECOMMENDATIONS

We referred to your instruction to appraise the above vehicle SLB 4853 B on 30-Aug-17 and in the accordance, we have carried out a physical assessment at your appointed workshop.

A static inspection was carried out and report is enclosed for your reference. The estimated repair cost submitted by the repairer for **SGD 13,880.60** as per attached schedule has been scrutinised and revised by us against the actual damages found on the vehicle and we recommended the replacements and rectifications accordingly.

The repair cost has been revised to **SGD 10,615.60** and therefore in the consideration of the repairer giving a further 20% even discount, it was agreed that the repairs to be carried out at a contractual lump sum of **SGD 8,500.00** nett.

In such event, the repairer shall has the prerogative to either use new, OEM, re-conditioned parts and/or repair any damaged body parts that the repairer is confident and capable of repairing as long as the vehicle is put on the road in its pre-accident and road worthy condition and to the entire satisfaction of the owner.

Under normal circumstances, the estimated period of repairs is **Seven (7)** working days.

Pursuant to your instructions, we have NOT AUTHORISED to carry out the repairs on your behalf and we are submitting this report for your consideration.

This survey and/or appraisalment was carried out to the best of our knowledge, ability and on a "STRICTLY WITHOUT PREJUDICE" basis to any party concern.

We are reverting the matter to you for your discretion.

Yours Truly,  
Treasure Appraisal Services

  
Dixon Yeo W  
Automobile Appraiser

The revised estimate was made from a visual inspection. Any discrepancies or unseen damage/s should be notified to the company within **Fourteen (14) days** from the date thereof. Otherwise, the revised amount should deem to be valid.

This report is strictly confidential and is given for the use of client and their authorised assigned agent and any disclosure or publication of it or part or whole shall be the responsibility of such person and no liability shall be attached to TREASURE APPRAISAL SERVICES thereof.

# Treasure Appraisal Services

9 Joo Chiat Place Singapore 427743  
HP: (65) 9833 1618 Fax: (65) 6747 1017  
Email: treasureappraisal@gmail.com  
Reg No: 53218791A



S/N	Labour Descriptions	Repairer's Estimate	Our Assessment
6	To carry out accident body repairs; dismantle vehicle body part/s, dismember affected damaged body panel/s, replace and/or repair, re-construction, weld to re-join and re-align vehicle body structures to pre-accident condition.	\$ 1,500.00	\$ 1,200.00
7	To furnish, putty, sanding, masking, prepare paint mixture & toning, complete cleaning, spray paint, polishing and waxing on affected areas.	\$ 1,200.00	\$ 600.00
8	To furnish and apply under-sealing & rust proofing coats on accident affected area.	\$ 200.00	\$ 160.00
9	Conduct water leakage tests to ensure proper air and water sealing.	\$ 120.00	\$ 60.00
Labour Total :		<u>\$ 4,130.00</u>	<u>\$ 2,890.00</u>
Parts & Labour Total :		<u><u>\$ 13,880.60</u></u>	<u><u>\$ 10,615.60</u></u>

**Note:** The repairer has agreed to undertake the repairs at our adjusted amount of **SGD 8,500.00** on a **\*Contractual Lump Sum Basis** corresponding to supply of all parts, labour and spray painting charges.

**N.B: \*Under Contractual Lump Sum Basis**, the repairer shall has the prerogative to either use new, OEM, re-conditioned parts and/or repair any damaged body parts that the repairer is confident and capable of repairing as long as the vehicle is put on the road in its pre-accident and road worthy condition and to the entire satisfaction of the owner.

Under normal circumstances, the estimated period of repairs is **Seven (7)** working days. Pursuant to your instruction, we have NOT AUTHORISED the repairs on your behalf.

Treasure Appraisal Services

Dixon Yeo T W  
Automobile Appraiser



































