

SMRT Accident Vehicle Repair Estimates

AG

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB967E
 Ref. No : TAX/02/18/2034
 Reg. Date : 23/01/2013
 Vehicle Type : TAXI
 Make : CHEVROLET EPICA 2.0 VCDI
 Model : EPICA-2.0
 Name of Driver : TEO AH LEONG
 Type of Accident : HEAD TO REAR
 Date / Time of Accident : 05/02/2018 04:15:00 PM
 Accident Reported Date / Time : 06/02/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024094495
 Special Instruction to ARC,if any :
 DROVE IN / SKW1234J
 Prepared Date : 06/02/2018 08:54:36 AM



Sebastian,
 7/2/18.
 - Lump Sum Repair.
 - Question Mark Item
 Photo.
 - Photo After Paint.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : KL1LA69RJBB138866 Mileage : 0

Work Shop : Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	1,352.00	0.00
Total Spray Painting Charges :	2,574.00	0.00
Total Material Charges :	11,481.44	11,481.44
Other Charges :	1,846.88	0.00
TOTAL :	17,254.32	0.00
Lum Sum Total :	17,250.00	0.00
No. of Repair Days :	9.00	0.00
Prepared / Adjusted By :		6 days.
Arc / Surveyor Sing Off Date :	07/02/2018 08:50:04 AM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 07/02/2018 08:50:04 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	1,352.00	0.00 800
Total Labour	1,352.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY BUMPER BEAM	180.00	0.00 100
TO RESPRAY REAR PANEL	180.00	0.00 100
TO RESPRAY REAR SPARE TYRE PANEL	180.00	0.00 100
TO RESPRAY REAR FLOOR SIDE PANEL LH	180.00	0.00 100
TO RESPRAY REAR CHASSIS LH	180.00	0.00 100
TO RESPRAY REAR CHASSIS RH	180.00	0.00 X
TO RESPRAY REAR LH WHEEL HOUSE	180.00	0.00 ?
TO RESPRAY REAR FENDER LH	378.00	0.00 200
TO RESPRAY TAIL LAMP PANEL LH	180.00	0.00 ?
TO RESPRAY REAR BOOT LID	378.00	0.00 200
Total Spray Painting & Panel Beating	2,574.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO PROVIDE LABOUR & MATERIAL TO REPLACE SHIELD REAR BUMPER (NET)	140.00	0.00 ✓
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	296.88	0.00 ✓
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 30
TO REMOVE AND REFIX REAR WINDSCREEN	120.00	0.00 X
TO ALIGN CHASSIS	350.00	0.00
TO TRANSFER REAR TAILGATE MECHANISM	120.00	0.00 50
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0.00 50
REMOVE AND REPLACE BOTH RR EXHAUST MUFFLER	120.00	0.00 50
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0.00 30
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 X
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 40
TO REPLACE SUNDRY PARTS	100.00	0.00 20
TO WASH AND VACUUM	60.00	0.00 X
Total Other Costs	1,846.88	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
93745100	REAR	6504569	BUMPER RR	1	1,238.00	10.00	1,114.20	Replace	Replace	No
96873838	REAR		ABSORBER ENGY RR BUMPER	1	70.00	10.00	63.00	Replace	Replace	No
96941154	REAR	6504571	BEAM RR BUMPER IMPACT	1	1,221.00	10.00	1,098.90	Replace	Replace	No
96858575		6504584	REFLECTOR REFLEX RR LH	1	264.00	10.00	237.60	Replace	Replace	No
	REAR		SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace	No
	REAR		BRACKET RR BUMPER SIDE LH	1	49.00	10.00	44.10	Replace	Replace	No
96647117	COMMON		W/HARNES RR BPR	1	227.34	10.00	204.61	Replace	Replace	No
			EXHAUST PIPE MOUNTING, REAR	2	4.40	10.00	7.92	Replace	Replace	No
96418400			MUFFLER A-EXH,RR	1	2,909.00	10.00	2,618.10	Replace	Replace	No
96632015	REAR	6504636	PANEL END REAR	1	255.00	10.00	229.50	Replace	Replace	No
96637759	REAR	6504579	TRIM REAR END PANEL	1	114.00	10.00	102.60	Replace	Replace	No
94503739			CLIP,TRIM	10	1.00	10.00	9.00	Replace	Replace	No
36515711			PANEL SPARE TYRE	1	2,299.00	10.00	2,069.10	Replace	Replace	No
	BODY		PNL SIDE LH SPARE TYRE	1	650.00	10.00	585.00	Replace	Replace	No
	BODY		CHASSIS MEMBER RR LH	1	525.38	10.00	472.84	Replace	Replace	No
	BODY		CHASSIS MEMBER RR RH	1	525.38	10.00	472.84	Replace	Replace	No
			INSULATOR SHEET	1	41.48	10.00	37.33	Replace	Replace	No
	COMMON	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Replace	No
			JACK FOAM COVER	1	35.00	10.00	31.50	Replace	Replace	No
16632583			PANEL A-SIDE, INR, RR LH	1	830.00	10.00	747.00	Replace	Replace	No
16632596	REAR		WHEELHOUSE A-RR LH	1	464.00	10.00	417.60	Replace	Replace	No
			TRIM REAR BOOT, LH	1	125.00	10.00	112.50	Replace	Replace	No
16632799	LEFT	6504637	FENDER LH REAR	1	1,191.00	10.00	1,071.90	Replace	Replace	No
	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace	No
	COMMON		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No
6633557	REAR	6504575	LINER LH REAR FENDER (PROTECTOR)	1	201.00	10.00	180.90	Replace	Replace	No
			PANEL TAIL LAMP, LH	1	143.40	10.00	129.06	Replace	Replace	No
6851763	REAR	6504563	LAMP RR COMBINATION LH	1	415.00	10.00	373.50	Replace	Replace	No
6632652	REAR	6504619	MOLDING WINDSCREEN REAR	1	45.00	10.00	40.50	Replace	Replace	No
	COMMON		SEALANT W/SCREEN	2	37.00	0.00	74.00	Replace	Replace	No
3636630	REAR	6504631	REAR BOOT LID	1	974.00	10.00	876.60	Replace	Replace	No

Part Number	Portion	Stock NO	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
96636677	REAR	6504634	REAR BOOT LOCK	1	77.00	10.00	69.30	Replace	Replace / JM	No
96636502	REAR		REAR BOOT HINGE	2	92.00	10.00	165.60	Replace	Replace x	No
96976171	REAR	6504635	REAR BOOT REFLECTOR	1	165.00	10.00	148.50	Replace	Replace	No ?
96634023	REAR	6504567	EMBLEM REAR	1	44.00	10.00	39.60	Replace	Replace ✓ N.E.C	No
96634035	REAR	6504564	LETTERING:"CHEVR OLET"	1	29.00	10.00	26.10	Replace	Replace ✓ N.E.C	No
96634897	REAR	6504565	LETTERING:"EPICA LT"	1	28.00	10.00	25.20	Replace	Replace ✓ N.E.C	No
	COMMO N		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace ✓ N.E.C	No
	COMMO N		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace ✓ N.E.C	No
96632854	REAR	6504632	REAR BOOT WEATHERSTRIP	1	49.00	10.00	44.10	Replace	Replace ✓ Deform	No
96851765	REAR	6504566	LAMP BACK UP LH	1	151.00	10.00	135.90	Replace	Replace ✓ N.E.C	No
TOTAL MATERIALS								14,351.80	14,351.80	
TOTAL MATERIALS(Discounted)							11,481.44	11,481.44		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									