

ASS. REC. BY:

REF:

CS/MSG18002566/T1td3

n2

Special Instructions:

Surveyor:
Menmen

Taufik

ASSIGNMENT (Office)

From (Person):

Catherine Thia

of

MSG

Date/Time:

8/2/2018 @ 10:27am

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

XB 8710L

Insured:

XB 7596G

at Workshop m/s:

ASM Automotive

Tel:

9236 8218

of

No. 2 Kwong Min Rd

Policy No.:

B28718557MKF

Claim No.:

548273

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

30/9/2018

CA / REV / REP. / REV 24 HRS

'wp'

H.O.D. Endorsement:

Date/Time:

12:52pm @ 8/2/18

Person Contacted:

jaclyn

Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	XB 8710L - X
	XB 7596G - X

Tamplin

REF

uslk

ASSIGNMENT

COE 249 March

2004 March

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MY
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: XB8710L (in Regn) 2004 March
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Nissan CKB45 cc 12503
 Colour: Green A/C Insured / Std / NI / NA
 Sp Reading: 881108 T Radio: Insured / Std / NI / NA
 Eng No: _____
 C.No: CKB45 ABT.00 282.
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: N / S/Rim / STD A/Rim or

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.
 Bal. or Market Value: 222k.
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS wp

<u>NS</u>	<u>OS</u>

Tyre Size: F: 10.00 - R20
 R: 4 - (D)
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Norton.
 Front: 8 mm R/Bal: 8/8 mm
 L/Bal: 8 mm L/Bal: 8/8 mm
 D.O.A. _____ D.O.I. 8/2/18
 Survey held at: ASM Auto
 Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Date: _____ Person Contacted: Jadyn Vehicle IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction check Unit
Repair Unit p/5 k.
25/4/18 E-mail Jadyn 4/5 @15,000, 18 days (Red: 21475.28 :58%)

RECEIVED 26 APR 2018

Date/Time File Pass 10: ☐ Preli. Report
26/4 Typist ☒ Final Report
 Date/Time File Returns:

Days Of Repair: 18
 Resurvey No. of Trip: 1

Survey Fee
 Transportation

Add Fee: ☐ Site Insp: \$
☐ Interview: \$
☐ Technical: \$
☐ Freezing: \$

Report Format: TP
 Lump Sum / L.B. \$ 15,000/-

350
10
360

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Feb 2018		08 Feb 2018 10:27 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	CWT INTEGRATED PTE.LTD., Co. Reg. No.: 197701671C		
Main Claimant:	XIN TRANSPORT (S) P/L, Co. Reg. No.: 200405461Z		
Vehicle Reg. No.:	XB8710L	Date of Loss:	30/01/2018 18:00 - :59
Claim Type:	TP / 548273	Policy/Cover Note No.:	B28718557MKF (Third Party Only) Coverage: 01/04/2017 - 31/03/2018
Vehicle Reg. No. (Insured):	XB7596G	Policy No. (Claimant):	
		Excess:	
Repairer:	Asm Automotive Services Kwong Min Rd (HQ) No. 2 Kwong Min Road, 628705 Pioneer - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 09/02/2018]		
Driver/Custodian (Insured):	TAN YELIN (43 / Male), NRIC: G5146983L, Tel: +6584911139		
Adj Asg. Remarks:	Please contact Ms Jaclyn Lai @ 9236 8218 or 6265 0980 to arrange for survey .		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Iryani Amin

From: Woon Choo Kwok
Sent: Wednesday, 7 February, 2018 3:37 PM
To: Catherine Thia; Iryani Amin
Cc: Christopher Chionh; Foo Ai Ngoh
Subject: FW: Third Party Claim: XB8710L and XB7596G (your insured); DOA: 30/01/18
Attachments: XB8710L - SAS (180130).PDF; XB8710L - Q.pdf

Categories: Red Category

Dear CT & IBA

FYA

Best Regards

Kwok Woon Choo
Senior Administrative Officer, Claims Services
Direct line +65 6643 1330 | Direct fax +65 6225 7402 | woonchoo_kwok@sg.msig-asia.com



MSIG



Insurer Claims
Team of the Year
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Koh Lay Hoon
Sent: Wednesday, February 07, 2018 2:24 PM
To: Woon Choo Kwok <WoonChoo_Kwok@sg.msig-asia.com>
Subject: FW: Third Party Claim: XB8710L and XB7596G (your insured); DOA: 30/01/18

From: ASM - Jaclyn [<mailto:jaclynlai@asmauto.com.sg>]
Sent: Wednesday, February 07, 2018 1:33 PM
To: Claims <claims@sg.msig-asia.com>
Subject: Third Party Claim: XB8710L and XB7596G (your insured); DOA: 30/01/18

Dear Sir / Madam,

Our client, the owner of vehicle no. XB 8710 L wishes to file claim for the damages sustained from the above-stated accident, against your insured, vehicle no. XB 7596 G.

We hereby append a copy of our estimate and SAS for your kind perusal.

Kindly advise on liability and arrange for survey. Thank you.

Best Regards,

Jaclyn Lai

Customer Service & Motor Claims Executive

ASM Automotive Services Pte Ltd

Add: No. 2 Kwong Min Road, Singapore 628705

H/P: 9236 8218

Tel: 6265 0980

Fax: 6265 6068

Web: www.asmauto.com.sg

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18002566/T1td3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 08-02-2018	
		Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	XB 7596G	Veh. Inspected	XB 8710L
Policy No.	B28718557MKF	Coverage (\$)	0.00
Claim No.	548273	Excess (\$)	0.00
Assign From	MERIMEN (CATHERINE THIA)	Assign Date	08/02/2018
2. Vehicle Particulars & Condition			
Make & Model	c.c		0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	30/01/2018	Inspection Date	08/02/2018
Survey held at	ASM AUTOMOTIVE SERVICES PTE LTD 2 KWONG MIN ROAD SINGAPORE 628705		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5461Z
Vehicle Details	
Vehicle No.:	XB8710L
Vehicle to be Exported:	Yes
Intended De-registration Date:	09 Feb 2018
Vehicle Make:	NISSAN
Vehicle Model:	CKB45ABTN2
Primary Colour:	White
Manufacturing Year:	2004
Engine No.:	PF6166692C
Chassis No.:	CKB45ABT00282
Maximum Power Output:	-
Open Market Value:	\$62,833.00
Original Registration Date:	31 Mar 2004
First Registration Date:	31 Mar 2004
Transfer Count:	1
Actual ARF Paid:	\$3,142.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Mar 2019
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5

PQP Paid:	\$25,158.00
COE Rebate Amount:	\$5,734.00
Total Rebate Amount:	\$5,734.00
Message	
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.	

The information contained herein is correct as at 09 Feb 2018

OK



ASM Automotive Services Pte Ltd.

No 2, Kwong Min Road, Singapore 628705
 Tel: 6265 0980 / 6265 8806 Fax: 6265 6068
 Email: enquiry@asmauto.com.sg
 Co. / GST Reg. No.: 201203813C

biSAFE₃

FROM : Jaclyn Lai
 TEL. NO. : 6265-0980 / 9236-8218
 EMAIL : jaclynlai@asmauto.com.sg

DATE : 07.02.2018

TO : MSIG Insurance (Singapore) P/L
 ATTN : Motor Claim Department
 TEL. NO. : 6827-7660
 EMAIL : claims@sg.msig-asia.com

VEHICLE NO. : XB 8710 L
 MODEL NO. : NISSAN CKB45ABTN2
 CHASSIS NO. : CKB45ABT00282
 ENGINE NO. : PF6166692C
 LTA REG DATE : 31-Mar-04

CC : Xin Transport (S) Pte Ltd
 ATTN : Ms. Angela

CLAIM TYPE : Third Party - XB 7596 G
 D.O.A : 30.01.2018
 CLAIM REF NO. : asm/AC18017/JL

Quotation for Accident Repair

S/N	SPARE PARTS	QUANTITY	UNIT PRICE	AMOUNT
1	Mirror stay, upper "V", LH	1	\$ 415.80	\$ 415.80
2	Mirror stay, long, LH	1	\$ 239.40	\$ 239.40
3	Round mirror, LH	1	\$ 63.00	\$ 63.00
4	Side mirror, center LH	1	\$ 88.20	\$ 88.20
5	Side mirror, lower LH	1	\$ 70.56	\$ 70.56
6	Mirror stay lower bracket, LH	1	\$ 214.20	\$ 214.20
7	Front bumper	1	\$ 453.60	\$ 453.60

SUB-TOTAL : \$ 1,544.76
 LESS 10% : \$ 154.48
 BALANCE : \$ 1,390.28

S/N	SPARE PARTS (SPECIAL NETT ITEMS)	QUANTITY	UNIT PRICE	AMOUNT
1	Used complete cabin (import) <i>* check price</i>	1	\$ 25,000.00	\$ 25,000.00 <i>15000</i>
2	ERP unit	1	\$ 145.00	\$ 145.00 <i>145.00</i>

S/N ITEMS TOTAL : \$ 25,145.00 *15145*

TOTAL PARTS : \$ 26,535.28

LABOUR CHARGES

1 Dismantle damaged cabin, install new cabin, check and transfer cabin wire harnesses.
 (\$280 x 20 days)

2 Knock and straighten chassis.

3 Spray painting whole cabin.

4 Logo writing

5 Towing Fee

4200
\$ 5,600.00

1500 X 17
\$ 2,500.00 ?
1000

\$ 1,500.00

\$ 220.00 *180 new*

\$ 120.00 *5500*

\$ 9,940.00

TOTAL LABOUR :

\$ 36,475.28

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

GRAND TOTAL :

Tan Jiah 97445740
-WP' 8/2/18 153
18 days
lumpsum
resurvey after repair
note lkkauto.com.

22035-28
 4/3/15,000

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18002566/T1TD3N2

Date: 27/04/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	B28718557MKF
Claimant Vehicle No :	XB8710L	Insured Vehicle No :	XB7596G
Date of Loss:	30/01/2018	Nature of Claim:	TP
		Claim No:	548273

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	XB8710L	Engine No:	PF6166692C
Make & Model:	NISSAN CKB45ABTN2, 12.5 D (M)	Chassis No:	CKB45ABT00282
Reg. Date:	31/03/2004 (Man. Year: 2004)	Odometer:	881108 km
Colour:	Green		
Engine Capacity:	12503 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	10.00-R20	Rear Tyre Size:	10.00-R20 (D)
Front Left Side:	Neuton 8 mm	Rear Left Side:	Neuton 8/8 mm
Front Right Side:	Neuton 8 mm	Rear Right Side:	Neuton 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,755.28	16,715.28	10,040.00	37.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,720.00	5,320.00	4,400.00	45.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	36,475.28	22,035.28	14,440.00	39.59
Approved Total (Overridden) (S\$)		15,000.00		
(S\$)	36,475.28	15,000.00	21,475.28	58.88
+ GST 7.00/7.00% (S\$)	2,553.27	1,050.00	1,503.27	58.88
Nett Amount (S\$)	39,028.55	16,050.00	22,978.55	58.88

INSPECTION

Date of Assignment: 08/02/2018

Date Inspected: 08/02/2018 Inspected At:

Asm Automotive Services Kwong Min
Rd (HQ)
No. 2 Kwong Min Road
Singapore 628705

Estimated Period of Repair: 18.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 27 Apr 2018)	
Parts:	N/A	NISSAN CKB45ABTN2 12.5 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XB8710L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*MIRROR STAY,UPPER V LH	Bent	415.80 FL	*415.80 FL
2	1		*MIRROR STAY, LONG, LH	Bent	239.40 FL	*239.40 FL
3	1		*ROUND MIRROR, LH	Missing	63.00 FL	*63.00 FL
4	1		*SIDE MIRROR, CENTER LH	Cut	88.20 FL	*88.20 FL
5	1		*SIDE MIRROR, LOWER LH	Cracked	70.56 FL	*70.56 FL
6	1		*MIRROR STAY LOWER BRACKET, LH	Bent	214.20 FL	*214.20 FL
7	1		*FRONT BUMPER	Bent	453.60 FL	*453.60 FL
8	1		*USED COMPLETE CABIN (IMPORT)	Buckled	25,000.00 FS	*15,000.00 FS
9	1		*ERP UNIT	Cracked	145.00 FS	*145.00 FS
10	1		*LOGO WRITING	Necessary	220.00 FS	*180.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	26,909.76	16,869.76
- List Item Discount on L Items 10.00/10.00% (\$\$)	154.48	154.48
Total Parts (\$\$)	26,755.28	16,715.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	DISMANTLE DAMAGED CABIN,INSTALL NEW CABIN,CHECK AND TRANSFER CABIN WIRE HARNESSSES	New	5,600.00	4,200.00
2	KNOCK AND STRAIGHTEN CHASSIS	New	2,500.00	-
3	SPRAY PAINTING WHOLE CABIN	New	1,500.00	1,000.00
4	TOWING FEE	New	120.00	120.00
Gross Labour Cost (\$\$)			9,720.00	5,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >