

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC: SHC5417M - JHOW

AAD1802-062

Not Notified
11 Sep @ 5600

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC5417M - JHOW

VF1ABL15AUC279625

RENAULT

LATITUDE

04.02.2018

AIG**PART****LIST**

1	1	BUMPER COVER REAR	\$	<i>Bu</i>	1,108.46	✓
2	1	BUMPER LOWER REAR	\$	<i>Ne</i>	768.84	✓
3	1	BUMPER BRACKET CTR REAR	\$	<i>Sn</i>	113.47	X
4	1	BUMEPR BRACKET SIDE RH REAR	\$	<i>Sn</i>	135.97	X
5	1	BUMEPR RETAINER RH REAR	\$	<i>Sn</i>	44.99	X
6	1	BUMPER REFLECTOR RH	\$	<i>cm</i>	43.61	X
7	1	BUMEPR BRACKET SIDE LH REAR	\$	<i>Sn</i>	135.97	X
8	1	BUMEPR RETAINER LH REAR	\$	<i>Sn</i>	44.99	X
9	1	BUMPER REFLECTOR LH	\$	<i>Sn</i>	43.61	X
10	1	BUMPER BEAM REAR	\$	<i>Ry</i>	777.52	✓
11	1	BUMPER BEAM BRACKET LH REAR	\$	<i>R</i>	225.95	X
12	1	BUMPER BEAM BRACKET RH REAR	\$	<i>Bu</i>	225.95	✓
13	1	BOOT REAR	\$	<i>Bu</i>	2,872.68	✓
14	1	BOOT FINISHER	\$	<i>Sn</i>	470.06	X
15	1	BOOT WHEATERSTRIP	\$	<i>Sn</i>	323.05	X
16	1	BOOT REFLECTOR LAMP LH	\$	<i>Sn</i>	493.35	X
17	1	BOOT REFLECTOR LAMP RH	\$	<i>Sn</i>	493.35	X
18	1	BOOT BADGE 'RENAULT'	\$	<i>Ne</i>	225.36	✓
19	1	BOOT BADGE	\$	<i>Ne</i>	225.36	✓
20	1	BOOT STRUT LH	\$	<i>Sn</i>	276.08	} X
21	1	BOOT STRUT RH	\$	<i>Sn</i>	276.08	
22	1	BOOT HINGE LH	\$	<i>R</i>	367.84	
23	1	BOOT HINGE RH	\$	<i>R</i>	367.84	
24	1	BOOT INNER TRIM	\$	<i>Sn</i>	586.45	
25	1	BOOT SWITCH	\$	<i>Sn</i>	168.13	
26	1	BOOT LOCK	\$	<i>R</i>	202.67	
27	1	BOOT LOCK CATCH	\$	<i>R</i>	74.40	
28	2	LICENCE PLATE LAMP	\$	<i>Sn</i>	50.52	
29	2	BOOT RUBBER PLUG	\$	<i>Sn</i>	221.81	
30	1	FENDER PANEL REAR LH	\$	<i>R</i>	3,299.13	
31	1	WHEELARCH REAR LH	\$	<i>Sn</i>	543.47	
32	1	FENDER PANEL REAR RH	\$	<i>R</i>	3,299.13	
33	1	WHEELARCH REAR RH	\$	<i>Sn</i>	543.47	
34	1	TAILLAMP RH	\$	<i>Sn</i>	552.55	

TRANS-CAB AUTO SERVICES PTE LTD**AAD1802-062**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5702P - III

35	1	TAILLAMP PANEL RH	\$	<i>R</i>	986.70	X
36	1	TAILLAMP LH	\$	<i>Sn</i>	552.55	X
37	1	TAILLAMP PANEL LH	\$	<i>R</i>	986.70	X
38	1	OUTER PANEL REAR (End Panel)	\$	<i>R</i>	1,471.77	X
39	1	OUTER PANEL REAR (End Panel)TRIM	\$	<i>Sn</i>	404.56	X
40	1	EXHAUST REAR	\$	<i>R</i>	7,489.05	X
41	1	EXHAUST CAP REAR	\$	<i>Bo</i>	230.49	✓

TOTAL	\$	31,723.96
10%	\$	3,172.40
	\$	28,551.56

Specical Nett

1	1SET	PARKING AID	\$	<i>Sn</i>	700.00	X
2	1SET	REAR BUMPER CLIP	\$	<i>nn</i>	66.00	—
3	1SET	BUMPER BRACKET CTR CLIP	\$	<i>nn</i>	33.00	—
4	1SET	BUMEPR BRACKET SIDE CLIP RH RR	\$	<i>nn</i>	10.00	X
5	1SET	BUMEPR RETAINER RH CLIP RR	\$	<i>nn</i>	20.00	X
6	1SET	BUMEPR BRACKET SIDE CLIP LH RR	\$	<i>nn</i>	10.00	X
7	1SET	BUMEPR RETAINER CLIP LH RR	\$	<i>nn</i>	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	<i>nn</i>	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	<i>nn</i>	66.00	✓
10	1	EXHAUST MOUNTING REAR	\$	<i>nn</i>	17.82	X
11	1SET	BOOT FINISHER CLIP	\$	<i>nn</i>	24.20	X
12	1	BOOT STICKER "Trans-cab"	\$	<i>nn</i>	30.00	—
13	1	BOOT STICKER "6555-3333"	\$	<i>nn</i>	30.00	—
14	1	BOOT INNER TRIM CLIP	\$	<i>nn</i>	45.00	} X
15	1SET	FENDER WHEELARCH REAR RH CLIP	\$	<i>nn</i>	35.00	
16	1SET	FENDER WHEELARCH REAR LH CLIP	\$	<i>nn</i>	35.00	
17	1	TAILLAMP CLIP RH	\$	<i>nn</i>	5.00	
18	1	TAILLAMP CLIP LH	\$	<i>nn</i>	5.00	
19	2	REAR WINDSCREEN SELANT	\$	<i>nn</i>	80.00	
20	1	WINDSCREEN MOULDING	\$	<i>nn</i>	100.00	
21	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>nn</i>	100.00	}
22	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	<i>Sn</i>	385.00	
23	1	SPARE TYRE	\$	<i>Sn</i>	330.00	

TOTAL	\$	2,169.02
TOTAL PARTS	\$	30,720.58

Putty And Spray Painting Of The Affected Portion.

\$ 4,500.00 *Bo*

TRANS-CAB AUTO SERVICES PTE LTD

AAD1802-062

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5702P - III

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00 <i>5001</i>
To Rust-Proofing Of The Affected Areas.	\$	170.00 <i>301</i>
To reinstall rear bumper parking sensor.	\$	170.00 <i>601</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00 <i>601</i>
To repair and realign rear exhaust pipe.	\$	170.00 <i>} 601</i>
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00 <i>} 601</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00 <i>X</i>
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00 <i>X</i>
To supply and re-do rear luggage floor panel insulation padding.	\$	<i>nn</i> 380.00 <i>X</i>
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 <i>X</i>
Towing Fees	\$	<i>nn</i> 120.00 <i>X</i>
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>nn</i> 170.00 <i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00 <i>X</i>

TOTAL \$ 11,160.00**Over All Total \$ 41,880.58****(PARTS BY PARTS)****Repair Days**LKK Auto Consultants hence notify
the repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

15 Days*3 days*