

INS. CASE OWNER:

CC 3 / H11800 <sup>TP</sup> 2572, KKA3

LKK:  
IDAC:

Surveyor:

Kenneth

**ASSIGNMENT**

DOI:

2/2/18

Date / Time:

2/2/18

Registered in Merimen:

8/2/18

Pre-assign / CCU / FTE

SHB 8574B



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

HP:

Excess See II :SS

D.O.A:

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

Is driver the owner?

( YES / NO )

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SHC 5702P



INSRS:

WSP:

Tel:

Liability:

RMKS:

Trans Cab



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

SHC 5702P. X: SHB 8574B - X	STAGE	DATE / PIC	
RECEIVED 9 OCT 2018 To submit independent.	Non-Reporting ltr (1st)		
	Non-Reporting ltr (2nd)		
	Non-Reporting ltr (Final)		
	Notification ltr (if non-pickup)		
	Call OI:		
	After call ltr to OI:		
	<b>Documentation Check List:</b> Handler Typist		
	Notification ltr (if non-pickup)	<input type="checkbox"/>	<input type="checkbox"/>
	After call ltr to OI:	<input type="checkbox"/>	<input type="checkbox"/>
	Authorisation To Act:	<input type="checkbox"/>	<input type="checkbox"/>
	Release Voucher:	<input type="checkbox"/>	<input type="checkbox"/>
	Final Repair Bill:	<input type="checkbox"/>	<input type="checkbox"/>
	Car Rental Invoice:	<input type="checkbox"/>	<input type="checkbox"/>
	Towing Invoice:	<input type="checkbox"/>	<input type="checkbox"/>
	LTA / GIA:	<input type="checkbox"/>	<input type="checkbox"/>
Medical Bill:	<input type="checkbox"/>	<input type="checkbox"/>	
PIR:	<input type="checkbox"/>	<input type="checkbox"/>	
Mandate/Reject Instruction:	<input type="checkbox"/>	<input type="checkbox"/>	
LOD:	<input type="checkbox"/>	<input type="checkbox"/>	
Payment Breakdown Form:	<input type="checkbox"/>	<input type="checkbox"/>	

**PRELIMINARY ADVICE** Date/Time: Sent By: Confirm with: Confirm by:

**FINALIZATION** Date/Time: Confirm with: Confirm by: Repair Cost: S\$ ( days) Reduction: % Email  Call

**FINAL SETTLEMENT** Date/Time: Confirm with: Email  Call  Final Liability: % (Agreed / Assessed) BOLA S/N No. : If NO or B 28, Ass. Lia :

Repair Cost: S\$ Loss of Rental (LOR): S\$ ( days) Loss of Use (LOU): S\$ (\$ x days) Loss of Income (LOI): S\$ (\$ x days) LOR only  LOU only  LOR + LOU  LOR + LOI  [Tick only one] GIA/LTA Search: S\$ Medical: S\$ Disbursement: S\$ (e.g. Tow/ Independent ) Legal Cost: S\$ Total: S\$ Global Sum S\$: 1) Claim status: Normal/Reject/Private Settle 2) Report Format: 3) Survey fee:

**FINAL PAYMENT** Date/Time: Confirm with: Email  Call

Payee 1: S\$ Name 1: Payee 2: (Str. to / / A.) S\$ Name 2: Payee 3: (Str. to / / A.) S\$ Name 3:

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	06/02/2018 11:37
Date Of Accident	05/02/2018 15:05
Exact Location Of Accident	ANG MO KIO AVE 6
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC5702P
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666
<b>Vehicle Particulars</b>	
Manufacturer	RENAULT
Model	LATITUDE-2.0 DCI AUTO D/AB 4DR (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

### Driver

Name of Driver	RENGASAMY SIVAPRAKASAM
NRIC No	S7366039D
Date Of Birth	15/06/1973
Occupation	OUTDOOR
Date Of Driving Pass	07/05/2003
Driving Experience	14 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93265300
Fax Number	
Contact Number	
EMail Address	NOEMAIL


No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name	RENGASAMY SIVAPRAKASAM
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SHC5702P
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

- Please refer to police reports

DECLARATION

I/We declare the foregoing particulars are true in every respect.

\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

  
\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



**SINGAPORE  
POLICE FORCE**



T/20180205/2164

4 of 4

Report No. T/20180205/2164

Police Station Of Origin:  
Kampong Ubi NPP  
9 Euros Crescent #01-2687 SINGAPORE  
400009  
Tel No: 1800-7479999

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: G / Sgt 2 LIM ZHENG HONG	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 05/02/2018 19:39
Officer In Charge Of Case: TP / AEIT / SSI 2 SITIMARSITA BOHARI Contact No.: 65476219	Classification Of Case:
Authentication Stamp NP155	



SINGAPORE  
POLICE FORCE



SIGNATURE



**SINGAPORE  
POLICE FORCE**



T/20180205/2164

2 of 4

Police Station Of Origin:  
Kampong Ubi NPP  
9 Eunos Crescent #01-2687 SINGAPORE  
400009  
Tel No: 1800-7479999

Report No. T/20180205/2164

## CONTINUATION OF REPORT

Driver			
Name	BALBIR SINGH S/O KATAR SINGH	ID No.	S1479499I
Related Vehicle	SHB8514B (Taxi)	Contact No.	97928906
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	RENGASAMY SIVAPRAKASAM	ID No.	S7366039D
Related Vehicle	SHC5702P (Taxi)	Contact No.	93265300
Hospital/Clinic	INTEMEDICAL 24HRS CLINIC	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	05/02/2018	Date Discharge	05/02/2018
No. of Days granted Medical Leave	05	Degree of Injury	Serious

**Brief Details.**

On 05/02/2018 at about 1505hrs, I was travelling (SHC5702P, RENAULT, LATITUDE 2.0L, Red) along Ang Mo Kio Avenue 6 on lane number 2.

At that point of time, there was heavy traffic and vehicles was moving slowly. Out of a sudden, I heard a loud bang and felt a impact on my vehicle.

After that, I stopped my vehicle and got down to make a check and realized that a taxi (SHB8514B, KIA, OPTIMA 1.7(A) DIESEL, Silver) behind me has collided onto the rear of my vehicle.

We then exchanged particulars and took some photos of the incident, the driver of SHB8514B then left the scene, he was not injured.

After the accident, I went to a clinic for consultation as i sustained some injuries on my neck, shoulder, back area and the right knee. I was given 5 days of MC.

There was no government properties damaged in the process, no pedestrian was involved.

I would like to state that there is a camera installed in my vehicle. I am lodging this report for insurance and medical claim purposes.

**TRANS-CAB AUTO SERVICES PTE LTD**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

**SHC5702P - III**

AAD1802-062

*Not Authored  
Assurvey By pain*

Vehicle No.:  
Chassis No.:  
Vehicle Make:  
Vehicle Model:  
Date of Accident :  
Third Party Insurer :

**SHC5702P - JHOW**  
VF1ABL15AUC281587  
RENAULT  
LATITUDE  
05.02.2018  
**III**

PART		LIST
1	1 BUMPER COVER REAR	\$ <i>B<sub>y</sub></i> 1,108.46 ✓
2	1 BUMPER LOWER REAR	\$ <i>D.I.T</i> 768.84 ✓
3	1 BUMPER BRACKET CTR REAR	\$ <i>D.I.T</i> 113.47 ✓
4	1 BUMEP R BRACKET SIDE LH REAR	\$ <i>D.I.T</i> 135.97 ✓
5	1 BUMEP R BRACKET CTR LH REAR	\$ <i>CM</i> 44.99 ✓
6	1 BUMEP R BRACKET SIDE RH REAR	\$ <i>Sm</i> 135.97 X
7	1 BUMEP R BRACKET CTR RH REAR	\$ <i>Sm</i> 44.99 X
8	1 BUMPER BEAM REAR	\$ <i>B<sub>y</sub></i> 777.52 ✓
9	1 BUMPER BEAM BRACKET LH REAR	\$ <i>B<sub>y</sub></i> 225.95 ✓
10	1 BUMPER BEAM BRACKET RH REAR	\$ <i>D.I.T</i> 225.95 ✓
11	1 BUMPER REFLECTOR LH	\$ <i>CM</i> 43.61 ✓
12	1 BUMPER REFLECTOR RH	\$ <i>Sm</i> 43.61 X
13	1 BOOT REAR	\$ <i>B<sub>y</sub></i> 2,872.68 ✓
14	2 BOOT RUBBER PLUG	\$ <i>Sm</i> 221.81
15	1 BOOT FINISHER	\$ <i>Sm</i> 470.06
16	1 BOOT SWITCH	\$ <i>Sm</i> 168.13
17	1 BOOT TRIM BOARD	\$ <i>Sm</i> 914.87
18	1 BOOT LOCK	\$ <i>R</i> 202.67
19	1 BOOT LOCK CATCH	\$ <i>R</i> 74.40
20	1 BOOT LOCK LINKAGE	\$ <i>Sm</i> 34.53
21	1 BOOT LOCK LINKAGE HOLDER	\$ <i>Sm</i> 154.52
22	1 BOOT LOCK CATCH TRIM BOARD	\$ <i>Sm</i> 249.24
23	1 BOOT WHEATERSTRIP	\$ <i>D.I.T</i> 323.05 ✓
24	1 BOOT REFLECTOR LAMP LH	\$ <i>CM</i> 493.35 ✓
25	1 BOOT REFLECTOR LAMP RH	\$ <i>Sm</i> 493.35 X
26	1 BOOT BADGE 'RENAULT'	\$ <i>Sm</i> 225.36 ✓
27	1 BOOT BADGE	\$ <i>Sm</i> 225.36 ✓
28	1 BOOT STRUT LH	\$ <i>Sm</i> 276.08 X
29	1 BOOT STRUT RH	\$ <i>Sm</i> 276.08 X
30	1 BOOT HINGE LH	\$ <i>R</i> 367.84 X
31	1 BOOT HINGE RH	\$ <i>R</i> 367.84 X
32	2 LICENCE PLATE LAMP	\$ <i>Sm</i> 50.52 X
33	1 WINDSCREEN REAR	\$ <i>Sm</i> 1,463.28 X
34	1 WINDSCREEN GARNISH INNER LH	\$ <i>Sm</i> 263.74 X

**TRANS-CAB AUTO SERVICES PTE LTD**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

**SHC5702P - III**

**AAD1802-062**

35	1	WINDSCREEN GARNISH INNER RH	\$	Sm	263.74	X
36	1	TAILLAMP LH	\$	CM	552.55	✓
37	1	TAILLAMP PANEL LH	\$	R	986.70	✓
38	1	TAILLAMP RH	\$	Sm	552.55	X
39	1	TAILLAMP PANEL RH	\$	R	986.70	X
40	1	FENDER PANEL REAR LH	\$	Bu	3,299.13	✓
41	1	FENDER PANEL REAR RH	\$	R	3,299.13	X
42	1	WHEELARCH REAR LH	\$	CM	543.47	✓
43	1	WHEELARCH REAR RH	\$	Sm	543.47	X
44	1	FENDER PANEL INNER TRIM REAR LH	\$	Return	671.45	✓
45	1	FENDER WHEEL HOUSE PANEL REAR LH	\$	R	3,039.04	X
46	1	LOWER ARM REAR LH	\$	Sm	905.99	X
47	1	KUCKLE ARM REAR LH	\$	Sm	736.67	X
48	1	ABSORBER REAR LH	\$	Sm	389.75	X
49	1	ABSORBER BOLT REAR LH	\$	Sm	52.10	X
50	1	ABSORBER DUST COVER REAR LH	\$	Sm	92.16	X
51	1	AIR VENT RH	\$	Sm	97.28	X
52	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	Blk Bu	2,189.88	✓
53	1	SPARE WHEEL PANEL TRIM (Luggage Floor Panel)	\$	Sm	612.21	X
54	1	SPARE WHEEL PANEL BRACKET LH	\$	R	123.73	X
55	1	SPARE WHEEL PANEL BRACKET RH	\$	R	121.36	X
56	1	OUTER PANEL REAR (End Panel)	\$	R	1,471.77	✓
57	1	OUTER PANEL REAR (End Panel)TRIM	\$	CM	401.02	✓
58	1	EXHAUST CAP REAR	\$	Sm	230.49	} X
59	1	EXHAUST MOUNTING REAR	\$	Sm	31.97	
60	1	EXHAUST BRACKET REAR	\$	R	39.86	
61	1	EXHAUST HEAT SHIELD REAR	\$	R	99.06	
62	1	SHIELD - HEAT - TUNNEL	\$	Sm	225.16	
63	1	FUEL FLAP	\$	Sm	343.57	
64	1	FUEL TANK NECK	\$	Sm	684.77	
65	1	FUEL CAP	\$	Sm	233.02	
66	1	DOOR PANEL REAR LH	\$	R	2,844.66	
67	1	DOOR SEAL REAR LH	\$	Sm	187.08	
68	1	DOOR PANEL REAR RH	\$	R	2,844.66	
69	1	DOOR SEAL REAR RH	\$	Sm	162.02	

<b>TOTAL</b>	<b>\$</b>	<b>43,716.28</b>
<b>10%</b>	<b>\$</b>	<b>4,371.63</b>
	<b>\$</b>	<b>39,344.66</b>

**Specical Nett**

1	1SET	BUMPER RR CLIP	\$	Mc	66.00	✓
---	------	----------------	----	----	-------	---

**TRANS-CAB AUTO SERVICES PTE LTD**

**AAD1802-062**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

**SHC5702P - III**

2	1SET	BUMPER BEAM BOLT	\$	Sn	22.22	X
3	1SET	PARKING AID	\$	phon	600.00	✓
4	1	BUMPER BRACKET CLIP CTR REAR	\$	nn	15.00	} X
5	1	BUMEPR BRACKET SIDE CLIP LH REAR	\$	nn	12.00	
6	1	BUMEPR RETAINER CLIP LH REAR	\$	nn	10.40	
7	1	BUMEPR BRACKET SIDE CLIP RH REAR	\$	nn	12.00	
8	1	BUMEPR RETAINER CLIP RH REAR	\$	nn	10.40	
9	1	CAP HUB LH RR	\$	Sn	35.00	
10	1	RIM LH RR	\$	Sn	385.00	
11	1	TYRE LH RR	\$	Sn	330.00	
12	1	CAP HUB RH RR	\$	Sn	35.00	
13	1	RIM RH RR	\$	Sn	385.00	
14	1	TYRE RH RR	\$	Sn	330.00	
15	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	Sn	385.00	
16	1	SPARE TYRE	\$	Sn	330.00	
17	1SET	BOOT FINISHER CLIP	\$	nn	25.10	
18	1	Rear boots sticker "trans-cab"	\$	nn	30.00	—
19	1	Rear boots sticker "6555-3333"	\$	nn	30.00	✓
20	1	FENDER PANEL INNER TRIM CLIP REAR LH	\$	nn	22.00	X
21	1SET	WHEELARCH CLIP LH RR	\$	nn	32.34	X
22	1SET	WHEELARCH CLIP RH RR	\$	nn	32.34	X
23	2	Rear windscreen sealant	\$	nn	80.00	400A
24	1	Windscreen moulding	\$	nn	100.00	✓
25	1	Rear Windscreen Inner Sponge Seal	\$	nn	100.00	300A
26	1	EXHAUST MOUNTING REAR	\$	Sn	65.50	X
27	1	EXHAUST BRACKET REAR	\$	X	22.22	X
28	1SET	Front licence plate with holder	\$	Sn	80.00	X
29	1SET	Rear licence plate with holder	\$	Sn	80.00	X
30	1	DOOR STICKER "6555-3333" LH	\$	nn	80.00	X
31	1	DOOR STICKER "6555-3333" RH	\$	nn	80.00	X
<b>TOTAL</b>			<b>\$</b>		<b>3,822.52</b>	
<b>TOTAL PARTS</b>			<b>\$</b>		<b>43,167.18</b>	

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 4,200.00 *2000*

Towing Fees.

\$ 120.00 *50*

To apply paint protection system (PPS) maintain and enhancement

\$ 380.00 *X*

**TRANS-CAB AUTO SERVICES PTE LTD**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

**SHC5702P - III**

**AAD1802-062**

Putty and spray painting of the affected portion.	\$	4,500.00	1100/
To rust-proofing of the affected areas.	\$	170.00	120/
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	100/
To check steering geometry and computer wheel alignment	\$	220.00	60/
To transfer of tire, rim and on wheel balancing.	\$	170.00	~ 170.00 X
To Check Electrical Lighting Concerned.	\$	170.00	20/
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	380.00	} 250/
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	~ 170.00 X
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	~ 170.00 X
To supply and re-do rear luggage floor panel insulation padding.	\$	380.00	80/
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	60/
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00	~ 380.00 X
To transfer of tailgate fittings and conduct water seepage test.	\$	170.00	~ 170.00 X
To transfer of rear windscreen fittings, attachments and perform water seepage test.	\$	380.00	120/
To reinstall rear bumper parking sensor.	\$	170.00	60/

**TRANS-CAB AUTO SERVICES PTE LTD**

AAD1802-062

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5702P - III

To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	280.00	} 601
To repair and realign rear exhaust pipe.	\$	170.00	
To dismantle and refit rear undercarriage parts, final checking and testing.	\$	<i>ru</i> 380.00	X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	<i>ru</i> 170.00	X
<b>TOTAL</b>		<b>\$</b>	<b>14,060.00</b>
<b>Over All Total</b>		<b>\$</b>	<b>57,227.18</b>

&lt; parts by parts &gt; Repair Days

15 DAYS ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary work(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3878K
Vehicle Details	
Vehicle No.:	SHC5702P
Vehicle to be Exported:	Yes
Intended De-registration Date:	07 Feb 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	M9R8839C002794
Chassis No.:	VF1ABL15AUC281587
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	12 Jun 2015
First Registration Date:	12 Jun 2015
Transfer Count:	0
Actual ARF Paid:	\$12,498.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Jun 2023
PARF Rebate Amount:	\$9,373.00
Intended COE Rebate Details	

COE Expiry Date:	11 Jun 2023
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$52,886.00
COE Rebate Amount:	\$35,330.00
<b>Total Rebate Amount:</b>	<b>\$44,703.00</b>

**Message**

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 07 Feb 2018

OK

## Thin Thin (LKKAuto)

---

**From:** claims <claims@transcab.com.sg>  
**Sent:** Wednesday, 3 October 2018 8:48 AM  
**To:** Hsiao Tong (LKKAuto); Thin Thin (LKKAuto); Mei Kwan (LKKAuto)  
**Cc:** 'jasminetan'; claims@transcab.com.sg  
**Subject:** FW: BULK SETTLEMENT 27.09.18 --- TCS REF: AAD1802-062--Accident involving SHB8514B & SHC5702P on 05.02.18  
**Attachments:** image004.wmz; AAD1802-062 - LOD.pdf

WITHOUT PREJUDICE

Dear All

We are agree to purchase the survey report, kindly send us the survey invoice for us to prepare the payment.

Thank You  
Best Regards,  
**Ng Wai Yin**  
Finance Department  
TEL: 6603 1265 Ext.308

**\*\*\* Please be reminded that all claims correspondence to be send to [claims@transcab.com.sg](mailto:claims@transcab.com.sg)**



### TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63, Singapore 569111  
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764  
Website: [www.transcab.com.sg](http://www.transcab.com.sg)

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

---

**From:** Hsiao Tong (LKKAuto) [mailto:chewht@lkkauto.com]  
**Sent:** Saturday, 29 September, 2018 12:43 PM  
**To:** 'Ng Wai Yin' <waiyin.ng@transcab.com.sg>  
**Cc:** claims@transcab.com.sg; Admin A <admin-a@lkkauto.com>; Thin Thin (LKKAuto) <thinthin@lkkauto.com>  
**Subject:** RE: BULK SETTLEMENT 27.09.18 --- TCS REF: AAD1802-062--Accident involving SHB8514B & SHC5702P on 05.02.18

**Without Prejudice**

Hi Wai Yin,

I don't think that we have discussed this case during our bulk settlement on 27/09/2018. Could you re-confirm with Jasmine?

For your information, SHB 8514B is not insured with Ill at the time of accident. SHB 8514B is insured with NTUC. In view of the above, kindly confirm if you are agreeable to purchase our independent survey report.

Appreciate an early reply.

By copy to Thin Thin/ Mei Kwan,

Kindly assist to follow up. CC3/TP18002572/Kua3

Best Regards,

**Hsiao Tong, Chew** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Ng Wai Yin <[waiyin.ng@transcab.com.sg](mailto:waiyin.ng@transcab.com.sg)>

**Sent:** Friday, 28 September 2018 8:29 AM

**To:** Hsiao Tong (LKKAuto) <[chewht@lkkauto.com](mailto:chewht@lkkauto.com)>

**Cc:** [claims@transcab.com.sg](mailto:claims@transcab.com.sg)

**Subject:** BULK SETTLEMENT 27.09.18 --- TCS REF: AAD1802-062--Accident involving SHB8514B & SHC5702P on 05.02.18

WITHOUT PREJUDICE

Dear Hsiao Tong

Please refer to the above mention case, kindly ignore the previous LOD due to COR incorrect.

The correct COR should be \$22,369.93 instead of \$5,992.00.

Original hard copy will pass to Kenneth's to bring back your office.

Thank You

Best Regards,

*Ng Wai Yin*

Finance Department

TEL: 6603 1265 Ext.308

**\*\*\* Please be reminded that all claims correspondence to be send to [claims@transcab.com.sg](mailto:claims@transcab.com.sg)**



**TRANS-CAB SERVICES PTE LTD**

No. 2 Ang Mo Kio Street 63, Singapore 569111

Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764

Website: [www.transcab.com.sg](http://www.transcab.com.sg)

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
TRANS-CAB AUTO SERVICES PTE LTD		Ref :	CC3/TP18002572/Kua3q2
NO.2 ANG MO KIO STREET 63SINGAPORE 569111		Date :	26-10-2018
		Code :	TP378
			
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.		Veh. Inspected	SHC 5702P
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	07/02/2018
2. Vehicle Particulars & Condition			
Make & Model	RENAULT LATITUDE (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	VF1ABL15AUC281587	Colour	METALLIC WHITE / RED
Odometer	327158	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/60 R16	GITI	7 mm
L/H Front Tyre	215/60 R16	GITI	7 mm
R/H Rear Tyre	215/60 R16	FALKEN	8 mm
L/H Rear Tyre	215/60 R16	FALKEN	8 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	05/02/2018	Inspection Date	07/02/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		15 Working Days	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 5

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5702P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>REPLACEMENT OF PARTS</b>			
1	BUMPER COVER REAR	BENT	1,108.46	1,108.46
1	BUMPER LOWER REAR	DISTORTED / DENTED	768.84	768.84
1	BUMPER BRACKET CTR REAR	DISTORTED	113.47	113.47
1	BUMPER BRACKET SIDE LH REAR	DISTORTED	135.97	135.97
1	BUMPER BRACKET CTR LH REAR	CRACKED	44.99	44.99
1	BUMPER BRACKET SIDE RH REAR	SERVICEABLE	135.97	-
1	BUMPER BRACKET CTR RH REAR	SERVICEABLE	44.99	-
1	BUMPER BEAM REAR	BENT	777.52	777.52
1	BUMPER BEAM BRACKET LH REAR	BENT	225.95	225.95
1	BUMPER BEAM BRACKET RH REAR	DISTORTED	225.95	225.95
1	BUMPER REFLECTOR LH	CRACKED	43.61	43.61
1	BUMPER REFLECTOR RH	SERVICEABLE	43.61	-
1	BOOT REAR	BENT	2,872.68	2,872.68
2	BOOT RUBBER PLUG	SERVICEABLE	221.81	-
1	BOOT FINISHER	SERVICEABLE	470.06	-
1	BOOT WITCH	SERVICEABLE	168.13	-
1	BOOT TRIM BOARD	SERVICEABLE	914.87	-
1	BOOT LOCK	TO REPAIR SEE LABOUR	202.67	-
1	BOOT LOCK CATCH	TO REPAIR SEE LABOUR	74.40	-
1	BOOT LID LINKAGE	SERVICEABLE	34.53	-
1	BOOT LID LINKAGE HOLDER	SERVICEABLE	154.52	-
1	BOOT LOCK CATCH TRIM BOARD	SERVICEABLE	249.24	-
1	BOOT WEATHERSTRIP	DENTED / CUT	323.05	323.05
1	BOOT REFLECTOR LAMP LH	CRACKED	493.35	493.35
1	BOOT REFLECTOR LAMP RH	CRACKED	493.35	-
1	BOOT BADGE 'RENAULT'	NECESSARY	225.36	225.36
1	BOOT BADGE	NECESSARY	225.36	225.36
1	BOOT STRUT LH	SERVICEABLE	276.08	-
1	BOOT STRUT RH	SERVICEABLE	276.08	-
1	BOOT HINGE LH	TO REPAIR SEE LABOUR	367.84	-
1	BOOT HINGE RH	TO REPAIR SEE LABOUR	367.84	-

Report Ref No. CC3/TP18002572/Kua3q2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607196R GST Reg. No. 19-9607196-R

Page No. 2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	LICENCE PLATE LAMP	SERVICEABLE	50.52	-
1	WINDSCREEN REAR	SERVICEABLE	1,463.28	-
1	WINDSCREEN GARNISH INNER LH	SERVICEABLE	263.74	-
1	WINDSCREEN GARNISH INNER RH	SERVICEABLE	263.74	-
1	TAILLAMP LH	CRACKED	552.55	552.55
1	TAILLAMP PANEL LH	BENT	986.70	986.70
1	TAILLAMP RH	SERVICEABLE	552.55	-
1	TAILLAMP PANEL RH	TO REPAIR SEE LABOUR	986.70	-
1	FENDER PANEL REAR LH	BUCKLED	3,299.13	3,299.13
1	FENDER PANEL REAR RH	TO REPAIR SEE LABOUR	3,299.13	-
1	WHEELARCH REAR LH	CRACKED	543.47	543.47
1	WHEELARCH REAR RH	SERVICEABLE	543.47	-
1	FENDER PANEL INNER TRIM REAR LH	DEFORMED	671.45	671.45
1	FENDER WHEEL HOUSE PANEL REAR LH	TO REPAIR SEE LABOUR	3,039.04	-
1	LOWER ARM REAR LH	SERVICEABLE	905.99	-
1	KNUCKLE ARM REAR LH	SERVICEABLE	736.67	-
1	ABSORBER REAR LH	SERVICEABLE	389.75	-
1	ABSORBER BOLT REAR LH	SERVICEABLE	52.10	-
1	ABSORBER DUST COVER REAR LH	SERVICEABLE	92.16	-
1	AIR VENT LH	SERVICEABLE	97.28	-
1	SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)	BENT / BUCKLED	2,189.88	2,189.88
1	SPARE WHEEL PANEL TRIM (LUGGAGE FLOOR PANEL)	SERVICEABLE	612.21	-
1	SPARE WHEEL PANEL BRACKET LH	TO REPAIR SEE LABOUR	123.73	-
1	SPARE WHEEL PANEL BRACKET RH	TO REPAIR SEE LABOUR	121.36	-
1	OUTER PANEL REAR (END PANEL)	BENT	1,471.77	1,471.77
1	OUTER PANEL REAR (END PANEL) TRIM	CRACKED	401.02	401.02
1	EXHAUST CAP REAR	SERVICEABLE	230.49	-
1	EXHAUST MOUNTING REAR	SERVICEABLE	31.97	-
1	EXHAUST BRACKET REAR	TO REPAIR SEE LABOUR	39.86	-
1	EXHAUST HEAT SHIELD REAR	TO REPAIR SEE LABOUR	99.06	-
1	SHIELD -HEAT -TUNNEL	SERVICEABLE	225.16	-

Report Ref No. CC3/TP18002572/Kua3q2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FUEL FLAP	SERVICEABLE	343.57	-
1	FUEL TANK NECK	SERVICEABLE	684.77	-
1	FUEL CAP	SERVICEABLE	233.02	-
1	DOOR PANEL REAR LH	TO REPAIR SEE LABOUR	2,844.66	-
1	DOOR SEAL REAR LH	SERVICEABLE	187.08	-
1	DOOR PANEL REAR RH	TO REPAIR SEE LABOUR	2,844.66	-
1	DOOR SEAL REAR RH	SERVICEABLE	162.02	-
	LESS 10% DISCOUNT		-4,371.63	-1,770.05
			39,344.63	15,930.48
	<b>SPECIAL NETT ITEMS</b>			
1	SET BUMPER RR CLIP (SN)	NECESSARY	66.00	66.00
1	SET BUMPER BEAM BOLT (SN)	SERVICEABLE	22.22	-
1	SET PARKING AID (SN)	SHORTED	600.00	600.00
1	BUMPER BRACKET CLIP CTR REAR (SN)	NOT NECESSARY	15.00	-
1	BUMPER BRACKET SIDE CLIP LH REAR (SN)	NOT NECESSARY	12.00	-
1	BUMPER RETAINER CLIP LH REAR (SN)	NOT NECESSARY	10.40	-
1	BUMPER BRACKET SIDE CLIP RH REAR (SN)	NOT NECESSARY	12.00	-
1	BUMPER RETAINER CLIP RH REAR (SN)	NOT NECESSARY	10.40	-
1	CAP HUB LH RR (SN)	SERVICEABLE	35.00	-
1	RIM LH RR (SN)	SERVICEABLE	385.00	-
1	TYRE LH RR (SN)	SERVICEABLE	330.00	-
1	CAP HUB RH RR (SN)	SERVICEABLE	35.00	-
1	RIM RH RR (SN)	SERVICEABLE	385.00	-
1	TYRE RH RR (SN)	SERVICEABLE	330.00	-
1	SPARE TYRE RIM (ROUE 7J 16H 2547) (SN)	SERVICEABLE	385.00	-
1	SPARE TYRE (SN)	SERVICEABLE	330.00	-
1	SET BOOT FINISHER CLIP (SN)	NOT NECESSARY	25.10	-
1	REAR BOOT STICKER 'TRANS-CAB' (SN)	NECESSARY	30.00	30.00
1	REAR BOOT STICKER '6555-3333' (SN)	NECESSARY	30.00	30.00
1	FENDER PANEL INNER TRIM CLIP REAR LH (SN)	NOT NECESSARY	22.00	-
1	SET WHEELARCH CLIP LH RR (SN)	NOT NECESSARY	32.34	-
1	SET WHEELARCH CLIP RH RR (SN)	NOT NECESSARY	32.34	-
2	REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	WINDSCREEN MOULDING (SN)	NECESSARY	100.00	100.00

Report Ref No. CC3/TP18002572/Kua3q2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607196R GST Reg. No. 19-9607196-R

Page No.: 4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NECESSARY	100.00	30.00
1	EXHAUST MOUNTING REAR (SN)	SERVICEABLE	65.50	-
1	EXHAUT BRACKET REAR (SN)	TO REPAIR SEE LABOUR	22.22	-
1	SET FRONT LICENCE PLATE WITH HOLDER (SN)	SERVICEABLE	80.00	-
1	SET REAR LICENCE PLATE WITH HOLDER (SN)	SERVICEABLE	80.00	-
1	DOOR STICKER '6555-3333' LH (SN)	NOT NECESSARY	80.00	-
1	DOOR STICKER '6555-3333' RH (SN)	NOT NECESSARY	80.00	-
			3,822.52	896.00
<b>LABOUR</b>				
PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF BOOT LOCK,BOOT LOCK CATCH ,BOOT HINGE LH ,BOOT HINGE RH,TAILLAMP PANEL RH,FENDER PANEL REAR RH,FENDER WHEEL HOUSE PANEL REAR LH,SPARE WHEEL PANEL BRACKET LH ,SPARE WHEEL PANEL BRACKET RH,EXHAUST BRACKET REAR,EXHAUST HEAT SHIELD REAR,DOOR PANEL REAR LH AND DOOR PANEL REAR RH .			4,200.00	2,000.00
TOWING FEES.			120.00	50.00
TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT .			380.00	-
PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.			4,500.00	1,100.00
TO RUST-PROOFING OF THE AFFECTED AREAS.			170.00	120.00
TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR.			380.00	100.00
TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.			220.00	60.00
TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.			170.00	-
TO CHECK ELECTRICAL LIGHTING CONCERNED.			170.00	20.00
TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK.)			380.00	250.00
LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH ,TO FACILITATE REPAIR.)			380.00	-
TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.			170.00	-

Report Ref No. CC3/TP18002572/Kua3q2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Page No.:5 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS ,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	REPEATED	170.00	-
	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING.		380.00	80.00
	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		170.00	60.00
	TO TRANSFER OF REAR FENDER FITTINGS ,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF TAILGATE FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR WINDSCREEN FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		380.00	120.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	TO DROP REAR EXHAUST BOX ,RENEW THE SAME ,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE. }		280.00	60.00
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.}		170.00	-
	TO DISMANTLE AND REFIT REAR UNDERCARRIAGE PARTS ,FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	-
	TO TRANSFER OF FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
			14,060.00	4,080.00
	<b>GRAND TOTAL</b>		<b>57,227.15</b>	<b>20,906.48</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>20,906.48</b>

Report Ref No. CC3/TP18002572/Kua3q2

**KONG SENG CHEONG**

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.