

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5702P - III

AAD1802-062

*Not Authorized
Resurvey B4 pain*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC5702P - JHOW

VF1ABL15AUC281587

RENAULT

LATITUDE

05.02.2018

III**PART****LIST**

QTY	PART	UNIT	PRICE	LIST	STATUS
1	BUMPER COVER REAR		\$	B ₁ 1,108.46	✓
2	BUMPER LOWER REAR		\$	D _{1/2} 768.84	✓
3	BUMPER BRACKET CTR REAR		\$	D _{1/2} 113.47	✓
4	BUMEPR BRACKET SIDE LH REAR		\$	D _{1/2} 135.97	✓
5	BUMEPR BRACKET CTR LH REAR		\$	CM 44.99	✓
6	BUMEPR BRACKET SIDE RH REAR		\$	SM 135.97	X
7	BUMEPR BRACKET CTR RH REAR		\$	SM 44.99	X
8	BUMPER BEAM REAR		\$	B ₁ 777.52	✓
9	BUMPER BEAM BRACKET LH REAR		\$	B ₁ 225.95	✓
10	BUMPER BEAM BRACKET RH REAR		\$	D _{1/2} 225.95	✓
11	BUMPER REFLECTOR LH		\$	CM 43.61	✓
12	BUMPER REFLECTOR RH		\$	SM 43.61	X
13	BOOT REAR		\$	B ₁ 2,872.68	✓
14	BOOT RUBBER PLUG		\$	SM 221.81	} X
15	BOOT FINISHER		\$	SM 470.06	
16	BOOT SWITCH		\$	SM 168.13	
17	BOOT TRIM BOARD		\$	SM 914.87	
18	BOOT LOCK		\$	R 202.67	
19	BOOT LOCK CATCH		\$	R 74.40	
20	BOOT LOCK LINKAGE		\$	SM 34.53	
21	BOOT LOCK LINKAGE HOLDER		\$	SM 154.52	
22	BOOT LOCK CATCH TRIM BOARD		\$	SM 249.24	
23	BOOT WHEATERSTRIP		\$	D _{1/2} 323.05	
24	BOOT REFLECTOR LAMP LH		\$	CM 493.35	✓
25	BOOT REFLECTOR LAMP RH		\$	SM 493.35	X
26	BOOT BADGE 'RENAULT'		\$	RM 225.36	✓
27	BOOT BADGE		\$	RM 225.36	✓
28	BOOT STRUT LH		\$	SM 276.08	X
29	BOOT STRUT RH		\$	SM 276.08	X
30	BOOT HINGE LH		\$	R 367.84	X
31	BOOT HINGE RH		\$	R 367.84	X
32	LICENCE PLATE LAMP		\$	SM 50.52	X
33	WINDSCREEN REAR		\$	SM 1,463.28	X
34	WINDSCREEN GARNISH INNER LH		\$	SM 263.74	X

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5702P - III

AAD1802-062

35	1	WINDSCREEN GARNISH INNER RH	\$	Sm	263.74	X
36	1	TAILLAMP LH	\$	CM	552.55	✓
37	1	TAILLAMP PANEL LH	\$	R	986.70	✓
38	1	TAILLAMP RH	\$	Sm	552.55	X
39	1	TAILLAMP PANEL RH	\$	R	986.70	X
40	1	FENDER PANEL REAR LH	\$	Bu	3,299.13	✓
41	1	FENDER PANEL REAR RH	\$	R	3,299.13	X
42	1	WHEELARCH REAR LH	\$	CM	543.47	✓
43	1	WHEELARCH REAR RH	\$	Sm	543.47	X
44	1	FENDER PANEL INNER TRIM REAR LH	\$	De form	671.45	✓
45	1	FENDER WHEEL HOUSE PANEL REAR LH	\$	R	3,039.04	X
46	1	LOWER ARM REAR LH	\$	Sm	905.99	X
47	1	KUCKLE ARM REAR LH	\$	Sm	736.67	X
48	1	ABSORBER REAR LH	\$	Sm	389.75	X
49	1	ABSORBER BOLT REAR LH	\$	Sm	52.10	X
50	1	ABSORBER DUST COVER REAR LH	\$	Sm	92.16	X
51	1	AIR VENT RH	\$	Sm	97.28	X
52	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	Bu/Bu	2,189.88	✓
53	1	SPARE WHEEL PANEL TRIM (Luggage Floor Panel)	\$	Sm	612.21	X
54	1	SPARE WHEEL PANEL BRACKET LH	\$	R	123.73	X
55	1	SPARE WHEEL PANEL BRACKET RH	\$	R	121.36	X
56	1	OUTER PANEL REAR (End Panel)	\$	R	1,471.77	✓
57	1	OUTER PANEL REAR (End Panel)TRIM	\$	CM	401.02	✓
58	1	EXHAUST CAP REAR	\$	Sm	230.49	} X
59	1	EXHAUST MOUNTING REAR	\$	Sm	31.97	
60	1	EXHAUST BRACKET REAR	\$	R	39.86	
61	1	EXHAUST HEAT SHIELD REAR	\$	R	99.06	
62	1	SHIELD - HEAT - TUNNEL	\$	Sm	225.16	
63	1	FUEL FLAP	\$	Sm	343.57	
64	1	FUEL TANK NECK	\$	Sm	684.77	
65	1	FUEL CAP	\$	Sm	233.02	
66	1	DOOR PANEL REAR LH	\$	R	2,844.66	
67	1	DOOR SEAL REAR LH	\$	Sm	187.08	
68	1	DOOR PANEL REAR RH	\$	R	2,844.66	
69	1	DOOR SEAL REAR RH	\$	Sm	162.02	

TOTAL	\$	43,716.28
10%	\$	4,371.63
	\$	39,344.66

Specical Nett

1	1SET	BUMPER RR CLIP	\$	Me	66.00	✓
---	------	----------------	----	----	-------	---

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5702P - III

AAD1802-062

2	1SET	BUMPER BEAM BOLT	\$	Sn	22.22	X	
3	1SET	PARKING AID	\$	Phon	600.00	✓	
4	1	BUMPER BRACKET CLIP CTR REAR	\$	nn	15.00	}	
5	1	BUMEPR BRACKET SIDE CLIP LH REAR	\$	nn	12.00		
6	1	BUMEPR RETAINER CLIP LH REAR	\$	nn	10.40		
7	1	BUMEPR BRACKET SIDE CLIP RH REAR	\$	nn	12.00		
8	1	BUMEPR RETAINER CLIP RH REAR	\$	nn	10.40		
9	1	CAP HUB LH RR	\$	Sn	35.00		} X
10	1	RIM LH RR	\$	Sn	385.00		
11	1	TYRE LH RR	\$	Sn	330.00		
12	1	CAP HUB RH RR	\$	Sn	35.00		
13	1	RIM RH RR	\$	Sn	385.00		
14	1	TYRE RH RR	\$	Sn	330.00		
15	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	Sn	385.00		
16	1	SPARE TYRE	\$	Sn	330.00		
17	1SET	BOOT FINISHER CLIP	\$	nn	25.10		
18	1	Rear boots sticker "trans-cab"	\$	nn	30.00	—	
19	1	Rear boots sticker "6555-3333"	\$	nn	30.00	✓	
20	1	FENDER PANEL INNER TRIM CLIP REAR LH	\$	nn	22.00	X	
21	1SET	WHEELARCH CLIP LH RR	\$	nn	32.34	X	
22	1SET	WHEELARCH CLIP RH RR	\$	nn	32.34	X	
23	2	Rear windscreen sealant	\$	nn	80.00	40SA	
24	1	Windscreen moulding	\$	nn	100.00	✓	
25	1	Rear Windscreen Inner Sponge Seal	\$	nn	100.00	30SA	
26	1	EXHAUST MOUNTING REAR	\$	Sn	65.50	X	
27	1	EXHAUST BRACKET REAR	\$	n	22.22	X	
28	1SET	Front licence plate with holder	\$	Sn	80.00	X	
29	1SET	Rear licence plate with holder	\$	Sn	80.00	X	
30	1	DOOR STICKER "6555-3333"LH	\$	nn	80.00	X	
31	1	DOOR STICKER "6555-3333"RH	\$	nn	80.00	X	

TOTAL	\$	3,822.52
TOTAL PARTS	\$	43,167.18

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 4,200.00 *2000l*

Towing Fees.

\$ 120.00 *50l*

To apply paint protection system (PPS) maintain and enhancement

\$ 380.00 *nn X*

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5702P - III

AAD1802-062

Putty and spray painting of the affected portion.	\$	4,500.00	1100/
To rust-proofing of the affected areas.	\$	170.00	120/
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	100/
To check steering geometry and computer wheel alignment	\$	220.00	60/
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	x
To Check Electrical Lighting Concerned.	\$	170.00	20/
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	380.00	} 250/
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nnnn 170.00	x
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	nn 170.00	x
To supply and re-do rear luggage floor panel insulation padding.	\$	380.00	80/
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	60/
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	nn 380.00	x
To transfer of tailgate fittings and conduct water seepage test.	\$	nn 170.00	x
To transfer of rear windscreen fittings, attachments and perform water seepage test.	\$	380.00	120/
To reinstall rear bumper parking sensor.	\$	170.00	60/

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5702P - III

AAD1802-062

To drop rear exhaust box, renew the same, to repair and
realign centre exhaust pipe.

\$ 280.00

To repair and realign rear exhaust pipe.

\$ 170.00

To dismantle and refit rear undercarriage parts, final
checking and testing.

\$ *ru* 380.00 X

To Transfer Of Fender Fittings, Attachments And
Perform Water Seepage Test.

\$ *ru* 170.00 X

TOTAL \$ 14,060.00

Over All Total \$ 57,227.18

< parts by parts > Repair Days

15 DAYS ✓

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: