

(5/5/2011)

INS. CASE OWNER:

Shawn

CC 6 / AIG1800256

a3
b3
c3
d3
e3
f3
g3
h3
i3
j3
k3
l3
m3
n3
o3
p3
q3
r3
s3
t3
u3
v3
w3
x3
y3
z3

LKK:

IDAC:

Surveyor:

Marais

DOI:

03/02/13

Date / Time:

02/02/13

Registered in Merimen:

08/02/13

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKA 29346

Claim No.:

251792021955

Name of Insured:

TAY LIANG CHEE

Policy No.:

2100247922

Insured Tel No.:

HP: 4367 3383

Make / Model:

TOYOTA WISH-1.8 CUT GA

Excess Sec II : \$5

D.O.A: 04/02/13

Place of Accident:

SERANGOON RD JUNCTION WITH HOUGANG CENTRAL

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L YES / NO)

OI GIA REPORT: YES / NO; TP GIA REPORT: YES / NO

Insured Liability:

Final? Yes / No

SKX 5354P



INSRS:

WSP: Tan Lim Motor

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

> THIN By Email.
218

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

21/8/18

OI rear-ended to TP. Send letter to OI via email.

RECEIVED 16 AUG 2018

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$5

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

16/8/18

Confirm with:

Johnson

Email

Call

Final Liability:

%

100

[Agreed / Assessed] BOLA S/N No.:

27

If NO or B 28. Ass. Lia:

Repair Cost:

\$5

5245.00

Loss of Rental (LOR):

\$5

(days)

Loss of Use (LOU):

\$5

200.00 (\$ 50 x 4 days)

Loss of Income (LOI):

\$5

(\$ x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

\$5

7.49

Medical:

\$5

Disbursement:

\$5

(e.g. Tow/ Independent)

Legal Cost

\$5

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

\$5

5450.49

Global Sum \$5:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$5

5450.49

Name 1:

TAN LIM MOTOR PTE LTD

Payee 2. (Strike if N.A.)

\$5

Name 2:

Payee 3. (Strike if N.A.)

\$5

Name 3:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/AIG18002576/Uus3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 08-02-2018		
		Code : AIG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKA 2934G	Veh. Inspected	SKX 5354P	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	08/02/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	04/02/2018	Inspection Date	08/02/2018	
Survey held at	TAN LIM MOTOR PTE LTD 51 DEFU LANE 10 SINGAPORE 539216			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SKA2934G
 Date of Accident : 04 February 2018

Mr Chin Jie

Date: 07 February 2018

Estimate To Repair SKX5354P - Volkswagen JETTA GP 1.4 TSI 90 A/T HL 163
Chassis No : WVGZZZ16ZFM028397

[illegible]



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216

Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

AlGAsia Insured's Veh No : SKA2934G

Date of Accident : 04 February 2018

Mr Chin Jie

Date : 07 February 2018

Estimate To Repair SKX5354P - Volkswagen JETTA GP 1.4 TSI 90 A/T HL 163

Chassis No : WVVZZZ16ZFM028397

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	bootlid <i>DD/Buc</i>	\$ 1,875.45
02	1 pc	bootlid lock	\$ 179.05
03	1 pc	bootlid lock sticker <i>1 1</i>	\$ 48.15
04	2 pc	bootlid rubber stopper @ \$2.50 <i>1 1</i>	\$ 5.00
05	1 pc	bootlid inner trim <i>1 1</i>	\$ 220.75
06	2 pc	bootlid hinge @ \$126.85 <i>1</i>	\$ 253.70
07	1 pc	bootlid TSI badge <i>mc</i>	\$ 61.85
08	1 pc	bootlid delta badge <i>mc</i>	\$ 82.10
09	1 pc	bootlid centre emblem badge <i>mc</i>	\$ 115.75
10	1 pc	bootlid weatherstrip	\$ 323.85
11	2 pc	rear license plate lamp @ \$255.85	\$ 511.70
12	1 pc	rear end panel	\$ 1,206.00
13	1 pc	rear end panel inner trim	\$ 145.75
14	1 pc	rear bumper <i>DD/oc</i>	\$ 1,366.35
15	1 pc	rear bumper reinforcement	\$ 606.05
16	2 pc	rear bumper reflector @ \$66.55	\$ 133.10
17	2 pc	rear bumper side retainer @ \$110.40 <i>mc</i>	\$ 220.80
18	1 pc	rear bumper centre beam	\$ 102.15
19	2 pc	rear lamp @ \$377.85 <i>1 1</i>	\$ 755.70
20	2 pc	rear lamp clip holder @ \$16.15 <i>1 1</i>	\$ 32.30
			\$ 8,245.55
<u>SPECIAL NETT ITEMS</u>			
21	1 pc	rear license plate <i>1 1</i>	\$ 80.00
22	1 pc	rear bumper parking sensor <i>shhh</i>	\$ 450.00
			\$ 530.00
<u>LABOUR & MISC. CHARGES</u>			
01		To reinstall of rear bumper parking sensor.	\$ 150.00
02		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 160.00
03		To check electrical lighting concerned.	\$ 60.00
04		To transfer of bootlid fittings, attachments and perform water seepage test.	\$ 150.00
05		To rust-proofing of the affected areas.	\$ 120.00
06		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 800.00

Not Affected
Wale Shih Sheng
4 days
8/2/18

(5.7)

1
?
x
x
x
x
11
11
1
?
1
x
x
x
200
50
60
30
60
30
?



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SKA2934G
Date of Accident : 04 February 2018

Mr Chin Jie

Date : 07 February 2018

Estimate To Repair SKX5354P - Volkswagen JETTA GP 1.4 TSI 90 A/T HL 163
Chassis No : WVWZZZ16ZFM028397

S/No	Quantity	Description	Amount
07		LABOUR & MISC. CHARGES	
		Putty and spray painting of the affected portion.	\$ 880.00
			\$ 2,320.00
		Total	\$ 11,095.55

600

LKY Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

Address: 51 Defu Lane 10 Singapore 539216

Tel: 6858 5151 Fax: 6858 0877

Our Ref TP002022018
Your Ref SKA2934G

Date 11-06-18

Claims Department - Executive in charge AIG Asia Pacific Ins Pte Ltd
C/O LKK

WITHOUT PREJUDICE

Dear Sir/Madam,

ACCIDENT INVOLVING SKX5354P & SKA2934G ON 04.02.2018

Refer to the above accident and please acknowledge receipt of this letter within 14 days.

It appears that the accident was caused by your insured. Enclosed documents to substantiate our client's property damaged claim as our client had authorized us to quantify, to act and to reach settlement within 6 weeks on their behalf: -

- ☐ Original survey report / copies of photographs
- ☒ Original Tax-invoice number TP0218/015 ☐ Original rental invoice number
- ☐ SAS / AS & IS / police report ☐ police result
- ☒ Certificate Of Insurance MSIG INS ☒ Vehicle search result
- ☒ Authorization to act ☐

*Survey under insurance instruction / Independent surveyor / ~~No survey~~.

a)	Cost of repair (inclusive GST)	\$ <u>5,243.00</u>
b)	Survey fees / Photographs as per request	\$ <u>—</u>
c)	Vehicle Search fees / GIA fees / Police Report fees / Reporting fees	\$ <u>7.49</u>
d)	Loss of hire / use / rental / earnings / rental fees <u>[#60 x 4 days]</u>	\$ <u>240.00</u>
e)	Scene photographs	\$ <u> </u>
f)	Administrative charges to negotiate settlement (Waive if 100% offer made within acknowledge timeframe)	\$ <u> </u>
g)	<u> </u>	\$ <u> </u>
	Total	\$ <u>5,490.49</u>

* Driver's injury and other losses exclude in this claim.

If you are agreeable to the above, please forward discharge voucher for our client's signature and payment issued directly to "Tan Lim Motor Pte Ltd" within 28 days.

Yours faithfully,

Patricia Tan / Sam Low / Johnson Chua

Email: pt@tlimotor.com.sg / sam@tlimotor.com.sg / johnson.chua@tlimotor.com.sg

"The contents of this document apply to vehicle damages only. All personal injuries and damages arising therefrom are excluded from the ambit and application of this document."

Thin Thin (LKKAUTO)

From: Thin Thin (LKKAUTO)
Sent: Thursday, 2 August 2018 1:51 PM
To: 'taylc@hotmail.com'
Subject: ACCIDENT INVOLVING SKA 2934G & SKX 5354P ON 04/02/2018



51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/AIG18002576/Uua3

TAY LIANG CHEE
69 COMPASSVALE BOW
#14-38
SINGAPORE 544993

Dear Sir/Madam,

ACCIDENT INVOLVING SKA 2934G & SKX 5354P ON 04/02/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

THIN THIN HLAING
Case Handler
DID: 6841 2360
FAX: 6741 4108
Email: thinthin@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

AUTHORIZATION TO ACT
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)


I, CHIN JIE ("the third party claimant")
of 35 LORONG BUKU LYE #01-05 S 536443 (address),
owner of SKX 5354P (vehicle no.) hereby authorize
TAN LIM MOTOR PTE LTD

("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. SKX 5354P that was
damaged pursuant to the accident which occurred on 09-02-2018 (date) along
SUP ROAD OF HOUANGH CENTRAL TOWARDS UPPER (location)
SERANJUAN ROAD
involving vehicle no/s SKA29346 ("the accident").

I further authorize the workshop to settle the above mentioned claim in a
manner that they deem fit and the workshop is further authorized to receive
payment further to settlement of my claim with payment cheque/s being made in
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my
behalf is on a without prejudice and without admission of liability basis insofar
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 5th day of FEB (month) 20 18 (year)



Signed by "the third party claimant"




Signed by "the workshop"

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, TAN LIM MOTOR PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$ 5,243.00 (Repair Cost), S\$200.00 (Loss of Rental/Use), S\$ 7.49 (Disbursement) for vehicle no. SKX 5354P that was damaged pursuant to the accident which occurred on 04/02/2018 (date) along SERANGOON ROAD TOWARDS HOUGANG CENTRAL (location) involving vehicle no/s SKA 2934G. This is pursuant to the inspection conducted on 08/02/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner CHIN JIE ("the third party claimant") of vehicle no. SKX 5354P make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SKX 5354P (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 16 (day) of August (month) 2018 (year)



Signed by appointed surveyor



Signed by "the workshop" (with chop)

"The contents of this document apply to vehicle damages only. All personal injuries and damages arising therefrom are excluded from the ambit and application of this document."



TAX-INVOICE
NUMBER: TP0218/015

(Please quote our reference number TP002022018 for payment)

陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD


Chin Jie

Date: 20/02/2018

Vehicle No: SKX5354P
Model: VOLKSWAGEN JETTA 1.4

Description	Amount
To lump sum repair as recommended by surveyor.	\$4,900.00
Reimbursement of LTA search fees.	\$7.00

Sub Total	\$4,907.00
Add 7% GST	\$343.49
Total	\$5,250.49


Tan Lim Motor Pte Ltd

Enquire Vehicle & Owner Information (Vehicle No. SKA2934G As At 04 Feb 2018 / 19:00:00)**Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: SKX5354P

Current Owner Details

Owner ID Type: Singapore NRIC

Owner ID: 51780268B

Owner Name: TAY LIANG CHEE

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House
No.: 69

Registered Street Name: COMPASSVALE BOW

Registered Unit No.: # 14 - 38

Registered Building Name: -

Registered Postal Code: 544993

Current Vehicle Details

Vehicle No.: SKA2934G

Make Description/Model: TOYOTA / WISH 1.8 CVT

Insurance Company Name: AIG ASIA PACIFIC INSURANCE PTE. LTD.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane



























CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Feb 2018 Edit Reg		08 Feb 2018 00:00 Edit Adj Rpt	S\$4,900.00 Edit Estimates	S\$4,900.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	Tay Liang Chee, ID: S1780268B								
Main Claimant:	CHIN JIE, ID: S8224556A								
Vehicle Reg. No.:	SKX5354P	Date of Loss:	04/02/2018 18:00 - :59 [25 Months and 18 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 2517920219SG	Policy/Cover Note No.:	2100247922 (Comprehensive)						
Vehicle Reg. No. (Insured):	SKA2934G	Policy No. (Claimant):	A28875521AVW						
		Excess:							
Repairer:	Tan Lim Motor Pte Ltd (Defu) 51 Defu Lane 10, 539216 Defu Lane - Tel: 6858 5151								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Wui, Shawn-KJ] Shawnkaijye.Wui@aig.com								
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 20/02/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKX5354P (2517920219SG)
[SKA2934G]
TP
CHIN JIE
Feb 4 2018 6:55PM
[Tay Liang Chee]
Tan Lim Motor Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View View in Browser			
Letters/Correspondences													1 per page			<input checked="" type="checkbox"/>		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)											Thumbnail			Print		
1	(Draft)	Third Party Express Settlement – Payment Breakdown											1			Edit		
Photos/Images													3 per page			<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)											Thumbnail			Print		
1	08/02/18 16:38	Odometer Reading											1			Load JPG <input checked="" type="checkbox"/>		
2	08/02/18 16:38	General View											1			Load JPG <input checked="" type="checkbox"/>		
3	08/02/18 16:38	Chassis Number											1			Load JPG <input checked="" type="checkbox"/>		
4	08/02/18 16:38	General View											1			Load JPG <input checked="" type="checkbox"/>		
5	08/02/18 16:38	General View											1			Load JPG <input checked="" type="checkbox"/>		
6	08/02/18 16:38	General View											1			Load JPG <input checked="" type="checkbox"/>		
7	08/02/18 16:38	General View											1			Load JPG <input checked="" type="checkbox"/>		
8	08/02/18 16:38	General View											1			Load JPG <input checked="" type="checkbox"/>		
9	08/02/18 16:38	General View											1			Load JPG <input checked="" type="checkbox"/>		
10	08/02/18 16:38	General View											1			Load JPG <input checked="" type="checkbox"/>		
11	08/02/18 16:38	General View											1			Load JPG <input checked="" type="checkbox"/>		
12	08/02/18 16:38	General View											1			Load JPG <input checked="" type="checkbox"/>		
13	08/02/18 16:38	General View											1			Load JPG <input checked="" type="checkbox"/>		
14	08/02/18 16:38	General View											1			Load JPG <input checked="" type="checkbox"/>		
15	08/02/18 16:38	General View											1			Load JPG <input checked="" type="checkbox"/>		
16	08/02/18 16:38	General View											1			Load JPG <input checked="" type="checkbox"/>		
17	08/02/18 16:38	General View											1			Load JPG <input checked="" type="checkbox"/>		
18	08/02/18 16:38	General View											1			Load JPG <input checked="" type="checkbox"/>		
19	08/02/18 16:38	General View											1			Load JPG <input checked="" type="checkbox"/>		
20	08/02/18 16:38	General View											1			Load JPG <input checked="" type="checkbox"/>		
21	08/02/18 16:38	General View											1			Load JPG <input checked="" type="checkbox"/>		
22	08/02/18 16:38	General View											1			Load JPG <input checked="" type="checkbox"/>		
23	08/02/18 16:38	General View											1			Load JPG <input checked="" type="checkbox"/>		
24	08/02/18 16:38	General View											1			Load JPG <input checked="" type="checkbox"/>		
25	08/02/18 16:38	General View											1			Load JPG <input checked="" type="checkbox"/>		
26	08/02/18 16:38	General View											1			Load JPG <input checked="" type="checkbox"/>		
27	08/02/18 16:38	General View											1			Load JPG <input checked="" type="checkbox"/>		
28	08/02/18 16:38	General View											1			Load JPG <input checked="" type="checkbox"/>		
29	08/02/18 16:38	General View											1			Load JPG <input checked="" type="checkbox"/>		
30	08/02/18 16:38	General View											1			Load JPG <input checked="" type="checkbox"/>		
31	08/02/18 16:38	General View											1			Load JPG <input checked="" type="checkbox"/>		
32	08/02/18 16:38	General View											1			Load JPG <input checked="" type="checkbox"/>		
33	12/02/18 16:21	Reinspection Photo											1			Load JPG <input checked="" type="checkbox"/>		
34	12/02/18 16:21	Reinspection Photo											1			Load JPG <input checked="" type="checkbox"/>		

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	12/02/18 16:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	12/02/18 16:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	12/02/18 16:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	12/02/18 16:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	12/02/18 16:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	12/02/18 16:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	12/02/18 16:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	12/02/18 16:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	12/02/18 16:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	12/02/18 16:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	12/02/18 16:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	12/02/18 16:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	12/02/18 16:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	12/02/18 16:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	12/02/18 16:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	12/02/18 16:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	12/02/18 16:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	12/02/18 16:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/02/18 12:18	TP GIA REPORT	 Load PDF	
2	12/02/18 12:18	TP ESTIMATE- MARKED	 Load PDF	
3	23/08/18 08:28	WORKSHOP INVOICE	 Load PDF	
4	23/08/18 08:28	AUTHORISATION TO ACT FORM	 Load PDF	
5	23/08/18 08:28	Release Voucher	 Load PDF	
6	23/08/18 08:28	LTA SEARCH	 Load PDF	
7	23/08/18 08:28	LETTER TO OI	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	12/02/18 15:45	OI GIA report	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKA2934G (Insd veh)	Model:	VOLKSWAGEN JETTA GP
	SKX5354P (TP veh)		1.4 TSI 90 A/T (A)
Date of Accident:	04/02/2018		

Global Sum Settlement	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	: \$	11,872.24
Final Repair Cost	: \$	5,243.00
Loss of Use	: \$	200.00
Rental (if any)	: \$	0.00
LTA / GIA Search Fee	: \$	7.49
Others:	: \$	0.00
	: \$	
Final Settlement Sum	: \$	5,450.49

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For <u>Non GIA Registered Workshop</u> :	Agreed Liability _____ 100 _____ (%)
B) For <u>GIA Registered Workshop</u> :	BOLA Applicable: Yes/ No BOLA Scenario No: _____
BOLA Liability: _____ (%)	Assessed Liability (*): _____ (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.	
Remarks _____	

Payment Instruction: Payee's Breakdown			
1)	Tan Lim Motor Pte Ltd	: \$	5,450.49
2)		: \$	
3)		: \$	
4)		: \$	

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

23 Aug
2018

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18002576/UUA3Q2

Date: 23/08/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No: 2100247922

Claimant Vehicle No: SKX5354P

Insured Vehicle No: SKA2934G

Date of Loss: 04/02/2018

Nature of Claim: TP

Claim No: 2517920219SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKX5354P

Make & Model: VOLKSWAGEN JETTA GP, 1.4 TSI 90 A/T (A)

Engine No: CAXF42145

Reg. Date: 17/12/2015 (Man. Year: 2015)

Chassis No: WVVZZZ16ZFM028397

Colour: Silver

Odometer: 27234 km

Engine Capacity: 1390 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17

Rear Tyre Size: 225/45 R17

Front Left Side: Goodyear 6 mm

Rear Left Side: Goodyear 6 mm

Front Right Side: Goodyear 6 mm

Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,775.55	4,886.73	3,888.82	44.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,320.00	1,280.00	1,040.00	44.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,095.55	6,166.73	4,928.82	44.42
Approved Total (Overridden) (S\$)		4,900.00		
(S\$)	11,095.55	4,900.00	6,195.55	55.84
+ GST 7.00/7.00% (S\$)	776.69	343.00	433.69	55.84
Nett Amount (S\$)	11,872.24	5,243.00	6,629.24	55.84
+ Loss of Use (4.0 x S\$50.00/day) (S\$)		200.00		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		5,450.49		

INSPECTION

Date of Assignment: 08/02/2018

Date Inspected: 08/02/2018

Inspected At:

Tan Lim Motor Pte Ltd (Defu)
51 Defu Lane 10
Singapore 539216

Estimated Period of Repair: 4.0 days

<

Adjuster: MARCUS CHUA

Manager: THIN THIN HLAING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented / Buckled	1,875.45 F	*1,875.45 FL
2	1		*BOOTLID LOCK	Twisted / Shorted	179.05 F	*179.05 FL
3	1		*BOOTLID LOCK STICKER	Not Necessary	48.15 F	*- FL
4	2		*BOOTLID RUBBER STOPPER	Not Necessary	5.00 F	*- FL
5	1		*BOOTLID INNER TRIM	Not Necessary	220.75 F	*- FL
6	2		*BOOTLID HINGE	Repair	253.70 F	*- FL
7	1		*BOOTLID TSI BADGE	Necessary	61.85 F	*61.85 FL
8	1		*BOOTLID DELTA BADGE	Necessary	82.10 F	*82.10 FL
9	1		*BOOTLID CENTRE EMBLEM BADGE	Necessary	115.75 F	*115.75 FL
10	1		*BOOTLID WEATHERSTRIP	Twisted	323.85 F	*323.85 FL
11	2		*REAR LICENSE PLATE LAMP	Not Necessary	511.70 F	*- FL
12	1		*REAR END PANEL	Repair	1,206.00 F	*- FL
13	1		*REAR END PANEL INNER TRIM	Not Necessary	145.75 F	*- FL
14	1		*REAR BUMPER	Dented / Deformed	1,366.35 F	*1,366.35 FL
15	1		*REAR BUMPER REINFORCEMENT	Bent	606.05 F	*606.05 FL
16	2		*REAR BUMPER REFLECTOR	Not Necessary	133.10 F	*- FL
17	2		*REAR BUMPER SIDE RETAINER	Necessary	220.80 F	*220.80 FL
18	1		*REAR BUMPER CENTRE BEAM	Cracked	102.15 F	*102.15 FL
19	2		*REAR LAMP	Not Necessary	755.70 F	*- FL
20	2		*REAR LAMP CLIP HOLDER	Not Necessary	32.30 F	*- FL
21	1		*REAR LICENSE PLATE	Not Necessary	80.00 FS	*- FS
22	1		*REAR BUMPER PARKING SENSOR	Shorted	450.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,775.55	5,133.40
- List Item Discount on L Items 0.00/5.00% (\$\$)	0.00	246.67
Total Parts (\$\$)	8,775.55	4,886.73

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REINSTALL OF REAR BUMPER PARKING SENSOR	New	150.00	50.00
2	TO REMOVE AND REFIT INTERIOR FITTINGS ,TRIMMINGS ,GARNISH AND OTHER ,TO ENABLE REPAIR	New	160.00	60.00
3	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	60.00	30.00
4	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	150.00	60.00
5	TO RUST-PROOFING OF THE AFFECTED AREAS	New	120.00	30.00
6	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	800.00	450.00
7	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	880.00	600.00
Gross Labour Cost (\$\$)			2,320.00	1,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >