



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216

Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

AlGAsia Insured's Veh No : SKA2934G

Date of Accident : 04 February 2018

Mr Chin Jie

Date : 07 February 2018

Estimate To Repair SKX5354P - Volkswagen JETTA GP 1.4 TSI 90 A/T HL 163

Chassis No : WVVZZZ16ZFM028397

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	bootlid <i>DD/Buc</i>	\$ 1,875.45
02	1 pc	bootlid lock <i>tm/6wdd</i>	\$ 179.05
03	1 pc	bootlid lock sticker <i>1 1</i>	\$ 48.15
04	2 pc	bootlid rubber stopper @ \$2.50' <i>1 1</i>	\$ 5.00
05	1 pc	bootlid inner trim <i>1 1</i>	\$ 220.75
06	2 pc	bootlid hinge @ \$126.85 <i>1</i>	\$ 253.70
07	1 pc	bootlid TSI badge <i>me</i>	\$ 61.85
08	1 pc	bootlid delta badge <i>me</i>	\$ 82.10
09	1 pc	bootlid centre emblem badge <i>me</i>	\$ 115.75
10	1 pc	bootlid weatherstrip <i>tm</i>	\$ 323.85
11	2 pc	rear license plate lamp @ \$255.85 <i>1 1</i>	\$ 511.70
12	1 pc	rear end panel <i>1</i>	\$ 1,206.00
13	1 pc	rear end panel inner trim <i>1 1</i>	\$ 145.75
14	1 pc	rear bumper <i>DD/oe</i>	\$ 1,366.35
15	1 pc	rear bumper reinforcement <i>me</i>	\$ 606.05
16	2 pc	rear bumper reflector @ \$66.55 <i>1 1</i>	\$ 133.10
17	2 pc	rear bumper side retainer @ \$110.40 <i>me</i>	\$ 220.80
18	1 pc	rear bumper centre beam <i>me</i>	\$ 102.15
19	2 pc	rear lamp @ \$377.85 <i>1 1</i>	\$ 755.70
20	2 pc	rear lamp clip holder @ \$16.15 <i>1 1</i>	\$ 32.30
			\$ 8,245.55
<u>SPECIAL NETT ITEMS</u>			
21	1 pc	rear license plate <i>1 1</i>	\$ 80.00
22	1 pc	rear bumper parking sensor <i>shhd</i>	\$ 450.00
			\$ 530.00
<u>LABOUR & MISC. CHARGES</u>			
01		To reinstall of rear bumper parking sensor.	\$ 150.00
02		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 160.00
03		To check electrical lighting concerned.	\$ 60.00
04		To transfer of bootlid fittings, attachments and perform water seepage test.	\$ 150.00
05		To rust-proofing of the affected areas.	\$ 120.00
06		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 800.00

not added
4 days
8/2/18
2/5 \$4900 OK

5%

1,875.45
179.05
48.15
5.00
220.75
253.70
61.85
82.10
115.75
323.85
511.70
1,206.00
145.75
1,366.35
606.05
133.10
220.80
102.15
755.70
32.30
8,245.55
4933.5
4686.7

80.00
450.00
530.00
150.00
160.00
60.00
150.00
120.00
800.00
50
60
30
60
30
450



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SKA2934G
Date of Accident : 04 February 2018

Mr Chin Jie

Date : 07 February 2018

Estimate To Repair SKX5354P - Volkswagen JETTA GP 1.4 TSI 90 A/T HL 163
Chassis No : WVWZZZ16ZFM028397

S/No	Quantity	Description	Amount
07		<u>LABOUR & MISC. CHARGES</u> Putty and spray painting of the affected portion.	\$ 880.00
			\$ 2,320.00
		Total	\$ 11,095.55

600
6166.73

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: