



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877
Registration No : SDX168B
Chassis No : JHMRC1890HC203698
Model : ODYSSEY 2.4 EXV-S 17YM (EURO 6)
Owner's Name : LIM BENG HONG
Ins Policy No. :
Date of Accident : 3/2/2018

Document No. : SQT18000572 **Page** 4
Date : 6. Feb 2018
Customer No. : WZF002
Svc Advisor : PATRICK MOK LIP KAY
Engine No : K24W72041345
Date | Time : 6. Feb 2018 3:17:57 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl GST
34150-T6A-003	LIGHT ASSYR.LID 283.95	1	378.60	25	567.90	39.75	607.65
34155-T6A-003	LIGHT ASSYL.LID 283.95	1	378.60	25	283.95	19.88	303.83
36530-T6A-J01	CAMERA ASSYMVCS RR.	1	509.80	25	382.35	26.76	409.11
Sum Item					16502.54	1,155.15	17,657.69

Survey By

Date & Time

Excess

Status

Signature

Total Amount 34,062.54 2,384.35 36,446.89

Total (Inclusive of GST) 36,446.89

34,199.26

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 15/2/2018 12:19:01 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)