

ASS. REC. BY:

REF:

CS/FCI18002591/TIvd3/9

Client's Instruction:

Surveyor:

CWS

Taufik

ASSIGNMENT (Office)

From (Person):

Aung Yin Min

of

FCI

Date/Time:

7/2/18 @ 5:13pm

Estimated Cost:

Bill to:

OD: ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No:

SDX168B

Insured:

SHD 8536C

at Workshop m/s:

Kah Motor

Tel:

82886302

of

15 Ubi Rd 4

Policy No:

Claim No:

D18001113MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A 03/02/2018

CA / REV / REP. / REV 24 HRS 1 w/2

H.O.D. Endorsement:

Date/Time:

9:17am 08/2/18

Person Contacted:

Patrick

Vehicle IN/OUT

Date/Time

Action/Instruction (-) Estimate

SDX168B -x

SHD 8536C-CS/FCI16015643/Alt302

D.O.A: 20/8/16

15/2/18

Email preli revised to FCI

8/3/18

@ 210pm Patrick said vehicle still under repair

26/4/18

Final fig \$19,972.18 Confirmed by email (Ref 14,227.08, 429)

Taufan

REP. FCI

ASSIGNMENT

From: Date: 12/2/18
 Estimated Cost:
 CO / TP / WS / TP RES / CO RES / EVA / INV / MV
 To inspect Vehicle No:
 at Worksite via
 of
 Insured
 Policy No
 Claims No
 Sum Insured Excess
 (Client's Record)
 Make of Veh

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection



Est. or Market Value: \$145K
 IDAC Accident Report Consistent? (Yes or No)
 DIA / PP Seen Consistent? (Yes or No)
 Est. Repairs days Fee Yes or No
 Lum Sum \$ Val. Yes or No
 CA / REV / REP. / 24 HRS

Date Person Contacted Patrick
 Date / Time Action / Instruction

Vehicle: SDX-168R 2017 Exp.
 Type Motorcycle Survived Long Term Police Major
 Truck / Trailer

Make Honda Odyssey CC 2356
 Colour Maroon Insured Stc
 Sp. Reading 5488 T. Road Insured Stc
 Eng. No
 C/Vs JHMRC1890HC203698
 Gen. Cond. Good Paint Foot Burnt
 Steering Order Jammed Leaked Burnt or
 Brake Order Jammed Leaked Burnt or
 Mod. NI / S / R / STD ARim or
 Tyre Size 215 / 85R17

BS / SUN / EXNOVA / GY / PS / LIZA / MIC / OHTSU / PIR / SUM /
 TOYO / YOKO

Front Rear
 R.Bal 6 mm R.Bal 6 mm
 L.Bal 6 mm L.Bal 6 mm
 D.O.A C.O. 12/2/18 @ 1545
 Surveyed at Kah Motor Drag Kee
 Des. of Damages Fr Rear O/S NE UC Roof or

The U/C / Chassis frame / Body Structure affected due to collision

RECEIVED 20 APR 2019

Case Time / File Pass / ☐ : Prel. Report
☐ : Final Report

Days Of Repair: 20
 Resurvey No. of Trip: 2

26/4- Typet

Add Fee: ☐ Site Visit
☐
☐
☐

Report Format CWS
 Lump Sum P/P \$19,972.18

3445-360
 1707360
 50
 50+50
 135
 813
 7/15/18

Survey Department Check List (Case Handler)

Reference No.: CS/FCL/800 2591/Tivd3
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all information created by the assignment team are ACCURATE.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From	✓			
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A				
C	Policy No	✓			
C	Claim No				
C	Insurance Authorisation (CA /REV/REP)	✓			
C	Report Type				
C	Weekend Charges	✓			
N	Survey held at/Repairer				
C	Excess				

Surveyor (

): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages				

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)	/			
C	Days of repair	/			
C	Finalised Amount				
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	/			
---	-------------------------	---	--	--	--

Check By: VERON 26/4/18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/20



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18002591/T1vd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 08-02-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 8536C		Veh. Inspected	SDX 168B
Policy No.			Coverage (\$)	0.00
Claim No.	D18001113MFSH		Excess (\$)	0.00
Assign From	CWS (AUNG YIN MIN)		Assign Date	08/02/2018
2. Vehicle Particulars & Condition				
Make & Model			c.c	0
Engine No.	HIDDEN		Year of Reg.	
Chassis No.			Colour	
Odometer	-		Steering	
Brakes			Modification	
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	03/02/2018		Inspection Date	
Survey held at	KAH MOTOR CO SDN BERHAD 15 UBI ROAD 4 SINGAPORE 408610			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 26 February 2018 10:33 AM
To: 'Patrick Mok'; SUR
Subject: RE: SDX 168B-DOA: 3/2/2018

Dear Patrick,

Case is Direct Settlement.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 15 February 2018 12:20 PM
To: 'Patrick Mok' <patrickmok@honda.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SDX 168B-DOA: 3/2/2018

Dear Patrick,

Survey on "WP"

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Patrick Mok [<mailto:patrickmok@honda.com.sg>]
Sent: Thursday, 15 February 2018 12:18 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Subject: RE: SDX 168B-DOA: 3/2/2018

Hi Veron,

Is this a Direct Settlement case?

From: Veron Chen (LKKAUTO) [<mailto:veronchen@lkkauto.com>]
Sent: Thursday, February 15, 2018 12:14 PM

To: Patrick Mok <patrickmok@honda.com.sg>; SUR <sur@lkkauto.com>

Subject: SDX 168B-DOA: 3/2/2018

Dear Patrick,

Kindly forward us complete set of estimate (pg 4 missing)

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

Patrick Mok

From: Claim Workflow System <cwsmotorclaims@msfirstcapital.com.sg>
Sent: Wednesday, February 07, 2018 5:43 PM
To: Patrick Mok
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG;
AUNGYINMIN@MSFIRSTCAPITAL.COM.SG
Subject: SURVEYOR APPOINTED; OUR REF : D18001113MFSH ; YOUR REF: SDX168B

Dear Sir/Madam

PRI Request For **SDX168B** Accident Involving **SHD8536C** On 03-02-2018 AT 11:10:00HRS.

Please find below details for your reference

- Claim number : D18001113MFSH
- Insured vehicle number : SHD8536C
- Accident date : 03-02-2018
- Third-party vehicle number : SDX168B
- Assignment type : WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED
- Surveyor : LKK AUTO CONSULTANTS PTE LTD
- Officer-in-Charge : AUNGYM

PS: This is a system generated mail. Please do not reply to this mail.

Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

*Albert - 11/02/18
909/0039*

MOTOR SURVEY ASSIGNMENT

Date	06-02-2018	Our Ref No. D18001113MFSH
Accident Date	03-02-2018	Claim Type. Third Party
Insured Vehicle	SHD8536C	Third Party Vehicle. SDX168B
Survey Location	15 UBI ROAD 4	
Contact Person.	PATRICK MOK ✓	
Contact No.	0/ 82886302	Fax No. 0
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	KAH MOTOR CO SDN BHD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	AUNGYM	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/234724)



PRI Documents



Close X

PRI Header Details

Claim No	D18001113MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & KAH MOTI
Workshop Name	KAH MOTOR CO SDN BHD (Contact Person : PATRICK MOK)	Survey Location & Contact Details	15 UBI ROAD 4 Mobile: 82886302 , Phone: 0 , Fax: 0 EmailId: PATRICKMOK@HONDA.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHD8536C	TP Vehicle No	SDX168B
PRI Recieved Date	07-02-2018 03:00:32 PM	Surveyor Appointed Date	07-02-2018 05:42:15 PM	Surveyor Accept Date	08-02-2018 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	08-02-2018	Upload Survey Report *:	Choose File
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 15 February 2018 12:53 PM
To: 'Claim Workflow System'
Cc: AUNGYINMIN@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18001113MFSH/1, SDX 168B
Attachments: SDX 168B PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SDX 168B
Date of survey: 12/2/2018
Number of days:20 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 8 February 2018 9:22 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: AUNGYINMIN@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18001113MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 7 February 2018 5:43 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; AUNGYINMIN@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18001113MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

- Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18001113MFSH
Our ref: CS/FC18002591/T1vd3

Date: 15/2/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Without Prejudice

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SDX 168B


We thank you for your instruction on 7/2/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 12/2/2018 at the premises of M/s KAH MOTOR CO SDN BERHAD and have the following to report:-

Workshop Estimate Amount	: S\$34,062.54
Revised Estimate Amount	: S\$17,928.85
"Check" Items Amount	: S\$13,119.74
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

MOHAMAD TAUFIKH
M.MATAL, AMSAE-A
Automobile Assessor

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7250I
Vehicle Details	
Vehicle No.:	SDX168B
Vehicle to be Exported:	No
Intended De-registration Date:	25 Apr 2018
Vehicle Make:	HONDA
Vehicle Model:	ODYSSEY 2.4 EXV-S CVT SR
Primary Colour:	Red
Manufacturing Year:	2017
Engine No.:	K24W72041345
Chassis No.:	JHMRC1890HC203698
Maximum Power Output:	129.0 kW (172 bhp)
Open Market Value:	\$30,986.00
Original Registration Date:	28 Sep 2017
First Registration Date:	28 Sep 2017
Transfer Count:	0
Actual ARF Paid:	\$35,381.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Sep 2027
PARF Rebate Amount:	\$26,535.00
Intended COE Rebate Details	
COE Expiry Date:	27 Sep 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$47,501.00
COE Rebate Amount:	\$44,756.00
Total Rebate Amount:	\$71,291.00

The information contained herein is correct as at 25 Apr 2018

OK

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7250I
Vehicle Details	
Vehicle No.:	SDX168B
Vehicle to be Exported:	No
Intended De-registration Date:	15 Feb 2018
Vehicle Make:	HONDA
Vehicle Model:	ODYSSEY 2.4 EXV-S CVT SR
Primary Colour:	Red
Manufacturing Year:	2017
Engine No.:	K24W72041345
Chassis No.:	JHMRC1890HC203698
Maximum Power Output:	129.0 kW (172 bhp)
Open Market Value:	\$30,986.00
Original Registration Date:	28 Sep 2017
First Registration Date:	28 Sep 2017
Transfer Count:	0
Actual ARF Paid:	\$35,381.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Sep 2027
PARF Rebate Amount:	\$26,535.00
Intended COE Rebate Details	
COE Expiry Date:	27 Sep 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)

COE Period(Years):	10
QP Paid:	\$47,501.00
COE Rebate Amount:	\$45,680.00
Total Rebate Amount:	\$72,215.00

The information contained herein is correct as at 15 Feb 2018

OK



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)


Honda Odyssey

Price Range

Depreciation

2017

Vehicle Type



Search

Advanced Search

[Home](#) > [Used Cars](#) > [Direct Owners](#) > Honda Odyssey 2.4A EXV-S

Resources

[Car Buying](#)
[Car Selling](#)
[Car Ownership](#)
[Car Aftermarket](#)
[On The Move](#)
[Lifestyle](#)

Vehicle Number Plates

BUY & SELL
Your AUSPICIOUS & UNIQUE Vehicle No.

Do you know? We are Singapore's **BIGGEST PLAYER** with the most vehicle plate numbers for sale!

Click here to see all Auctions & Listings

Honda Odyssey 2.4A EXV-S

[Overview](#)
[Financial](#)
[Accessories](#)
[Similar](#)
[Research](#)
[Photos](#)
[Map](#)
[DIRECT OWNER](#)
[Add to Shortlist](#)
[Add to Compare](#)
[Add a Note](#)
[Report Error](#)
[More Actions](#)
[Share](#)

Car Details

Price	\$145,000	
Depreciation	\$13,530 /yr	View models with similar depreciation
Reg Date	20-Sep-2017	(9yrs 4mths 25days COE left)
Manufactured	2017	
Mileage	6,000 km	
Transmission	Auto	
Engine Cap	2,356 cc	
Road Tax	\$1,630 /yr	
Power	129.0 kW (172 bhp)	View specs of the Honda Odyssey (2014)
Curb Weight	1,855 kg	
Features	-	
Accessories	-	
COE	\$49,000	
OMV	\$30,986	
ARF	\$35,381	
Derog Value	\$72,636 as of today (change)	
No. of Owners	1	
Type of Veh	MPV	
Category	PARF Car, Direct Owner Sale, Almost New Car	
Availability	Available	DIRECT OWNER

[Add to Shortlist](#)
[Add to Compare](#)
[Add a Note](#)

Posted on: 10-Apr-2018 | Last Updated on: 24-Apr-2018

Tags: Honda Odyssey, 2017 Honda Odyssey, Honda, Odyssey, Used Honda

Upfront Payment

[+ more Financial info](#)

Transfer Fee	N.A.	
Down Payment	\$58,000 (change)	Maximum 60% Loan
1st Instalment	\$1,252	
Total Upfront Payment	N.A.	

Estimates based on 60% loan at 2.98% interest rate. Check with seller for exact figure.

Items for Honda Odyssey

[+ View All](#)

100% FREE
PAPERWORK
SUPPORT FOR
BOTH BUYER
& SELLER


Seller Information

Contact Person(s) Jack Yeo

Contact No. 98379264

Enquiry [Contact Seller](#)

USEFUL FORMS

[Indemnity form](#) [Sales agreement](#)
[Receipt](#) [Hand-over form](#)
[M01](#)

Instructions on how to complete a seller to end-consumer deal

Regardless of buying or selling, we'll handle your paperwork, loans & insurance for FREE.



Useful Services



Make sure of this car condition with STA Evaluation.

Vehicle Evaluation



Find out the market value for your car. Get a free Car Valuation.

Free Valuation

[Compare](#)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/02/2018 15:38
Date Of Accident	03/02/2018 11:00
Exact Location Of Accident	ALONG ALEXANDRA RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDX168B
Insured/Policyholder	
Name Of Registered Owner	LIM BENG HONG
NRIC No	S1697250I
Email Address	CLEMENT.TAN1990@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96635252
Alternative Phone No	OFFICE-96635252

Vehicle Particulars

Manufacturer	HONDA
Model	ODYSSEY 2.4 EXV-S CVT SR
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AVIVA LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	10760011
Cover Note Number	N.A.

Driver

Name of Driver	CLEMENT TAN JUN LONG
NRIC No	S9008902A
Date Of Birth	06/03/1990
Occupation	INDOOR
Date Of Driving Pass	20/07/2010
Driving Experience	7 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96635252
Fax Number	
Contact Number	
Email Address	CLEMENT.TAN1990@GMAIL.COM

Address	NIL
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

My vehicle was stopped of the red light along the said location, I was on the first lane of three lane road. While waiting for traffic ahead to move off, I felt an impact from my rear. Vehicle b had collided onto my car, there was. No injuries.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHD8536C
Vehicle Make/Model/Colour	HYUNDAI/ I40/ YELLOW
Details Of Properties	NA
Vehicle Category	TAXI
Name of Driver	ONG KWANG SENG
NRIC/Passport Number	S1547332J
Contact Number	85001732
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/postal packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/are be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

VERIFIED BY AJAX MARS
REPORTING OFFICER
MOHAMAD HELMY BIN
ALEHAM

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre
Personnel

Sketch Plan

ACCIDENT STATEMENT (2000 characters)

My vehicle was stopped of the red light along the said location, I was on the first lane of three lane road. While waiting for traffic ahead to move off, I felt an impact from my rear. Vehicle b had collided onto my car, there was. No injuries.

Taxi Voucher No.:

Are you claiming your own insurance policy for the repair of your vehicle?

No, Claim 3rd party

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
MOHAMAD HELMY BIN ALEHAM

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

Date/Time:

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: LIM BENG HONG OWNER INSURER: AVIVA LTD ACC DATE: 03/02/2018 SURVEYED BY: DATE: REF NO: TP INSURER: FIRST CAPITAL TP VEH: SHD8536C						
					Taufik 97495749. - WP 12/2/18 @ 4pm Reammy before print. taufik@lkkauto.com sir@lkkauto.com 20 days.		
BOSUN	SUNDRIES New	1	100.00	50 ✓	100.00	7.00	107.00
BOJSE	SEALANT FOR TAILGATE	1	100.00	✓✓	100.00	7.00	107.00
BOJSE	SEALANT FOR TAILGATE WINDSCREEN	2	100.00	✓✓ 60	200.00	14.00	214.00
BOJSE	SEALANT FOR REAR END PANEL	1	100.00	✓✓	100.00	7.00	107.00
BOJSE	SEALANT FOR REAR FLOOR PAN	1	100.00	✓✓	100.00	7.00	107.00
BOJSE	SEALANT FOR REAR CHASSIS	1	100.00	✓✓	100.00	7.00	107.00
BKRP02B	CUT OFF & RENEW RR FLOOR PANEL 560/day FENDERS.STRAIGHTEN	1 ✓	6720 8400.00	720 7280	8400.00	588.00	8988.00
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00	✓✓	180.00	12.60	192.60
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00	✓✓	180.00	12.60	192.60
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	560.00	✓✓	560.00	39.20	599.20
BMI02D	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	1	560.00	✓✓	560.00	39.20	599.20
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	560.00	✓✓	560.00	39.20	599.20
BODAMKIT	WINDSCREEN DAM KIT.	1	80.00	✓✓	80.00	5.60	85.60
BKB001R	REMOVE/REFIT/RESET TAILGATE REVERSE CAMERA	1	280.00	✓✓	280.00	19.60	299.60
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	450.00	✓✓	450.00	31.50	481.50
BKOT00R	REMOVE & RENEW RR FLOOR INSULATOR.(N)	1	450.00	✓✓	450.00	31.50	481.50
BMF00D	RREMOVE & INSTALL FUEL TANK FUEL PIPES.(N)	1	560.00	✓ photo	560.00	39.20	599.20
BMU30A	STRAIGHTEN ALIGN & PULL BACK EXHAUST SYSTEM. (N)	1	100.00	✓✓	100.00	7.00	107.00

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

Registration No : SDX168B

Chassis No : JHMRC1890HC203698

Model : ODYSSEY 2.4 EXV-S 17YM (EURO 6)

Owner's Name : LIM BENG HONG

Ins Policy No. :

Date of Accident : 3/2/2018

Document No. : SQT18000572

Date : 6. Feb 2018

Customer No. : WZF002

Svc Advisor : PATRICK MOK LIP KAY

Engine No : K24W72041345

Date | Time : 6. Feb 2018 3:17:57 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl GST
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	4500.00		4500.00	315.00	4815.00
	<i>\$450 / panel</i>		<i>3600 ✓</i>				
	Sum Labor				17560.00	1,229.20	18,789.20
RS-4CS	4PCS CORNER SENSOR W DISPLAY	1	272.00		272.00	19.04	291.04
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N)	1	45.00		45.00	3.15	48.15
04656-T6A-300ZZ	PAN SET3RD SEAT	1	331.30	25	248.47	17.39	265.86
04659-T6A-300ZZ	CROSSMEMBER COMPRR.UPPER	1	206.50	25	154.87	10.84	165.71
65549-T6A-003	SEPARATORR.RR.PILLAR	1	7.90	25	5.92	0.41	6.33
65599-T6A-003	SEPARATORL.RR.PILLAR	1	7.90	25	5.92	0.41	6.33
65620-T6A-J00ZZ	FRAME SUB COMPR.RR.LOWER	1	619.50	25	464.62	32.52	497.14
65670-T6A-J00ZZ	FRAME SUB COMPL.RR.LOWER	1	619.50	25	464.62	32.52	497.14
66100-T6A-Q00ZZ	PANEL COMP.REAR	1	451.70	25	338.77	23.71	362.48
63320-T6A-300ZZ	GUTTER COMPR.RR.PILLAR	1	129.10	25	96.82	6.78	103.60
63720-T6A-300ZZ	GUTTER COMPL.RR.PILLAR	1	129.10	25	96.82	6.78	103.60
73214-T6A-003	MOLDINGRR.WINDSHIELD SIDE	2	17.60	25	26.40	1.85	28.25
73215-T6A-003	MOLDINGR.RR.WINDSHIELD CORNER	1	16.60	25	12.45	0.87	13.32
73216-T6A-003	MOLDINGL.RR.WINDSHIELD CORNER	1	16.60	25	12.45	0.87	13.32
73221-SR4-000	SPACERRR.W/SHIELD	4	3.90	25	11.70	0.82	12.52
73225-TM8-000	RUBBER A WINDSHIELD DAM	1	3.60	25	2.70	0.19	2.89
73226-SZW-000	DAMPERSTD 5X5	2	8.30	25	12.45	0.87	13.32
91501-S70-003	FASTENER BW/SHIELD	4	3.20	25	9.60	0.67	10.27
91502-S70-003	FASTENER B	2	4.90	25	7.35	0.51	7.86
68100-T6A-Q10ZZ	TAILGATE COMP	1	1049.80	25	787.35	55.11	842.46
68210-T6A-003ZZ	HINGE COMPTAILGATE	1	35.00	25	26.25	1.84	28.09
74440-T6A-003	WEATHERSTRIPTAILGATE	1	115.10	25	86.32	6.04	92.36
74800-TF0-J02	LOCKTAILGATE	1	181.70	25	136.27	9.54	145.81
74810-T4N-H01	SWITCH ASSYTAILGATE OPENER	1	103.20	25	77.40	5.42	82.82
74813-SEY-003	STRIKER ASSYTAILGATE	1	27.20	25	20.40	1.43	21.83
74820-T6A-013	STAY ASSYR.TAILGATE OPEN	1	161.40	25	121.05	8.47	129.52
74870-T6A-013	STAY ASSYL.TAILGATE OPEN	1	161.40	25	121.05	8.47	129.52

Printed on 6/2/2018 6:02:03 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877
Registration No : SDX168B
Chassis No : JHMRC1890HC203698
Model : ODYSSEY 2.4 EXV-S 17YM (EURO 6)
Owner's Name : LIM BENG HONG
Ins Policy No. :
Date of Accident : 3/2/2018

Document No. : SQT18000572 Page 3
Date : 6. Feb 2018
Customer No. : WZF002
Svc Advisor : PATRICK MOK LIP KAY
Engine No : K24W72041345
Date | Time : 6. Feb 2018 3:17:57 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl GST
74890-T6A-J01	GARNISH ASSYRR.LICENSE	1 <i>at</i>	225.90	25	169.42 ✓	11.86	181.28
74891-T6A-003	MOLDING ASSYRR.LICENSE GARN	1 <i>at</i>	172.10	25	129.07 ✓	9.03	138.10
90856-TR0-A01	PLUGTRUNK DRAIN	1 <i>new</i>	0.30	25	0.22 ✗	0.02	0.24
84640-T6A-003ZA	LINING ASSYRR.PANEL	1 ?	101.60	25	76.20 ✓	5.33	81.53
84665-T6A-N91ZC	LINING COMP,L.RR.SIDE <i>SEI 45</i>	1 ?	850.70 <i>de</i>	25	638.02 ✓	44.66	682.68
84615-T6A-N72ZD	LINING COMP,R.RR.SIDE	1 ?	705.40 <i>de</i>	25	529.05 ✓	37.03	566.08
84643-T6A-Q01ZA	COMP LIDTOOL	1 ?	60.20 <i>Xun</i>	25	45.15 ✗	3.16	48.31
84662-T6A-Q01ZA	LID,L.RR. SIDE LINING	1 ?	9999.99 <i>Xun</i>	25	7499.99 ✗	525.00	8024.99
84431-T6A-J01ZA	LINING ASSYTAILGATE LOWER	1 ?	202.20 <i>de</i>	25	151.65 ✓	10.62	162.27
84433-T6A-J01ZA	GARNISH ASSYTAILGATE UPPER	1 ?	41.70	25	31.27 ✗	2.19	33.46
84485-T6A-J01ZA	GARNISH ASSYL.TAILGATE SIDE	1 ?	40.40	25	30.30 ✗	2.12	32.42
84435-T6A-J01ZA	GARNISH ASSYR.TAILGATE SIDE	1 ?	40.40	25	30.30 ✗	2.12	32.42
84439-T6A-J01ZA	LID,R.COMBI MAIN	1 ?	19.60	25	14.70 ✗	1.03	15.73
84441-T6A-J01ZA	POCKETTAILGATE LINING PULL	1 ?	10.50 <i>new</i>	25	7.87 ✓	0.55	8.42
75701-T6A-000	EMBLEMH	1 <i>new</i>	25.80	25	19.35 ✓	1.35	20.70
74551-T6A-000	FENDERR.RR.INNER	1 ?	114.00 <i>new</i>	25	85.50 ✗	5.99	91.49
74591-T6A-000	FENDERL.RR INNER	1 ?	114.00 <i>new</i>	25	85.50 ✗	5.99	91.49
04715-T6A-900ZZ	FACERR.BUMPER	1 <i>de</i>	557.20	25	417.90 ✓	29.25	447.15
33505-SLJ-013	REFLECTOR ASSYR.RR.	1 <i>at</i>	44.50	25	33.37 ✓	2.34	35.71
33555-SLJ-013	REFLECTOR ASSYL.RR.	1 ?	44.50 <i>at</i>	25	33.37 ✓	2.34	35.71
71502-T6A-003ZA	FACER.RR.BUMPER GARNISH	1 <i>de</i>	75.30	25	56.47 ✓	3.95	60.42
71507-T6A-003ZA	FACEL.RR.BUMPER GARNISH	1 <i>de</i>	75.30	25	56.47 ✓	3.95	60.42
71512-T6A-921ZA	SPOILER ASSYR.RR.SIDE	1 <i>de</i>	111.80	25	83.85 ✓	5.87	89.72
71517-T6A-921ZA	SPOILER ASSYL.RR.SIDE	1 <i>de</i>	111.80	25	83.85 ✓	5.87	89.72
71593-T6A-003	SPACERR.RR.BUMPER SIDE	1 <i>new</i>	18.70	25	14.02 ✓	0.98	15.00
71598-T6A-003	SPACERL.RR.BUMPER SIDE	1 <i>new</i>	18.70	25	14.02 ✓	0.98	15.00
91505-TM8-003	CLIPBUMPER	7 <i>new</i>	2.00	25	10.50 ✓	0.74	11.24
33500-T6A-003	TAILLIGHT ASSYR.	1 ?	821.70 <i>new</i>	25	616.27 ✗	43.14	659.41
33550-T6A-003	TAILLIGHT ASSYL.	1 ?	821.70	25	616.27 ✗	43.14	659.41
34100-T5A-003	LIGHT ASSYLICENSE	1 ?	31.20	25	23.40 ✗	1.64	25.04

Printed on 6/2/2018 6:02:03 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877
Registration No : SDX168B
Chassis No : JHMRC1890HC203698
Model : ODYSSEY 2.4 EXV-S 17YM (EURO 6)
Owner's Name : LIM BENG HONG
Ins Policy No. :
Date of Accident : 3/2/2018

Document No. : SQT18000572 Page 4
Date : 6. Feb 2018
Customer No. : WZF002
Svc Advisor : PATRICK MOK LIP KAY
Engine No : K24W72041345
Date | Time : 6. Feb 2018 3:17:57 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl GST
34150-T6A-003	LIGHT ASSYRLID 283.95	1/2	378.60	25	567.90	39.75	607.65 CPM ✓
34155-T6A-003	LIGHT ASSYLID 283.95	1	378.60	25	283.95	19.88	303.83 CPM ✓
36530-T6A-J01	CAMERA ASSYMVCS RR.	1	509.80	25	382.35	26.76	409.11 ?X
Sum Item					16502.54	1,155.15	17,657.69

Survey By _____
Date & Time _____
Excess _____
Status _____
Signature _____

(5)48
Total Amount 34,062.54 2,384.35 36,446.89
Total (Inclusive of GST) 36,446.89

34,199.26

Printed on 15/2/2018 12:19:01 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: WZF002 / FIRST CAPITAL
Chassis No: JHMRC1890HC203698
License No: SDX168B
Mileage: 6156
Engine No: K24W72041345

Document No: SVO18011047
Printed By: PATRICKMOK
Order Date: 26. February 2018
Order Time: 11:32:09 AM
Service Advisor: PATRICK MOK LIP KAY

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount Incl GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: LIM BENG HONG OWNER INSURER: AVIVA LTD ACC DATE: 03/02/2018 SURVEYED BY: TAUFIKH DATE: 12/02/2018 REF NO: D18001113MFSH TP INSURER: FIRST CAPITAL TP VEH: SHD8536C						
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N)	1	45.00		45.00	3.15	48.15
04656-T6A-310ZZ	PAN SET,3RD SEAT	1	331.30	25	248.47	17.39	265.86
66100-T6A-300ZZ	PANEL COMPR.	1	451.70	25	338.77	23.71	362.48
73214-T6A-003	MOLDINGRR.WINDSHIELD SIDE	2	17.60	25	26.40	1.85	28.25
73215-T6A-003	MOLDINGR.RR.WINDSHIELD CORNER	1	16.60	25	12.45	0.87	13.32
73216-T6A-003	MOLDINGL.RR.WINDSHIELD CORNER	1	16.60	25	12.45	0.87	13.32
73221-SR4-000	SPACERRR.W/SHIELD	4	3.90	25	11.70	0.82	12.52
73225-TM8-000	RUBBER A WINDSHIELD DAM	1	3.60	25	2.70	0.19	2.89
73226-SZW-000	DAMPERSTD 5X5	2	8.30	25	12.45	0.87	13.32
91501-S70-003	FASTENER BW/SHIELD	4	3.20	25	9.60	0.67	10.27
91502-S70-003	FASTENER B	2	4.90	25	7.35	0.51	7.86
68100-T6A-Q10ZZ	TAILGATE COMP	1	1,049.80	25	787.35	55.11	842.46
74440-T6A-003	WEATHERSTRIPTAILGATE	1	115.10	25	86.32	6.04	92.36
74800-TF0-J02	LOCKTAILGATE	1	181.70	25	136.27	9.54	145.81
74813-SEY-003	STRIKER ASSYTAILGATE	1	27.20	25	20.40	1.43	21.83
74890-T6A-J01	GARNISH ASSYRR.LICENSE	1	225.90	25	169.42	11.86	181.28
74891-T6A-003	MOLDING ASSYRR.LICENSE GARN	1	172.10	25	129.07	9.03	138.10
84640-T6A-003ZA	LINING ASSYRR.PANEL	1	101.60	25	76.20	5.33	81.53
84665-T6A-N71ZD	LINING COMPL.RR.SIDE	1	748.60	25	561.45	39.30	600.75
84615-T6A-N72ZD	LINING COMP,R.RR.SIDE	1	705.40	25	529.05	37.03	566.08
84431-T6A-J01ZA	LINING ASSYTAILGATE LOWER	1	202.20	25	151.65	10.62	162.27
84441-T6A-J01ZA	POCKETTAILGATE LINING PULL	1	10.50	25	7.87	0.55	8.42
75701-T6A-000	EMBLEMH	1	25.80	25	19.35	1.35	20.70
04715-T6A-900ZZ	FACERR.BUMPER	1	557.20	25	417.90	29.25	447.15
33505-SLJ-013	REFLECTOR ASSYR.RR.	1	44.50	25	33.37	2.34	35.71
33555-SLJ-013	REFLECTOR ASSYL.RR.	1	44.50	25	33.37	2.34	35.71
71502-T6A-003ZA	FACER.RR.BUMPER GARNISH	1	75.30	25	56.47	3.95	60.42
71507-T6A-003ZA	FACEL.RR.BUMPER GARNISH	1	75.30	25	56.47	3.95	60.42
71512-T6A-921ZA	SPOILER ASSYR.RR.SIDE	1	111.80	25	83.85	5.87	89.72
71517-T6A-921ZA	SPOILER ASSYL.RR.SIDE	1	111.80	25	83.85	5.87	89.72
71593-T6A-003	SPACERRR.BUMPER SIDE	1	18.70	25	14.02	0.98	15.00
71598-T6A-003	SPACERL.RR.BUMPER SIDE	1	18.70	25	14.02	0.98	15.00
91505-TM8-003	CLIPBUMPER	7	2.00	25	10.50	0.74	11.24
34150-T6A-003	LIGHT ASSYR.LID	1	378.60	25	283.95	19.88	303.83
34155-T6A-003	LIGHT ASSYL.LID	1	378.60	25	283.95	19.88	303.83
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR	1	320.00		320.00	22.40	342.40
38387-SLE-003	ANTENNA ASSY,L.RR.	1	59.40	25	44.55	3.12	47.67
74940-TR0-003	BUZZER ASSYSMART	1	58.90	25	44.17	3.09	47.26
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20
SUM PARTS:					5,242.18	366.93	5,609.11

20 REPAIR DAYS.

(A) de
(A) Gup



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer:	WZF002 / FIRST CAPITAL	Document No:	SVO18011047
Chassis No:	JHMRC1890HC203698	Printed By:	PATRICKMOK
License No:	SDX168B	Order Date:	26. February 2018
Mileage:	6156	Order Time:	11:32:09 AM
Engine No:	K24W72041345	Service Advisor:	PATRICK MOK LIP KAY

BOSUN	0672	1	50.00	50.00	3.50	53.50
	SUNDRIES					
BOJSE		1	100.00	100.00	7.00	107.00
	SEALANT FOR TAILGATE					
BOJSE		1	100.00	100.00	7.00	107.00
	SEALANT FOR REAR END PANEL					
BOJSE		1	100.00	100.00	7.00	107.00
	SEALANT FOR REAR FLOOR PAN					
BOJSE		1	100.00	100.00	7.00	107.00
	SEALANT FOR REAR CHASSIS					
BKRP02B	EXT-YJ	1	6,720.00	6,720.00	470.40	7,190.40
	CUT OFF & RENEW RR FLOOR PANEL					
	FENDERS.STRAIGHTEN					
	ALIGN RR CHASSIS & RENEW DAMAGE					
	PARTS.					
BML02I	EXT-YJ	1	180.00	180.00	12.60	192.60
	INSPECT RR LIGHTING MECHANISMS.					
	PERFORM WATER					
	TEST.(N)					
BA02R	EXT-YJ	1	180.00	180.00	12.60	192.60
	REMOVE & RENEW REVERSE					
	SENSORS-4 PCS (N)					
BG02D	EXT-YJ	1	560.00	560.00	39.20	599.20
	REMOVE & INSTALL RR. WINDSCREEN.					
	(N)					
BMI02D		1	560.00	560.00	39.20	599.20
	REMOVE & INSTALL SPEAKER BOARD					
	RR SEATS TRUNK					
	LININGS GARNISHES & ETC.(N)					
BKTG02R	EXT-YJ	1	560.00	560.00	39.20	599.20
	REMOVE & TRANSFER ITEMS TO NEW					
	TAILGATE. ADJUST &					
	ALIGN TAILGATE.(N)					
BODAMKIT		1	80.00	80.00	5.60	85.60
	WINDSCREEN DAM KIT.					
BKBU01R	EXT-YJ	1	280.00	280.00	19.60	299.60
	REMOVE/REFIT/RESET TAILGATE					
	REVERSE CAMERA					
BP00R		1	450.00	450.00	31.50	481.50
	APPLY BODY UNDERSIDE COATING (N).					
BKOT00R	EXT-YJ	1	450.00	450.00	31.50	481.50
	REMOVE & RENEW RR FLOOR					
	INSULATOR.(N)					
BMF00D		1	560.00	560.00	39.20	599.20
	RREMOVE & INSTALL FUEL TANK FUEL					
	PIPES.(N)					
BMU30A		1	100.00	100.00	7.00	107.00
	STRAIGHTEN ALIGN & PULL BACK					
	EXHAUST SYSTEM.(N)					
BP06R	EXT-YBH	1	3,600.00	3,600.00	252.00	3,852.00
	SPRAY PAINTING ON REPAIRED OR					
	REPLACED AREAS. (6P)					
			SUM LABOUR:	14,730.00	1,031.10	15,761.10
			TOTAL SGD	19,972.18	1,398.03	21,370.21

Total Payable (SGD)

21,370.21

Veron Chen (LKKAuto)

From: Patrick Mok <patrickmok@honda.com.sg>
Sent: Thursday, 26 April 2018 11:15 AM
To: Veron Chen (LKKAuto); Taufikh (LKKAuto); SUR
Subject: RE: REQUEST TO CONFIRM FINAL BILL FOR SDX168B

Thank you very much Taufikh and Veron for your finalization on the cost of repair and number of repair days recommended for the above mentioned vehicle, SDX168B. 😊

From: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Sent: Thursday, April 26, 2018 11:11 AM
To: Patrick Mok <patrickmok@honda.com.sg>; Taufikh (LKKAuto) <Taufikh@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: REQUEST TO CONFIRM FINAL BILL FOR SDX168B

Dear Patrick,

WITHOUT PREJUDICE

Confirmed \$19,972.18 before GST

No of days: 20 days

Final invoice and all supporting documents sent over to First Capital Ins Ltd.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Patrick Mok [mailto:patrickmok@honda.com.sg]
Sent: Monday, 23 April 2018 2:43 PM
To: Taufikh (LKKAuto) <Taufikh@lkkauto.com>
Cc: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Subject: RE: REQUEST TO CONFIRM FINAL BILL FOR SDX168B

Hi Taufikh,

These are your requested photos for the check items.

Awaiting for your finalization.

Thank you Taufikh and Team.

Patrick Mok

From: Taufikh (LKK Auto) <taufikh@lkkauto.com>
Sent: Monday, April 23, 2018 10:16 AM
To: Patrick Mok <patrickmok@honda.com.sg>
Cc: 'Veron Chen (LKKAuto)' <veronchen@lkkauto.com>
Subject: RE: REQUEST TO CONFIRM FINAL BILL FOR SDX168B

Hi Patrick,

Any photos for the check items?

Regards
Taufikh
Lkk Auto

From: Patrick Mok [mailto:patrickmok@honda.com.sg]
Sent: Saturday, 21 April 2018 8:58 AM
To: taufikh@lkkauto.com; Veron Chen (LKKAuto)
Subject: REQUEST TO CONFIRM FINAL BILL FOR SDX168B

Hi good morning Taufikh and Team,

Kindly assist to confirm final cost of repair and the number of repair days recommended for the above said vehicle.

Awaiting for your finalization soonest.

Thank you for your time.

Warm regards,
Patrick Mok
Bodyshop Service Advisor
Kah Motor Co. Sdn. Bhd.
Mobile : **82886302**



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and

exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 26 April 2018 11:11 AM
To: Patrick Mok; Taufikh (LKKAUTO); SUR
Subject: RE: REQUEST TO CONFIRM FINAL BILL FOR SDX168B

Dear Patrick,

WITHOUT PREJUDICE

Confirmed \$19,972.18 before GST

No of days: 20 days

Final invoice and all supporting documents sent over to First Capital Ins Ltd.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Patrick Mok [mailto:patrickmok@honda.com.sg]
Sent: Monday, 23 April 2018 2:43 PM
To: Taufikh (LKKAUTO) <taufikh@lkkauto.com>
Cc: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Subject: RE: REQUEST TO CONFIRM FINAL BILL FOR SDX168B

Hi Taufikh,

These are your requested photos for the check items.

Awaiting for your finalization.

Thank you Taufikh and Team.

Patrick Mok

From: Taufikh (LKK Auto) <taufikh@lkkauto.com>
Sent: Monday, April 23, 2018 10:16 AM
To: Patrick Mok <patrickmok@honda.com.sg>
Cc: 'Veron Chen (LKKAUTO)' <veronchen@lkkauto.com>
Subject: RE: REQUEST TO CONFIRM FINAL BILL FOR SDX168B

Hi Patrick,

Any photos for the check items?

•Regards
Taufikh
Lkk Auto

From: Patrick Mok [<mailto:patrickmok@honda.com.sg>]
Sent: Saturday, 21 April 2018 8:58 AM
To: taufikh@lkkauto.com; Veron Chen (LKKAuto)
Subject: REQUEST TO CONFIRM FINAL BILL FOR SDX168B

Hi good morning Taufikh and Team,

Kindly assist to confirm final cost of repair and the number of repair days recommended for the above said vehicle.

Awaiting for your finalization soonest.

Thank you for your time.

Warm regards,

Patrick Mok
Bodyshop Service Advisor
Kah Motor Co. Sdn. Bhd.
Mobile : 82886302



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18002591/T1vd3q2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 07-05-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 8536C	Veh. Inspected	SDX 168B	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D18001113MFSH	Excess (\$)	0.00	
Assign From	AUNGYM	Assign Date	07/02/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA ODYSSEY	c.c	2356	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JHMRC1890HC203698	Colour	MAROON	
Odometer	5488	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/55R17	DUNLOP	6 mm	
L/H Front Tyre	215/55R17	DUNLOP	6 mm	
R/H Rear Tyre	215/55R17	DUNLOP	6 mm	
L/H Rear Tyre	215/55R17	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	03/02/2018	Inspection Date	12/02/2018	
Survey held at	KAH MOTOR CO SDN BERHAD 15 UBI ROAD 4 SINGAPORE 408610			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		20 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDX 168B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	SUNDRIES (SN)	NECESSARY	100.00	50.00
4	CORNER SENSOR W DISPLAY (SN)	NOT WORKING	320.00	320.00
1	NUMBER PLATE WITH CASING -L (SN)	BENT	45.00	45.00
1	PAN SET3RD SEAT (SN)	DEFORMED	248.47	248.47
1	CROSSMEMBER COMPRR.UPPER (SN)	NOT NECESSARY	154.87	-
1	SEPARATORR.RR.PILLAR (SN)	NOT NECESSARY	5.92	-
1	SEPARATORL.RR.PILLAR (SN)	NOT NECESSARY	5.92	-
1	FRAME SUB COMPR.RR.LOWER (SN)	NOT NECESSARY	464.62	-
1	FRAME SUB COMPL.RR.LOWER (SN)	NOT NECESSARY	464.62	-
1	PANEL COMP,REAR (SN)	BENT	338.77	338.77
1	GUTTER COMPR.RR.PILLAR (SN)	NOT NECESSARY	96.82	-
1	GUTTER COMPL.RR.PILLAR (SN)	NOT NECESSARY	96.82	-
2	MOLDINGRR.WINDSHIELD SIDE (SN)	NECESSARY	26.40	26.40
1	MOLDINGR .RR.WINDSHIELD CORNER (SN)	NECESSARY	12.45	12.45
1	MOLDINGL.RR.WINDSHIELD CORNER (SN)	NECESSARY	12.45	12.45
4	SPACERRR.W/SHIELD (SN)	NECESSARY	11.70	11.70
1	RUBBER AWINDSHIELD DAM (SN)	NECESSARY	2.70	2.70
2	DAMPERSTD 5X5 (SN)	NECESSARY	12.45	12.45
4	FASTENER BW/SHIELD (SN)	NECESSARY	9.60	9.60
2	FASTENER B (SN)	NECESSARY	7.35	7.35
1	TAILGATE COMP (SN)	BENT	787.35	787.35
1	HINGE COMPTAILGATE (SN)	NOT NECESSARY	26.25	-
1	WEATHERSTRIPTAILGATE (SN)	NECESSARY	86.32	86.32
1	LOCKTAILGATE (SN)	JAMMED	136.27	136.27
1	SWITCH ASSYTAILGATE OPENER (SN)	NOT NECESSARY	77.40	-
1	STRIKER ASSYTAILGATE (SN)	BENT	20.40	20.40
1	STAY ASSYR.TAILGATE OPEN (SN)	NOT NECESSARY	121.05	-
1	STAY ASSYL.TAILGATE OPEN (SN)	NOT NECESSARY	121.05	-
1	GARNISH ASSYRR.LICENSE (SN)	CUT	169.42	169.42
1	MOLDING ASSYRR.LICENSE GARN (SN)	CUT	129.07	129.07
1	PLUGTRUNK DRAIN (SN)	NOT NECESSARY	0.22	-

Report Ref No. CS/FCI18002591/T1vd3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	LINING ASSYRR.PANEL (SN)	DEFORMED	76.20	76.20
1	LINING COMP,L.RR.SIDE (SN)	DEFORMED	638.02	561.45
1	LINING COMP,R.RR.SIDE (SN)	DEFORMED	529.05	529.05
1	COMP LIDTOOL (SN)	NOT NECESSARY	45.15	-
1	LID,L.RR.SIDE LINING LINING (SN)	NOT NECESSARY	7,499.99	-
1	LINING ASSYTAILGATE LOWER (SN)	DEFORMED	151.65	151.65
1	GARNISH ASSYTAILGATE UPPER (SN)	NOT NECESSARY	31.27	-
1	GARNISH ASSYL.TAILGATE SIDE (SN)	NOT NECESSARY	30.30	-
1	GARNISH ASSYR.TAILGATE SIDE (SN)	NOT NECESSARY	30.30	-
1	LID ,R.COMBI MAIN (SN)	NOT NECESSARY	14.70	-
1	POCKETTAILGATE LINING PULL (SN)	NECESSARY	7.87	7.87
1	EMBLEMH (SN)	NECESSARY	19.35	19.35
1	FENDERR.RR.INNER (SN)	NOT NECESSARY	85.50	-
1	FENDERL.RR.INNER (SN)	NOT NECESSARY	85.50	-
1	FACERR.BUMPER (SN)	DEFORMED	417.90	417.90
1	REFLECTOR ASSYR.RR (SN)	CUT	33.37	33.37
1	REFLECTOR ASSYL.RR (SN)	CUT	33.37	33.37
1	FACER.RR.BUMPER GARNISH (SN)	DEFORMED	56.47	56.47
1	FACEL.RR.BUMPER GARNISH (SN)	DEFORMED	56.47	56.47
1	SPOILER ASSYR.RR.SIDE (SN)	DEFORMED	83.85	83.85
1	SPOILER ASSYL.RR.SIDE (SN)	DEFORMED	83.85	83.85
1	SPACERR.RR.BUMPER SIDE (SN)	NECESSARY	14.02	14.02
1	SPACERL.RR.BUMPER SIDE (SN)	NECESSARY	14.02	14.02
7	CLIPBUMPER (SN)	NECESSARY	10.50	10.50
1	TAILLIGHT ASSYR (SN)	NOT NECESSARY	616.27	-
1	TAILLIGHT ASSYL (SN)	NOT NECESSARY	616.27	-
1	LIGHT ASSYLICENSE (SN)	NOT NECESSARY	23.40	-
2	LIGHT ASSYR.LID (SN)	CRACKED (1 PCS ONLY)	567.90	283.95
1	LIGHT ASSYL.LID (SN)	CRACKED	283.95	283.95
1	CAMERA ASSYMVCS RR (SN)	NOT NECESSARY	382.35	-
1	ANTENNA ASSY,L.RR (ADDITIONAL) (SN)	DEFORMED	44.55	44.55

Report Ref No. CS/FCI18002591/T1vd3q2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BUZZER ASSYSMART (ADDITIONAL) (SN)	CRACKED	44.17	44.17
			16,739.26	5,232.18
	LABOUR			
	SEALANT FOR TAILGATE .		100.00	100.00
	SEALANT FOR TAILGATE WINDSCREEN.		200.00	60.00
	SEALANT FOR REAR END PANEL.		100.00	100.00
	SEALANT FOR REAR FLOOR PAN .		100.00	100.00
	SEALANT FOR REAR CHASSIS .		100.00	100.00
	CUT OFF & RENEW RR FLOOR PANEL FENDERS .STRAIGHTEN .		8,400.00	6,720.00
	INSPECT RR LIGHTING MECHANISMS .PERFORM WATER.		180.00	180.00
	REMOVE & RENEW REVERSE SENSORS .		180.00	180.00
	REMOVE & INSTALL RR .WINDSCREEN.		560.00	560.00
	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK .		560.00	560.00
	REMOVE & TRANSFER ITEMS TO NEW TAILGATE ADJUST &.		560.00	560.00
	WINDSCREEN DAM KIT .		80.00	80.00
	REMOVE /REFIT /RESET TAILGATE REVERSE CAMERA.		280.00	280.00
	APPLY BODY UNDERSIDE COATING .		450.00	450.00
	REMOVE & RENEW RR FLOOR INSULATOR .		450.00	450.00
	REMOVE & INSTALL FUEL TANK FUEL PIPES.		560.00	560.00
	STRAIGHTEN ALING & PULL BACK EXHAUST SYSTEM.		100.00	100.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.		4,500.00	3,600.00
			17,460.00	14,740.00
GRAND TOTAL			34,199.26	19,972.18
RECOMMENDED COST OF REPAIRS				19,972.18

Report Ref No. CS/FCI18002591/T1vd3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.