

15/5/2010

INS. CASE OWNER:

Stacey

CC 4 / AXA 1800 2592

LKK:

IDAC:

Surveyor:

Kamal

DOI:

ASSIGNMENT

12/12/18

Date / Time:

8/2/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SJK 6365G

Name of Insured:

TEO ENG FENG

Insured Tel No.:

HP: 98349668

Excess Sec II :SS

D.O.A: 01/02/18

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

S8M0089A / 29973

Policy No.:

VPA1031696

Make / Model:

Honda

Place of Accident:

Mtl of Jln Jambak & upp
EAST LOST RD

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SN 478



INSRS:

WSP:

Tel:

Liability:

RMKS:

STUTTGART



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

8/2/18
jms

SJK 6365G - X

SJK 6365G - X

Start claim.

13/2/18 @ 1:30

Spoken with Mr. Confirmed coming out
from side Road & collected with TP
on main Road. Agreed to settle &
aware NCD issue.

To and better after survey conducted.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OE:

After call ltr to OE:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OE:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: MEB

Repair Cost:

PIP \$522,336.86

(12 days)

Reduction:

43 %

Email

Call

FINAL SETTLEMENT

Date/Time: 07-12-18

Confirm with: JANCE

Email

Call

Final Liability:

%

00

(Agreed / Assessed) BOLA S/N No.:

912

Repair Cost:

with:

SS 23,900.44

Loss of Rental (LOR):

SS

(days)

Loss of Use (LOU):

SS

2,240.00 (\$180 x 12 days)

Loss of Income (LOI):

SS

(\$ x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

SS 2-00

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

Total:

SS 27,142.44

Global Sum SS:

FINAL PAYMENT

Date/Time: 07-12-18

Confirm with: JANCE

Email

Call

Payee 1:

SS 27,142.44

Name 1:

STUTTGART AUTO PTE LTD

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

350

COPY SENT

Date / Time	Action / Instruction
	18.1
	P P: +22,336.86 (REV: +16,476.77 +2%/-)

Date/Time, File Pass to?	☐ : Preli. Report	Days Of Repair:	
1) _____	☐ : Final Report	Resurvey No. of Trip:	Survey Fee: _____
Date/Time, File Return to?			Transportation: _____
2) _____		Add Fee:	
		☐ : Site Insp. (\$ _____)	(\$ + RS \$)
		☐ : Interview (\$ _____)	Photo _____
		☐ : Tech. Invs (\$ _____)	Other: _____
		☐ : Weekend (\$ _____)	
Report Format : _____			
Lump Sum / I.B.I. (\$ _____)			
			TOTAL _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM18002592/yb3	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 08-02-2018	
		Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJK 6365G	Veh. Inspected	SN 47S
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	08/02/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	01/02/2018	Inspection Date	
Survey held at	STUTTGART AUTO PTE LTD 12 SUNGEI KADUT AVE . SINGAPORE 729648		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

ESTIMATED COST OF REPAIRS

NATURE OF WORKS	
1	2
3	4
5	6
7	8
9	10
11	12
13	14
15	16
17	18
19	20
21	22
23	24
25	26
27	28
29	30
31	32
33	34
35	36
37	38
39	40
41	42
43	44
45	46
47	48
49	50
51	52
53	54
55	56
57	58
59	60
61	62
63	64
65	66
67	68
69	70
71	72
73	74
75	76
77	78
79	80
81	82
83	84
85	86
87	88
89	90
91	92
93	94
95	96
97	98
99	100

[illegible][illegible]

3	TO CARRY OUT BODY CAVITY PRESERVATION TO ALL AFFECTED AREAS.		150	\$ 300.00
4	TO APPLY THEROSTAT SEALANT TO AFFECTED AREAS		X	\$ 300.00
5	TO REMOVE / REFIT SEATS, CARPETS, TRIM BOARDS, PILLAR TRIMS, HEAD LINING.		X	\$ 3,900.00
6	TO REMOVE / REFIT REAR WINDSCREEN. NETT QUARTER GLASS TO FACILITATE REPAIRS		X	\$ 480.00
7	TO SUPPLY WINDSCREEN SEALANT <i>nn</i> NETT		X	\$ 160.00
8	TO REMOVE, REPLACE, REFIT DOORS INCLUDE TRANSFER WINDOW MECHANISM FROM DAMAGE DOOR TO NEW DOOR & CHECK FUNCTION ABILITY NETT		780	\$ 1,400.00
9	TO CHECK STEERING GEOMETRY & CONDUCT WHEEL ALIGNMENT ACCORDING TO SPECIFICATIONS. NETT			\$ 680.00
10	TO REMOVE / REPLACE TYRES & RIMS @ \$60/-			\$ 60.00
11	TO SUPPLY 1 PCS TYRE \$980.00 ea <i>nn</i>		102 X	\$ 980.00
12	TO RE-PROGRAMMED SYSTEM & ERASE FAULT CODES AFTER ACCIDENT REPAIR. NETT		480	\$ 600.00
13	SUNDRIES. <i>nn</i>		50	\$ 100.00
		TOTAL LABOUR		\$ 26,420.00
		TOTAL PARTS		\$ 12,393.63
		GRAND TOTAL		\$ 38,813.63

Please note that this is **only an estimate**, base on our visual inspection. However should there be any additional work be found necessary in the course of repair and thus additional parts, materials and labor cost will be deem necessary, you will be inform accordingly prior to any action taken. In view of this, expected delays will be indivertible and therefore additional working days will be required. As such the loss of use and other incidentals will be adjusted accordingly.

4/258.98

Prepared By

Acknowledge By

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

RASUL
Hp 90010068
10-11 days
13/02/18 @ 1135
Reg 64 print

STUTTGART AUTO
NO:12 SUNGEI KADUT AVE (S) 729648 (FAX NO. 63602899)
FINALIZATION COST OF REPAIRS

AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811		NAME : Mr Goh Yong Khoon ADDRESS : 7 Siglap Road #17-67 Mandarin Garden Singapore 448909		WIP : 31556 DATE: 07.02.2018	
ATTN :	MOTOR CLAIM DEPT	TEL :			
FAX :	68804838 / 68804739				
VEH NO :	SN47S	DATE IN :		CONTACT PERSON :	RICK 63602445
CHASSIS NO :	WP0ZZZ96ZLS401671	MILEAGE :		TYPE OF CLAIM :	TP AGAINST SJK6365G
MODEL :	Porsche 911 C4	DATE REG.:	11.12.1989	POLICY NO. :	

NATURE OF WORKS

S/NO	Parts Description	QTY	PART NO	REVISED	PRICES
1	SIDE SECTION(LHS)	1	P964-503-061-01-GRV	\$ -	\$ 3,839.40
2	SEALING STRAP	1	P000-043-204-88-	\$ -	\$ 68.40
3	REAR BUMPER LH LINING	1	P964-505-163-00-G2X	\$ -	\$ 1,090.60
4	BLIND RIVET	10	P999-190-104-30-	\$ 11.00	\$ 11.00
5	DOOR IN WHITE PRIME COATED	1	P964-531-005-03-GRV	\$ 4,132.80	\$ 4,132.80
6	SPECIAL NUT	2	P999-591-498-40-	\$ 17.20	\$ 17.20
7	LH DOOR INNER SEAL	1	P911-531-889-00-	\$ -	\$ 118.90
8	RIVET	13	P999-190-204-00-	\$ 23.40	\$ 23.40
9	SILL COVER	1	P964-559-093-01-G2X	\$ -	\$ 1,011.70
10	REAR LH FENDER SILL TRIM	1	P964-559-095-01-G2X	\$ 296.80	\$ 296.80
11	LH SILL COVER STRIP	1	P964-559-293-01-01C	\$ 73.40	\$ 73.40
12	LH REAR COVER STRIP	1	P964-559-295-01-01C	\$ 66.50	\$ 66.50
13	SUPPORT FOR LH SIDE TRIM	1	P964-559-501-01-	\$ -	\$ 54.10
14	CLAMPING PIECE	1	P965-559-795-00-	\$ 11.00	\$ 11.00
15	BLIND RIVET	1	P999-190-104-30-	\$ 1.10	\$ 1.10
16	P999-049-022-40-/PLASTIC NUT	7	P999-049-007-40-	\$ 3.50	\$ 3.50
17	CLAMP PIECE FOR D/SILL	1	P964-559-797-00-	\$ 21.10	\$ 21.10
18	SUPPORT FOR DOOR SILL	3	P999-507-373-00-	\$ 25.20	\$ 25.20
19	SILL COVER GROMMET	6	P999-702-160-40-	\$ 10.80	\$ 10.80
20	DOORSILL TRIM RETAIN/BRAC	1	P965-559-471-00-	\$ -	\$ 87.30
21	ALLOY WHEEL	1	P964-362-116-01-	\$ 2,630.10	\$ 2,630.10
22	HUB CAP	1	PEXC-964-038-00-	\$ -	\$ 176.40
SUPPLEMENTARY					
1	MOULDING	1	P911-531-431-00-70K	\$ 263.90	✓
2	DOOR SILL TRIM EXP NUT	5	P999-591-717-40-	\$ 13.50	✓
3	LH DOOR GLASS SLOT SEAL	1	P911-531-931-02-	\$ 71.30	✓
4	DOOR FRAME OUTER SEAL	1	P901-531-933-20-	\$ 42.40	✓
5	LH DOOR GLASS SLOT SEAL	1	P901-531-935-20-	\$ 426.20	✓
6	LH DOOR BEADING	1	P911-531-297-01-01C	\$ 72.70	✓
7	DOOR INNER SLOT SEAL	1	P911-531-951-01-	\$ 66.85	✓
8	RH DOOR BEADING	1	P911-531-298-00-01C	\$ 72.70	✓
9	CLIP	14	P999-591-326-01-	\$ 166.60	✓
10	FOAM RING	7	P911-531-309-00-	\$ 77.70	✓
11	SILL COVER	1	P964-559-093-01-G2X	\$ 1,011.70	✓
12	LH DOOR INNER SEAL	1	P911-531-889-00-	\$ 118.90	✓
13	LH DOOR STEP RUBBER PAD	1	P911-551-619-00-	\$ 136.20	✓
14	WHEEL CAP	1	P928-361-032-11-TPP	\$ 176.40	✓
SUB TOTAL				\$ 10,040.95	\$ 13,770.70
				LESS 10%	\$ 1,004.10
					\$ 1,377.07

			Total Parts	\$ 9,036.86	\$ 12,393.63
	Labour Description				
1	TO REMOVE / REPLACE LH DAMAGED			\$ 7,800.00	\$ 13,260.00
	REAR BUMPER, LH REAR FENDER, LH DOOR,				
	LH SILL COVER & OTHER AFFECTED BODY PARTS,				
	INCLUDING PANEL BEAT / STRAIGHTEN BODY PANELS				
	& FITTINGS WHICHEVER NECESSARY INCLUDING				
	ALIGNMENT OF BODY STRUCTURE.				
2	TO SPRAY PAINT REAR BUMPER, LH REAR FENDER,			\$ 3,300.00	\$ 4,200.00
	LH DOOR & LH SILL COVER				
3	TO CARRY OUT BODY CAVITY PRESERVATION TO ALL			\$ 150.00	\$ 300.00
	AFFECTED AREAS.				
4	TO APPLY THEROSTAT SEALANT TO AFFECTED AREAS			\$ -	\$ 300.00
5	TO REMOVE / REFIT SEATS, CARPETS, TRIM			\$ -	\$ 3,900.00
	BOARDS, PILLAR TRIMS, HEAD LINING.				
6	TO REMOVE / REFIT REAR WINDSCREEN,		NETT	\$ -	\$ 480.00
	QUARTER GLASS TO FACILITATE REPAIRS				
7	TO SUPPLY WINDSCREEN SEALANT		NETT	\$ -	\$ 160.00
8	TO REMOVE, REPLACE, REFIT DOORS INCLUDE TRANSFER		NETT	\$ 780.00	\$ 1,400.00
	WINDOW MECHANISM FROM DAMAGE DOOR TO NEW DOOR				
	& CHECK FUNCTION ABILITY				
9	TO CHECK STEERING GEOMETRY & CONDUCT WHEEL		NETT	\$ 680.00	\$ 680.00
	ALIGNMENT ACCORDING TO SPECIFICATIONS.				
10	TO REMOVE / REPLACE TYRES & RIMS @ \$60/-			\$ 60.00	\$ 60.00
11	TO SUPPLY 1 PCS TYRE \$980.00 ea			\$ -	\$ 980.00
12	TO RE-PROGRAMMED SYSTEM & ERASE FAULT CODES		NETT	\$ 480.00	\$ 600.00
	AFTER ACCIDENT REPAIR.				
13	SUNDRIES.			\$ 50.00	\$ 100.00
			TOTAL LABOUR	\$ 13,300.00	\$ 26,420.00
			TOTAL PARTS	\$ 9,036.86	\$ 12,393.63
			GRAND TOTAL	\$ 22,336.86	\$ 38,813.63
			GST 7 %	\$ 1,563.58	
			TOTAL AFTER GST	\$ 23,900.43	

NUMBER OF DAYS: 12 WORKING DAYS(EXCLUDE WAITING FOR PARTS,SURVEY,AUTHORIZATION,SAT,SUN & PH)

Line	T	Product	Description	Quantity	Price	Disc%	Total	V	P	I
1	L	CST	TP CLAIM AGAINST	0	0		0	O	C	I
5	P	P999-190-104-30-	BLIND RIVET	10	1.1		20 \$ 11.00	S	X	I
6	P	P964-531-005-03-GRV	Door in white Prime coated	1	4132.8		20 \$ 4,132.80	S	X	I
7	P	P999-591-498-40-	SPECIAL NUT	2	8.6		20 \$ 17.20	S	X	I
10	P	P999-190-204-00-	RIVET	13	1.8		20 \$ 23.40	S	X	I
12	P	P964-559-095-01-G2X	REAR LH FENDER SILL TRIM	1	296.8		20 \$ 296.80	S	X	I
13	P	P964-559-293-01-01C	LH SILL COVER STRIP	1	73.4		20 \$ 73.40	S	X	I
14	P	P964-559-295-01-01C	LH REAR COVER STRIP	1	66.5		20 \$ 66.50	S	X	I
16	P	P965-559-795-00-	CLAMPING PIECE	1	11		20 \$ 11.00	S	X	I
17	P	P999-190-104-30-	BLIND RIVET	1	1.1		20 \$ 1.10	S	X	I
18	P	P999-049-007-40-	P999-049-022-40-/PLASTIC NUT	7	0.5		20 \$ 3.50	S	X	I
19	P	P964-559-797-00-	CLAMP PIECE FOR D/SILL	1	21.1		20 \$ 21.10	S	X	I
20	P	P999-507-373-00-	SUPPORT FOR DOOR SILL	3	8.4		20 \$ 25.20	S	X	I
21	P	P999-702-160-40-	SILL COVER GROMMET	6	1.8		20 \$ 10.80	S	X	I
23	P	P964-362-116-01-	ALLOY WHEEL	1	2630.1		20 \$ 2,630.10	S	X	I
25	P	P911-531-431-00-70K	MOULDING	1	263.9		20 \$ 263.90	S	X	I
26	P	P999-591-717-40-	DOOR SILL TRIM EXP NUT	5	2.7		20 \$ 13.50	S	X	I
27	P	P911-531-931-02-	LH DOOR GLASS SLOT SEAL	1	71.3		20 \$ 71.30	S	X	I
28	P	P901-531-933-20-	DOOR FRAME OUTER SEAL	1	42.4		20 \$ 42.40	S	X	I
29	P	P901-531-935-20-	LH DOOR GLASS SLOT SEAL	1	426.2		20 \$ 426.20	S	X	I
30	P	P911-531-297-01-01C	LH DOOR BEADING	1	72.7		20 \$ 72.70	S	X	I
31	P	P911-531-951-01-	DOOR INNER SLOT SEAL	1	66.85		20 \$ 66.85	S	X	I
32	P	P911-531-298-00-01C	RH DOOR BEADING	1	72.7		20 \$ 72.70	S	X	I
33	P	P999-591-326-01-	CLIP	14	11.9		20 \$ 166.60	S	X	I
34	P	P911-531-309-00-	FOAM RING	7	11.1		20 \$ 77.70	S	X	I
36	P	P964-559-093-01-G2X	SILL COVER	1	1011.7		20 \$ 1,011.70	S	X	I
37	P	P911-531-889-00-	LH DOOR INNER SEAL	1	118.9		20 \$ 118.90	S	X	I
38	P	P911-551-619-00-	LH DOOR STEP RUBBER PAD	1	136.2		20 \$ 136.20	S	M	I
39	P	P928-361-032-11-TPP	WHEEL CAP	1	176.4		20 \$ 176.40	S	M	I

\$ 10,040.95

Vic (LKKAuto)

From: jessicahs@eurokars.com.sg
Sent: Thursday, 12 April, 2018 9:51 AM
To: Rasul (LKKAuto); Admin A; CS A Team
Subject: finalization AXA TP - SN47S.xls
Attachments: finalization AXA TP - SN47S.xls

Dear Rasul,

Please find our computation attached for your agreement.

COR: \$22,336.86 before GST

12 repair days (not including preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)

Appreciate your confirming the above as soon as possible.

Thank you very much.

Regards,

Jessica Shastri

Admin Executive – Insurance Claims

Eurokars Group of Companies

(Porsche, Rolls Royce, Saab, Mini, Mazda, Mc.Laren)

Eurokars Centre

12 Sungei Kadut Avenue

Singapore 729648

Tel: +65 63633003

DID: +65 63602863

Fax: +65 63602899

ok

11.00	/
4,132.80	/
17.20	/
23.40	/
296.80	/
73.40	/
66.50	/
11.00	/
1.10	/
7,800.00	/
3.50	/
3,300.00	/
21.10	/
150.00	/
25.20	/
780.00	/
10.80	/
680.00	/
2,630.10	/
60.00	/
7,323.90	/
480.00	/
90%	/
50.00	/
6,591.51	13,300.00
19,891.51	

REVISED

176.40
90%
158.76
CHECK

= 20,050.27
TOTAL



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: S8M0089A
Our ref: CC4/ASM18002592/R1yb3

Date: 14.02.2018

The Motor Claims Department
M/s AXA INSURANCE SINGAPORE PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SN47S


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 13.02.2018 at the premises of M/s Stuttgart Auto Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	38,813.63
Revised Estimate Amount	: S\$	19,891.51
"Check" Items Amount	: S\$	158.76
Total (Including Check Items)	: S\$	20,050.27
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
N/S Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 10-11 days

Yours faithfully,

MOHD. RASUL
Licensed Appraiser

LKK AUTO CONSULTANTS PTE LTD (TP) ▾



Service Request Details

Claim

S8M0089A

Reference

None

Loss Date

February 1, 2018

Request Date

February 8, 2018

Due Date

February 15, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

08/02/2018 @ 9:47am
Eva veh not in

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SN47S

Make

TPVD PORSCHE

Service Address

...

Primary Contact/Insured

TEO ENG KENG

BLK 44 BEDOK SOUTH ROAD, 460044, Singapore

98349668

TEOEK48@YAHOO.COM.SG

Claim Handler

NG Stacey

6568804351

stacey.ng@axa.com.sg

Additional Instructions

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

Document Type

Document SubType

[+ Upload Documents](#)

NAME

 EMAIL WITH TP GIA & ESTIMATE.msg

TYPE

Forms / Claim Documents

SUB-TYPE

Others

AUTHOR

KUMAR Shailendra

DATE UPLOADED

February 8, 2018

NAME

 SJK6365G INS GIA.PDF

TYPE

Reports & Statement

SUB-TYPE

GIA Report

DATE UPLOADED

February 8, 2018



MANDATE REQUEST FOR S8M0089A

STASH

Type

🔔 Question

Message

Liability: Insured make a right turn into the main road hit third party vehicle. Spoken to insured and he aware that his NCD is affected and AXA to settle at best. Settlement: Repair Cost : \$23,900.44 (w/GST) Loss of Use: \$3,240.00 (18days x \$180) LTA : \$2.00 Total: \$27,142.44 Immediate Advice with Mandate uploaded for your easy reference. Please kindly let us have your approval / instruction if any. Thank you - Asher Sng (23/11/2018)

Reply



Re:MANDATE REQUEST FOR S8M0089A

Type

🔗 Question

Message

Please proceed.

Reply

PORSCHE

DISCHARGE VOUCHER

I/ We hereby acknowledge having received from the under-mentioned
Repairers my/our vehicle No: 84 HKS which has been
repaired to my satisfaction and I/we admit that the payment for such repairs
by Stuttgart Auto Pte Ltd is in full and final discharge of my claim under
policy number: _____ in respect of damage
caused to the said vehicle as a result of an accident that occurred on
01/02/2018 at junction between upper East coast road & Jalan Jermal.

Janice Syn



Witnessed by Repairers

29/03/2018

Date:

Song Huan

Signature by Insured

29/03/2018

Date:

Porsche Centre Singapore
Stuttgart Auto Pte Ltd
Eurocars Group of Companies
Company Reg. No. 198403740N

Corporate Head office & Postal add:
Eurocars Centre
12 Sungai Madau Ave
Singapore 729648

Tel: (65) 6363 0911
Fax: (65) 6363 3911

Website:
www.porsche.com.sg

City Centre:
29 Lang Koo Road
Singapore 159099

Tel: (65) 6472 4433
Fax: (65) 6474 3101

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SJK 6365G (Insd veh)	Model:	PORSCHE
	SN 47S (TP veh)		911 C-4 COUP
Date of Accident:	01/02/2018		

Global Sum Settlement	:	[] Yes	[X] No
Repair Estimate	:	\$	44,147.11
Final Repair Cost	:	\$	23,900.44
Loss of Use	:	\$	3,240.00
Rental (if any)	:	\$	18 days at \$180.00 per day
LTA / GIA Search Fee	:	\$	2.00

Others:	:	\$
---------	---	----

	:	\$
Final Settlement Sum	:	\$ 27,142.44

Is Third Party Workshop GIA Registered?		[] YES	[X] NO	(Kindly indicate below)
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 _____ (%)		
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____		
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks _____				

Payment Instruction: Payee's Breakdown			
1)	STUTTGART AUTO PTE LTD	:	\$ 27,142.44

NUR SHAQILAH BTE ABDOL
WAHAB

12/12/2018
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

Service Request Details

Claim	S8M0089A	Reference	CC4/ASM18002592/R1et3s2 	Loss Date	February 1, 2018	Request Date	February 8, 2018	Due Date	February 8, 2019	Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)	Type of Loss	Third Party Vehicle Damage	Services	Pending verification - Direct Settlement		
Actions Next Step Finish the work Complete Work More		Document Type Document Sub Type		Upload Documents		Vehicle Information		Incident Vehicle Registration # SN47S		Service Address Make		Model TPVD PORSCHE		Primary Contact/Insured 911/BLACK		TEO ENG KENG BLK 44 BEDOK SOUTH ROAD, 460044, Singapore 98349668 TEOEK48@YAHOO.COM.SG	
Claim Handler NG Stacey 6568804351 stacey.ng@axa.com.sg		Messages Invoices Assessment		History Metrics Notes		Documents		DATE UPLOADED November 23, 2018									
Additional Instructions		Reports & Statement		Others		LKK AUTO CONSULTANTS PTE LTD (TP)		LTA PARF COE Rebate Details, pdf									

SERVICE REQUESTS MESSAGES CLAIMS

<< Service Request Details

Claim	S8M0089A	Actions		Add	
Reference					
CC4/ASM18002592IR1eb3s2	Loss Date	Next Step		Finish the work	Complete Work
February 1, 2018	Request Date				Move
February 8, 2018	Due Date				
February 8, 2019	Vendor Name				
LKK AUTO CONSULTANTS PTE LTD (TP)	Type of Loss	Vehicle Information			
Third Party Vehicle Damage	Services	Incident Vehicle Registration #	SN47S	Make	Service Address
Pending verification - Direct Settlement		TPVD PORSCHE	Model	...	
		/811/BLACK	Primary Contact/Insured		
		TEO ENG KENG BLK 44 BEDOK SOUTH ROAD, 460044, Singapore 98349668 TEOEK48@YAHOO.COM.SG			
Claim Handler					
NG Stacey 6568804351 stacey.ng@axa.com.sg					
Additional Instructions					
CREATED USER	VERSION DATE	ESTIMATED AMOUNT	APPROVED AMOUNT	STATUS	SHARE
KUMAR Shailendra	2/8/18 9:02 AM	22336.86	22336.86	Open	Share
					Clone



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Vehicle & Driver Details

Vehicle Registration#	SN47S	Purchase Date	mm/dd/yyyy
Registration State	SINGAPORE	Registration Date *	12/11/1989
Mileage	19895	Age of Vehicle	28
Driver Details			
CATEGORY	POLICY INFORMATION	FNOL INFORMATION	POST SURVEY INFORMATION
Manufacturing Year	1989	Driver Name	GOH YONH KHOON
Make	TPVD PORSCHE	Date of Birth	December 31, 1899
Model	/911/BLACK	Age	118
Type		Occupation	Unknown
Type of Paint		Education Qualification	Other
Chassis No	WPOZZZ96ZLS401671	Driving Experience	0
Engine No	62L02693	Driver License #	
Engine Capacity	3600 cc		



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Detailed Assessment

Inspection Date *

02/13/2018

Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/Unlicensed Driver Excess

0

Other Excess

Condition of Vehicle at time of survey

General condition

Fair

Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good

Tyre Condition

Age of Tyres

Front Tyre Size

225/50ZR16

Front left side

MICHELIN 6mm

Front right side

MICHELIN 6mm

Spare wheel

Rear Tyre Size

225/50ZR16

Rear left side

MICHELIN 6mm

Rear right side

MICHELIN 6mm

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary Parts

Add		Approve		Early		Submit All										
	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC COUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		1	1			SIDE SECTION (LHS)			Repair	0		10		0	Reviewing	
		2	1			SEALING STRAP			Serviceable	0		10		0	Reviewing	
		3	1			REAR BUMPER LH LINING			Repair	0		10		0	Reviewing	
		4	10			BLIND RIVET			Necessary	1.1		10		9.9	Reviewing	
		5	1			DOOR IN WHITE PRIME COATED			Bent	4132.8		10		3719.52	Reviewing	
		6	2			SPECIAL NUT			Necessary	8.5		10		15.48	Reviewing	
		7	1			LH DOOR INNER SEAL			Serviceable	0		10		0	Reviewing	
		8	13			RIVET			Necessary	1.8		10		21.06	Reviewing	
		9	1			SILL COVER			Repair	0		10		0	Reviewing	
		10	1			REAR LH FENDER SILL TRIM			Deformed	296.8		10		267.12	Reviewing	
		11	1			LH SILL COVER STRIP			Necessary	73.4		10		66.06	Reviewing	

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ 8116%	DISC COUNTH	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	27	1			LH DOOR GLASS SLOT SEAL			Necessary	426.2		10		383.58	Reviewing	
	28	1			LH DOOR BEADING			Necessary	72.7		10		65.43	Reviewing	
	29	1			DOOR INNER SLOT SEAL			Necessary	66.85		10		60.17	Reviewing	
	30	1			RH DOOR BEADING			Necessary	72.7		10		65.43	Reviewing	
	31	14			CLIP			Necessary	11.9		10		149.94	Reviewing	
	32	7			FOAM RING			Necessary	11.1		10		69.93	Reviewing	
	33	1			SILL COVER			Deformed	1011.7		10		910.53	Reviewing	
	34	1			LH DOOR INNER SEAL			Necessary	118.9		10		107.01	Reviewing	
	35	1			LH DOOR STEP RUBBER PAD			Necessary	136.2		10		122.58	Reviewing	
	36	1			WHEEL CAP			Damaged	176.4		10		158.76	Reviewing	

Labour

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
	1		TO REMOVE / REPLACE LH DAMAGED REAR BUMPER, LH REAR FENDER, LH DOOR, LH SILL COVER & OTHER AFFECTED BODY PARTS, INCLUDING PANEL BEAT / STRAIGHTEN BODY PANELS & FITTINGS WHICHEVER NECESSARY INCLUDING ALIGNMENT OF BODY STRUCTURE.	7800	0	0	Reviewing		
	2		TO SPRAY PAINT REAR BUMPER, LH REAR FENDER, LH DOOR & LH SILL COVER.	3300	0	0	Reviewing		
	3		TO CARRY OUT BODY CAVITY PRESERVATION TO ALL AFFECTED AREAS	150	0	0	Reviewing		

SERVICE REQUESTS MESSAGES CLAIMS

<<

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Pans & Labour

Miscellaneous

Summary

Act

Approve

Deny

Submit All

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		1	DAYS OF REPAIR	Reviewing		11	
		2	WINDSCREEN SEALANT	Reviewing	0	NOT NECESSARY	
		3	TYRE	Reviewing	0	NOT NECESSARY	
		4	SUNDRIES	Reviewing	50	NECESSARY	

SERVICE REQUESTS MESSAGES CLAIMS

<< **Assessment Details**

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Claim Amount \$22,336.86

Claim Amount \$22,336.86

CATEGORY ESTIMATE REVISED AMOUNT

Spare Parts \$9,036.86 \$9,036.86

Labour \$13,250.00 \$13,250.00

Miscellaneous \$50.00 \$50.00

Submit for Review