

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
	4		TO APPLY THEROSATAT SEALANT TO AFFECTED AREAS.	0	0	0	Reviewing		
	5		TO REMOVE / REFIT SEATS, CARPETS, TRIM BOARDS, PILLAR TRIMS, HEAD LINING.	0	0	0	Reviewing		
	6		TO REMOVE / REFIT REAR WINDSCREEN, QUARTER GLASS TO FACILITATE REPAIRS.	0	0	0	Reviewing		
	7		TO REMOVE, REPLACE, REFIT DOORS INCLUDE TRANSFER WINDOW MECHANISM FROM DAMAGE DOOR TO NEW DOOR & CHECK FUNCTION ABILITY.	780	0	0	Reviewing		
	8		TO CHECK STEERING GEOMETRY & CONDUCT WHEEL ALIGNMENT ACCORDING TO SPECIFICATIONS.	680	0	0	Reviewing		
	9		TO REMOVE / REPLACE TYRES & RIMS.	60	0	0	Reviewing		
	10		TO RE-PROGRAMMED SYSTEM & ERASE FAULT CODES AFTER ACCIDENT REPAIR.	480	0	0	Reviewing		

018

Claim Portal

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPRJ BTR%	DISC CUNT%	SALV AGEN	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		12	1			LH REAR COVER STRIP			Necessary	66.5		10		59.85	Reviewing	
		13	1			SUPPORT FOR LH SIDE TRIM			Serviceable	0		10		0	Reviewing	
		14	1			CLAMPING PIECE			Necessary	11		10		9.9	Reviewing	
		15	1			BLIND RIVET			Necessary	1.1		10		0.99	Reviewing	
		16	7			P999-049-022-40-PLASTIC NUT			Necessary	0.5		10		3.15	Reviewing	
		17	1			CLAMP PIECE FOR D/SILL			Necessary	21.1		10		18.99	Reviewing	
		18	3			SUPPORT FOR DOOR SILL			Necessary	8.4		10		22.68	Reviewing	
		19	6			SILL COVER GROMMET			Necessary	1.8		10		9.72	Reviewing	
		20	1			DOORSILL TRIM RETAINBRAC			Serviceable	0		10		0	Reviewing	
		21	1			ALLOY WHEEL			Damaged	2630.1		10		2367.09	Reviewing	
		22	1			HUB CAP			Serviceable	0		10		0	Reviewing	
		23	1			MOULDING			Cut	263.9		10		237.51	Reviewing	
		24	5			DOOR SILL TRIM EXP NUT			Necessary	2.7		10		12.15	Reviewing	
		25	1			LH DOOR GLASS SLOT SEAL			Necessary	71.3		10		64.17	Reviewing	
		26	1			DOOR FRAME OUTER SEAL			Necessary	42.4		10		38.16	Reviewing	

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION	CATEGORY	PNOL INFORMATION	POST SURVEY INFORMATION
Sum Insured	0		License Type		
Market Value	0		License Issue Date		mm/dd/yyyy
			License Expiration Date		mm/dd/yyyy
			Address		
			Address type		
			Gender	Unknown	
			Marital status	Unknown	
			Identification #	S0161263H	

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
Immediate Advice with Mandate.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	November 23, 2018
GIA SEARCH.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	November 23, 2018
LKK Survey Photo.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	November 23, 2018
GIA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	May 30, 2018
TP_ESTIMATE_MARKED.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	March 19, 2018
Preliminary_Advice.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	March 19, 2018
SJK636SG INS GIA.PDF	Reports & Statement	GIA Report	KUMAR Shalendra	February 8, 2018
EMAIL WITH TP GIA & ESTIMATE.msg	Forms / Claim Documents	Others	KUMAR Shalendra	February 8, 2018